

Effective: 15/02/2021 to 15/02/2022
Service: Roads General
Site: Gogarmuir Road (7905192)

Asset Number: 1.00 to 99.00
Display Action Officer: No

Site: Gogarmuir Road (7905192)

Locality: Gogar, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 1 - From Gogarbank at Hermiston House Road west to we	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41098395 - Inspection Batch		Route:	Ad hoc Route			Date:	18/08/2021
42076205	Road: Defective / Damaged (Enquiry 1228493) Pothole on carriageway	18/08/2021	Junction Roddinglaw Road	RD: CW Pothole	Internal		Committed	50089926
Batch:	41090581 - Inspection Batch		Route:	NW_CF1_GogarSouth1			Date:	19/04/2021
42067189	Refresh both bus stop road markings	19/04/2021	Bus stops road markings faded on East bound & west bound carriageway at junction with roddinglaw road	RD: Markings Refresh	Internal		Uncommitted	50013272
42067190	1 x pothole	19/04/2021	Near junction with roddinglaw road	RD: CW Pothole	Internal		Action Required	
42067188	Refreshing white centre lines	19/04/2021	Faded white central carriageway lines require refreshing at junction with roddinglaw road	RD: Markings Refresh	Internal		Uncommitted	50013273
Asset:	2.00	Asset - Locn.:	Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type:	Road Asset		Area:	South West Locality
Batch:	41114750 - Inspection Batch		Route:	SW_CW1_West1			Date:	04/02/2022
	No actionable defects found							
Batch:	41112548 - Inspection Batch		Route:	SW_CW1_West1			Date:	10/01/2022
	No actionable defects found							
Batch:	41109528 - Inspection Batch		Route:	SW_CW1_West1			Date:	06/12/2021
	No actionable defects found							
Batch:	41109473 - Inspection Batch		Route:	Ad hoc Route			Date:	06/12/2021
42086058	Pothole on cw	06/12/2021	Just before bridge	RD: CW Pothole	Internal		Committed	50099362
Batch:	41106245 - Inspection Batch		Route:	SW_CW1_West1			Date:	02/11/2021
42081919	Pothole on cw	02/11/2021	At bridge over moto	RD: CW Pothole	Internal		Committed	50095478
Batch:	41102209 - Inspection Batch		Route:	SW_CW1_West1			Date:	30/09/2021
	No actionable defects found							
Batch:	41100006 - Inspection Batch		Route:	SW_CF1_Ransfield1			Date:	14/09/2021
42078003	Open joint potholing	14/09/2021	Approximately 50m from motorway bridge	RD: CW Open Joint	Internal		Uncommitted	50091587
42077999	Broken surface	14/09/2021	As marked on map	RD: CW Cracked/Broken	Internal		Uncommitted	50091583
42078002	Broken surface where temp repairs are beginning to fail	14/09/2021	As marked on map	RD: CW Cracked/Broken	Internal		Uncommitted	50091586
42077996	Broken surface	14/09/2021	As marked on map	RD: CW Cracked/Broken	Internal		Uncommitted	50091580
42078000	Broken surface	14/09/2021	As marked on map	RD: CW Cracked/Broken	Internal		Uncommitted	50091584
42078004	Broken surface	14/09/2021	At entrance to field	RD: CW Cracked/Broken	Internal		Uncommitted	50091588
42077997	Open joint cw centre	14/09/2021	As marked on map	RD: CW Open Joint	Internal		Uncommitted	50091581
42077995	1 x broken surface	14/09/2021	Just before bridge	RD: CW Cracked/Broken	Internal		Action Required	
42077998	Broken surface for approximately 50m	14/09/2021	As marked on map,	RD: CW Cracked/Broken	Internal		Uncommitted	50091582
Batch:	41099099 - Inspection Batch		Route:	SW_CW1_West1			Date:	27/08/2021
	No actionable defects found							

Effective: 15/02/2021 to 15/02/2022

Service: Roads General

Site: Gogarmuir Road (7905192)

Asset Number: 1.00 to 99.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road		Feature Type: Road Asset		Area: South West Locality		
Batch:	41096956 - Inspection Batch			Route:	SW_CW1_West1			Date: 27/07/2021
	No actionable defects found							
Batch:	41094670 - Inspection Batch			Route:	SW_CW1_West1			Date: 22/06/2021
	No actionable defects found							
Batch:	41092675 - Inspection Batch			Route:	SW_CW1_West1			Date: 19/05/2021
	No actionable defects found							
Batch:	41090830 - Inspection Batch			Route:	SW_CW1_West1			Date: 21/04/2021
	No actionable defects found							
Batch:	41088526 - Inspection Batch			Route:	SW_CW1_West1			Date: 23/03/2021
	No actionable defects found							
Batch:	41086946 - Inspection Batch			Route:	Ad hoc Route			Date: 09/03/2021
42063749	Road: Defective / Damaged (Enquiry 1135095)	09/03/2021	Gogarmuir Road. From Addiston Farm Road to bridge over M8. potholes on road.	RD: CW Pothole	Internal		Committed	50077846
Batch:	41086154 - Inspection Batch			Route:	SW_CW1_West1			Date: 03/03/2021
	No actionable defects found							

Customer Services

Enquiry No.:	1323419	Logged by:	Verint CRM Connector	on:	09/02/2022 16:43
Service:	Roads General	Subject:	Road: Defective / Damaged	Classification:	Request for service
Desc.:					
Location:	There is a 200 yard area of deep potholes forming and cars are nearly hitting each other by having to swerve these potholes. Only a matter of time before someone is seriously injured or an accident occurs.				Contact:
Plot Number:	2.00	Feature Id - Location:	Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type:	Road Asset
Enquiry No.:	1318733	Logged by:	Verint CRM Connector	on:	02/02/2022 11:37
Service:	Roads General	Subject:	Road: Defective / Damaged	Classification:	Request for service
Desc.:					
Location:	Broken up surface				Contact:
Plot Number:	2.00	Feature Id - Location:	Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type:	Road Asset
Enquiry No.:	1318731	Logged by:	Verint CRM Connector	on:	02/02/2022 11:35
Service:	Roads General	Subject:	Road: Defective / Damaged	Classification:	Request for service
Desc.:					
Location:	Series of potholes				Contact:
Plot Number:	2.00	Feature Id - Location:	Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type:	Road Asset

Effective: 15/02/2021 to 15/02/2022
Service: Roads General
Site: Gogarmuir Road (7905192)

Asset Number: 1.00 to 99.00
Display Action Officer: No

Customer Services

Enquiry No.: 1318729	Logged by: Verint CRM Connector	on: 02/02/2022 11:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of potjholes	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1318720	Logged by: Verint CRM Connector	on: 02/02/2022 11:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of potholes	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1318716	Logged by: Verint CRM Connector	on: 02/02/2022 11:26
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of potholes	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1318706	Logged by: Verint CRM Connector	on: 02/02/2022 11:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of potholes	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1318701	Logged by: Verint CRM Connector	on: 02/02/2022 11:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of potholes	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1318698	Logged by: Verint CRM Connector	on: 02/02/2022 11:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1311469	Logged by: Verint CRM Connector	on: 21/01/2022 15:30
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road from the bridge over the canal adjacent to the entrance to Ratho Park golf club right through to the bridge over the M8 extension is literally riddled with potholes.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset

Effective: 15/02/2021 to 15/02/2022
Service: Roads General
Site: Gogarmuir Road (7905192)

Asset Number: 1.00 to 99.00
Display Action Officer: No

Customer Services

Enquiry No.: 1300360	Logged by: Verint CRM Connector	on: 04/01/2022 11:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road surface condition very poor along this stretch, worsening recently.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1238669	Logged by: Verint CRM Connector	on: 02/09/2021 19:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 4 large potholes heading east side	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1238033	Logged by: Verint CRM Connector	on: 01/09/2021 20:14
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sevral potholes heading east Lumps of tarmac surrounds potholes .	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1238025	Logged by: Verint CRM Connector	on: 01/09/2021 20:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole heading east	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1238024	Logged by: Verint CRM Connector	on: 01/09/2021 19:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 4 potholes next to each other. heading east . As seen in picture	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1229099	Logged by: Verint CRM Connector	on: 17/08/2021 15:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Next to a track road on gogarmuir rd .collection of potholes together.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1228499	Logged by: Verint CRM Connector	on: 16/08/2021 17:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several potholes together	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset

Effective: 15/02/2021 to 15/02/2022
Service: Roads General
Site: Gogarmuir Road (7905192)

Asset Number: 1.00 to 99.00
Display Action Officer: No

Customer Services

Enquiry No.: 1228496	Logged by: Verint CRM Connector	on: 16/08/2021 17:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 3 large potholes heading east side near roddinglaw junction	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 1 - From Gogarbank at Hermiston House Road west to we	Feature Type: Road Asset
Enquiry No.: 1228493	Logged by: Verint CRM Connector	on: 16/08/2021 16:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole just before junction heading east	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 1 - From Gogarbank at Hermiston House Road west to we	Feature Type: Road Asset
Job Number: 50089926	Defect Number: 42076205	
Enquiry No.: 1217248	Logged by: Verint CRM Connector	on: 28/07/2021 20:26
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: Damaged sign, incorrectly positioned and covered in foliage	Contact:	
Enquiry No.: 1184707	Logged by: Verint CRM Connector	on: 03/06/2021 04:50
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This needs urgent repair, road is in a terrible state. Folk are having to drive in the middle of the road to avoid huge potholes and rough surfaces, this is likely to have 2 outcomes an accident or damaged vehicles or possibly both. Plus it's highly dangerous for vulnerable road users. Words fail me how the council can allow it to become that bad. The patching attempted was exceptionally poor "workmanship".	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1135099	Logged by: Verint CRM Connector	on: 05/03/2021 10:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Ransfield Road. Dalmahoy Road to Addiston Farm Road. potholes on road.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Enquiry No.: 1135095	Logged by: Verint CRM Connector	on: 05/03/2021 10:22
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Gogarmuir Road. From Addiston Farm Road to bridge over M8. potholes on road.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road	Feature Type: Road Asset
Job Number: 50077846	Defect Number: 42063749	

Effective: 15/02/2021 to 15/02/2022
 Service: Roads General
 Site: Gogarmuir Road (7905192)

Asset Number: 1.00 to 99.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 1 - From Gogarbank at Hermiston House		Feature Type: Road Asset		Area: North West Locality	
50013272	Refresh both bus stop road markings (RD: Markings Refresh)	Bus stops road markings faded on East bound & west bound carriageway at junction with roddinglaw road	RD: Cat 4 - 12 Months	Job Annulled	22/07/2018	22/07/2019	Est.
50013273	Refreshing white centre lines (RD: Markings Refresh)	Faded white central carriageway lines require refreshing at junction with roddinglaw road	RD: Cat 4 - 12 Months	No code allocated	22/07/2018	22/07/2019	Est.
50089926	Road: Defective / Damaged (Enquiry 1228493) Pothole on carriageway (RD: CW Pothole)	Junction Roddinglaw Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/08/2021	19/08/2021	Act. ROAD/82053337
Asset: 2.00		Asset - Locn.: Ward 2 - From M8 to Addiston Farm Road at Ransfield Road		Feature Type: Road Asset		Area: South West Locality	
50077846	Road: Defective / Damaged (Enquiry 1135095) (RD: CW Pothole)	Gogarmuir Road. From Addiston Farm Road to bridge over M8. potholes on road.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/03/2021	11/03/2021	Act. ROAD/82046603
50091580	Broken surface (RD: CW Cracked/Broken)	As marked on map	RD: Cat 4 - 12 Months	No code allocated	14/09/2021	14/09/2022	Est.
50091581	Open joint cw centre (RD: CW Open Joint)	As marked on map	RD: Cat 4 - 12 Months	No code allocated	14/09/2021	14/09/2022	Est.
50091582	Broken surface for approximately 50m (RD: CW Cracked/Broken)	As marked on map,	RD: Cat 4 - 12 Months	No code allocated	14/09/2021	14/09/2022	Est.
50091583	Broken surface (RD: CW Cracked/Broken)	As marked on map	RD: Cat 4 - 12 Months	No code allocated	14/09/2021	14/09/2022	Est.
50091584	Broken surface (RD: CW Cracked/Broken)	As marked on map	RD: Cat 4 - 12 Months	No code allocated	14/09/2021	14/09/2022	Est.
50091586	Broken surface where temp repairs are beginning to fail (RD: CW Cracked/Broken)	As marked on map	RD: Cat 4 - 12 Months	No code allocated	14/09/2021	14/09/2022	Est.
50091587	Open joint potholing (RD: CW Open Joint)	Approximately 50m from motorway bridge	RD: Cat 4 - 12 Months	No code allocated	14/09/2021	14/09/2022	Est.
50091588	Broken surface (RD: CW Cracked/Broken)	At entrance to field	RD: Cat 4 - 12 Months	No code allocated	14/09/2021	14/09/2022	Est.
50095478	Pothole on cw (RD: CW Pothole)	At bridge over moto	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/11/2021	03/11/2021	Act. ROAD/82055613
50099362	Pothole on cw (RD: CW Pothole)	Just before bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/12/2021	08/12/2021	Act. ROAD/82057167