Site History Report

Effective: 08/04/2023 to 27/05/2025

Service: Roads General

No actionable defects found **Batch:** 41156538 - Inspection Batch

No actionable defects found

No actionable defects found

Batch: 41155169 - Inspection Batch

Site: Marionville Road (7901954)

Asset Number: 2.00 to 2.00

Display Action Officer: No

	Site: Marionville	e Road (7901954)										
Site: Marionville Road (7901954)			Locality: Meadowbank, Edinburgh, City of Edinburgh					Area: North East Locality				
Condition Sur	vey											
Defect No: Descr	ription	Log	Date	Location		Defect	Туре	Class.	Organisation	Status	J	ob No.
Asset:	2.00	Asset - Locn.: Ward	14 - Bra	anch north-wes	st off roundabout to Moray	Park	Feature Type: Ro	ad Asset		Area: North	East Locality	
Batch: 412	223677 - Inspection	n Batch			Route: NE	_CW1_V	/est1				Date: 21/03	3/2025
No ac	tionable defects for	und										
Batch: 412	n Batch			Route: NE	_CF1_M	arionvilleRd1				Date: 17/02	2/2025	
No ac	tionable defects for	und										
Batch: 412	214762 - Inspection	n Batch			Route: NE	_CW1_V	/est1				Date: 15/01	1/2025
No ac	tionable defects for	und										
Batch: 412	208023 - Inspection	n Batch			Route: NE	_CW1_V	/est1				Date : 19/11	/2024
No ac	tionable defects for	und										
Batch: 412	200766 - Inspection	n Batch			Route: NE	_CW1_V	/est1				Date: 17/09	9/2024
No ac	tionable defects for	und										
Batch: 411	193972 - Inspection	Batch			Route: NE	_CW1_V	/est1				Date: 10/06	6/2024
No ac	tionable defects for	und										
Batch: 411	187243 - Inspection	Batch			Route: NE	_CW1_V	/est1				Date: 22/03	3/2024
No ac	tionable defects for	und										
Batch: 41184003 - Inspection Batch		Batch			Route: NE	_CF1_M	arionvilleRd1				Date: 27/02	2/2024
No ac	tionable defects for	und										
Batch: 41177960 - Inspection Batch		Batch			Route: NE	_CW1_V	/est1				Date: 09/01	1/2024
No ac	tionable defects for	und										
Batch: 411	168341 - Inspection	Batch			Route: NE	_CW1_V	/est1				Date: 11/10)/2023
No ac	tionable defects for	und										
Batch: 411	161735 - Inspection	n Batch			Route: NE	_CW1_V	/est1				Date: 26/07	7/2023
No ac	tionable defects for	und										
Batch: 411	160361 - Inspection	Batch			Route: NE	_FW2_N	orth1				Date: 03/07	7/2023
No ac	tionable defects for	und										
Batch: 411	158655 - Inspection	Batch			Route: NE	_FW2_N	orth1				Date: 05/06	6/2023

Route: NE_FW2_North1

Route: NE_CW1_West1

Date: 03/05/2023

Date: 19/04/2023

Site History Report

Contact:

on: 26/04/2025 15:57

Effective: 08/04/2023 to 27/05/2025

Service: Roads General

Site: Marionville Road (7901954)

Asset Number: 2.00 to 2.00

Display Action Officer: No

Customer Services

Logged by: Verint CRM Connector **Enquiry No.:** 1952035 on: 22/05/2025 16:57

Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: Problem: Causing Obstruction.

Location:Pavement. Type:Foliage / Bush

Location: The hedge is on the property of 18 Marionville Road and is causing an obstruction Contact:

on the pavement.

Logged by: Verint CRM Connector on: 19/05/2025 14:36 Enquiry No.: 1950201 Subject: Trees & Foliage: Defect Classification: Request for service

Service: Roads General Desc.: Problem: Causing Obstruction.

Location:Footpath.

Type:Foliage / Bush

Location: hedge overgrown to cover entire footpath Contact:

Logged by: Verint CRM Connector **Enquiry No.:** 1947707

on: 14/05/2025 08:40 Subject: Trees & Foliage: Defect Service: Roads General Classification: Request for service

Desc.: Problem: Causing Obstruction.

Location:Footpath. Type:Foliage / Bush

Location: Hedge. Overgrown. Building is a HMO.

Obstructing footpath for wheelchairs.

Enquiry No.: 1939109 Logged by: Verint CRM Connector

Subject: Trees & Foliage: Defect Classification: Request for service Service: Roads General

Desc.: Problem: Causing Obstruction.

Location:Footpath. Type:Foliage / Bush

Location: Repeated obstruction by the owners hedge neglect. Reported multiple times Contact:

Enquiry No.: 1937880 Logged by: Verint CRM Connector on: 24/04/2025 08:44 Subject: Trees & Foliage: Defect Classification: Request for service

Service: Roads General Desc.: Problem: Overgrown.

Location:Pavement. Type:Foliage / Bush

Location: I think it might be address 18 or 20, not sure. But no more than a single person can

cross that pavement because it's so overgrown

on: 16/04/2025 11:25 **Enquiry No.:** 1934409 Logged by: Verint CRM Connector

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: There is a pothole forming right beside the pavement tiles at the traffic lights Contact:

entering Meadowbank Retail Park. This photo was taken in January but a member of the public has phoned to advise this is in a bad state and a serious trip hazard as

she has tripped up on this.

Plot Number: 2.00 Feature Id - Location: Ward 14 - Branch north-west off roundabout to Moray Park Feature Type: Road Asset

Site History Report

Effective: 08/04/2023 to 27/05/2025

Service: Roads General

Site: Marionville Road (7901954)

Asset Number: 2.00 to 2.00

Display Action Officer: No

on: 23/03/2025 17:58

Customer Services

Logged by: Verint CRM Connector **Enquiry No.:** 1922449

Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: Problem: Overgrown. Location:Pavement.

Service: Roads General

Location: The hedge at 18 marionville road is vastly overgrown and takes over half the width of Contact:

tbe pavement

Type:Foliage / Bush

on: 27/01/2025 09:04 Enquiry No.: 1893089 Logged by: Classification: Request for service

Subject: Trees & Foliage: Defect Service: Roads General

Desc.: Fallen tree on pavement

Location: o/s 111 Contact:

Logged by: Verint CRM Connector on: 25/10/2024 12:16 Enquiry No.: 1849331 Subject: Trees & Foliage: Defect Classification: Request for service Service: Roads General

Desc.: Problem: Other. Location:Park.

Type:Foliage / Bush

Location: Bus stop at Marionville Road before the bend to Restalrig Road South. Contact:

on: 26/08/2024 09:20

Enquiry No.: 1822216 Logged by: Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.: Unavoidable potholes when exiting the roundabout

Location: Contact:

Logged by: Verint CRM Connector **Enquiry No.:** 1814100 on: 11/08/2024 10:56 Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: Problem: Overgrown. Location: Footpath. Type: Foliage / Bush Hedge at 264 Marionville rd continually very overgrown over pavement area near bus stop, also very large brambles growing from

unkempt garden at 266 Marionville Road which members of the public have to push back to prevent scratching p[assing pedestrians.

Location: Contact:

Enquiry No.: 1750808 Logged by: Verint CRM Connector on: 09/05/2024 12:21 Subject: Pavement: Damaged / Defective Classification: Request for service Service: Roads General

Desc.:

Location: Uneven pathway to the pedestrian crossing next to the entrance of Meadowbank Contact:

Shopping Park in Edinburgh.

Plot Number: 2.00 Feature Id - Location: Ward 14 - Branch north-west off roundabout to Moray Park Feature Type: Road Asset

Enquiry No.: 1575708 Logged by: Verint CRM Connector on: 03/07/2023 13:15 Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: Problem: Causing Obstruction. Location:Footpath. Type:Foliage / Bush

Location: An overgrown bush / hedge forces people to walk on the road. Contact: