Effective: 01/03/2025 to 30/04/2025 Service: Roads General

Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Newcraighall Road (7906128)			Locality: Newcraighall, Edinburgh, City of Edinburgh				Area: North East Locality		
Condition Survey									
Defect No: Description		Log Date	Location	Def	ect Type	Class.	Organisation	Status	Job No.
Asset: 1.	00 Asset - Loci	n.: Ward 17 - Fro	m The Wisp to southbound	d on-ramp to A1 Mu	ssell Feature Type: Road	Asset		Area: North Ea	ast Locality
Batch: 41225582 -	Inspection Batch			Route: South M	obile Inspection Route				Date: 09/04/2025
No actionable	defects found								
Batch: 41225456 -	Inspection Batch			Route: NE_New	craighall_6Month				Date: 08/04/2025
42180945 x5 patches as Approx 1.5x2m .5x1.5m 0.25x1m 0.25x0.25m .5mx1m	marked	08/04/2025	At fort kinnaird east bus	stop RD	FW HRA Cracked/Broken	Interna	I	Committed	50178305
Batch: 41222335 -	Inspection Batch			Route: South M	obile Inspection Route				Date: 12/03/2025
No actionable	defects found				·				
Batch: 41222312 -	Inspection Batch			Route: Ad hoc F	coute				Date: 12/03/2025
42178416 1 number poth	nole	12/03/2025	Under bridge At Lamposi NAW60	t number RD	CW Pothole	Interna	I	Committed	50176782
Asset: 2.	00 Asset - Loci	n.: Ward 17 - Fro	m Musselburgh Bypass ea	ast to Newcraighall	Orive Feature Type: Road	Asset		Area: North Ea	ast Locality
Batch: 41225581 -	Inspection Batch			Route: South M	obile Inspection Route				Date: 09/04/2025
No actionable	defects found								
Batch: 41222334 -	Inspection Batch			Route: South M	obile Inspection Route				Date: 12/03/2025
No actionable	defects found								
Batch: 41221756 -	Inspection Batch			Route: Ad hoc F	loute				Date: 07/03/2025
42178010 Sunken cracke carriageway	ed BT manhole cover on	07/03/2025	Outside number 93	RU	Utility Apparatus	Interna	I	Uncommitted	50176524
Customer Services									
Enquiry No.: 34009792 Service: Roads Ger		ged by: Subject: Road M	arkings: General Enquiry		6/03/2025 08:58 eneral Enquiry				
Desc.: Hi	please pass this onto TC	:D this has been	resurfaced but bus stop ma	arkings have not be	en nut hack				
Location: Opposite t				Contact:					
Plot Number: 1.00	Feature Id - Lo	ocation: Ward 17	7 - From The Wisp to south	nbound on-ramp to	A1 Mussell Feature Type:	Road Ass	set		
Enquiry No.: 1935373		ged by: Verint C			8/04/2025 08:52				
Service: Roads Ger Desc.:		•	efective / Damaged	Classification: F	equest for service				
Location: Two large	potholes after the round a	about, heading to	the south end of the fort	Contact:					
Plot Number: 1.00	Feature Id - Lo	ocation: Ward 17	7 - From The Wisp to south	nbound on-ramp to	A1 Mussell Feature Type :	Road Ass	set		

Effective: 01/03/2025 to 30/04/2025

Service: Roads General

Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1935370 **Logged by:** Verint CRM Connector **on:** 18/04/2025 08:51

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Two large potholes and now a few smaller ones, on the stretch of road heading to Contact:

the fort, coming from Newcraighall, under the A1 bridge

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1934687 Logged by: Verint CRM Connector on: 16/04/2025 19:01
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole next to roundabout Contact:

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1932584 Logged by: Verint CRM Connector on: 12/04/2025 11:45

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole heading towards fort u def bypass Contact:

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1931363 Logged by: Verint CRM Connector on: 09/04/2025 21:47

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: The timing of these lights have been changed causing long queues along past fort **Contact:**

kinaird.

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1929477 Logged by: Verint CRM Connector on: 06/04/2025 20:13

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Its on the Road in front of the entrance to 114 Newcraighall Road **Contact:**

Plot Number: 2.00 Feature Id - Location: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive Feature Type: Road Asset

Enquiry No.: 1927127 Logged by: Verint CRM Connector on: 01/04/2025 22:23

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: On the roundabout. The potholes and surfaces of this roundabout has not been

repaired in any way shape or form since i last reported it nearly 2 years ago.

Contact:

The roundabout at the other side of fort kinnaird retail park was resurfaced, down as far as Niddrie. I dont understand why that side was done and this side was ignored.

It needs done urgently!

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Effective: 01/03/2025 to 30/04/2025

Service: Roads General

Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1926877 **Logged by:** Verint CRM Connector **on**: 01/04/2025 14:33

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: There are two potholes in the road just after the round about at Screwfix and before Contact:

the one at the Boots end of the Fort.

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1924266 Logged by: Verint CRM Connector on: 27/03/2025 08:41
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Potholes forming and worsening fast on the roundabout at fort Kinnaird shopping

centre. This is already a very busy junction however people are now starting to

swerve to avoid the pot holes causing a danger to others.

The whole roundabout could do with being resurfaced to be honest as you can see it wearing away at multiple sections. Maybe this is something that could be looked into

being down during the night to cause less disruption to traffic flow? Thanks

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1923477 Logged by: on: 25/03/2025 15:36
Service: Roads General Subject: Traffic Sign:Defective/Damaged Classification: Request for service

Desc.: Twitter - Hello @edinhelp could we please have someone help us keep our children safe ¿ It has been reported by the loopy pop man several times, that the School sign is facing the wrong way.

Contact:

Location: Twitter - Hello @edinhelp could we please have someone help us keep our children Contact:

safe ; It has been reported by the loopy pop man several times, that the School sign

is facing the wrong way.

Enquiry No.: 1923430 Logged by: Verint CRM Connector on: 25/03/2025 14:18
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: There is an uneven pot hole that's been there for well over a year the road is starting **Contact:**

to go all uneven at that part located. My car had hit it the other day causing a

strange noise to my car resulting in my cv joint braking

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1922235 Logged by: Verint CRM Connector on: 23/03/2025 08:59
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole on east bound side Contact:

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1922232 Logged by: Verint CRM Connector on: 23/03/2025 08:54
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole on roundabout Contact:

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Effective: 01/03/2025 to 30/04/2025 **Asset Number:** 1.00 to 9.00

Site: Newcraighall Road (7906128)

Service: Roads General Display Action Officer: No

Customer Services

Logged by: Verint CRM Connector **Enquiry No.:** 1920176 on: 19/03/2025 07:53 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Deep but small pothole, been reported twice, nearly damaged my alloy wheel this Contact:

morning

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1916696 on: 11/03/2025 19:30 Logged by: Verint CRM Connector Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Multiples of deep potholes on the road heading to the fort which is under the bypsss **Contact:**

/ A1

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Job Number: 50176782 Defect Number: 42178416

Logged by: Verint CRM Connector on: 11/03/2025 07:55 **Enquiry No.:** 1916178 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole in road between underpass and round about before B&M, heading TO fort Contact:

Plot Number: 1.00 Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset

Enquiry No.: 1916176 Logged by: Verint CRM Connector on: 11/03/2025 07:54 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole on same side of road as fire station Contact:

Feature Id - Location: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive Feature Type: Road Asset Plot Number: 2.00

Logged by: Verint CRM Connector Enquiry No.: 1915091 on: 08/03/2025 14:11 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole in road outside Cuddie brae Contact:

Plot Number: 3.00 Feature Id - Location: Ward 17 - From Newcraighall Road south at entrance to Newcra Feature Type: Road Asset

Logged by: Verint CRM Connector Enquiry No.: 1914123 on: 06/03/2025 13:39 Subject: Road: Defective / Damaged Service: Roads General Classification: Request for service

Desc.:

Plot Number: 2.00

Location: On road outside 93 Newcraighall Road. Contact:

BT chamber has cracked lid

Feature Id - Location: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive Feature Type: Road Asset

Defect Number: 42178010 Job Number: 50176524

Logged by: Verint CRM Connector on: 05/03/2025 18:52 **Enquiry No.:** 1913770 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Contact: Location: Large deep

Pothole

Plot Number: 2.00 Feature Id - Location: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive Feature Type: Road Asset

Effective: 01/03/2025 to 30/04/2025

Service: Roads General

Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 9.00

Display Action Officer: No

	aighall Road (7906128)		
Customer Services			
Enquiry No.: 1913314 Service: Roads General Desc.:	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 05/03/2025 07:14 Classification: Request for service	
Location: Road surface is cr	rumbling and depressed	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 17 - From Musselburgh By	rpass east to Newcraighall Drive Feature Type: Road Asse	et
Service: Roads General Desc.:	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged in road, were marked up and never repaired previously	on: 04/03/2025 20:25 Classification: Request for service Contact:	
Plot Number: 2.00		rpass east to Newcraighall Drive Feature Type: Road Asse	et
Enquiry No.: 1913228 Service: Roads General Desc.:	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/03/2025 20:24 Classification: Request for service	
Location: Crumbling road		Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 17 - From Musselburgh By	pass east to Newcraighall Drive Feature Type: Road Asse	et
Enquiry No.: 1913227	Logged by: Verint CRM Connector	on: 04/03/2025 20:23	
Service: Roads General Desc.:	Subject: Road: Defective / Damaged	Classification: Request for service	
Location: Deep pothole		Contact:	
Diet Neurale en 0.00	Footone Id. Location Wood 47. From Managhamah Di		
Plot Number: 2.00	Feature Id - Location: Ward 17 - From Musselburgh By	pass east to Newcraighall Drive Feature Type: Road Asse	et
Enquiry No.: 1913226	Logged by: Verint CRM Connector	rpass east to Newcraighall Drive Feature Type: Road Asse on: 04/03/2025 20:23	et
Enquiry No.: 1913226 Service: Roads General Desc.:	<u> </u>		et
Enquiry No.: 1913226 Service: Roads General	Logged by: Verint CRM Connector	on: 04/03/2025 20:23	et .
Enquiry No.: 1913226 Service: Roads General Desc.:	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/03/2025 20:23 Classification: Request for service	
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asseon: 04/03/2025 20:22	
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asse	
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913225 Service: Roads General	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asseon: 04/03/2025 20:22	
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913225 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sout Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asse on: 04/03/2025 20:22 Classification: Request for service	et
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913225 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913224	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asse on: 04/03/2025 20:22 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asse on: 04/03/2025 20:21	et
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913225 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913224 Service: Roads General Desc.:	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asse on: 04/03/2025 20:22 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asse on: 04/03/2025 20:21 Classification: Request for service	et
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913225 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913224 Service: Roads General Desc.: Location: Potholes on round	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Assertion: 04/03/2025 20:22 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Assertion: 04/03/2025 20:21 Classification: Request for service Contact: Contact: Contact:	et et
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913225 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913224 Service: Roads General Desc.:	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged labout Feature Id - Location: Ward 17 - From The Wisp to sou	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asse on: 04/03/2025 20:22 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Asse on: 04/03/2025 20:21 Classification: Request for service	et et
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913225 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913224 Service: Roads General Desc.: Location: Potholes on round Plot Number: 1.00 Enquiry No.: 1913223 Service: Roads General	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/03/2025 20:23 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Assertion: 04/03/2025 20:22 Classification: Request for service Contact: uthbound on-ramp to A1 Mussell Feature Type: Road Assertion: 04/03/2025 20:21 Classification: Request for service Contact: Contact: Contact:	et et
Enquiry No.: 1913226 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913225 Service: Roads General Desc.: Location: Deep potholes Plot Number: 1.00 Enquiry No.: 1913224 Service: Roads General Desc.: Location: Potholes on round Plot Number: 1.00 Enquiry No.: 1913223	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector Subject: Road: Defective / Damaged labout Feature Id - Location: Ward 17 - From The Wisp to sou Logged by: Verint CRM Connector	on: 04/03/2025 20:23 Classification: Request for service Contact: Ithbound on-ramp to A1 Mussell Feature Type: Road Asservice On: 04/03/2025 20:22 Classification: Request for service Contact: Ithbound on-ramp to A1 Mussell Feature Type: Road Asservice on: 04/03/2025 20:21 Classification: Request for service Contact: Ithbound on-ramp to A1 Mussell Feature Type: Road Asservice Contact: Ithbound on-ramp to A1 Mussell Feature Type: Road Asservice Contact: Ithbound on-ramp to A1 Mussell Feature Type: Road Asservice On: 04/03/2025 20:21	et et

Effective: 01/03/2025 to 30/04/2025

Service: Roads General

Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1913222 Service: Roads General Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 04/03/2025 20:20 Classification: Request for service

Desc.:

Location: Deep potholes

Contact:

Plot Number: 2.00

Feature Id - Location: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive Feature Type: Road Asset

Enquiry No.: 1913221

Logged by: Verint CRM Connector

on: 04/03/2025 20:19

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: Deep

Contact: Potholes

Plot Number: 1.00

Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Feature Type: Road Asset