

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Magnet Active Play Area (PL3035)

Site: Meadows Magnet Active Play Area (PL3035)	Locality:	Area: South East Locality
------------------------------------------------	-----------	---------------------------

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 9,001.00	Asset - Locn.: East Side of Meadows			Feature Type: PL: Play Area			Area: South East Locality	
Batch: 2015967 - Inspection Batch	No actionable defects found			Route: PR: South East Route 2				Date: 21/01/2026
Batch: 2015494 - Inspection Batch	No actionable defects found			Route: PR: South East Route 2				Date: 03/12/2025
Batch: 2013858 - Inspection Batch	No actionable defects found			Route: PR: South East Route 2				Date: 06/11/2025
Batch: 2013575 - Inspection Batch	No actionable defects found			Route: PR: South East Route 2				Date: 17/10/2025
Batch: 2013488 - Inspection Batch	No actionable defects found			Route: PR: South East Route 2				Date: 01/10/2025
Batch: 2013355 - Inspection Batch	No actionable defects found			Route: PR: South East Route 2				Date: 29/08/2025
Batch: 2011717 - Inspection Batch				Route: PR: South East Route 2				Date: 20/03/2025
2001053	Missing bolt on shoot	20/03/2025	Magnet play area	PL: Damaged Equipment	Internal		Committed	30001086
Asset: 9,002.00	Asset - Locn.: Play Safety Surface - Woodchip			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015110 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP				Date: 27/11/2025
Batch: 2011809 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP				Date: 21/03/2025
Asset: 9,003.00	Asset - Locn.: Multiplay - Kanope Multi Unit			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015125 - Inspection Batch				Route: Meadows Magnet Active PP				Date: 27/11/2025
2001191	Requires 4 new climbing boards. Removed.	27/11/2025		PL: Worn Equipment	Internal		Committed	30001216
Batch: 2011810 - Inspection Batch				Route: Meadows Magnet Active PP				Date: 21/03/2025
2001061	1 coach bolt missing	21/03/2025		PL: Damaged Equipment	Internal		Committed	30001093
Asset: 9,004.00	Asset - Locn.: Swing - Tyre Swing			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015111 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP				Date: 27/11/2025
Batch: 2011813 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP				Date: 24/03/2025
Asset: 9,008.00	Asset - Locn.: Carousel - Pyramid Climber			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015126 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP				Date: 27/11/2025
Batch: 2011814 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP				Date: 24/03/2025

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Magnet Active Play Area (PL3035)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	9,009.00	Asset - Locn.:	Multiplay - Nexus Velocity 2	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015121 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	27/11/2025
2001189		27/11/2025	Requires a new pull up rope.	PL: Worn Equipment	Internal		Committed	30001214
Batch:	2011815 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	24/03/2025
	No actionable defects found							
Asset:	9,010.00	Asset - Locn.:	Climber - Nexus Core	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015112 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	27/11/2025
	No actionable defects found							
Batch:	2011816 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	24/03/2025
	No actionable defects found							
Asset:	9,011.00	Asset - Locn.:	Climber - Cliff Boulder	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015124 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	27/11/2025
	No actionable defects found							
Batch:	2011817 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	24/03/2025
	No actionable defects found							
Asset:	9,012.00	Asset - Locn.:	Climber - Hill Boulder	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015123 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	27/11/2025
2001190	Requires an aluminium patch.	27/11/2025		PL: Worn Equipment	Internal		Committed	30001215
Batch:	2011818 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	24/03/2025
	No actionable defects found							
Asset:	9,013.00	Asset - Locn.:	Social Play - Simon Game	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015113 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	27/11/2025
	No actionable defects found							
Batch:	2011819 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	24/03/2025
	No actionable defects found							
Asset:	9,014.00	Asset - Locn.:	Social Play - OXO Game	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015114 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	27/11/2025
	No actionable defects found							
Batch:	2011820 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	24/03/2025
	No actionable defects found							
Asset:	9,015.00	Asset - Locn.:	Social Play - Effect Disc	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015122 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	27/11/2025
	No actionable defects found							
Batch:	2011821 - Inspection Batch			Route:	Meadows Magnet Active PP		Date:	24/03/2025
	No actionable defects found							

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Magnet Active Play Area (PL3035)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 9,016.00	Asset - Locn.: Social Play - Talk Tubes			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015115 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 27/11/2025	
Batch: 2011822 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 24/03/2025	
Asset: 9,017.00	Asset - Locn.: Water Play - Archimedes Screw			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015116 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 27/11/2025	
Batch: 2011823 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 24/03/2025	
Asset: 9,018.00	Asset - Locn.: Seating			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015117 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 27/11/2025	
Batch: 2011824 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 24/03/2025	
Asset: 9,019.00	Asset - Locn.: Sculpture - Art Spinning Top			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015119 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 27/11/2025	
Batch: 2011825 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 24/03/2025	
Asset: 9,020.00	Asset - Locn.: Sculpture - Diablo			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015118 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 27/11/2025	
Batch: 2011826 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 24/03/2025	
Asset: 9,021.00	Asset - Locn.: Sculpture - Gird & Gleek			Feature Type: Play Equipment			Area: South East Locality	
Batch: 2015120 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 27/11/2025	
Batch: 2011827 - Inspection Batch	No actionable defects found			Route: Meadows Magnet Active PP			Date: 24/03/2025	

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 9,001.00	Asset - Locn.: East Side of Meadows			Feature Type: PL: Play Area		Area: South East Locality	
30000684	PL: Play Surface Damaged Worn Hole needing filled at flying fox		Parks - Low	Job Committed	28/08/2024		PGPT14/545
30001086	Missing bolt on shoot (PL: Damaged Equipment)	Magnet play area	Parks - Low	Job Complete	20/03/2025	22/05/2025	Act. PGPT14/933

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Magnet Active Play Area (PL3035)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 9,003.00	Asset - Locn.: Multiplay - Kanope Multi Unit		Feature Type: Play Equipment		Area: South East Locality	
30000427	2 nets, crossover nets and brackets required		Parks - Medium	Job Complete	28/02/2024	18/02/2026	Act.
30001093	1 coach bolt missing (PL: Damaged Equipment)		Parks - Low	Job Complete	21/03/2025	22/05/2025	Act. PGPT14/940
30001216	Requires 4 new climbing boards. Removed. (PL: Worn Equipment)		Parks - Low	PL: Park Inspection Required	27/11/2025		PGPT14/1063
	Asset: 9,009.00	Asset - Locn.: Multiplay - Nexus Velocity 2		Feature Type: Play Equipment		Area: South East Locality	
30001214	PL: Worn Equipment	Requires a new pull up rope.	Parks - Low	PL: Requires Material Ordered	27/11/2025		PGPT14/1061
	Asset: 9,011.00	Asset - Locn.: Climber - Cliff Boulder		Feature Type: Play Equipment		Area: South East Locality	
30000872	Small holes at the top. (PL: Worn Equipment)		Parks - Low	Job Complete	21/10/2024	18/02/2026	Act. PGPT14/730
	Asset: 9,012.00	Asset - Locn.: Climber - Hill Boulder		Feature Type: Play Equipment		Area: South East Locality	
30001215	Requires an aluminium patch. (PL: Worn Equipment)		Parks - Low	PL: Park Inspection Required	27/11/2025		PGPT14/1062