

From: [REDACTED]
To: [Michael Kellett](#); [Joanne Allison](#); [Sean Macdonald](#); [Gordon Brown](#); [Gavin Dunn](#); [Michael Ferry](#); [Euan Dalrymple](#)
Subject: RE: EICR High Rise Blocks Landlord SAUNDERS STREET BLOCKS 1/2,3/4 and 7/8
Date: 26 April 2026 10:16:51
Attachments: [REDACTED]

[13121 EICR 1+2 Saunders Street 16-04-2026 \(2891-AF-028\).pdf](#)

[REDACTED]

Morning All

Please see attached certs for the 3 blocks at Saunders Street. [REDACTED]

[REDACTED]

See below for summary

SUMMARY

Main Panel and Consumer units in here with BS3871 and 3036 Fuse Wire Devices, could do with replacement for maintenance and protection purposes.

None of these have been rewired, although Blocks 1 and 2 have had lighting replacement , although appears not by CEC.

Minor electrical repairs required throughout

It should also be noted that there is minimal emergency lighting within these blocks

Meeting required on site to discuss Remedial works.

If you need anything further please let me know

[REDACTED]
Managing Director
Maclin Electric Ltd

Phone 0131 [REDACTED]

Web www.maclinelectric.co.uk Email [REDACTED]

Block 2 Unit 3 Inveresk Industrial Estate Musselburgh EH21 7UL

