

Effective: 01/01/2021 to 20/07/2026

Service: Roads General

Site: Clifton Terrace (7904047)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services



Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Job Number: 50159719

Defect Number: 42156368

Enquiry No.: 1744695

Logged by: Verint CRM Connector

on: 29/04/2024 07:39

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: The cycle lane going west past Haymarket station is dangerous because of the proximity to the trams. Taxis and lorries frequently park badly in the drop-off taxi bay outside the station and the end of their vehicles stick out into the cycle lane. This makes the problem worse. The trams themselves at that point come over the cycle lane and not just a little but probably about halfway over. This is dangerous for cyclists.

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Enquiry No.: 1633844

Logged by: Verint CRM Connector

on: 26/10/2023 17:24

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: With he roadworks in place, it squeezes cars into cyclists and several cyclists have been forced onto the tracks by aggressive drivers where they are getting thrown off bikes. A colleague broke his scapula today because of this.

Contact:

The best solution to the tram track issue is to adopt the same measures as the Netherlands and install rubber in the groves that would compress if a tram was to roll over but a cyclist is not heavy enough to depress the rubber making it safe to cross at any angle.

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset