Repair No	Type	Status	Raised Date	Priority	Target Date	Location	No. Jobs	App	Description
3957475/1	WOR	CAN	17-Sep-2026	2WK	01-Oct-2026	PRO	2		96 - [redacted] - Gas engineer required tenant has no hot water. AGS on 06/10 but tenant unable to wait that long but is not in today for a 1D. Please assess. 2nd person needed to sit in van/ no parking
3957475	SRQ	CAN	17-Sep-2026	2WK	01-Oct-2026	PRO			96 - [redacted] - Gas engineer required tenant has no hot water. AGS on 06/10 but tenant unable to wait that long but is not in today for a 1D. Please assess and repair.
3948451	SRQ	RAI	25-Aug-2026			PRO			Copied from Works Order 3948301/1
3948451/1	WOR	ISS	25-Aug-2026	8WK	20-Oct-2026	PRO	1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3905501/1	WOR	CLO	23-Apr-2026	2WK	07-May-2026	PRO	2		11 - [redacted] ¿ 2-person job ¿ As [redacted] Case officer - labourer to go out and put down plastic/sheet covers (ladders may be required), as the tenant has exposed flooring, and a lot of dust is coming through the property.
3905501	SRQ	RAI	23-Apr-2026	2WK	07-May-2026	PRO			11 - [redacted] ¿ 2-person job ¿ As [redacted] Case officer - labourer to go out and put down plastic/sheet covers (ladders may be required), as the tenant has exposed flooring, and a lot of dust is coming through the property.
3872428	SRQ	RAI	21-Jan-2026			PRO			Copied from Works Order 3872408/1
3872428/1	WOR	CLO	21-Jan-2026	8WK	18-Mar-2026	PRO	1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3866992/3	WOR	CLO	20-Jan-2026	2WK	03-Feb-2026	PRO	1		re raised as per [redacted] Lift the laminate flooring and the make access holes for a structural engineer and then relay the laminate flooring
3866992/2	WOR	CLO	17-Jan-2026	2WK	02-Feb-2026	PRO	2		02 - [redacted] - FAO [redacted] - 2MV for parking - Lift the laminate flooring and the make access holes for a structural engineer and then relay the laminate flooring
3866992/1	WOR	CLO	07-Jan-2026	2WK	21-Jan-2026	PRO	2		02 - Craig Morrison request - FAO [redacted] - 2MV - Lift the laminate flooring and the make access holes for a structural engineer and then relay the laminate flooring
3866992	SRQ	RAI	07-Jan-2026	2WK	21-Jan-2026	PRO			02 - Craig Morrison request - FAO [redacted] - 2MV - Lift the laminate flooring and the make access holes for a structural engineer and then relay the laminate flooring
3850541/3	WOR	CLO	18-Nov-2025	2WK	02-Dec-2025	PRO	2		11 [redacted] 2 mv parking issue . pick up temp heaters.
3850541/2	WOR	CLO	18-Nov-2025	4HR	18-Nov-2025	PRO	2		11 [redacted] 2 mv parking issue. deliver temp heaters. .
3850541/1	WOR	CLO	18-Nov-2025	1D	19-Nov-2025	PRO	5		96 [redacted] gch and hot water not working. boook folow on for electric fire.
3850541	SRQ	RAI	18-Nov-2025	1D	19-Nov-2025	PRO			96 [redacted] gch and hot water not working. boook folow on for electric fire.
3814915/1	WOR	CLO	14-Aug-2025	1WK	21-Aug-2025	PRO	2		19/2mv - [redacted] 2nd man to assost with parking- assess walls and ceilings for plastering
3814915	SRQ	RAI	14-Aug-2025	1WK	21-Aug-2025	PRO			19/2mv - [redacted] 2nd man to assost with parking- assess walls and ceilings for plastering
3763827	SRQ	RAI	19-Mar-2025			PRO			Copied from Works Order 3763772/1
3763827/1	WOR	CLO	19-Mar-2025	8WK	16-May-2025	PRO	1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3651581	SRQ	RAI	22-May-2024			PRO			Copied from Works Order 3651521/1
3651581/1	WOR	CLO	22-May-2024	8WK	17-Jul-2024	PRO	1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3637876/1	WOR	CLO	11-Apr-2024	1D	12-Apr-2024	PRO	6		96 - 2MV due to parking - [redacted] - Please repair GCH, brown liquid coming from boiler - no heating/hot water
3637876	SRQ	RAI	11-Apr-2024	1D	12-Apr-2024	PRO			96 - 2MV due to parking - [redacted] - Please repair GCH, brown liquid coming from boiler - no heating/hot water
3621873/1	WOR	CAN	28-Feb-2024	2WK	13-Mar-2024	PRO	1		02 - as per [redacted] - [redacted] - description on total
3621873	SRQ	CAN	28-Feb-2024	2WK	13-Mar-2024	PRO			02 - as per [redacted] - [redacted] - description on total
3560384/1	WOR	CLO	22-Sep-2023	2WK	06-Oct-2023	PRO	3		90/03 MT - [redacted] - Please re-fit shower as was disconnected to allow for other works
3560384	SRQ	RAI	22-Sep-2023	2WK	06-Oct-2023	PRO			90/03 MT - [redacted] - Please re-fit shower as was disconnected to allow for other works
3560378/2	WOR	CLO	05-Oct-2023	2WK	19-Oct-2023	PRO	2		02 - [redacted] - FOLLOWING PREVIOUS WORKS NOW COMPLETED - Please re-instate skirting, re-hang door frame and renew bath panel.
3560378/1	WOR	CAN	22-Sep-2023	2WK	06-Oct-2023	PRO	3		02 - [redacted] - FOLLOWING PREVIOUS WORKS NOW COMPLETED - Please re-instate skirting, re-hang door frame and renew bath panel
3560378	SRQ	RAI	22-Sep-2023	2WK	06-Oct-2023	PRO			02 - [redacted] - FOLLOWING PREVIOUS WORKS NOW COMPLETED - Please re-instate skirting, re-hang door frame and renew bath panel
3546276/1	WOR	CLO	10-Aug-2023	4HR	10-Aug-2023	PRO	3		[02] [redacted] [Wood Door to property needs Forced Entry]

3546276	SRQ	RAI	10-Aug-2023	4HR	10-Aug-2023	PRO			[02] [redacted] [Wood Door to property needs Forced Entry]
3541747/1	WOR	CAN	26-Jul-2023	1WK	02-Aug-2023	PRO	1		19 [redacted] QCO to inpsect an area requiring plaster works
3541747	SRQ	CAN	26-Jul-2023	1WK	02-Aug-2023	PRO			19 [redacted] QCO to inpsect an area requiring plaster works
3533261/2	WOR	CLO	30-Jun-2023	4HR	30-Jun-2023	PRO	2		03- [redacted] raised plumber to attend to unsafe shower- taken down by sparky as it was hanging off - unit is now in bath - needs attended to
3533261/1	WOR	CLO	29-Jun-2023	1D	30-Jun-2023	PRO	3		90 [redacted] MAKE SAFE SHOWER AS HANGING OFF OF WALL & WIRING EXPOSED, 2 MEN REQ DUE TO PARKING ISSUES, OK TO ATTEND 30/06/23
3533261	SRQ	RAI	29-Jun-2023	1D	30-Jun-2023	PRO			90 [redacted] MAKE SAFE SHOWER AS HANGING OFF OF WALL & WIRING EXPOSED, 2 MEN REQ DUE TO PARKING ISSUES, OK TO ATTEND 30/06/23
3531386	SRQ	RAI	22-Jun-2023			PRO			Copied from Works Order 3531226/1
3531386/1	WOR	CLO	22-Jun-2023	8WK	19-Sep-2023	PRO	1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3513417/7	WOR	CLO	02-Jun-2023	2WK	16-Jun-2023	PRO	4		92 - FAO contractor [redacted] faulty handset or main panel- intermittent working; tnt struggles to hear visitors @ main panel; assess & repair if possible of f/on via t/leader to progress as required.
3513417/6	WOR	CLO	02-Jun-2023	2WK	16-Jun-2023	PRO	5		05 - work with 02/03/90/96 - [redacted] - as per [redacted] - please see detail on total
3513417/5	WOR	CLO	02-Jun-2023	2WK	16-Jun-2023	PRO	10		90/02 - work with 03/96/05 - as per [redacted] - please see detail on total
3513417/4	WOR	CLO	02-Jun-2023	2WK	16-Jun-2023	PRO	8		03/96 - work with 90/05/02 - as per [redacted] - see detail on totsl
3513417/3	WOR	CLO	24-May-2023	1WK	31-May-2023	PRO	1		19 [redacted] INSPECT FOR PLASTERING / TILING WORK IN BATHROOM, PLASTERING ALREADY RAISED FOR COVING IN HALL & BOX ROOM FOR SEPTEMBER- tnt told to re book by prev qco
3513417/2	WOR	CAN	04-May-2023	2WK	18-May-2023	PRO	5		02/05 as per [redacted] - [redacted] - Bathroom; Bring 3m high ladder. Frame out redundant hatch in wall and S&F plasterboard flush to existing wall.
3513417/1	WOR	CLO	26-Apr-2023	1WK	03-May-2023	PRO	2		19 [redacted] INSPECT FOR PLASTERING / TILING WORK IN BATHROOM, PLASTERING ALREADY RAISED FOR COVING IN HALL & BOX ROOM FOR SEPTEMBER
3513417	SRQ	RAI	26-Apr-2023	1WK	03-May-2023	PRO			19 [redacted] INSPECT FOR PLASTERING / TILING WORK IN BATHROOM, PLASTERING ALREADY RAISED FOR COVING IN HALL & BOX ROOM FOR SEPTEMBER
3483560/2	WOR	CLO	01-Feb-2023	1D	02-Feb-2023	PRO	5		[96] [redacted] [Gas CH - Leaking radiator] [leaking oil] X 2 rads, NO SHOW FROM CES GAS ENGINEER, IF ANY ISSUES GAINING ACCESS - CALL TNT TO ARRANGE ACCESS AS MAY HAVING TO RAISE A CLAIM
3483560/1	WOR	CLO	30-Jan-2023	1D	31-Jan-2023	PRO	2		[96] [redacted] [Gas CH - Leaking radiator] [leaking oil]
3483560	SRQ	RAI	30-Jan-2023	1D	31-Jan-2023	PRO			[96] [redacted] [Gas CH - Leaking radiator] [leaking oil]
3473498/1	WOR	CAN	29-Dec-2022	1D	30-Dec-2022	PRO	1		[96] [redacted] [Young children,Health] [Gas CH - no heating or hot water] [Boiler showing faulty, no back ups]
3473498	SRQ	RAI	29-Dec-2022	1D	30-Dec-2022	PRO			[96] [redacted] [Young children,Health] [Gas CH - no heating or hot water] [Boiler showing faulty, no back ups]
3427995	SRQ	RAI	09-Aug-2022			PRO			Copied from Works Order 3427831/1
3427995/1	WOR	CAN	09-Aug-2022	8WK	10-Oct-2022	PRO	1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3417131/1	WOR	CLO	01-Jul-2022	2WK	15-Jul-2022	PRO	3		06 - [redacted] - Glass cracked in the little window above tenants bedroom door, measure up for new glass
3417131	SRQ	RAI	01-Jul-2022	2WK	15-Jul-2022	PRO			06 - [redacted] - Glass cracked in the little window above tenants bedroom door, measure up for new glass
3417126/3	WOR	CAN	26-Apr-2023	2WK	10-May-2023	PRO	3		05 [redacted] high ceiling flat- as per c thomson - FULL DESCRIPTION ON TOTAL
3417126/2	WOR	CAN	19-Oct-2022	2WK	02-Nov-2022	PRO	2		05 [redacted] high ceiling flat- as per c thomson - FULL DESCRIPTION ON TOTAL
3417126/1	WOR	CAN	01-Jul-2022	2WK	15-Jul-2022	PRO	2		05 - [redacted] - high ceiling flat- as per [redacted] - info on total
3417126	SRQ	RAI	01-Jul-2022	2WK	15-Jul-2022	PRO			05 - [redacted] - high ceiling flat- as per [redacted] - info on total
3378530/3	WOR	CLO	19-Jul-2022	2WK	02-Aug-2022	PRO	2		02 - [redacted] - F/on [redacted] - Supply and fit vertical pipe box in bathroom to hide pipes using 9mm plywood - 1220x110, 1220x 220, 1650x110, 1650x220. Also needs 5 lengths of 2"x1" timber
3378530/2	WOR	CLO	01-Jul-2022	2WK	15-Jul-2022	PRO	1		02 - [redacted] - Tenant needs pipes in the bathroom boxed in
3378530/1	WOR	CLO	02-Mar-2022	2WK	16-Mar-2022	PRO	1		03 - [redacted] - TNT vun - Pipes above bath need assessed to be made smaller so joiner can pipe box them

3378530	SRQ	RAI	02-Mar-2022	2WK	16-Mar-2022	PRO			03 - [redacted] - TNT vun - Pipes above bath need assessed to be made smaller so joiner can pipe box them
3366482/1	WOR	CLO	01-Feb-2022	4HR	01-Feb-2022	PRO	5		No heat hw - passed to Gas Call
3366482	SRQ	RAI	01-Feb-2022	4HR	01-Feb-2022	PRO			[redacted] No heat hw - passed to Gas Call
3366012/1	WOR	CLO	31-Jan-2022	1D	01-Feb-2022	PRO	1		96, [redacted] tnt reporting got no heating and hot water from gch boiler , no backups , showing spanner signal on boiler
3366012	SRQ	RAI	31-Jan-2022	1D	01-Feb-2022	PRO			96, [redacted] tnt reporting got no heating and hot water from gch boiler , no backups , showing spanner signal on boiler
3365952/4	WOR	CAN	02-Mar-2022	2WK	16-Mar-2022	PRO	4		06- [redacted] PHONE 30 MINS BEFORE ARRIVING- FAO Response, F/O [redacted] Supply and fit new glass to screen in kitchen, supply and fit new glass above front door. Approx. Sizes (1200x900 4mm clear)(1200 x500 6.4 lam)
3365952/3	WOR	CLO	22-Feb-2022	2WK	08-Mar-2022	PRO	1		02 - [redacted] - [redacted] QCO - Subject of ongoing complaint - Kitchen behind fridge - Renew mouse bead skirting - Approx 3 linear meters cut on site to suit
3365952/2	WOR	CLO	22-Feb-2022	2WK	08-Mar-2022	PRO	1		06 - [redacted] - [redacted] QCO - Subject of ongoing complaint - Box room cracked clear SG - Measure & renew as req; check front door glass fanlight & f/on if renewal required
3365952/1	WOR	CLO	31-Jan-2022	1WK	07-Feb-2022	PRO	1		19 - [redacted] - Tenant has foundation works, slats in flooring and cracks in masonry in bedroom. Please asses for works. (Please do not allocate to [redacted] as they don't do internal 01's).
3365952	SRQ	RAI	31-Jan-2022	1WK	07-Feb-2022	PRO			19 - [redacted] - Tenant has foundation works, slats in flooring and cracks in masonry in bedroom. Please asses for works. (Please do not allocate to [redacted] as they don't do internal 01's).
3350688/1	WOR	CLO	03-Dec-2021	2WK	17-Dec-2021	PRO	1		78 - FAO JB BELLS - COVER ORDER AS PER [redacted]
3350688	SRQ	RAI	03-Dec-2021	2WK	17-Dec-2021	PRO			78 - FAO JB BELLS - COVER ORDER AS PER [redacted]
3334678/1	WOR	CLO	12-Oct-2021	2WK	26-Oct-2021	PRO	1		90- [redacted] elderly-please repair socket next to cooker switch, no power coming through
3334678	SRQ	RAI	12-Oct-2021	2WK	26-Oct-2021	PRO			90- [redacted] elderly-please repair socket next to cooker switch, no power coming through
3330988	SRQ	RAI	29-Sep-2021			PRO			Copied from Works Order 3330804/1
3330988/1	WOR	CLO	29-Sep-2021	8WK	15-Dec-2021	PRO	1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3315042/4	WOR	CAN	09-May-2022	8WK	04-Jul-2022	PRO	10		15 - FAO FIRST CALL - [redacted] - SEE SORS FOR DETAILS - [redacted] NO ACCESS ON PREV JOB - 29/04/22
3315042/3	WOR	CLO	12-Nov-2021	8WK	11-Jan-2022	PRO	10		15 - FAO FIRST CALL - [redacted] - SEE SORS FOR DETAILS - [redacted]
3315042/2	WOR	CLO	19-Aug-2021	2WK	02-Sep-2021	PRO	1		17 - [redacted] - Dampness survey as per [redacted] QCO
3315042/1	WOR	CLO	05-Aug-2021	1WK	12-Aug-2021	PRO	1		19- [redacted] Inspector can you assess the bathroom ceiling after water damage from flat above , following the removal of water tank, tenant is advising that the cieling has mould on it starting at the left side.
3315042	SRQ	RAI	05-Aug-2021	1WK	12-Aug-2021	PRO			19- [redacted] Inspector can you assess the bathroom ceiling after water damage from flat above , following the removal of water tank, tenant is advising that the cieling has mould on it starting at the left side.
3308414/1	WOR	CAN	08-Jul-2021	8WK	02-Sep-2021	PRO	1		73 [redacted] As per [redacted] S/F new door
3308414	SRQ	RAI	08-Jul-2021	8WK	02-Sep-2021	PRO			73 [redacted] As per [redacted] S/F new door
3301020/6	WOR	CLO	04-Aug-2021	1D	05-Aug-2021	PRO	3		03/02 f/o Colin McInnes from Response [redacted] - please drain down cap f/on via t/leader for complete removal Tank no longer required. joiner to remove boxing to allow plumber to remove water tank
3301020/5	WOR	CLO	07-Jul-2021	2WK	21-Jul-2021	PRO	2		02 - [redacted] - 2 man job - [redacted] QCO - temporary repair to all timber s&c windows- replacement request already lodged- conservation area permit req- please o/haul & m/good as poss until new windows installed.
3301020/4	WOR	CLO	07-Jul-2021	2WB	21-Jul-2021	PRO	8		01 - [redacted] - [redacted] QCO - Description on Total
3301020/3	WOR	CLO	07-Jul-2021	2WB	21-Jul-2021	PRO	1		04 - [redacted] - [redacted] QCO - rear elevation 2nd floor W/ingress to kitchen & bathroom when raining- suspect defective ci Rhones & d/pipe- scaffold req- assess & f/on as req please.
3301020/2	WOR	CAN	07-Jul-2021	2WK	21-Jul-2021	PRO	1		03 - [redacted] - [redacted] QCO - redundant leaking main tank in bathroom- please drain down; cap & f/on via t/leader for complete removal, tnt has gch combi. Tank no longer required.

3301020/1	WOR	CLO	16-Jun-2021	1WK	23-Jun-2021	PRO	1		19 CRACKS IN CEILING & WALLS, BED WINDOW ISSUES, WOODEN PARTS MISSING, INTERIOR DOORS NEEDING INSPECTED MIGHT NOT BE FIRE SAFE, 1 OF THE BEDROOMS FLOORING IS UNEVEN & BATHROOM BOILER - INSPECT FOR REMOVAL - TNT REQ FOR QCO
3301020	SRQ	RAI	16-Jun-2021	1WK	23-Jun-2021	PRO			19 CRACKS IN CEILING & WALLS, BED WINDOW ISSUES, WOODEN PARTS MISSING, INTERIOR DOORS NEEDING INSPECTED MIGHT NOT BE FIRE SAFE, 1 OF THE BEDROOMS FLOORING IS UNEVEN & BATHROOM BOILER - INSPECT FOR REMOVAL - TNT REQ FOR QCO
3282087/2	WOR	CLO	28-Jul-2021	2WK	11-Aug-2021	PRO	3		04/09 - Scaffold Required - F/O Stuart O'Rourke, Roofer - Tel No - Clear rhones at rear property above stair - check downpipe above Flat 2F3 - scaffold required
3282087/1	WOR	CLO	18-Apr-2021	4HR	19-Apr-2021	BTHR	3		40 - - Uncontainable leak from toilet cistern, as per Scott Main @ Gordon Forsyth 15:53
3282087	SRQ	RAI	18-Apr-2021	4HR	19-Apr-2021	BTHR			40 - - Uncontainable leak from toilet cistern, as per Scott Main @ Gordon Forsyth 15:53
3282084/1	WOR	CLO	18-Apr-2021	4HR	19-Apr-2021	KTCH	4		ces gch and hot water not working. passed to Scott Main
3282084	SRQ	RAI	18-Apr-2021	4HR	19-Apr-2021	KTCH			ces gch and hot water not working. passed to Scott Main
3262268/2	WOR	CLO	16-Feb-2021	4HR	16-Feb-2021	PRO	1		02- Bedroom and kitchen window has gaps and leak coming through causing damage/dampness (please make secure)
3262268/1	WOR	CLO	16-Feb-2021	4HR	16-Feb-2021	PRO	2		90- Kitchen/bathroom light is flickering and struggle too see when turning kitchen on making both flicker (dangerous)
3262268	SRQ	RAI	16-Feb-2021	4HR	16-Feb-2021	PRO			90- Kitchen/bathroom light is flickering and struggle too see when turning kitchen on making both flicker (dangerous)
3238963	SRQ	RAI	17-Nov-2020			PRO			Copied from Works Order 3238764/1
3238963/1	WOR	CLO	17-Nov-2020	8WK	29-Jan-2021	PRO	2		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3200529/1	WOR	CLO	26-May-2020	4HR	26-May-2020	KTCH	1		90 - Tel No - Please attend and repair as cooker switch has jammed and tenant doesnt know if on or off
3200529	SRQ	RAI	26-May-2020	4HR	26-May-2020	KTCH			90 - Tel No - Please attend and repair as cooker switch has jammed and tenant doesnt know if on or off
3172036/2	WOR	CLO	10-Feb-2020	2WK	24-Feb-2020	PRO	1		02 - - Attend and asses kitchen window as leaking very badly when raining and all wood has rotted around it - f/o
3172036/1	WOR	CLO	10-Feb-2020	2WK	24-Feb-2020	PRO	1		03 - - Attend and repair kitchen hot tap which is leaking and very cloudy all other fine - under sink slow leak - check bathroom wall for burst pipe also.
3172036	SRQ	RAI	10-Feb-2020	2WK	24-Feb-2020	PRO			03 - - Attend and repair kitchen hot tap which is leaking and very cloudy all other fine - under sink slow leak - check bathroom wall for burst pipe also.
3144442	SRQ	RAI	22-Nov-2019			PRO			Copied from Works Order 3144204/1
3144442/1	WOR	CLO	22-Nov-2019	8WK	07-Feb-2020	PRO	1	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3126625/1	WOR	CLO	17-Oct-2019	8WK	12-Dec-2019	PRO	1		73 - - as pas supp and fit new sash and case window to bedroom MUST BE LIKE FOR LIKE.
3126625	SRQ	RAI	17-Oct-2019	8WK	12-Dec-2019	PRO			73 - - as pas supp and fit new sash and case window to bedroom MUST BE LIKE FOR LIKE.
3109232/1	WOR	CLO	12-Aug-2019	4HR	12-Aug-2019	PRO	1		03 - - Please attend trace and repair leak - leaking into private tenant in flat 1f3 - private tenant also states outside of this leak every time tnt uses her washing machine it leaks outside and into her window sills
3109232	SRQ	RAI	12-Aug-2019	4HR	12-Aug-2019	PRO			03 - - Please attend trace and repair leak - leaking into private tenant in flat 1f3 - private tenant also states outside of this leak every time tnt uses her washing machine it leaks outside and into her window sills
3106180/1	WOR	CAN	30-Jul-2019	2WK	13-Aug-2019	PRO	2		02 please repair the windows in the kitche, bathroom and living room and tnt has advised that front door is a temp and needing renewed
3106180	SRQ	RAI	30-Jul-2019	2WK	13-Aug-2019	PRO			02 please repair the windows in the kitche, bathroom and living room and tnt has advised that front door is a temp and needing renewed
3095071/3	WOR	CLO	14-Jun-2019	4HR	14-Jun-2019	PRO	1		78 - - please attend and unblock toilet - severely chocked

3095071/2	WOR	CAN	13-Jun-2019	4HR	13-Jun-2019	PRO	2		40- as per tommy, [redacted] toilet severely choked. plumber already attempted. passed to Lanes @ 16:45
3095071/1	WOR	CAN	13-Jun-2019	4HR	13-Jun-2019	PRO	2		40 - 03 - CES plummer - [redacted] - Vul DI Please attend as unblock toilet as tnt is unable to use a bucket - passed over to Thomas Anstruther @ 1542
3095071	SRQ	RAI	13-Jun-2019	4HR	13-Jun-2019	PRO			40 - 03 - CES plummer - [redacted] - Vul DI Please attend as unblock toilet as tnt is unable to use a bucket - passed over to Thomas Anstruther @ 1542
3094690	SRQ	CAN	12-Jun-2019			PRO			Copied from Works Order 3094435/1
3094690/1	WOR	CAN	12-Jun-2019	8WK	07-Aug-2019	PRO	1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
3090928/1	WOR	CLO	10-Jun-2019	2WK	24-Jun-2019	KTCH	1		02- [redacted] Tnt states kitchen and bathroom window needs to be repair as draughts are coming in
3090928	SRQ	RAI	10-Jun-2019	2WK	24-Jun-2019	KTCH			02- [redacted] Tnt states kitchen and bathroom window needs to be repair as draughts are coming in
3090927/2	WOR	CLO	21-Jun-2019	2WK	05-Jul-2019	BTHR	3		02- [redacted] FO [redacted] - renew boxing in around bath, renew bath panel & skirting - 3qtr ply will be required
3090927/1	WOR	CLO	10-Jun-2019	2WK	24-Jun-2019	BTHR	1		02- [redacted] repair worktop, skating board and bath panel - raise Fo if necessary
3090927	SRQ	RAI	10-Jun-2019	2WK	24-Jun-2019	BTHR			02- [redacted] repair worktop, skating board and bath panel - raise Fo if necessary
3090925/3	WOR	CLO	29-Aug-2019	2WK	12-Sep-2019	BTHR	2		90 COVER ORDER SUB CONTRACTOR SUPPORT 3090925/2
3090925/2	WOR	CLO	13-Jun-2019	2WK	27-Jun-2019	BTHR	1		re raised 90- [redacted] tnt states bathroom light is not working-renew with white or bright light- hall way light some times flickers
3090925/1	WOR	CLO	10-Jun-2019	1D	11-Jun-2019	BTHR	1		90- [redacted] tnt states bathroom light is not working-renew with white or bright light- hall way light some times flickers
3090925	SRQ	RAI	10-Jun-2019	1D	11-Jun-2019	BTHR			90- [redacted] tnt states bathroom light is not working-renew with white or bright light- hall way light some times flickers
3075947/1	WOR	CLO	27-Apr-2019	4HR	29-Apr-2019	BTHR	3		CES- As per EBS manager, electrician to attend property to remove light fixture/make safe due to leak from private property above. Passed to [redacted]
3075947	SRQ	RAI	27-Apr-2019	4HR	29-Apr-2019	BTHR			CES- As per EBS manager, electrician to attend property to remove light fixture/make safe due to leak from private property above. Passed to [redacted]
3053382/15	WOR	CLO	24-Apr-2019	2WK	08-May-2019	PRO	1		03 COVER ORDER SUB CONTRACTOR SUPPORT 3053382/13
3053382/14	WOR	CLO	11-Apr-2019	2WK	29-Apr-2019	PRO	1		03 - [redacted] - FO TB [redacted] - Switch bath and WHB supply from tank to mainsto prevent reoccurring air blocks - 15mm tee piece, 22mm bend and reducer to 15mm will be required
3053382/13	WOR	CLO	05-Apr-2019	2WK	23-Apr-2019	PRO	1		03/02 - F/O - MT - [redacted] - Bathroom. ongoing issue. Please persevere to find cause. No cold water supply to bath & WHB taps. Check water supply from tank as everything else has been checked. Bring 2.5 m ladder - work with joiner
3053382/12	WOR	CLO	05-Apr-2019	2WK	23-Apr-2019	PRO	2		02/03 - F/O - MT - [redacted] - Bathroom - Remove/Reinstate water tank box facing to allow plumbing works. Remove/Reinstate bath panel also Bring 2.5 metre ladder - Work with Plumber
3053382/11	WOR	CLO	29-Mar-2019	2WK	12-Apr-2019	PRO	1		RERAISE - 05 - [redacted] - bond out skim patch in kitchen , cut out cracks in bathroom and make good.
3053382/10	WOR	CLO	28-Mar-2019	2WK	11-Apr-2019	PRO	1		02 PER R [redacted] JOINER, 2MJ FOR PARKING [redacted] supply and fit 1220x1220x6mm plywood to kitchen floor near sink unit
3053382/9	WOR	CLO	25-Mar-2019	2WK	08-Apr-2019	PRO	1		05 - [redacted] - bond out skim patch in kitchen , cut out cracks in bathroom and make good
3053382/8	WOR	CLO	19-Mar-2019	1WK	26-Mar-2019	PRO	1		19 , as per [redacted] [redacted] , inspect pipework as may be piped up wrongly.
3053382/7	WOR	CLO	18-Mar-2019	2WK	01-Apr-2019	PRO	1		03 [redacted] [redacted] Bathroom; Repair cold tap at WHB and bath as no water coming out. Job Re-raised due to no show
3053382/6	WOR	CAN	13-Mar-2019	2WM	27-Mar-2019	PRO	4		02; 05; [redacted] Kitc, Secure down protruding nails k/floor. S&F 1750x1220x4mm ply cut suit near window floor is rotten. S&F 750x25x25 1/4 round. S&F 1000x170x15 skirting piece LHS units, fix backing piece/battens similar secure fixing.
3053382/5	WOR	CLO	13-Mar-2019	2WM	27-Mar-2019	PRO	1		05; 02; [redacted] 2 men req as 3.5m high ceilings. Bed2; Cut out several large cracks at wall head & patch with plaster flush to existing. Kitchen; Plaster fill raggle to wall & beneath to ensure sound backing for joiner to fix to.
3053382/4	WOR	CLO	13-Mar-2019	2WK	27-Mar-2019	PRO	1		76; [redacted] [redacted] FAO CONTRACTOR, Kitchen; S&F vinyl complete to floor. Note; Ensure joinery work has been completed before attending.

3053382/3	WOR	CLO	13-Mar-2019	2WK	27-Mar-2019	PRO	1		03; [redacted] Bathroom; Repair cold tap at WHB and bath as no water coming out.
3053382/2	WOR	CLO	13-Mar-2019	2WK	27-Mar-2019	PRO	4		90; [redacted] 2 men required as 3.5m high ceilings. Hall; Repair lights as not switches not working. Renew mains smoke alarm.
3053382/1	WOR	CLO	26-Feb-2019	1WK	05-Mar-2019	PRO	1		19 - [redacted] - please inspect for plaster where electrician left hole in wall - flooring in kitchen damaged also in hall - cold taps in bathroom working then not working tempramental - also please look into new linoleum in kitchen
3053382	SRQ	RAI	26-Feb-2019	1WK	05-Mar-2019	PRO			19 - [redacted] - please inspect for plaster where electrician left hole in wall - flooring in kitchen damaged also in hall - cold taps in bathroom working then not working tempramental - also please look into new linoleum in kitchen
3051271/2	WOR	CLO	18-Feb-2019	2WK	04-Mar-2019	PRO	1		90 - [redacted] - Wires exposed from sockets. Tnt requested Appt.
3051271/1	WOR	CLO	18-Feb-2019	2WK	04-Mar-2019	PRO	1		02 - [redacted] - Repair hole in skirting boards.
3051271	SRQ	RAI	18-Feb-2019	2WK	04-Mar-2019	PRO			02 - [redacted] - Repair hole in skirting boards.
3040740/6	WOR	CAN	26-Feb-2019	8WK	25-Apr-2019	PRO	1		73 - [redacted] - as pas [redacted] supp and fit new sash and case window to bedroom MUST BE LIKE FOR LIKE.
3040740/5	WOR	CLO	05-Feb-2019	2WK	19-Feb-2019	PRO	1		02 - [redacted] - TNT Now Requires her bedroom Window inspected - Very bad damp - was advised that we would be attending but nothing booked in - Pls investigate with possible view to replacing -
3040740/4	WOR	CAN	25-Jan-2019	8WK	22-Mar-2019	PRO	1		73 as per [redacted] Joiner Team Manager - please supply a new front door
3040740/3	WOR	CLO	23-Jan-2019	2WK	06-Feb-2019	PRO	1		02 - [redacted] - FO [redacted] - S&F new temp door, old locks have fallen off - 915 x 2100 solid core door appointment needed
3040740/2	WOR	CAN	23-Jan-2019	2WK	06-Feb-2019	PRO	1		71 - [redacted] - FO [redacted] 02 - Pls inspect living room window, severe condensation
3040740/1	WOR	CAN	18-Jan-2019	2WK	01-Feb-2019	PRO	3		02 - [redacted] - as per tenant please repair door as best you can and follow on for measuring up if requred - repair letter box also - please also repair window in bedroom as damaged may need replaced also
3040740	SRQ	RAI	18-Jan-2019	2WK	01-Feb-2019	PRO			02 - [redacted] - as per tenant please repair door as best you can and follow on for measuring up if requred - repair letter box also - please also repair window in bedroom as damaged may need replaced also
3022222/4	WOR	CLO	12-Feb-2019	2WK	26-Feb-2019	BTHR	2		03- As per tnt [redacted] - [redacted] Please repair cold tap from bath and whb as no water is coming out
3022222/3	WOR	CAN	18-Jan-2019	2WK	01-Feb-2019	BTHR	1		03- [redacted] Please repair cold tap from bath and whb as no water is coming out - air lock
3022222/2	WOR	CLO	19-Nov-2018	2WK	03-Dec-2018	BTHR	2		03- As per tnt [redacted] - [redacted] Please repair cold tap from bath and whb as no water is coming out / leak coming from under kitchen sink -
3022222/1	WOR	CLO	14-Nov-2018	1D	15-Nov-2018	BTHR	3		03- As per tnt [redacted] - [redacted] Please repair cold tap from bath and whb as no water is coming out / leak coming from under kitchen sink -
3022222	SRQ	RAI	14-Nov-2018	1D	15-Nov-2018	BTHR			03- As per tnt [redacted] - [redacted] Please repair cold tap from bath and whb as no water is coming out / leak coming from under kitchen sink -
3019767/1	WOR	CLO	05-Nov-2018	2WK	19-Nov-2018	PRO	1		90- [redacted] repair socket in kitchen as not working.
3019767	SRQ	RAI	05-Nov-2018	2WK	19-Nov-2018	PRO			90- [redacted] repair socket in kitchen as not working.
3019766/1	WOR	CLO	05-Nov-2018	2WK	19-Nov-2018	PRO	1		03- [redacted] leak @ kitchen sink- containable.
3019766	SRQ	RAI	05-Nov-2018	2WK	19-Nov-2018	PRO			03- [redacted] leak @ kitchen sink- containable.
3011323/1	WOR	CLO	05-Oct-2018	4HR	05-Oct-2018	BTHR	3		CES- [redacted] fully blocked toilet, flush mechanism broken and not working, unable to manual flush, called [redacted] plumber 3pm
3011323	SRQ	RAI	05-Oct-2018	4HR	05-Oct-2018	BTHR			CES- [redacted] fully blocked toilet, flush mechanism broken and not working, unable to manual flush, called [redacted] plumber 3pm
3004084/1	WOR	CLO	08-Sep-2018	4HR	10-Sep-2018		3		CES - Leak into private below - passed to plumber [redacted]
3004084	SRQ	RAI	08-Sep-2018	4HR	10-Sep-2018				CES - Leak into private below - passed to plumber [redacted]
2985048/5	WOR	CLO	25-Jul-2018	2WK	08-Aug-2018	PRO	1		03 MT 90 - Tel No: [redacted] - S+F New Maira sports thermostatic shower.
2985048/4	WOR	CLO	25-Jul-2018	2WK	08-Aug-2018	PRO	2		90 MT 03 - Tel No: [redacted] - S+F New Maira sports thermostatic shower.

2985048/3	WOR	CLO	24-Jul-2018	2WK	07-Aug-2018	PRO	2		90 Faulty shower - only cold water coming out, ay be a temperature fault on the shower unit.
2985048/2	WOR	CLO	13-Jul-2018	2WK	27-Jul-2018	PRO	1		90 - F/O - Tel No: - S&F 2 gang light switch
2985048/1	WOR	CLO	11-Jul-2018	2WK	25-Jul-2018	PRO	1		90 - Tel No: - Please attend repair light switch outside bathroom door as stuck in the middle between off and on
2985048	SRQ	RAI	11-Jul-2018	2WK	25-Jul-2018	PRO			90 - Tel No: - Please attend repair light switch outside bathroom door as stuck in the middle between off and on
2985043/1	WOR	CLO	11-Jul-2018	2WK	25-Jul-2018	BTHR	1		03 - Tel No: - Please attend and repair shower pressure fault - only cold water coming out
2985043	SRQ	RAI	11-Jul-2018	2WK	25-Jul-2018	BTHR			03 - Tel No: - Please attend and repair shower pressure fault - only cold water coming out
2970131	SRQ	RAI	05-Jun-2018			PRO			Copied from Works Order 2969933/1
2970131/1	WOR	CLO	05-Jun-2018	8WK	07-Aug-2018	PRO	1	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
2953590/1	WOR	CLO	24-Apr-2018	2WK	08-May-2018	PRO	1		02 - Repair/Renew yale lock. Property still secure mortice being used atm
2953590	SRQ	RAI	24-Apr-2018	2WK	08-May-2018	PRO			02 - Repair/Renew yale lock. Property still secure mortice being used atm
2836451	SRQ	RAI	16-May-2017			PRO			Copied from Works Order 2836170/1
2836451/1	WOR	CLO	16-May-2017	8WK	12-Oct-2017	PRO	1	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
2829404/1	WOR	CLO	06-May-2017	4HR	08-May-2017		2		Ces Heating system damaged,eak going into property below, workmen who are carrying out work in the property below in the ceiling have knocked the pipes and caused a leak passed at 16;00
2829404	SRQ	RAI	06-May-2017	4HR	08-May-2017				Ces Heating system damaged,eak going into property below, workmen who are carrying out work in the property below in the ceiling have knocked the pipes and caused a leak passed at 16;00
2772391/1	WOR	CLO	23-Nov-2016	2WK	07-Dec-2016		1		Carry out force entry for Gas Engineer including replacing locks and making good door and surrounds. Per door
2772391	SRQ	RAI	23-Nov-2016	2WK	07-Dec-2016				Carry out force entry for Gas Engineer including replacing locks and making good door and surrounds. Per door
2755951	SRQ	RAI	11-Oct-2016						Copied from Works Order 2755900/1
2755951/1	WOR	CLO	11-Oct-2016	8WK	22-Dec-2016		4		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
2686240/1	WOR	CLO	29-Feb-2016	1D	01-Mar-2016	PRO	1		96 PLEASE REPAI Rgch AND HOT WATER NO BACK UPS.
2686240	SRQ	RAI	29-Feb-2016	1D	01-Mar-2016	PRO			96 PLEASE REPAI Rgch AND HOT WATER NO BACK UPS.
2677675/1	WOR	CAN	09-Feb-2016	2WK	23-Feb-2016	PRO	1		96 - - Please check GCH as on 24/7 -
2677675	SRQ	RAI	09-Feb-2016	2WK	23-Feb-2016	PRO			96 - - Please check GCH as on 24/7 -
2674447/1	WOR	CLO	29-Jan-2016	2WK	12-Feb-2016		3		05 - as per qco - 261 7341 - remove defective ceiling complete at hallway closetaprox 5sqm to renew new plasterboard, apply bonding coat to tape finish. ladders req
2674447	SRQ	RAI	29-Jan-2016	2WK	12-Feb-2016				05 - as per qco - 261 7341 - remove defective ceiling complete at hallway closetaprox 5sqm to renew new plasterboard, apply bonding coat to tape finish. ladders req
2666668/1	WOR	CLO	13-Jan-2016	2WK	27-Jan-2016		2		03 blocked bath TC
2666668	SRQ	RAI	13-Jan-2016	2WK	27-Jan-2016				03 blocked bath TC
2666667/1	WOR	CLO	13-Jan-2016	2WK	27-Jan-2016	PRO	1		96 repair few radiators not heating up properly
2666667	SRQ	RAI	13-Jan-2016	2WK	27-Jan-2016	PRO			96 repair few radiators not heating up properly
2666662/3	WOR	CLO	19-Jan-2016	2WK	02-Feb-2016	PRO	3		05- remove bost Defective plaster at bed1 walls up to 10SQM - make good same apply bonding coat&patch same skimmed to flush finish up to10SQM-assess ceiling to hall closet and contact QCO with
2666662/2	WOR	CLO	19-Jan-2016	2WK	02-Feb-2016	PRO	2		02 - As per - S&F new kirsting at bedroom1 use timber with OGEE mould size Aprox 5.5Mx20MMx145MM - Cut on sight to suit
2666662/1	WOR	CLO	13-Jan-2016	1WK	20-Jan-2016	PRO	1		19 inspect cracks in bedroom wall
2666662	SRQ	RAI	13-Jan-2016	1WK	20-Jan-2016	PRO			19 inspect cracks in bedroom wall
2645719/1	WOR	CAN	17-Nov-2015	2WK	01-Dec-2015		1		Carry out force entry for Gas Engineer including replacing locks and making good door and surrounds. Per door

2645719	SRQ	CAN	17-Nov-2015	2WK	01-Dec-2015				Carry out force entry for Gas Engineer including replacing locks and making good door and surrounds. Per door
2627145	SRQ	RAI	28-Sep-2015			PRO			Copied from Works Order 2627080/1
2627145/1	WOR	CLO	28-Sep-2015	8WK	24-Dec-2015	PRO	2	Y	DUE NOV 2015 - Annual Routine Service to ALL council owned gas heating appliances contained within the property.
2622305/1	WOR	CLO	13-Sep-2015	4HR	14-Sep-2015		4		CES Forced entry, tnt locked out - Passed to
2622305	SRQ	RAI	13-Sep-2015	4HR	14-Sep-2015				CES Forced entry, tnt locked out - Passed to
2619220/4	WOR	CLO	07-Oct-2015	2WK	21-Oct-2015	PRO	2		02 - relace folding door at bedroom size 660x2.1 and framing 7 meters long dpr.
2619220/3	WOR	CLO	29-Sep-2015	2WK	13-Oct-2015	PRO	2		02 - relace folding door at bedroom size 660x2.1 and framing 7 meters long dpr.
2619220/2	WOR	CLO	10-Sep-2015	2WK	24-Sep-2015	PRO	2		02 - f/on as per - shave down internal doors to allow for threshold plate at flooring measure for facings to inside bed 2 as req and measure or s/f new folding door to bed 2 as req and arrange follow on app
2619220/1	WOR	CAN	02-Sep-2015	2WK	16-Sep-2015	PRO	1		19 - Please inspect all internal doors for repair/replacement
2619220	SRQ	RAI	02-Sep-2015	2WK	16-Sep-2015	PRO			19 - Please inspect all internal doors for repair/replacement
2552367/1	WOR	CLO	06-Mar-2015	2WK	20-Mar-2015		1	Y	92 - - handset not working - wont buzz people into building
2552367	SRQ	RAI	06-Mar-2015	2WK	20-Mar-2015				92 - - handset not working - wont buzz people into building
2542455/I1	INS	COM	11-Feb-2015	2WK	25-Feb-2015				Inspect damage to private property below from leak above
2542455/1	WOR	CLO	10-Feb-2015	4HR	10-Feb-2015		2		03 - - trace and repair leak going to private TNTS below -
2542455	SRQ	RAI	10-Feb-2015	4HR	10-Feb-2015				03 - - trace and repair leak going to private TNTS below -
2488227	SRQ	RAI	14-Oct-2014						Copied from Works Order 2488186/1
2488227/1	WOR	CLO	14-Oct-2014	8WK	12-Jan-2015		3	Y	DUE DECEMBER 2014 - Annual Routine Service to ALL council owned gas heating appliances contained within the property.
2479005/9	WOR	CAN	16-Mar-2015	2WK	30-Mar-2015	PRO	2		02 - f/on as per - shave down internal doors to allow for threshold plate at flooring measure for facings to inside bed 2 as req and measure or s/f new folding door to bed 2 as req and arrange follow on app
2479005/8	WOR	CLO	06-Mar-2015	1WK	13-Mar-2015	PRO	1		19 - please inspect doors throughout -
2479005/7	WOR	CLO	26-Feb-2015	2WK	12-Mar-2015	PRO	1		02 - As per facings to bedroom window, and new door to bathroom: Facings : 70ml x 2 and half metre x 3. Door: 45ml x 2120 x 680, handles and slipbolt, inspect other work completed also
2479005/6	WOR	CLO	10-Feb-2015	2WK	24-Feb-2015	PRO	3		02 - re-raised as per - s/f grounds with finished short face to door, s/f facings to 3 sides of door frame. materials, 6m 70mm facing, 3m 40x12 ground 2.5 m 60x12 ground - also overhall 5 doors not closing properly -
2479005/5	WOR	CLO	29-Sep-2014	2WK	13-Oct-2014		2		2 man job 05 as per - box room , repair hole in ceiling at light pendant. hall cornice at box room door wall and press rhs of bathroom wall repair cracks - ladder req- tnt can advise.
2479005/4	WOR	CLO	24-Sep-2014	2WK	08-Oct-2014		2		02 - as per - s/f lining and facing to window in boxroom ingo 80mm deep and facing required to fit edge of ingo and plaster - approx 4 metres in length of ingo and facing
2479005/3	WOR	CLO	24-Sep-2014	2WK	08-Oct-2014		1		05 as per - box room , repair hole in ceiling at light pendant. hall cornice at box room door wall and press rhs of bathroom wall - tnt can advise.
2479005/2	WOR	CLO	24-Sep-2014	2WK	08-Oct-2014		3		02 as per - box room, s/f skirting to all 4 walls and pipebox, seal. s/f grounds with finished short face to door, s/f facings to 3 sides of door frame. materials, 6m 70mm facing, 8m skirting, 3m 40x12 ground 2.5 m 60x12 ground
2479005/1	WOR	CLO	19-Sep-2014	1WK	26-Sep-2014		1		19 as per - to inspect plaster works required - see
2479005	SRQ	RAI	19-Sep-2014	1WK	26-Sep-2014				19 as per - to inspect plaster works required - see
2456764/2	WOR	CLO	30-Jul-2014	2WK	13-Aug-2014		3		90 - f/on as per - s/f two double sockets and 1 gang 2 way light swith to box room.
2456764/1	WOR	CLO	24-Jul-2014	2WK	07-Aug-2014		2		90 - as per - refix light fitting back to ceiling.
2456764	SRQ	RAI	24-Jul-2014	2WK	07-Aug-2014				90 - as per - refix light fitting back to ceiling.
2456762/1	WOR	CLO	24-Jul-2014	2WK	07-Aug-2014		1		96 - f/on as per - refix radiator back wall in box room
2456762	SRQ	RAI	24-Jul-2014	2WK	07-Aug-2014				96 - f/on as per - refix radiator back wall in box room
2451551/1	WOR	CLO	07-Jul-2014	1WK	14-Jul-2014	PRO	1		pest control - mice-

2451551/I1	INS	COM	07-Jul-2014	2WK	21-Jul-2014				pest control - mice- [redacted]
2451551	SRQ	RAI	07-Jul-2014	2WK	21-Jul-2014				pest control - mice- [redacted]
2447987/8	WOR	CLO	28-Jul-2014	1WK	04-Aug-2014		1		19 -261 7341 -as per [redacted] FAO [redacted] - inspect for supplying and fitting skirtings, facings and door standards in box bedroom.
2447987/7	WOR	CLO	24-Jul-2014	2WK	07-Aug-2014		1		02 - f/on as per [redacted] - new box for pipes 3 meters high at box room
2447987/6	WOR	CLO	10-Jul-2014	2WK	24-Jul-2014		2		03 - f/on as per [redacted] - supply and fit three shelves to the hall shelves to be cut - 3x 1meterx500x18mm - supply and fit 2x1 strapping
2447987/5	WOR	CLO	07-Jul-2014	2WM	21-Jul-2014		1		MT02&05 [redacted] as per [redacted] hack out and make good boss plater to hallway alcove supply new bonding cout and skim same
2447987/4	WOR	CLO	07-Jul-2014	2WM	21-Jul-2014		3		MT02&05 - [redacted] as per [redacted] remove excisting sjelfing to hallway alcove ahead of platerwork to s&f new brass lock for upper sach and case window at kitchen large size measure for new shelves for alcove after plasterwork
2447987/3	WOR	CLO	07-Jul-2014	2WK	21-Jul-2014		3		MT05&90 [redacted] as per [redacted] remove 4 internal walls to box room plaster workl lass and plater all boss ceiling okay not to be touched s%f pboard to all walls skim same allowing for refitting of lightswitch and sockets up 22 sq
2447987/2	WOR	CLO	07-Jul-2014	2WK	21-Jul-2014		1		90&05 - [redacted] -as per [redacted] box room remove light sockets ahead of plaster work arrange follow on for refixing
2447987/1	WOR	CAN	25-Jun-2014	1WK	02-Jul-2014		1		19 - [redacted] - Cracks in the walls and skirting boards missing
2447987	SRQ	RAI	25-Jun-2014	1WK	02-Jul-2014				19 - [redacted] - Cracks in the walls and skirting boards missing
2370980/7	WOR	CLO	17-Jul-2014	2WK	31-Jul-2014		2		02 - [redacted] - supply new pipebox to box room 1 at 2.440 x 110 1 at 950 x110 1 at 2.440 x180 and 1 at 950x180 and supply 12 metres of 2 by 1 framing
2370980/6	WOR	CLO	17-Jul-2014	1D	18-Jul-2014		1		02 [redacted] As per [redacted] - frame and plasterboard pipe box 3 metres
2370980/5	WOR	CLO	17-Jul-2014	1D	18-Jul-2014		1		96 [redacted] As per [redacted] - remove radiators from wall to allow plastering work
2370980/4	WOR	CLO	04-Feb-2014	2WK	18-Feb-2014		1		02- [redacted] -S&F new sash stay to kitchen window
2370980/3	WOR	CLO	27-Jan-2014	2WK	10-Feb-2014		2		02- [redacted] as per [redacted] rehang existing bedropom door door in bedroom kitchen cupboard try & fix facings to jam & head use 75x15mm fittings approx 5m
2370980/2	WOR	CLO	27-Jan-2014	2WK	10-Feb-2014		1		71- [redacted] as per [redacted] upper case og fgeargian sash & case window keeps dropping req new weights case size approx 1.1x1.2m single glazed
2370980/1	WOR	CLO	20-Jan-2014	1WK	27-Jan-2014		1		19 [redacted] please inspect kitchen window as draughty also replacement facings at pantry door as removed for plastering work and bedroom door
2370980	SRQ	RAI	20-Jan-2014	1WK	27-Jan-2014				19 [redacted] please inspect kitchen window as draughty also replacement facings at pantry door as removed for plastering work and bedroom door
2370978/2	WOR	CAN	10-Feb-2014	2WK	24-Feb-2014		1		02 f/o as per [redacted] s+f new sash lock for kitchen window
2370978/1	WOR	CLO	20-Jan-2014	1D	21-Jan-2014		2		90 [redacted] please repair/replace smoke alarm as damaged
2370978	SRQ	RAI	20-Jan-2014	1D	21-Jan-2014				90 [redacted] please repair/replace smoke alarm as damaged
2370974/1	WOR	CAN	20-Jan-2014	2WK	03-Feb-2014		1		02 [redacted] please rehang bedroom door after being removed to carry out plastering work door on site
2370974	SRQ	CAN	20-Jan-2014	2WK	03-Feb-2014				02 [redacted] please rehang bedroom door after being removed to carry out plastering work door on site
2354342/6	WOR	CLO	13-Jan-2014	2WK	27-Jan-2014		1		06 - Follow on as per [redacted] - New Single paned laminated glass required sizes 820 x 523 6.4lam - 261 7341
2354342/5	WOR	CLO	13-Jan-2014	2WK	27-Jan-2014		1		06 tnt was in for morning appt - please ring ahead at front door [redacted] black main door with surname [redacted] on. - [redacted] s/f new single pane of glass - kitchen dining room area to bedroom
2354342/4	WOR	CAN	08-Jan-2014	2WK	22-Jan-2014		1		06 RE-RAISED - [redacted] s/f new single pane of glass - kitchen dining room area to bedroom
2354342/3	WOR	CAN	03-Jan-2014	2WK	17-Jan-2014		1		06 [redacted] s/f new single pane of glass - kitchen dining room area to bedroom
2354342/2	WOR	CLO	03-Jan-2014	2WK	17-Jan-2014		3		19 [redacted] f/on as per [redacted] - s/f slip bolt to bathroom door and sham handles to bedroom door
2354342/1	WOR	CLO	30-Dec-2013	1WK	08-Jan-2014		1		19 [redacted] please inspect dampness in bathroom and bedroom door as damaged
2354342	SRQ	RAI	30-Dec-2013	1WK	08-Jan-2014				19 [redacted] please inspect dampness in bathroom and bedroom door as damaged

2348066/1	WOR	CAN	10-Dec-2013	2WK	24-Dec-2013		1		Carry out force entry for Gas Engineer including replacing locks and making good door and surrounds. Per door
2348066	SRQ	CAN	10-Dec-2013	2WK	24-Dec-2013				Carry out force entry for Gas Engineer including replacing locks and making good door and surrounds. Per door
2336916/2	WOR	CLO	16-Dec-2013	2WK	03-Jan-2014		3		90 -RERAISED - [redacted] please reinstate sockets in kitchen after plastering work x2 also check and repair light fitting in bedroom
2336916/1	WOR	CAN	19-Nov-2013	2WK	03-Dec-2013		2		90 [redacted] please reinstate sockets in kitchen after plastering work x2 also check and repair light fitting in bedroom
2336916	SRQ	RAI	19-Nov-2013	2WK	03-Dec-2013				90 [redacted] please reinstate sockets in kitchen after plastering work x2 also check and repair light fitting in bedroom
2332189/1	WOR	CLO	06-Nov-2013	4HR	08-Nov-2013		2		03 - Leak from 2f3 into 1f3 - Been leaking since 3pm yesterday and no answer from 2f3. Please attend - possible force entry required
2332189	SRQ	RAI	06-Nov-2013	4HR	06-Nov-2013				03 - Leak from 2f3 into 1f3 - Been leaking since 3pm yesterday and no answer from 2f3. Please attend - possible force entry required
2320313/6	WOR	CLO	22-Nov-2013	1D	25-Nov-2013	PRO	1		02 as per [redacted] ebs - parking issues - take off bedroom door to allow scaffolding and plastering work to start - please inform planner once completed - tel [redacted]
2320313/5	WOR	CAN	29-Oct-2013	2WK	12-Nov-2013	PRO	1		09 - [redacted] - as per [redacted] - scaffolding req for internal plaster work - ceiling approx 3.2 metres - work with plasterers - who are due to start work on monday 14/10/13
2320313/4	WOR	CLO	29-Oct-2013	2WK	12-Nov-2013	PRO	1		05 f/n d burnside replace bedroom ceiling x2 plasterers 09 12ft scaffold required
2320313/3	WOR	CLO	29-Oct-2013	2MV	12-Nov-2013	PRO	3		05 2 MAN JOB FOR PARKING FAO [redacted] - as per [redacted] - patch cupboard walls and skim coat - [redacted]
2320313/2	WOR	CAN	11-Oct-2013	2WK	25-Oct-2013	PRO	2		05 2 MAN JOB FOR PARKING FAO [redacted] - as per [redacted] - patch cupboard walls and skim coat - [redacted]
2320313/1	WOR	CLO	09-Oct-2013	8WK	24-Dec-2013	PRO	1	Y	GASSERV-LEICC-Annual Routine Gas Service
2320313	SRQ	RAI	09-Oct-2013	8WK	04-Dec-2013	PRO			GASSERV-LEICC-Annual Routine Gas Service
2315384/3	WOR	CLO	19-Nov-2013	2WK	03-Dec-2013		2		02 [redacted] -02 f/on [redacted] - s/f 5 meters of skirting to cupboard in kitchen plastering work completed - also please repair handle on bedroom door
2315384/2	WOR	CAN	11-Oct-2013	2WK	25-Oct-2013		1		02 f/on [redacted] - s/f 5 meters of skirting to cupboard in kitchen - [redacted]
2315384/1	WOR	CLO	26-Sep-2013	4HR	26-Sep-2013		1		02 [redacted] - Please renew lock on front door as hanging off due to many times being screwed back in just keeps falling off
2315384	SRQ	RAI	26-Sep-2013	4HR	26-Sep-2013				02 [redacted] - Please renew lock on front door as hanging off due to many times being screwed back in just keeps falling off
2314495/5	WOR	CLO	29-Oct-2013	2WK	21-Nov-2013		1		02 f/on [redacted] - s/f 5 meters of skirting to cupboard in kitchen - [redacted]
2314495/4	WOR	CLO	27-Sep-2013	2WK	11-Oct-2013		4		96 as per [redacted] - s&f eat exchanger pads and PRV - to [redacted] 14se - part ref 646892 hawkhill -
2314495/3	WOR	CLO	26-Sep-2013	1D	27-Sep-2013		5		96 [redacted] - Repair faulty boiler as no GCH or HW - No back ups
2314495/2	WOR	CAN	26-Sep-2013	1D	27-Sep-2013		1		99 [redacted] - re raised - Please repair boiler as no gch or hot water - no backs ups
2314495/1	WOR	CAN	24-Sep-2013	1D	25-Sep-2013		1		96 [redacted] - Repair faulty boiler as no GCH or HW - No back ups
2314495	SRQ	RAI	24-Sep-2013	1D	25-Sep-2013				96 [redacted] - Repair faulty boiler as no GCH or HW - No back ups
2314071/12	WOR	CLO	27-Nov-2013	2WK	11-Dec-2013		2		05 - [redacted] - f/n d burnside replace bedroom ceiling x 2 plasterers 09 12ft scaffold required - kc scaffolding erecting scaffold
2314071/11	WOR	CAN	15-Oct-2013	2WK	29-Oct-2013		2		90 f/o [redacted] meterials required re instal elecetice socket in cup board - s & 1x double patrice 2 x single patrice 1x duel single patrice2 x single socket 2 x feuse spur 1x double 25 x 40 trucking 2.5 cable socket [redacted] -
2314071/10	WOR	CAN	15-Oct-2013	2WK	29-Oct-2013		1		09 f/n 12 ft scaffold required 05 replace bedroom ceiling x2 plasterers
2314071/9	WOR	CLO	15-Oct-2013	2WK	29-Oct-2013		1		05 f/n d burnside replace bedroom ceiling x2 plasterers 09 12ft scaffold required
2314071/8	WOR	CLO	11-Oct-2013	2WK	25-Oct-2013		1		09 - [redacted] - as per [redacted] - scaffolding req for internal plaster work - ceiling approx 3.2 metres - work with plasterers - who are due to start work on monday 14/10/13
2314071/7	WOR	CLO	02-Oct-2013	2WK	16-Oct-2013		1		MT as per [redacted] 05 & 02 & 90 to work 2gether 261 7341 - make good plaster following removal of timber lining approx 1.3 x 1.2. + 1.3 + 1.2 + 0.5m

2314071/6	WOR	CLO	02-Oct-2013	2WK	16-Oct-2013		2		MT as per [redacted] 02 & 05 & 90 to work 2gether 261 7341 - remove panelling from cupboard low level 1.3 mtrs above floor approx 4 mtrs in length s/f skirting approx 1.2 ,1.3, 0.5, 500mm
2314071/5	WOR	CLO	02-Oct-2013	2WK	16-Oct-2013		1		MT as per [redacted] 90 & 05 & 02 to work 2gether 261 7341 remove electical trunking and socket replace after plasterworks,
2314071/4	WOR	CLO	02-Oct-2013	2WK	16-Oct-2013		4		90, flown as per [redacted] 261 7341, repair light fitting - circuit to hall -
2314071/3	WOR	CLO	02-Oct-2013	2WK	16-Oct-2013		1		05 - flown as per [redacted] [redacted] - replace bedroom ceiling 3.6 x 2.7 mtrs - ceiling is 3.1 above AFFL - lath and plaster at moment -
2314071/2	WOR	CLO	02-Oct-2013	2WK	16-Oct-2013		2		02 fllown as per [redacted] - [redacted] - remove and refit yale latch on front door in new position - make good resultant reduntant holes -
2314071/1	WOR	CLO	23-Sep-2013	1WK	30-Sep-2013		1		19 - [redacted] - Please inspect the storage cupboard, whole in the wall under wallpaper which has been filled with newspaper. Walls crumbling
2314071	SRQ	RAI	23-Sep-2013	1WK	30-Sep-2013				19 - [redacted] - Please inspect the storage cupboard, whole in the wall under wallpaper which has been filled with newspaper. Walls crumbling
2299828/6	WOR	CLO	26-Aug-2013	2WM	09-Sep-2013		2		03 MT 02 f/o [redacted] fit new bath as cradle is loose work with joiner
2299828/5	WOR	CLO	26-Aug-2013	2WM	09-Sep-2013		1		02 MT 03 f/o [redacted] renew 2 white bath pannels and renew skirting 4 meters long - work with plumber renew floors board under bath
2299828/4	WOR	CAN	14-Aug-2013	2WM	28-Aug-2013		2		03 MT 02 f/o [redacted] fit new bath as cradle is loose work with joiner
2299828/3	WOR	CAN	14-Aug-2013	2WM	28-Aug-2013		1		02 MT 03 f/o [redacted] renew 2 white bath pannels and renew skirting 4 meters long - work with plumber renew floors board under bath
2299828/2	WOR	CAN	14-Aug-2013	2WM	28-Aug-2013		2		03 MT 02 f/o [redacted] fit new bath as cradle is loose work with joiner
2299828/1	WOR	CLO	14-Aug-2013	4HR	14-Aug-2013		1		03 Trace and repair leak in property. [redacted]
2299828	SRQ	RAI	14-Aug-2013	4HR	14-Aug-2013				03 Trace and repair leak in property. [redacted]
2254357/1	WOR	CAN	18-Apr-2013	1WK	25-Apr-2013	PRO	1		Rats/Mice treatment - Contact the tenant for access - [redacted]
2254357/I1	INS	COM	16-Apr-2013	2WK	30-Apr-2013	PRO			PEST CONTROL - [redacted] - Has found mice droppings in property
2254357	SRQ	RAI	16-Apr-2013	2WK	30-Apr-2013	PRO			PEST CONTROL - [redacted] - Has found mice droppings in property
2252335/1	WOR	CLO	10-Apr-2013	4HR	10-Apr-2013		2		03 - Trace and repair uncontainable leak going to 2 private properties below
2252335	SRQ	RAI	10-Apr-2013	4HR	10-Apr-2013				03 - Trace and repair uncontainable leak going to 2 private properties below
2252296/1	WOR	CLO	10-Apr-2013	1D	11-Apr-2013		6		96 [redacted] - no gch or hot water - no back ups
2252296	SRQ	RAI	10-Apr-2013	1D	11-Apr-2013				96 [redacted] - no gch or hot water - no back ups
2249667/2	WOR	CLO	11-Apr-2013	2WK	26-Apr-2013		1		02- FON R MELROSE - [redacted] - patch at yale and secure the yale
2249667/1	WOR	CLO	08-Apr-2013	1WK	16-Apr-2013		1		19 [redacted] - please inspect front door
2249667	SRQ	RAI	08-Apr-2013	1WK	16-Apr-2013				19 [redacted] - please inspect front door
2249657/1	WOR	CAN	08-Apr-2013	1D	09-Apr-2013		1		96 [redacted] - no gch or hot water - no back ups
2249657	SRQ	CAN	08-Apr-2013	1D	09-Apr-2013				96 [redacted] - no gch or hot water - no back ups
2248449/1	WOR	CLO	03-Apr-2013	4HR	03-Apr-2013		2		CES - leaking waste or soil pipe to rear of building causing water ingress to private tnt in PF1 - - passed [redacted]
2248449	SRQ	RAI	03-Apr-2013	4HR	03-Apr-2013				CES - leaking waste or soil pipe to rear of building causing water ingress to private tnt in PF1 - - passed [redacted]
2238405/6	WOR	CAN	27-Mar-2013	2WK	12-Apr-2013		1		03- [redacted] possible over flow running down side of the building down neighbours windows - re raised as carded
2238405/5	WOR	CAN	20-Mar-2013	2WK	05-Apr-2013		1		03- [redacted] possible over flow runni8ng down side of the building down neighbours windows
2238405/4	WOR	CLO	20-Mar-2013	2WK	05-Apr-2013		3		02 - fllown as per [redacted] - lev er handles to boys bedroom - new flush panel door to bedroom - 2110 x 800 x 40 - lever handles - overhaul bathroom door and boys bedroom door - thanks
2238405/3	WOR	CAN	07-Mar-2013	2WK	21-Mar-2013		3		02 - fllown as per [redacted] - lev er handles to boys bedroom - new flush panel door to bedroom - 2110 x 800 x 40 - lever handles - overhaul bathroom door and boys bedroom door - thanks
2238405/2	WOR	CLO	06-Mar-2013	1WK	13-Mar-2013		1		19- [redacted] pls access internal doors within the property
2238405/1	WOR	CAN	06-Mar-2013	2WK	20-Mar-2013		1		03- [redacted] possible over flow runni8ng down side of the building down neighbours windows
2238405	SRQ	RAI	06-Mar-2013	2WK	20-Mar-2013				03- [redacted] possible over flow runni8ng down side of the building down neighbours windows
2188305	SRQ	RAI	05-Nov-2012						Copied from Works Order 2188249/1

2188305/1	WOR	CLO	05-Nov-2012	8WK	28-Jan-2013		4	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
2188094	SRQ	CAN	05-Nov-2012						Copied from Works Order 2188035/1
2188094/1	WOR	CAN	05-Nov-2012	8WK	04-Jan-2013		1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
2171790/2	WOR	CLO	03-Oct-2012	2WK	17-Oct-2012		4		02 as per - s&f living room door SC 905x40x2120, cupboard 2100x35x810 not SC. quarter round 20x25x2m at skirting. lift loose floorboards and refit in living room - tel
2171790/1	WOR	CLO	02-Oct-2012	1WK	09-Oct-2012		1		19-floor boards in the living room are uneven and also living room door wont close properly
2171790	SRQ	RAI	02-Oct-2012	1WK	09-Oct-2012				19-floor boards in the living room are uneven and also living room door wont close properly
2171786/2	WOR	CLO	03-Oct-2012	1D	04-Oct-2012		2		03 as per - no running water in property - has drinking water
2171786/1	WOR	CLO	02-Oct-2012	1D	03-Oct-2012		2		96-GCH & Hot water not working no back ups in the property if poss pls make 1day for wed as tnt going out at 2pm today to work not promised
2171786	SRQ	RAI	02-Oct-2012	1D	03-Oct-2012				96-GCH & Hot water not working no back ups in the property if poss pls make 1day for wed as tnt going out at 2pm today to work not promised
2129670/1	WOR	CLO	13-Jun-2012	1D	14-Jun-2012		1		03 bath not draining away -
2129670	SRQ	RAI	13-Jun-2012	1D	14-Jun-2012				03 bath not draining away -
2052853/1	WOR	CAN	16-Dec-2011	1D	19-Dec-2011		1		96 - -SAY'S ON BUZZER FOR THIS TNT- RE-RAISED AS CARDED - no gch no hot water no backups
2052853	SRQ	RAI	16-Dec-2011	1D	19-Dec-2011				96 - -SAY'S ON BUZZER FOR THIS TNT- RE-RAISED AS CARDED - no gch no hot water no backups
2051193/1	WOR	CAN	14-Dec-2011	1D	15-Dec-2011		1		96 no gch no hot water no backups
2051193	SRQ	RAI	14-Dec-2011	1D	15-Dec-2011				96 no gch no hot water no backups
2050473	SRQ	RAI	13-Dec-2011						Copied from Works Order 2050029/1
2050473/1	WOR	CLO	13-Dec-2011	8WK	02-Apr-2012		4	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
2037827/1	WOR	CLO	16-Nov-2011	1D	17-Nov-2011		3		96 faulty GCH no heat no hot water no back up - boiler keeps asking to be re set - tnt has tried but is unable to do this
2037827	SRQ	RAI	16-Nov-2011	1D	17-Nov-2011				96 faulty GCH no heat no hot water no back up - boiler keeps asking to be re set - tnt has tried but is unable to do this
2032533/1	WOR	CLO	07-Nov-2011	2WK	21-Nov-2011		2		96 - gch faulty, no heating, hot water ok - tel
2032533	SRQ	RAI	07-Nov-2011	2WK	21-Nov-2011				96 - gch faulty, no heating, hot water ok - tel
2021274/2	WOR	CLO	19-Oct-2011	2WK	02-Nov-2011		2		02 - - f/on as per -suplpy and fit thresholds to 6mm ply materiels on site to length of faceings also at site
2021274/1	WOR	CAN	11-Oct-2011	2WK	25-Oct-2011		1		02 FAO supply and fit 2 new weight for top sash window weights on window are size 14
2021274	SRQ	RAI	11-Oct-2011	2WK	25-Oct-2011				02 FAO supply and fit 2 new weight for top sash window weights on window are size 14
2017132/1	WOR	CLO	04-Oct-2011	4HR	04-Oct-2011		2		CES Tnt reported that she has no water after plumber left. Passed to
2017132	SRQ	COM	04-Oct-2011	4HR	04-Oct-2011				CES Tnt reported that she has no water after plumber left. Passed to
2015298/9	WOR	CLO	14-Oct-2011	2WK	28-Oct-2011		2		02 F/ON as per screw down boards and ply hall using 6mm ply and 2 facings 110x18 oj facings 2800 and 2300
2015298/8	WOR	CLO	11-Oct-2011	2WK	25-Oct-2011		1		09 f/n I Scaffolding req - tel 623 0422
2015298/7	WOR	CLO	11-Oct-2011	2WK	25-Oct-2011		1		05 f/n I - Repair wall and ceiling where req - old prop - hall area - tel 623 0422 scaffolding req -
2015298/6	WOR	CLO	04-Oct-2011	2WM	18-Oct-2011		1		MT 90 and 05 to work together F/ON as per 90 to remove pendant and mains smoke alarm and refit once complete
2015298/5	WOR	CLO	04-Oct-2011	2WM	18-Oct-2011		1		MT 05 and 90 to work together F/ON as per 05 to repair walls and ceiling where required - old property lathe and plaster ceilings - if more time required call Robin
2015298/4	WOR	CLO	04-Oct-2011	2WK	18-Oct-2011		1		02 F/ON as per screw down boards and ply hall using 6mm ply
2015298/3	WOR	CAN	04-Oct-2011	2WK	18-Oct-2011		1		05 F/ON as per repair walls and ceiling where required - old property lathe and plaster ceilings - if more time required call Robin
2015298/2	WOR	CLO	04-Oct-2011	2WK	18-Oct-2011		1		02 as per - overhaul case and sash windows where required
2015298/1	WOR	CLO	29-Sep-2011	1WK	06-Oct-2011		1		19 - please inspect windows in property

2015298	SRQ	COM	29-Sep-2011	1WK	06-Oct-2011				19 - please inspect windows in property
2015296/1	WOR	CLO	29-Sep-2011	2WK	13-Oct-2011		3		03 as per asupply and fit new close coupled toilet and cistern - re raised as carded
2015296	SRQ	COM	29-Sep-2011	2WK	13-Oct-2011				03 as per asupply and fit new close coupled toilet and cistern - re raised as carded
1995663/1	WOR	CAN	10-Aug-2011	2WK	24-Aug-2011		2		03 as per asupply and fit new close coupled toilet and cistern
1995663	SRQ	CAN	10-Aug-2011	2WK	24-Aug-2011				03 as per asupply and fit new close coupled toilet and cistern
1992108/3	WOR	CLO	04-Aug-2011	2WK	18-Aug-2011	PRO	1		03 CES F/N S - New multi quick pabn connector -
1992108/2	WOR	CAN	02-Aug-2011	1D	03-Aug-2011		1		03 ces f/on as per S s&f new multi quick pan connector
1992108/1	WOR	CLO	01-Aug-2011	4HR	01-Aug-2011		3		CES - TOILET LEAKING INTO NEIGHBOUR BELOW - PASSED TO
1992108	SRQ	RAI	01-Aug-2011	4HR	01-Aug-2011				CES - TOILET LEAKING INTO NEIGHBOUR BELOW - PASSED TO
1957068/1	WOR	CAN	09-May-2011	1D	10-May-2011		1		90 - - Mains smoke alarm is not working atall - there is no power going to it
1957068	SRQ	CAN	09-May-2011	1D	10-May-2011				90 - - Mains smoke alarm is not working atall - there is no power going to it
1950176/4	WOR	CLO	04-May-2011	2WK	18-May-2011		3		90 - As per - supply anf fit new pendant 3ft cable in box bedroom take ladders 11ft 6 ceilings
1950176/3	WOR	CLO	03-May-2011	1WK	10-May-2011		1		19 F/ON - please evaluate how electrcian is going to reach light in bedroom within saftey regulations as per
1950176/2	WOR	CLO	26-Apr-2011	2WK	12-May-2011		2		90 f/on - tel repair bedroom light
1950176/1	WOR	CLO	20-Apr-2011	1WK	03-May-2011		1		19 please inspect cracks in walls and various other repairs - tel
1950176	SRQ	RAI	20-Apr-2011	1WK	03-May-2011				19 please inspect cracks in walls and various other repairs - tel
1927731	SRQ	COM	01-Mar-2011						Copied from Works Order 1927639/1
1927731/1	WOR	CLO	01-Mar-2011	8WK	31-May-2011		1	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
1913399/2	WOR	CLO	01-Feb-2011	2WK	15-Feb-2011		3		90 check top entry immersion thermostat for overheating as per
1913399/1	WOR	CLO	01-Feb-2011	4HR	01-Feb-2011		4		03- - trace and repair leak going to bellow tnt's
1913399	SRQ	RAI	01-Feb-2011	4HR	01-Feb-2011				03- - trace and repair leak going to bellow tnt's
1911748/1	WOR	CAN	30-Jan-2011	4HR	31-Jan-2011		2		ces - as per water ingress leak coming from here into flat below passed to 10.14
1911748	SRQ	CAN	30-Jan-2011	4HR	31-Jan-2011				ces - as per water ingress leak coming from here into flat below passed to 10.14
1880669/7	WOR	CLO	20-Dec-2010	2WK	07-Jan-2011	BTHR	4		05 small plaster patch to walls check and ceilings ladder required renew tiles to bath white in colour as per - 623 0422
1880669/6	WOR	CLO	13-Dec-2010	2WK	29-Dec-2010		2		02 2MV - F/O as per Supply and fit ply to the bathroom floor and ply for pipe box in bathroom - 4 half sheets of 6mil ply and 2400 x 400 x 12mil ply x 2 and 6meters of 2x1 - 3 meter Ladder reqr'd
1880669/5	WOR	CLO	25-Nov-2010	2WK	09-Dec-2010		2		02 2MV - F/O as per Supply and fit ply to the bathroom floor and ply for pipe box in bathroom - 4 half sheets of 6mil ply and 2400 x 400 x 12mil ply x 2 and 6meters of 2x1 - 3 meter Ladder reqr'd
1880669/4	WOR	CAN	25-Nov-2010	2WK	09-Dec-2010		2		02 F/O as per Supply and fit ply to the bathroom floor and ply for pipe box in bathroom - 4 half sheets of 6mil ply and 2400 x 400 x 12mil ply x 2
1880669/3	WOR	CAN	22-Nov-2010	2WK	06-Dec-2010		2		05 small plaster aptch to wals check and ceilings ladder required renew tiles to bath white in colour as epr
1880669/2	WOR	CLO	22-Nov-2010	2WK	06-Dec-2010		4		02 bagth panel and end shelf to end of bath 600x700x18ml ply renew pipe box 3.5 mt x300x300 refix floorboards and ply as per
1880669/1	WOR	CLO	17-Nov-2010	1WK	29-Nov-2010		1		19 - please inspect walls as crumbling and bath pannel due to flood damage
1880669	SRQ	RAI	17-Nov-2010	1WK	24-Nov-2010				19 - please inspect walls as crumbling and bath pannel due to flood damage
1835354/2	WOR	CLO	11-Aug-2010	4HR	11-Aug-2010		1		03 & 02 MT - trace and repair leak with joiner
1835354/1	WOR	CLO	11-Aug-2010	4HR	11-Aug-2010		2		02 & 03 MT - force entry and lock change to allow for plumber to trace and repair leak going into property below, owner's ceiling is about to collapse
1835354	SRQ	RAI	11-Aug-2010	4HR	11-Aug-2010				02 & 03 MT - force entry and lock change to allow for plumber to trace and repair leak going into property below, owner's ceiling is about to collapse
1815518/1	WOR	CAN	28-Jun-2010	1WK	05-Jul-2010		1		19 - qco - Pls insp property after flood damage - some plaster work needing done - bath panel - tiles missing

1815518	SRQ	CAN	28-Jun-2010	1WK	05-Jul-2010				19 - qco - [redacted] Pls insp property after flood damage - some plaster work needing done - bath panel - tiles missing
1804222	SRQ	RAI	02-Jun-2010						Copied from Works Order 1804200/1
1804222/1	WOR	CLO	02-Jun-2010	8WK	02-Aug-2010		3	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
1789482/1	WOR	CLO	04-May-2010	1WK	11-May-2010		1		19 RERAISED AS CARDED ongoing work since xmas still unfinished pls check and raise repairs ISSUES WITH BUZZER PLS CALL IF UNABLE TO GAIN ACCESS 623 0422
1789482	SRQ	RAI	04-May-2010	1WK	11-May-2010				19 RERAISED AS CARDED ongoing work since xmas still unfinished pls check and raise repairs ISSUES WITH BUZZER PLS CALL IF UNABLE TO GAIN ACCESS 623 0422
1777958/1	WOR	CAN	08-Apr-2010	1WK	15-Apr-2010		1		19 ongoing work since xmas still unfinished pls check and raise repairs [redacted]
1777958	SRQ	CAN	08-Apr-2010	1WK	15-Apr-2010				19 ongoing work since xmas still unfinished pls check and raise repairs [redacted]
1759543	SRQ	CAN	01-Mar-2010						Copied from Works Order 1759522/1
1759543/1	WOR	CAN	01-Mar-2010	8WK	28-Jul-2010		1		Annual Routine Service to ALL council owned gas heating appliances contained within the property.
1759188/3	WOR	CAN	01-Mar-2010	2WK	15-Mar-2010		2		09 Scaffold Required RERASIED AS CARDED CALL [redacted] FOR ACCESS FEW DAYS BEFORE ARRIVING FOR ACCESS [redacted] work with plumber as per [redacted] & [redacted] on Order Number 1759188/1
1759188/2	WOR	CAN	01-Mar-2010	2WK	15-Mar-2010		2		09 Scaffold Required RERASIED AS CARDED work with plumber as per [redacted] & [redacted] on Order Number 1759188/1
1759188/1	WOR	CLO	01-Mar-2010	2WK	15-Mar-2010		1		03PLEASE CALL [redacted] TO ARRANGE ACCESS FEW DAYS BEFORE ATTENDING [redacted] as per [redacted] check drain pipe at the ceiling possible leak and repair requires scaffolding break away ceiling for access
1759188	SRQ	RAI	01-Mar-2010	2WK	15-Mar-2010				03PLEASE CALL [redacted] TO ARRANGE ACCESS FEW DAYS BEFORE ATTENDING [redacted] as per [redacted] check drain pipe at the ceiling possible leak and repair requires scaffolding break away ceiling for access
1747333/3	WOR	CAN	08-Feb-2010	2WK	22-Feb-2010		2		09 Scaffold Required - work with plumber as per [redacted] & [redacted] on Order Number 1747333/1
1747333/2	WOR	CAN	08-Feb-2010	2WK	22-Feb-2010		2		03 as per [redacted] check drain pipe at the ceiling possible leak and repair requires scaffolding break away ceiling for access
1747333/1	WOR	CLO	04-Feb-2010	2WK	18-Feb-2010		1		03 as per [redacted] check drain pipe at the ceiling possible leak and repair requires scaffolding break away ceiling for access
1747333	SRQ	RAI	04-Feb-2010	2WK	18-Feb-2010				03 as per [redacted] check drain pipe at the ceiling possible leak and repair requires scaffolding break away ceiling for access
1740014/1	WOR	CLO	22-Jan-2010	4HR	22-Jan-2010		2		03 uncontainable leak comming into property
1740014	SRQ	RAI	22-Jan-2010	4HR	22-Jan-2010				03 uncontainable leak comming into property
1736497/2	WOR	CLO	25-Jan-2010	2WK	08-Feb-2010		1		03 as per [redacted] check drain pipe at the ceiling possible leak and repair requires scaffolding break away ceiling for access
1736497/1	WOR	CLO	15-Jan-2010	1WK	22-Jan-2010		1		19 please inspect ceiling as she has slow leak. Might have to make hole in ceiling to make access for 03.
1736497	SRQ	RAI	15-Jan-2010	1WK	22-Jan-2010				19 please inspect ceiling as she has slow leak. Might have to make hole in ceiling to make access for 03.
1734548/1	WOR	CAN	12-Jan-2010	1D	13-Jan-2010		1		03 trace and repair leak from under bath containable.
1734548	SRQ	RAI	12-Jan-2010	1D	13-Jan-2010				03 trace and repair leak from under bath containable.
1724651/1	WOR	CLO	21-Dec-2009	2WK	08-Jan-2010		1		Adaptations ([redacted] Pls fit long g/rail to bathroom wall by steop up toilet. RHS ascending in diagonal position.([redacted]
1724651	SRQ	RAI	21-Dec-2009	2WK	08-Jan-2010				Adaptations ([redacted] Pls fit long g/rail to bathroom wall by steop up toilet. RHS ascending in diagonal position.([redacted]
1719066/1	WOR	CLO	08-Dec-2009	2WK	22-Dec-2009		1		URGENT: Adaptations ([redacted] Pleas fix toilet frame to floor over toilet. Frame & Floor fixings ordered and in situ.([redacted]
1719066	SRQ	RAI	08-Dec-2009	2WK	22-Dec-2009				URGENT: Adaptations ([redacted] Pleas fix toilet frame to floor over toilet. Frame & Floor fixings ordered and in situ.([redacted]
1704478/2	WOR	CLO	17-Nov-2009	2WK	01-Dec-2009		2		03 - [redacted] - as per [redacted] - trace leak from cast iron pipe in bathroom
1704478/1	WOR	CLO	12-Nov-2009	1WK	19-Nov-2009		1		19 [redacted] please inspect bathroom after leak

1704478	SRQ	RAI	12-Nov-2009	1WK	19-Nov-2009				19 please inspect bathroom after leak
1696600/5	WOR	CLO	04-Nov-2009	4HR	04-Nov-2009		3		03 to work with 02 re raised as emer as leak now uncontainable F/ON MT work with 02. 03 to take out bath and trace leak.
1696600/4	WOR	CAN	04-Nov-2009	4HR	04-Nov-2009		1		02 to work with 03 re raised as emer as leak now uncontainable F/ON MT Uplift part of floor to allow 03 to trace leak
1696600/3	WOR	CAN	03-Nov-2009	2WK	17-Nov-2009		1		02-F/ON MT Uplift part of floor to allow 03 to trace leak
1696600/2	WOR	CAN	03-Nov-2009	2WK	17-Nov-2009		2		03-F/ON MT work with 02. 03 to take out bath and trace leak.
1696600/1	WOR	CLO	02-Nov-2009	4HR	02-Nov-2009		2		03 Hiden leak in property bathroom going to tnt below which is private tnt
1696600	SRQ	RAI	02-Nov-2009	4HR	02-Nov-2009				03 Hiden leak in property bathroom going to tnt below which is private tnt
1692366/1	WOR	CLO	21-Oct-2009	2WK	04-Nov-2009		1		03 - - please repair flush on wc
1692366	SRQ	RAI	21-Oct-2009	2WK	04-Nov-2009				03 - - please repair flush on wc
1689625/1	WOR	CLO	14-Oct-2009	4HR	14-Oct-2009		2		40 - leak from pipe box going into tnt below
1689625	SRQ	RAI	14-Oct-2009	4HR	14-Oct-2009				40 - leak from pipe box going into tnt below
1671526/1	WOR	CLO	02-Sep-2009	1D	03-Sep-2009		2		03 - re-raised as carded - - partial loss of water in bathroom
1671526	SRQ	RAI	02-Sep-2009	1D	03-Sep-2009				03 - re-raised as carded - - partial loss of water in bathroom
1664174/1	WOR	CAN	18-Aug-2009	1D	19-Aug-2009		1		03 - re-raised as carded - - partial loss of water in bathroom
1664174	SRQ	CAN	18-Aug-2009	1D	19-Aug-2009				03 - re-raised as carded - - partial loss of water in bathroom
1664022/1	WOR	CLO	18-Aug-2009	4HR	18-Aug-2009		1		03 partial loss of water in no water in bathroom
1664022	SRQ	RAI	18-Aug-2009	4HR	18-Aug-2009				03 partial loss of water in no water in bathroom
1662735/1	WOR	CAN	14-Aug-2009	1D	17-Aug-2009		1		03 loss of water to the bathroom no water at all
1662735	SRQ	CAN	14-Aug-2009	1D	17-Aug-2009				03 loss of water to the bathroom no water at all
1662732/2	WOR	CLO	14-Aug-2009	1D	17-Aug-2009		3		96 - F/ON M - Pls s/f heat exchanger and pads to 14SE - tnt
1662732/1	WOR	CLO	14-Aug-2009	1D	17-Aug-2009		2		96 Boiler is kleaking cant contain was just repaird
1662732	SRQ	RAI	14-Aug-2009	1D	17-Aug-2009				96 Boiler is kleaking cant contain was just repaird
1659658/3	WOR	CLO	24-Aug-2009	2WK	07-Sep-2009		3		02 - - as per - relay floorboards between hall and bedrooms
1659658/2	WOR	CLO	17-Aug-2009	1WK	24-Aug-2009	LVRM	1		QCO - F/ON - Pls inspect flooring in l/room - tnt 556 3956
1659658/1	WOR	CLO	06-Aug-2009	2WK	20-Aug-2009		1		02 556 3956 floor boards are uneven and dipping down outside kids bedroom
1659658	SRQ	RAI	06-Aug-2009	2WK	20-Aug-2009				02 556 3956 floor boards are uneven and dipping down outside kids bedroom
1659654/1	WOR	CLO	06-Aug-2009	2WK	20-Aug-2009		2		96 faulty boiler water not heating up properly also radiators not heating up
1659654	SRQ	RAI	06-Aug-2009	2WK	20-Aug-2009				96 faulty boiler water not heating up properly also radiators not heating up
1659653/1	WOR	CAN	06-Aug-2009	1D	07-Aug-2009		1		03 loss of water to the bathroom no water at all
1659653	SRQ	RAI	06-Aug-2009	1D	07-Aug-2009				03 loss of water to the bathroom no water at all
1648608/1	WOR	CLO	14-Jul-2009	2WK	28-Jul-2009		2		02 yale lock not working tnt still has mortus
1648608	SRQ	RAI	14-Jul-2009	2WK	28-Jul-2009				02 yale lock not working tnt still has mortus
1647603/1	WOR	CLO	10-Jul-2009	1HR	10-Jul-2009		1		CES-> 02 - Front door lock not working - tnt unable to secure - Wooden door - Passed to @ 16:49
1647603	SRQ	RAI	10-Jul-2009	1HR	10-Jul-2009				CES-> 02 - Front door lock not working - tnt unable to secure - Wooden door - Passed to @ 16:49
1613535	SRQ	RAI	21-Apr-2009						Copied from Works Order 1613273/1
1613535/1	WOR	CLO	21-Apr-2009	8WK	18-Jun-2009		4	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
1603205/1	WOR	CLO	25-Mar-2009	1D	26-Mar-2009		3		96 - - Pls check and repair the gch as the tnt has no heat through the gas or hot water.
1603205	SRQ	RAI	25-Mar-2009	1D	26-Mar-2009				96 - - Pls check and repair the gch as the tnt has no heat through the gas or hot water.
1587226/1	WOR	CLO	24-Feb-2009	2WK	10-Mar-2009		2		03- Repair taps on bath as no water coming out of hot or cold taps
1587226	SRQ	RAI	24-Feb-2009	2WK	10-Mar-2009				03- Repair taps on bath as no water coming out of hot or cold taps
1574442/1	WOR	CLO	29-Jan-2009	1WK	05-Feb-2009		1		19 - to meet structural engineer on site either d- or j .in ref to crack in the wall . as per

1574442	SRQ	RAI	29-Jan-2009	1WK	05-Feb-2009				19 - [redacted] to meet structural engineer on site either d-[redacted] or j[redacted] .in ref to crack in the wall . as per [redacted]
1569468/4	WOR	CAN	29-Jan-2009	2WK	12-Feb-2009		1		08 F/N [redacted] - Strip off to walls in kitchen and dinning room - 64 square meters - tnt [redacted]
1569468/3	WOR	CLO	26-Jan-2009	2WK	09-Feb-2009		1		05 - no contact no - patch walls and ceiling in kitchen and bedroom - take scaffolding - as per [redacted]
1569468/2	WOR	CAN	26-Jan-2009	2WK	09-Feb-2009		1		08 - no contact no - remove paper for plasterer - as per [redacted]
1569468/1	WOR	CLO	20-Jan-2009	1WK	27-Jan-2009		1		repairs insp-pls inspect property kitchen and bathroom dampness and cracked ceiling (not artex)
1569468	SRQ	RAI	20-Jan-2009	1WK	27-Jan-2009				repairs insp-pls inspect property kitchen and bathroom dampness and cracked ceiling (not artex)
1536405/1	WOR	CLO	08-Nov-2008	1HR	10-Nov-2008		1		CES - [redacted] - passed to [redacted] - no heating or hot water - elderly tnt - needs heating - [redacted]
1536405	SRQ	RAI	08-Nov-2008	1HR	10-Nov-2008				CES - [redacted] - passed to [redacted] - no heating or hot water - elderly tnt - needs heating - [redacted]
1442933/1	WOR	CLO	30-Apr-2008	1D	01-May-2008		1		96-[redacted] urgent elderly tnt***pls repair boiler as not working tnt has no back
1442933	SRQ	RAI	30-Apr-2008	1D	01-May-2008				96-[redacted] urgent elderly tnt***pls repair boiler as not working tnt has no back
1432477	SRQ	CAN	03-Apr-2008	1D	04-Apr-2008				Ref no KS25 system down opertaive W[redacted] All dark stair
1428107/1	WOR	CLO	26-Mar-2008	1HR	26-Mar-2008		1		CES =PASSED TO [redacted] DAYWORKS RATE - Gas Technician
1428107	SRQ	RAI	26-Mar-2008	1HR	26-Mar-2008				CES =PASSED TO [redacted] DAYWORKS RATE - Gas Technician
1426239/1	WOR	CLO	20-Mar-2008	1D	25-Mar-2008		1		96- [redacted] - please call this number first as tnt ill in bed thanks please repair gas ch as nto working at allt ahns
1426239	SRQ	RAI	20-Mar-2008	1D	25-Mar-2008				96- [redacted] - please call this number first as tnt ill in bed thanks please repair gas ch as nto working at allt ahns
1426231/1	WOR	CAN	20-Mar-2008	1D	25-Mar-2008		1		90 - [redacted] please call this number before goign to prop as tnt is in bed ill, please supply 2 temp heaters as no heating in property thanks
1426231	SRQ	CAN	20-Mar-2008	1D	25-Mar-2008				90 - [redacted] please call this number before goign to prop as tnt is in bed ill, please supply 2 temp heaters as no heating in property thanks
1426225/1	WOR	CAN	20-Mar-2008	1D	25-Mar-2008		1		96- [redacted] - please repair gas ch as nto working at allt ahns
1426225	SRQ	CAN	20-Mar-2008	1D	25-Mar-2008				96- [redacted] - please repair gas ch as nto working at allt ahns
1399168	SRQ	RAI	24-Jan-2008						Copied from Works Order 1399159/1
1399168/1	WOR	CLO	24-Jan-2008	8WK	23-Oct-2008		1	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
1264678/1	WOR	CLO	20-Apr-2007	2WK	04-May-2007	KTCH	1		05 - remove damaged plaster work at top of cupboard and repair and any patches inside the cupboard aswell.....as per [redacted] tel: [redacted]
1264678/I1	INS	COM	12-Apr-2007	2WK	27-Apr-2007	KTCH		Y	pls inspect cupboard as tnt says its falling apart, there had been 02 out before but he couldnt do work required becasue he was too small?? There is a tank/boiler in the cupboard (in kitchen) - tel: [redacted]
1264678	SRQ	COM	12-Apr-2007	2WK	27-Apr-2007	KTCH			pls inspect cupboard as tnt says its falling apart, there had been 02 out before but he couldnt do work required becasue he was too small?? There is a tank/boiler in the cupboard (in kitchen) - tel: [redacted]
1262011/1	WOR	CLO	04-Apr-2007	1HR	04-Apr-2007		1		CEs elderly tenant has no heating -> S.[redacted]
1262011	SRQ	RAI	04-Apr-2007	1HR	04-Apr-2007				CEs elderly tenant has no heating -> S.[redacted]
1245804/1	WOR	CLO	22-Mar-2007	2WK	05-Apr-2007	KTCH	1		05/ patch walls in kitchen cupboard as per [redacted] [redacted]
1245804/I1	INS	COM	06-Mar-2007	2WK	20-Mar-2007	KTCH		Y	pls inspect wall in kitchen as tnt states that its crumbling away - [redacted]
1245804	SRQ	COM	06-Mar-2007	2WK	20-Mar-2007	KTCH			pls inspect wall in kitchen as tnt states that its crumbling away - [redacted]
1188422	SRQ	COM	04-Dec-2006						Copied from Works Order 1187921/1
1188422/1	WOR	CLO	04-Dec-2006	8WK	17-Apr-2007		3	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
1034056	SRQ	COM	02-Mar-2006						Copied from Works Order 1033567/1
1034056/1	WOR	CLO	02-Mar-2006	8WK	03-May-2006		3	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
934501/1	WOR	CLO	26-Sep-2005	1DY	26-Sep-2005		3		90-**URGENT** [redacted] pls repair faulty smoke alarms-constantly going off.
934501	SRQ	COM	26-Sep-2005	1DY	26-Sep-2005				90-**URGENT** [redacted] pls repair faulty smoke alarms-constantly going off.

934498/1	WOR	CLO	26-Sep-2005	1DY	26-Sep-2005		1		90 CES F/On ([redacted] check and repair smoke alarm - no access by CES
934498	SRQ	COM	26-Sep-2005	1DY	26-Sep-2005				90 CES F/On ([redacted] check and repair smoke alarm - no access by CES
934197/1	WOR	CLO	24-Sep-2005	1HR	26-Sep-2005		1		ces elec. alarms in all rooms going off. passed to w [redacted] electrician
934197	SRQ	COM	24-Sep-2005	1HR	26-Sep-2005				ces elec. alarms in all rooms going off. passed to w [redacted] electrician
928570/1	WOR	CLO	13-Sep-2005	2WK	28-Sep-2005		2	Y	90 - 1s - [redacted] - Pls check and repair electrical switch or fitting in bedroom ceiling as it does not work at all.
928570	SRQ	COM	13-Sep-2005	2WK	28-Sep-2005				90 - 1s - [redacted] - Pls check and repair electrical switch or fitting in bedroom ceiling as it does not work at all.
925060/1	WOR	CAN	06-Sep-2005	2WK	21-Sep-2005		1	Y	90 - 1s - [redacted] - Pls check and repair electrical switch or fitting in bedroom ceiling as it does not work at all.
925060	SRQ	CAN	06-Sep-2005	2WK	21-Sep-2005				90 - 1s - [redacted] - Pls check and repair electrical switch or fitting in bedroom ceiling as it does not work at all.
916532/1	WOR	CLO	24-Aug-2005	2WK	07-Sep-2005		1	Y	71/1s - [redacted] pls check and repair pvc window in bedroom as tnt states opens and goes up itself poss weight inbalance
916532	SRQ	COM	24-Aug-2005	2WK	07-Sep-2005				71/1s - [redacted] pls check and repair pvc window in bedroom as tnt states opens and goes up itself poss weight inbalance
856704	SRQ	COM	19-May-2005						Copied from Works Order 856454/1
856704/1	WOR	CLO	19-May-2005	8WK	15-Jul-2005		3	Y	Annual Routine Service to ALL council owned gas heating appliances contained within the property.
851222/1	WOR	CLO	09-May-2005	2WK	24-May-2005		2	Y	71/2s [redacted] - draught proof windows as elderly tnt and complaining of cold. Report back.
851222	SRQ	COM	09-May-2005	2WK	24-May-2005				71/2s [redacted] - draught proof windows as elderly tnt and complaining of cold. Report back.
556871	SRQ	COM	27-Jan-2004			ALLRMS			Copied from Works Order 556828/1
556871/1	WOR	CLO	27-Jan-2004	8WK	23-Mar-2004	ALLRMS	2	Y	annual gas routine service of all council owned appliances (due before 21/5/04).
482580/1	WOR	CAN	02-Oct-2003	1DY	02-Oct-2003	KTCH	1		ces follow on for electrician to renew stat at immersion
482580	SRQ	RAI	02-Oct-2003	2WK	16-Oct-2003	KTCH			ces follow on for electrician to renew stat at immersion
392390/1	WOR	CLO	23-Apr-2003	2WK	07-May-2003	ALLRMS	1		CHECK AND REMEDY FAULT WITHIN G.C.H.S TNT RECEIVING NO HOT WATER CHECK AND TRACE FAULT
392390	SRQ	COM	23-Apr-2003	2WK		ALLRMS			CHECK AND REMEDY FAULT WITHIN G C H S TNT RECEIVING NO HOT WATER CHECK AND TRACE FAULT
381624/1	WOR	CLO	07-Apr-2003	8WK	02-Jun-2003	ALLRMS	2		
381624	SRQ	COM	07-Apr-2003	8WK		ALLRMS			ROUTINE SERVICE VISIT
270764/1	WOR	CLO	07-Aug-2002	2WK	21-Aug-2002	ENTDR	3		FRONT DOOR STICKING POSSIBLY DUE TO BUILDING SU BSIDING
270764	SRQ	COM	07-Aug-2002	2WK		ENTDR			FRONT DOOR STICKING POSSIBLY DUE TO BUILDING SU BSIDING
230225/1	WOR	CLO	24-May-2002	8WK	19-Jul-2002	ALLRMS	1		
230225	SRQ	COM	24-May-2002	8WK		ALLRMS			ROUTINE SERVICE VISIT
44943/1	WOR	CLO	03-May-2001	8WK	28-Jun-2001	ALLRMS	2		
44943	SRQ	COM	03-May-2001	8WK		ALLRMS			ROUTINE SERVICE VISIT