


# MAP OF UNITS


## READINGS FOR 2020

NB – There are some anomalies with the readings as there are extremely high levels of vibration magnitude in some instances, not consistent with construction works, we can not identify the source, however, it could be down to force being applied to the box and / or damage to the sensor

These readings are not related to construction works given the extremely high level of vibration magnitude.




# UNIT 1




## UNIT 2

Readings from 01-01-2020 07:00 for 1 year




# UNIT 3

Readings from 01-01-2020 07:00 for 1 year




# UNIT 4

Readings from 01-01-2020 07:00 for 1 year




# UNIT 5






## UNIT 6

Readings from 01-01-2020 07:00 for 1 year



# UNIT 7



Not installed until Nov 2020