

Saughton Road North / Roull Road – Defect 42200112 and Road

Concerning the carriageway on Saughton Road North, Edinburgh, specifically the area at and immediately around the junction with Roull Road and the pedestrian/refuge crossing adjacent to approximately 100B Saughton Road North, EH12 7JN.

This request relates in particular to Defect 42200112 / Job 50192445, which is recorded in the Council's Site History Report as a pothole "beside the island crossing".

Further to 60535, request for the following information surrounding the notification, inspection and repair of Defect 42200112.

The notification received on 14 February 2026 The Council has confirmed that a notification of a potential defect was received on 14 February 2026 at 17:18:27. Please provide the underlying record of that notification.

[See attached "64264 - 1. Report 2095171"](#)

Defect 42200112 / Job 50192445 Please provide the complete underlying record for Defect 42200112 / Job 50192445. The Site History Report records the defect as Category 2 – 5 Day and as a "Made Safe Job".

Please provide the records identifying what physical work constituted the "made safe" treatment, and whether that treatment was temporary or permanent.

[All records held are attached.](#)

Inspection on 20 February 2026 the Council has stated that the notification received on 14 February was inspected on 20 February. Provide further information.

[Please refer to report "64264 - 1. Report 2095171 - 14.02.26"](#)

Repair on 21 February 2026 Please provide the complete record of the repair carried out on 21 February 2026.

[All records held are attached – please refer to "64264 - 2. Job 50192445"](#)

Previous reports and repairs at the precise location Please provide all records of potholes, carriageway defects, road-surface defects, complaints, reports, inspections and repairs concerning: Saughton Road North at or immediately adjacent to the junction with Roull Road, including the pedestrian/refuge crossing and the area around 100B Saughton Road North, EH12 7JN. Please provide this information for the period 1 January 2025 to 21 February 2026.

Previous repairs to the same or substantially similar defect or a pothole at substantially the same physical location

[We cannot provide a report for the precise location. The Site History Report \(SHR\) is attached which includes all records held for the entire length of Saughton Road North.](#)

The 15 January 2026 inspection The Council's original rejection relied upon a "previous 3-monthly mandatory inspection" dated 15 January 2026, stating that no actionable defects were identified.

Please provide the underlying record for that inspection, including:

* the inspection route;

Inspection carried out on 15 Jan 2026 covered full length of the road

* date and time;

15/01/26, time is not recorded

* inspecting officer/contractor;

This is not recorded.

* inspection method;

Mobile (driven)

* records demonstrating that the relevant section of Saughton Road North was inspected;

The inspection carried out on 15 Jan 2026 covered full length of the road

* photographs;

This defect was not recorded during this inspection, no photographs are available

* all defects recorded

Please refer to the SHR

* and the complete inspection notes.

No notes are recorded on this inspection

Please provide the relevant Asset Management System records relating to the above location and defect insofar as they contain information falling within this request.

Please refer to the attached SHR.

Please provide any records available to the Council identifying previous incidents, claims, complaints or defect reports relevant to this particular location during the requested period.

Please see the attached information. Additionally, please refer to claims report provided for the same period (01.01.25 – 21.02.26) and note - we cannot provide records for the precise location or defect. Claims report attached includes all claims recorded for the entire length of Saughton Road North submitted within that period.