

64704 Asbestos and Reinforced Autoclaved Aerated Concrete (RAAC)

Please provide copies of all information held by the City of Edinburgh Council relating to asbestos at Queensferry Sports & Community Hub, including, where available

Any asbestos surveys or inspections previously carried out at the building.

The current or most recent Asbestos Register for the premises.

Details of any asbestos-containing materials (ACMs) identified within the building, including their locations and recorded condition.

Any asbestos management plans, risk assessments or monitoring records.

Details and records of any asbestos removal, encapsulation, treatment or other remedial works previously undertaken.

Dates and outcomes of previous inspections or re-inspections, including any recommendations or actions identified.

Any records relating to known or suspected asbestos-containing materials within areas of the building that have subsequently been refurbished or altered.

Any other records held by the Council concerning known or suspected asbestos-containing materials within the premises.

Whether the building has previously been assessed, inspected or surveyed for the presence of RAAC.

Copies of any RAAC surveys, inspection reports, structural assessments or associated correspondence.

Confirmation of whether RAAC has been identified, suspected or ruled out within any part of the building.

If RAAC has been identified, details of its location, condition and any risk assessment undertaken.

Details of any monitoring, management, remedial or replacement works recommended or undertaken in relation to RAAC.

Dates of any previous RAAC inspections or assessments and any recommendations or actions arising from them.

Any other records held by the Council relating to the potential presence, condition or management of RAAC within the premises.

The property in question has gone through a community asset transfer and was previously managed by Edinburgh Leisure. Therefore, we do not hold any information in relation to your request. We can confirm that the Council did not undertake any RAAC inspections.