

36683

When was the St Marks Park footpath leading from Powderhall Village footbridge to the tarmac path adjoining the footbridge to McDonald Road last inspected, and what was the text of the report?

Unfortunately, we are unable to provide you with the information requested as it is not held by the Council.

The path in question is not adopted and so is not subject to regular inspection by the Roads Operations team. The section that sits within the boundary of St Marks Park is checked and observed by the Park Rangers when onsite though we do not keep official records of this. The section beyond the Water of Leith leading to Broughton Road will be seen less frequently by parks staff and issues relating to this section will mostly be dealt with through customer feedback on a case by case basis.