58044

On what date was the cabling and box for this streetlight last electrically tested? What specifically was noted in the report? Was any observation about the cabling recorded?

The last electrical test took place on 22 April 2019, when measurements were recorded of the Voltage and Earth Loop Impedance.

This is not a column as it is attached to the wall as described above. Are these units also subject to structural inspections? If so, on what date was this unit last inspected? What specifically was noted in the report?

With Wall brackets not being subject to structural testing or inspection, any non-structural inspection in undertaken by the Approved Electricians when repairing electrical faults.

Can I have information about the maintenance activity that is recorded on the Council's asset management system for PA09S? Aside from the actual lamp being replaced a number of years ago, have any other faults or issues been reported and recorded in relation to this light? If so, on what dates, what was recorded and what action was taken?

PA09S is the specification for the lantern on streetlight ref: BNT28. Aside from the lantern being converted to an LED, the only other recorded repairs were:

Legacy Work (Ladder work) – Dark Lamp. attended and lamp replaced on 4 January. No other notes recorded.

Exposed Wires – The wall box door was open, electrician attended on 10 June 2024 and closed the door, no other notes taken.

Reactive response times are noted in the Street Lighting Management Arrangements document for emergency repairs, priority repairs and non-priority repairs. These relate specifically to emergency repairs or whether the lamp itself is dark or not dark. What is the reactive response time for other street lighting faults that have caused damage to private property and require repair to prevent further damage?

There are no specified response times for street lighting faults that have caused damage to private property, with the owner/occupier of the property provided with a Claim Form for completion and return to the Council.