

Site History Report

Effective: 23/12/2020 to 23/12/2025
Service: Roads General
Site: Cleekim Drive (7902352)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Cleekim Drive (7902352)

Locality: Newcraighall, Edinburgh, City of Edinburgh

Area: North East Locality

Customer Services

Enquiry No.: 34005740 **Logged by:** [REDACTED] **on:** 07/09/2022 10:53
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: Faded Give Way markings needing refreshed
Location: Outside 59 Cleekim drive **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50118499 **Defect Number:** 42122058

Enquiry No.: 34005739 **Logged by:** [REDACTED] **on:** 07/09/2022 10:48
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: Faded SLOW
Refresh Road marking
Location: Outside 11 Cleekim Drive **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50118498 **Defect Number:** 42122061

Enquiry No.: 34005738 **Logged by:** [REDACTED] **on:** 07/09/2022 10:46
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: Faded School patrol sign
Sign size 600mm
Sub plate 240mm ^ by 590mm >
Replace with new signs.
On column CJP2
Location: Outside 9 Cleekim Drive **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50119579 **Defect Number:** 42107858

Enquiry No.: 2048505 **Logged by:** Verint CRM Connector **on:** 25/11/2025 11:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is massive ditch close to the curb, on the farmfoods side, this hole is brutally deep and caused me injury after falling into it **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50187563 **Defect Number:** 42194040

Enquiry No.: 2030796 **Logged by:** Verint CRM Connector **on:** 20/10/2025 15:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2030794 **Logged by:** Verint CRM Connector **on:** 20/10/2025 15:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole. This comes up ankle high if you put your foot inside the hole. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50185893 **Defect Number:** 42191589

Site History Report

Effective: 23/12/2020 to 23/12/2025
Service: Roads General
Site: Cleekim Drive (7902352)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1966808 **Logged by:** [REDACTED] **on:** 23/06/2025 10:25
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Pavement is crumbled up and is causing trap hazard to residents of [REDACTED] 2 Elderly residents who are worried they might fall on this piece of pavement.
Location: [REDACTED] **Contact:**

Enquiry No.: 1950890 **Logged by:** Verint CRM Connector **on:** 20/05/2025 18:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50180159 **Defect Number:** 42183926

Enquiry No.: 1904142 **Logged by:** Verint CRM Connector **on:** 15/02/2025 18:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Two huge pot holes in the road causing damage to tyres of passing traffic, cars parked along the side road so it's hard to avoid them in both directions, it is a heavily used road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1904109 **Logged by:** Verint CRM Connector **on:** 15/02/2025 17:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50175157 **Defect Number:** 42176085

Enquiry No.: 1793595 **Logged by:** Verint CRM Connector **on:** 06/07/2024 09:27
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Pavement.
Type:Grass
Location: This mess is a blight on the neighbourhood and is now dangerous. It is the view from our front windows and is totally unacceptable. The pavement has also now been seeded and it is a battle to keep gardens weed free. **Contact:**

Enquiry No.: 1758894 **Logged by:** Verint CRM Connector **on:** 22/05/2024 08:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The pedestrian crossing at Duddingston park south **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1661423 **Logged by:** Verint CRM Connector **on:** 14/12/2023 08:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in middle of the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50148364 **Defect Number:** 42142240

Site History Report

Effective: 23/12/2020 to 23/12/2025
Service: Roads General
Site: Cleekim Drive (7902352)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1647768 **Logged by:** Verint CRM Connector **on:** 20/11/2023 22:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big pothole in the middle of the road, cars are parked on side and often u have to use the middle of the road to navigate through oncoming cars etc the road is heavily used. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1592587 **Logged by:** Verint CRM Connector **on:** 04/08/2023 13:22
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Pavement.
Type:Foliage / Bush
Location: **Contact:**

Enquiry No.: 1487545 **Logged by:** Verint CRM Connector **on:** 08/01/2023 16:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Drain sinking **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1481226 **Logged by:** Verint CRM Connector **on:** 29/12/2022 15:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pot hole in middle of road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50125084 **Defect Number:** 42113936

Enquiry No.: 1427672 **Logged by:** [REDACTED] **on:** 08/09/2022 08:00
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: please inspect the 20mph signage/ road markings in Cleekim Drive, raise jobs etc as required and report back to [REDACTED] BLUF: "He highlighted that Cleekim Drive is a 20mph zone and is not a through road. However, has advised that the road markings are very worn, the 20mph signs are non-existent at the start of the street and alleged that there is a significant speeding issue which is a danger to pedestrians."
Location: please inspect the 20mph signage/ road markings in Cleekim Drive, raise jobs etc as required and report back to [REDACTED] BLUF: "He highlighted that Cleekim Drive is a 20mph zone and is not a through road. However, has advised that the road markings are very worn, the 20mph signs are non-existent at the start of the street and alleged that there is a significant speeding issue which is a danger to pedestrians."
Contact:

Enquiry No.: 1365539 **Logged by:** Verint CRM Connector **on:** 21/04/2022 11:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Drain cover has sunk into ground. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 23/12/2020 to 23/12/2025
Service: Roads General
Site: Cleekim Drive (7902352)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1351272 **Logged by:** Verint CRM Connector **on:** 25/03/2022 12:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Potholes Easting/Northing: 330468/671943 (55.935492, -3.11458)
Location: **Contact:**

Enquiry No.: 1275587 **Logged by:** Verint CRM Connector **on:** 16/11/2021 09:18
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: due to RTA on Monday (15/11) 3 potholes have appeared at junction of Cleekim Drive and Cleekim Road. need to be treated ASAP **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50097430 **Defect Number:** 42084085

Enquiry No.: 1274953 **Logged by:** Verint CRM Connector **on:** 15/11/2021 10:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: road to be cleared car debris on cleekim drive after RTA **Contact:**

Enquiry No.: 1263708 **Logged by:** Verint CRM Connector **on:** 23/10/2021 15:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1263392 **Logged by:** [REDACTED] **on:** 22/10/2021 13:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Large pothole at number 77 please inspect
Location: O/S Number 77 on left hand side **Contact:**

Enquiry No.: 1167179 **Logged by:** Verint CRM Connector **on:** 28/04/2021 12:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Manhole next to 30 Cleekim Drive very badly damaged by heavy vans reversing in the area. I dont know what is under the manhole cover. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset