

60246 Rothesay Terrace Pavement Works

The pavement was renewed for the adjacent stretches of Rothesay Terrace which forms part of the associated development which no. 10 and 11 are within but was not continued to the frontages of 10 and 11. This dates back several years.

I request the Work Order and information relating to the intended replacement of slabs in Rothesay Terrace.

There is no Work Order as such. Please refer to the attached documents. Following concerns raised regarding the condition of the footways in Rothesay Terrace, including a report of a fall in the area, an assessment identified approximately 105m² as the most affected section of uneven pavement as per the attached drawing.

Why was the work stopped at 10 and 11?

The identified area of approximately 105m² was renewed as per the attached drawing to replace damaged/uneven slabs that were present in the location.

Third party personal information has been redacted from the documents provided in compliance with the Data Protection Act 2018.