

60869 Hurricane swings, rotating swing, or similar spinning swing equipment

Please provide the following information in relation to hurricane swings, rotating swing, or similar spinning swing equipment.

We request this information from 1st January 2016 to date

A list of all sites where such swings have been installed.

Magdalene Glen – Rota Glide

Burdiehouse Burn Valley Park – Twin Fly Rotator

King George V Park (Eyre Place) – Overhead Rotator

Spylaw Park - Overhead Rotator

Records of complaints received relating to these swings, including the nature of the complaint and the date received.

No complaints have been recorded.

Records of any reported accidents, injuries, or incidents involving these swings.

No accidents have been recorded.

Details of any investigations carried out following complaints, incidents, or accident involving these swings.

No investigations have been recorded.

Copies of risk assessments, safety reviews, inspection reports or safety audits relating to these swings.

Please find the latest inspection reports attached. The Council undertake an annual independent inspection of all playpark equipment where the risk level is formally assessed. Operational inspections are completed quarterly by a Royal Society for the Prevention of Accidents-qualified technician who repair and service the equipment. There is also a target of a monthly visual inspection of play equipment completed by our park rangers' team who report any concerns. These combined are used to assess and negate the risks associated with play equipment and its use.

Third party personal information has been redacted from the documents provided.

Any internal safety guidance, policies or documented health and safety considerations relating specifically to the installation, maintenance or operation of these swings.

None.

Details of any of these swings being decommissioned including, location of swing, date of removal, reasons for removal.

None.