

Reporting

Enquiry Trace Form

Enquiry Number 2145496
Logged Date 11 May 2026 15:26
Last Updated First Name [REDACTED]
Last Updated Last Name [REDACTED]
Service Roads General
Subject Road: Defective / Damaged
Classification Request for service
Description
Site Alnwickhill Drive
Area South East Locality
Ward 16-Liberton/Gilmerton

Location

Markings on the speed bump here (outside number 9) and in the rest of Alnwickhill and Howdenhall Drive area have worn off. This particularly dangerous at night for motorcyclists. Can you also confirm that this speed bump and many others in the area comply with the relevant design criteria for speed bumps as many now appear to be excessively high, possibly due to carriageway erosion.

<https://tsrgd.co.uk/pdf/tal/1996/tal-7-96.pdf>

Linked Customers

Customer Number 2132330
Time 11 May 2026 15:26
Method Web
First Name Anon
Last Name Anon
Their Customer Reference

Status History

Log Number	Effective	Status	Officer	Notes	Follow Up
1	11 May 2026 15:26	Enquiry Raised	[REDACTED]		21 May 2026 15:26
2	21 May 2026 09:31	No Actionable Issue	[REDACTED]	Speed humps are at the correct level	

Documents

Document

May 8, 2025

No sign, this is stinking the street out. Can you advise when this will be emptied and why it hasn't been

5:56 PM

Afternoon, Thanks for getting in touch. Can you please provide more information on what you are referring to? Thanks again,

6:00 PM

Jun 6, 2025

Hi. Thanks for getting in touch with us on Twitter. Please send us any questions you have and we'll get back to you as soon as we can.

11:20 PM

Today



Hi the marking on the speedbumps on Alwickhill and Howdownhall Drive have deteriorated to the point of being unusable. They need surveyed and refreshed. Specifically the first 3 in Alwickhill Drive from Alwickhill Rd are invisible and damaging peoples cars as they cant be seen.

11:51 AM

Hi, I have passed this to the team and attached your photo and comments. Kind regards,

12:43 PM

Document Description

Modified By First Name

Modified By Surname

Modified Date

Confirm Image Upload

Verint

CRM Connector

11 May 2026 15:26

Document



Document Description

Photo added by Coedn80001 on 21 May 2026 at 09:22

Modified By First Name

██████████

Modified By Surname

████████████████████

Modified Date

21 May 2026 09:31

Document



Document Description

Photo added by Coedn80001 on 21 May 2026 at 09:24

Modified By First Name

[REDACTED]

Modified By Surname

[REDACTED]

Modified Date

21 May 2026 09:32

Document



Document Description

Photo added by Coedn80001 on 21 May 2026 at 09:25

Modified By First Name

[REDACTED]

Modified By Surname

[REDACTED]

Modified Date

21 May 2026 09:32

Document



Document Description

Photo added by Coedn80001 on 21 May 2026 at 09:26

Modified By First Name

[Redacted]

Modified By Surname

[Redacted]

Modified Date

21 May 2026 09:32

Document



Document Description

Photo added by Coedn80001 on 21 May 2026 at 09:26

Modified By First Name

[REDACTED]

Modified By Surname

[REDACTED]

Modified Date

21 May 2026 09:32