

63878 Craigleith Drive - roadworks under the Roseburn Path

Concern at the size and steepness of the speed bumps is widespread. Can you confirm that the design of these, and in particular height and gradients as i stalled, complies with the legislation max height etc.. Has installed heights etc. been checked by engineers for compliance. I understand the design is covered by Road Humps (Scotland) Regulations and the Roads (Scotland) Act.

The speed humps were constructed to the specification provided, as attached. Post construction checks have been carried out and meet the specification within reasonably practicable measuring tolerances.

Please also confirm the overall cost of the works and the justification for the length of the road closure.

Overall cost of the project is £146,522.86 and the project took longer than anticipated due to the late arrival of signs due to a manufacturing issue. It was anticipated the new sign units would communicate through a wireless link; however, it was established that a permanent wired link would be more appropriate in this situation.