

Repair No	Type	Status	Raised Date	Priority	Target Date	No. Jobs	Description
3910270/3	WOR	CLO	11-Jun-2026	2WB	25-Jun-2026	3	09 - FO saltire - FAO form access - scaffold request below for slate repairs. 1 bay, 3 high & picture attached. Scaffold to be up for 17/06/2026
3910270/2	WOR	ISS	06-May-2026	2WB	20-May-2026	3	Owner in dispute with CEC. Erect scaffold to repair slates and gutter at flat 3
3910270/1	WOR	CAN	06-May-2026	2WB	20-May-2026	2	Owner in dispute with CEC. Erect scaffold to repair slates and gutter at flat 4
3910270/11	INS	RAI	06-May-2026	1D	07-May-2026		Owner in dispute with CEC. Erect scaffold to repair slates and gutter at flat 5
3910270	SRQ	RAI	06-May-2026	1D	07-May-2026		Owner in dispute with CEC. Erect scaffold to repair slates and gutter at flat 6
3908588/2	WOR	CLO	07-May-2026	4HR	07-May-2026	2	CES COVER ORDER-PREVIOUS ORDER DID NOT CROSS OVER TOTAL
3908588/1	WOR	ISS	02-May-2026	4HR	04-May-2026	2	Ces tnt called xxx roof is leaking again, please make safe with plastic sheeting in attic space over weekend job passed to Saltire
3908588	SRQ	RAI	02-May-2026	4HR	04-May-2026		Ces tnt called xxx roof is leaking again, please make safe with plastic sheeting in attic space over weekend job passed to Saltire
3904185/1	WOR	CLO	21-Apr-2026	2WB	05-May-2026	1	97 - as reported by xxx - aerial tenant getting no signal please repair
3904185	SRQ	RAI	21-Apr-2026	2WB	05-May-2026		97 - as reported by xxx - aerial tenant getting no signal please repair
3898652/1	WOR	CLO	01-Apr-2026	2WB	15-Apr-2026	5	fao saltire - The flat roof above the rear bedroom of flat 5 is suspect as water ingress has taken place to the rear bedroom.
3898652	SRQ	RAI	01-Apr-2026	2WB	15-Apr-2026		fao saltire - The flat roof above the rear bedroom of flat 5 is suspect as water ingress has taken place to the rear bedroom.
3800683/11	INS	RAI	16-Jul-2025	1D	17-Jul-2025		please assess and repair roof, leak is flooding stair, has gotten worse