36721 Lauriston Castle - Internal Work

Please provide full details (dates, full descriptions of work carried out and costs) of work carried out inside Lauriston Castle itself from September 2019 to the current date.

Please refer to the tables below which include details extracted from the Repairs and Maintenance database. Where it is unclear if the description relates specifically to the inside of Lauriston Castle, the information has been provided. Where there is no 'Works Description' provided, this is because it has not been entered on the database.

2019/2020 - September 2019 to March 2020

| Centre Description | Period | Works Description | Value |
|---------------------------|--------|--|----------|
| Lauriston Castle | SEP | Please attend as the fire panel is showing 'general fault' fire service were on site at 6:30 this morning | |
| Lauriston Castle | SEP | Please attend first thing tomorrow morning. Please fix&repair fire alarm. Not allowing fire alarm to restart needs investigated. | |
| Lauriston Castle | SEP | To fix&repair leak coming from central dining room window panelling directly above window frame. | |
| Lauriston Castle | SEP | To action 8 b defects on attached Zurich report. The loose front cover should be secured. | 75.20 |
| Lauriston Castle | SEP | 1/tower landing - the open hole in the base should be blanked off. | 75.20 |
| Lauriston Castle | OCT | Action Section 8b Defect on the Zurich report. Single Phase Low Voltage Distribution Board located On The G/East Wing C | 169.20 |
| Lauriston Castle | OCT | Please attend to fix& investigate fault with fire alarm located at the main area of building. | 58.55 |
| Lauriston Castle | OCT | Please attend and inspect connections for the dualcom so it can send signals out using both channels to the arc | |
| Lauriston Castle | NOV | Carry out fabric preventative maintenance in accordance with fabric maintenance standards, including all the relevant elemental items contained within the attached schedule. | |
| Lauriston Castle | JAN | Carry out fabric preventative maintenance in accordance with fabric maintenance standards to include items as per the attached schedule and the provision of relevant service records subject to access being arranged prior | 4,043.23 |

| Lauriston Castle | JAN | Carry out fabric preventative maintenance in accordance with fabric maintenance standards. To include all items as per the attached schedule and the provision of relevant service records. | 50.00 |
|------------------|-----|---|----------|
| Lauriston Castle | FEB | Check alarm system | 33.50 |
| Lauriston Castle | FEB | Gas engineer required, fault - flexi on meter outlet, remove flexi and hard pipe outlet gas safety warning notice attached | 295.69 |
| Lauriston Castle | MAR | (4 day) attend and repair light that is out in the library corridor | 67.11 |
| Lauriston Castle | MAR | Confirmation order of work complete (4 hour) check alarm system as going off without activation | 33.50 |
| Lauriston Castle | MAR | Confirmation order of work complete check alarm system | 33.50 |
| Lauriston Castle | MAR | Carry out fabric preventative maintenance in accordance with fabric maintenance standards. To include all items as per the attached schedule and the provision of relevant service records. | 1,227.00 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 10.35 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 10.35 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 10.35 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 10.35 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 10.35 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 30.95 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 39.05 |

| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 39.05 |
|--|-----|---|-------|
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 39.05 |
| Lauriston Castle | JUL | Lauriston Castle & Other Buildings | 39.05 |
| R & M - Int Fees Scientific Services Reporting | JUL | Lauriston Castle & Other Buildings | 39.05 |
| R & M - Int Fees Scientific Services Reporting | JUL | Lauriston Castle & Other Buildings | 39.05 |
| R & M - Int Fees Scientific Services Reporting | FEB | Lauriston Castle Estate / Castle/Kitchen Sink | 10.35 |
| R & M - Int Fees Scientific Services Reporting | FEB | Lauriston Castle Estate / Castle/Far Toilet | 10.35 |
| R & M - Int Fees Scientific Services Reporting | FEB | Lauriston Castle Estate / Castle/Far Toilet | 30.95 |
| R & M - Int Fees Scientific Services Reporting | FEB | Lauriston Castle Estate / Castle/Kitchen Sink | 30.95 |
| R & M - Int Fees Scientific Services Reporting | FEB | Lauriston Castle Estate / Castle/Belfast Sink | 30.95 |
| R & M - Int Fees Scientific Services Reporting | FEB | Lauriston Castle Estate / Castle/Belfast Sink | 39.05 |

2020/2021

| Centre Description | Date | Works Description | Value |
|---------------------------|------------|---|-----------|
| Lauriston Castle | 14/04/2020 | Carry out fabric preventative maintenance in accordance with fabric maintenance standards. To include all items as per the attached schedule and the provision of relevant service records. | -1,227.00 |
| Lauriston Castle | 19/08/2020 | Confirmation order of work complete intruder alarm - 1279472 | 110 |
| Lauriston Castle | 19/08/2020 | Confirmation order of work complete intruder alarm fault - 1282908 | 67 |
| Lauriston Castle | 02/09/2020 | Manual keypad for the door in the courtyard is not working - building unsecure. Lock is broken and number aren't working | 419.85 |
| Lauriston Castle | 03/09/2020 | There are mouse droppings found in the downstairs rooms | 40 |
| Lauriston Castle | 07/09/2020 | No hot water in the hot water. | 59.14 |
| Lauriston Castle | 09/09/2020 | Fuse has blown in fuse box leaving them with no wifi, microwave etc. All electronic equipment has been removed from that side of the building. | 134.22 |
| Lauriston Castle | 28/09/2020 | Change two yale locks on site due to a security breach *urgent* | 219.58 |
| Lauriston Castle | 23/10/2020 | There is a leak coming through the middle window in the dining room, there is a bucket catching it for now | 115.88 |
| Lauriston Castle | 30/11/2020 | There are mice at the castle, there are furnishings that are irreplaceable which could be effected | 200 |
| Lauriston Castle | 13/12/2020 | Door/frame may have slightly warped now temperatures are dropping. | 107.87 |
| Lauriston Castle | 20/12/2020 | Confirmation order of work complete alarm will not set - 1279866 | 122 |
| Lauriston Castle | 22/12/2020 | Confirmation order of work complete intruder alarm engineer attend Lauriston Castle please we need our master code changed for | 33.5 |
| Lauriston Castle | 31/12/2020 | Attend and clean smoke / fire detector as the fire alarm activated - Fire Officer think was due to dust | 89.58 |
| Lauriston Castle | 08/01/2021 | Confirmation order of work complete security alarm for building- won't let it be set- csecure building. | 33.5 |
| Lauriston Castle | 20/01/2021 | Lauriston Castle Estate / House/Basement | 42.55 |
| Lauriston Castle | 20/01/2021 | Lauriston Castle Estate / Castle / Kitchen Sink | 42.55 |
| Lauriston Castle | 22/01/2021 | Attend and change the light in the toilet please attend and rectify | 86.16 |

| Lauriston Castle | 27/01/2021 | Remove damaged leaded glass window and undertake repairs. Upon completion re-install window with lime mortar pointing. Window is not to be removed or worked on until Wednesday 16th September due to filming on site. | 2,390.00 |
|------------------|------------|--|----------|
| Lauriston Castle | 27/01/2021 | Attend and investigate water leaking into one of the tower bedrooms | 372.71 |
| Lauriston Castle | 01/03/2021 | Internal circulation areas and external doors - 6 monthly fire door inspection ppm fabric | 41 |
| Lauriston Castle | 03/03/2021 | There is an unbearable smell from the toilet by the front door, it's all the way up the stairs and into the maids' hall | 63.8 |
| Lauriston Castle | 12/03/2021 | Attend and check intruder alarm. | 33.5 |
| Lauriston Castle | 20/03/2021 | Confirmation order of work complete attend and repair intruder alarm going off and hav with this and resets | 67 |
| Lauriston Castle | 31/03/2021 | Confirmation order of work complete check intruder alarm as this will reset | 33.5 |
| Lauriston Castle | 14/09/2020 | Lauriston Castle - 1y 37-01 emergency lighting - self contained | 24 |
| Lauriston Castle | 12/11/2020 | Firemark remedial works - Lauriston Castle | 250.39 |
| Lauriston Castle | 07/01/2021 | Budget fixed wire testing remedial costs e | 2,818.30 |
| Lauriston Castle | 31/03/2021 | Lauriston Castle 2a Cramond Road South, EH4 5QD Dualcom Airtime & Alarm Maintenance 2020-21 | 225 |
| Lauriston Castle | 31/10/2020 | Lauriston Castle CWST 18.08 Clean, disinfect and flush 1 x 500ltr CWST | 775 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / Castle / Far Toilet | 10.65 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / House/Kitchen | 10.65 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / House / Basement | 10.65 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / House/Basement | 10.65 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / Castle/Kitchen Sink | 10.65 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / House/Utility Room | 40.2 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / House / Kitchen | 40.2 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / House / Toilet | 40.2 |
| Lauriston Castle | 21/12/2020 | Lauriston Castle Estate / Castle/Belfast Sink | 40.2 |

2021/2022

| Centre | Date | Works Description | Value |
|------------------|------------|---|--------|
| Description | | | |
| Lauriston Castle | 19/04/2021 | Order of work complete check intruder alarm as this will reset | -33.5 |
| Lauriston Castle | 19/05/2021 | Work complete tested batteries, chargers and signal to nph int,pmaterials used 3 x 7amp batteries | 58.55 |
| Lauriston Castle | 24/05/2021 | Work complete check intruder alarm as this will reset | 33.5 |
| Lauriston Castle | 17/06/2021 | | 170.94 |
| Lauriston Castle | 13/10/2021 | | 105.6 |
| Lauriston Castle | 13/10/2021 | | 50.5 |
| Lauriston Castle | 20/10/2021 | | 77.23 |
| Lauriston Castle | 26/10/2021 | | 33.5 |
| Lauriston Castle | 28/10/2021 | | 172.57 |
| Lauriston Castle | 29/10/2021 | | 68.38 |
| Lauriston Castle | 03/11/2021 | | 172.47 |
| Lauriston Castle | 03/11/2021 | | 172.47 |
| Lauriston Castle | 22/11/2021 | | 65.52 |
| Lauriston Castle | 22/11/2021 | | 167.1 |
| Lauriston Castle | 22/11/2021 | | 242.76 |
| Lauriston Castle | 28/01/2022 | Light bulbs although most of the light bulbs have been replaced there were a couple of areas with no light - The linen store and the corridor that leads to the maids' hall | 13.91 |
| Lauriston Castle | 28/01/2022 | Light bulbs although most of the light bulbs have been replaced there were a couple of areas with no light - The linen store and the corridor that leads to the maids' hall | 35.43 |

| Lauriston Castle | 04/03/2022 | Contractor required to attend and repair the stair edge nosing to be re glued Its a potential trip hazard. The aluminium strip in place measures approx 31 inches. Please see pictures for reference | 59.86 |
|------------------|------------|--|-----------|
| Lauriston Castle | 04/03/2022 | Damp patches on the ceiling of tower bedroom 4. These do seem worse please check full area cloakroom chimney the fireplace also looks damp please investigate resolve | 111.72 |
| Lauriston Castle | 31/03/2022 | CR06 Outstanding Planned & Reactive R&M Lauriston Castle (See Below) | 25,056.73 |
| Lauriston Castle | 28/03/2022 | INS003497638 Lauriston Castle 23-17B_1M | 61.01 |
| Lauriston Castle | 28/03/2022 | INS003498939 Lauriston Castle 40-10_1Y | 117.02 |
| Lauriston Castle | 28/03/2022 | INS003499928 Lauriston Castle 05-23_1Y | 105.49 |