

Date Served	Status	Project Reference	Notice Reference	Details	Total Cost	No. Shares	Cost-per-Share
06/12/1991	Lifted	3FA53	A6817/JT	Emergency drainage works.	£211.44	12	£17.62
10/05/1994	Lifted	3RC79	A/4859/JM	Emergency drainage works.			No Information Held
26/01/1995	Active	3FB58	A/7569	Emergency roof works.	£471.54	6	£78.59
30/06/1995	Lifted	1FA30	A1269/JM	Repairs to roof and rainwater goods.	£1,880.82	6	£313.47
18/12/1996	Lifted	3FC16	n/7782bdr/d	Emergency drainage works.	£54.40	10	£5.44
26/02/1999	Lifted	1FA59	N/9372/BR/Repairs	Repair defective waste pipes.	£1,181.70	10	£118.17
22/03/2000	Lifted	3FD14	N/15370/BR/Repairs	Emergency roof repairs.	£869.50	10	£86.95
25/10/2000	Lifted	3FD30	N/18655/1/RH/Repairs Superseded by N/18655/4/RH/R	Emergency masonry works.	£36,435.56	14	£2,602.54
09/01/2001	Active	1FA79	N/18655/6/RH/Repairs, N/30241/3/MJ/DR and N/18655/5/RH/Repairs	N/18655/5/RH/R Erection of emergency scaffolding in the interest of public safety. N/18655/6/RH/R Demolish to safe level defective mutual gable to Rose Street elevation and rebuild to original dimensions. Repair, pick out and repoint defective areas to lower level. Repair defective west elevation 6-vent chimney stack. Repair, pick out and repoint Rose Street Lane North elevation gable. Repair defective chimneys to rear elevations. Repair entire slated slopes, pick and repoint all defective skews and raggles. Renew all defective zinc forming ridging, flashings and backgutters. Clean out grass and debris from entire rhones and roofpipes and renew where required. N/30241/3/MJ/DR Eradicate wet/dry rot as evident in roof timbers on Rose Street and Frederick Street elevations, including the removal of all affected plasters and timbers in adjoining rooms and flats as required.	£274,247.74	13	£21,095.98
04/04/2003	Lifted	1RC19	N/30241/1/MJ	Repair of defective entryphone system.	£1,422.13	8	£154.46, plus £62.15 for 3x properties where replacement handsets required
13/05/2003	Lifted	1RC24	N/30241/2/MJ/R	Renew defective lathe and plaster ceiling to top floor landing within common stair of 77 Rose Street. Hack off defective wall plaster to common stair walls and replaster.			No Information Held
08/07/2008	Active	3R081290	08/01506/31_DE	Clear choked mutual rain water pipe to front elevation.	£242.20	14	£17.30
26/08/2008	Active	3R081491	08/01791/24_E	Replace missing and loose slates at front elevation and clean rhones of all debris.	£351.67	11	£31.97
17/04/2014	Active	1N140257	14/00252/31_DE	Attend and clear choked mutual drainage system at rear of properties in Rose Street, causing waste water to back up into shop.	£373.75	13	£28.75