

Effective: 01/04/2018 to 31/03/2020

Asset Number: 1.00 to 99.00

Display Action Officer: No

Site: Turnhouse Road (7900553)

Site: Turnhouse Road (7900553)

Locality: Cammo, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.:	Ward 1 - From No 98 to Lennymuir	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41051784 - Inspection Batch			Route:	Ad hoc Route		Date:	11/02/2020
42045882	Collapsed manhole. Please dig out and replace manhole.	11/02/2020	At pin. Opp 12 Linnie Cottages	RD: Other Defect Type	Internal		Committed	50051672
Batch:	41051783 - Inspection Batch			Route:	Ad hoc Route		Date:	11/02/2020
42045881	Broken manhole cover, please replace lids. Road: Defective / Damaged (Enquiry 954635)	11/02/2020	At pin.	RD: Other Defect Type	Internal		Committed	50051671
Batch:	41051180 - Inspection Batch			Route:	Ad hoc Route		Date:	03/02/2020
42045333	Road: Defective / Damaged (Enquiry 949664) Nearest postcodes is EH12 OAD Turnhouse golf club	03/02/2020	Collapsed value cover on East bound carriageway at junction with Meadow field road	RU: Utility Apparatus	Internal		Uncommitted	50051093
Batch:	41050895 - Inspection Batch			Route:	Ad hoc Route		Date:	30/01/2020
42045049	Dig out damaged manhole cover and reset to le	30/01/2020	High ways sunken manhole cover on west heading carriageway approximately 20m East of junction with Craig's road	RD: Other Defect Type	Internal		Action Required	
Batch:	41047011 - Inspection Batch			Route:	Ad hoc Route		Date:	02/12/2019
42041861	Replace damaged manhole covers and frame	02/12/2019	Damaged highways manhole covers and frame on west heading carriageway approximately 30m east of junction with Craig's road	RU: Utility Apparatus	Internal		Committed	50046832
Batch:	41041944 - Inspection Batch			Route:	Ad hoc Route		Date:	02/10/2019
42039328	Road: Defective / Damaged (Enquiry 894981) Place T.M around damaged manhole cover	02/10/2019	Collapsed manhole cover. Temporary cover which has been in place for weeks has also been displaced and is a significant hazard. Traffic management is required around damaged manhole cover on west bound carriageway approximately 100m east of junction with Craig's road	RD: Other Defect Type	Internal		Committed	50043365
Batch:	41028256 - Inspection Batch			Route:	Ad hoc Route		Date:	27/02/2019
42027075	Hot temp make safe	27/02/2019	Pothole on west heading carriageway approximately 350yds west of euro car parts, at manhole cover	RD: CW Pothole	Internal		Committed	50027276
Batch:	41028255 - Inspection Batch			Route:	Ad hoc Route		Date:	27/02/2019
42027074	Hot temp make safe	27/02/2019	Pothole on east bound carriageway in between junctions for Craigs road , opposite l/p 45	RD: CW Pothole	Internal		Committed	50027275

Effective: 01/04/2018 to 31/03/2020

Asset Number: 1.00 to 99.00

Display Action Officer: No

Site: Turnhouse Road (7900553)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.:	Ward 1 - From No 98 to Lennymuir	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41028251 - Inspection Batch		Route:	Ad hoc Route			Date:	27/02/2019
42027070	Road: Defective / Damaged (Enquiry 802940)	27/02/2019	Pothole on carriageway outside Queensferry motor company	RD: CW Pothole	Internal		Committed	50027271
	Hot temp make safe							
Batch:	41028248 - Inspection Batch		Route:	Ad hoc Route			Date:	27/02/2019
42027067	Hot temp make safe	27/02/2019	Pothole on west heading carriageway opposite entrance to Turnhouse golf club	RD: CW Pothole	Internal		Committed	50027268
Batch:	41028020 - Inspection Batch		Route:	Ad hoc Route			Date:	25/02/2019
42026905	Hot temp make safe	25/02/2019	Pothole on west heading carriageway approximately 300yds west of euro car parts , at manhole cover	RD: CW Pothole	Internal		Committed	50026967
Batch:	41028018 - Inspection Batch		Route:	Ad hoc Route			Date:	25/02/2019
42026903	replace damaged manhole cover	25/02/2019	Broken manhole cover on west heading carriageway approximately 300yds west of euro car parts	RD: Other Defect Type	Internal		Committed	50026962
Batch:	41028017 - Inspection Batch		Route:	Ad hoc Route			Date:	25/02/2019
42026902	Replace damaged manhole cover ,	25/02/2019	Broken manhole cover on west heading RU: Utility Apparatus carriageway approximately 300yds west of euro car parts		Internal		Uncommitted	50026957
Batch:	41008812 - Inspection Batch		Route:	Ad hoc Route			Date:	18/04/2018
42008449	hot temp make safe	18/04/2018	Potholes on carriageway at junction with meadowfield road	RD: CW Pothole	Internal		Committed	50007484
Batch:	41008811 - Inspection Batch		Route:	Ad hoc Route			Date:	18/04/2018
42008447	hot temp make safe	18/04/2018	Potholes on city bound carriageway at sign for braehead quarry	RD: CW Pothole	Internal		Committed	50007483
Batch:	41008809 - Inspection Batch		Route:	Ad hoc Route			Date:	18/04/2018
42008445	Hot temp make safe	18/04/2018	Pothole on carriageway opposite car park entrance to Turnhouse golf course	RD: CW Pothole	Internal		Committed	50007481
Batch:	41008808 - Inspection Batch		Route:	Ad hoc Route			Date:	18/04/2018
42008444	Hot temp make safe	18/04/2018	Potholes on footway at entrance to Turnhouse golf course car park	RD: CW Pothole	Internal		Committed	50007480
Batch:	41008807 - Inspection Batch		Route:	Ad hoc Route			Date:	18/04/2018
42008443	Clean gully	18/04/2018	Gully blocked on carriageway outside Turnhouse golf course car park	Gully: Blocked / Flooding	Internal		Action Required	
Batch:	41008806 - Inspection Batch		Route:	Ad hoc Route			Date:	18/04/2018
42008442	Hot temp make safe	18/04/2018	Pothole on footway out side Turnhouse golf course entrance	RD: CW Rutting	Internal		Committed	50007479

Effective: 01/04/2018 to 31/03/2020

Asset Number: 1.00 to 99.00

Display Action Officer: No

Site: Turnhouse Road (7900553)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 1 - From No 98 to Lennymuir		Feature Type: Road Asset			Area: North West Locality	
Batch: 41008805 - Inspection Batch		Route: Ad hoc Route			Date: 18/04/2018			
42008441	Hot temp make safe	18/04/2018	Various potholes on carriageway outside golf course entrance	RD: CW Pothole	Internal		Committed	50007478
Batch: 41008804 - Inspection Batch		Route: Ad hoc Route			Date: 18/04/2018			
42008440	Hot temp make safe	18/04/2018	Pothole on carriageway outside Queensferry motor company	RD: CW Pothole	Internal		Committed	50007477
Asset:	3.00	Asset - Locn.: Ward 3 - From Turnhouse Road at Glasgow Road north-west to		Feature Type: Road Asset			Area: North West Locality	
Batch: 41034881 - Inspection Batch		Route: Ad hoc Route			Date: 19/06/2019			
42032927	outside saicapack	19/06/2019	Sunken, loose and very nosiy manhole covers on carriageway	RU: Utility Apparatus	Internal		Uncommitted	50035956