

Effective: 01/01/2020 to 31/03/2020		Asset Number: 1.00 to 99.00	
Display Action Officer: No		Site: Turnhouse Road (7900553)	
Site: Turnhouse Road (7900553)		Locality: Cammo, Edinburgh, City of Edinburgh	Area: North West Locality


Customer Services



Enquiry No.: 975470 Logged by: [REDACTED] on: 16/03/2020 15:43
Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim
Desc.: Accident Claim form received.
Location: Turnhouse Road opposite entrance to Turnhouse Golf Club Contact: 975


Enquiry No.: 954635 Logged by: Verint CRM Connector on: 04/02/2020 09:20
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: THERE IS A MAN HOLE COVER MISSING FROM A DRAIN. VERY LARGE HOLE IN ROAD. A LOT A VEHICLES ACTUALLY USING THIS ROAD INCLUDING THE EMERGENCY SERVICES IF THERE IS ANY PROBLEST THE AIRPORT AND VIP TRAVELLING THE EDINBURGH. I NEARLY DROVE INTO IT THIS MORNING, THERE ARE NO STREET LIGHT SO SOMEONE WILL HAVE AN ACCIDENT VERY SOON IF NOT FIX QUICKLY. PLEASE MEND. Contact:

Plot Number: 2.00 Feature Id - Location: Ward 1 - From No 98 to Lennymuir Feature Type: Road Asset
Job Number: 50051671 Defect Number: 42045881



Effective: 01/01/2020 to 31/03/2020	Asset Number: 1.00 to 99.00
Display Action Officer: No	Site: Turnhouse Road (7900553)

Customer Services



Enquiry No.: 949664	Logged by: Verint CRM Connector	on: 26/01/2020 03:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Stop valve cover displaced leaving dangerous hole in roadway on Turnhouse Road at junction.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 1 - From No 98 to Lennymuir	Feature Type: Road Asset
Job Number: 50051093	Defect Number: 42045333	
Enquiry No.: 948118	Logged by: Verint CRM Connector	on: 23/01/2020 13:13
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Location: Gap in pavement surface	Contact:	
Plot Number: 3.00	Feature Id - Location: Ward 3 - From Turnhouse Road at Glasgow Road north-west to	Feature Type: Road Asset