

## Site History Report

**Effective:** 01/01/2020 to 25/06/2021  
**Display Action Officer:** Yes

**Asset Number:** 1.00 to 3.00  
**Site:** George IV Bridge (7903433)

**Site:** George IV Bridge (7903433)

**Locality:** Old Town, Edinburgh, City of Edinburgh

**Area:** South East Locality

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality			
<b>Batch:</b> 41094263 - Inspection Batch	No actionable defects found		<b>Route:</b> SE_FW1_Mound1		<b>Officer:</b> [REDACTED]	<b>Date:</b> 14/06/2021		
<b>Batch:</b> 41094204 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Officer:</b> [REDACTED]	<b>Date:</b> 14/06/2021		
42071057	Missing bollards and bases needs replaced soon as possible	14/06/2021		RD: SFP Damaged Bollard	Internal		Committed	50085180
<b>Batch:</b> 41093866 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Officer:</b> [REDACTED]	<b>Date:</b> 08/06/2021		
42070680	Missing bollards and bases at pedestrian crossing at the scan cafe outside	08/06/2021		RD: SFP Damaged Bollard	Internal		Committed	50084835
<b>Batch:</b> 41093541 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Officer:</b> [REDACTED]	<b>Date:</b> 02/06/2021		
42070191	Missing cat Posts and missing bases on George the fourth Bridge pedestrian crossing as seen by Photos.. bases and Posts need to be replaced and phone contractor contraflow for inspection and daily maintenance checks that should be daily inspections	02/06/2021		RD: SFP Damaged Bollard	Internal		Committed	50084433
<b>Batch:</b> 41093254 - Inspection Batch	No actionable defects found		<b>Route:</b> SE_CW1_Central1		<b>Officer:</b> [REDACTED]	<b>Date:</b> 31/05/2021		
<b>Batch:</b> 41093213 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Officer:</b> [REDACTED]	<b>Date:</b> 28/05/2021		
42069881	Missing bollards cat posts	28/05/2021		RD: SFP Damaged Bollard	Internal		Committed	50084119
<b>Batch:</b> 41092722 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Officer:</b> [REDACTED]	<b>Date:</b> 20/05/2021		
42069367	Cat posts missing and bases need to be replaced soon as possible	20/05/2021		RD: SFP Damaged Bollard	Internal		Committed	50083479
<b>Batch:</b> 41092566 - Inspection Batch			<b>Route:</b> SE_FW1_Mound1		<b>Officer:</b> [REDACTED]	<b>Date:</b> 18/05/2021		
42069237	2 rocking Caithness slabs	18/05/2021	At crossing outside Nando's	RD: FW Slabs Rocking	Internal		Committed	50083316
42069236	1 rocking Caithness slab	18/05/2021	Opposite greyfriars bobby	RD: FW Slabs Rocking	Internal		Committed	50083315
42069239	1 rocking Caithness slab	18/05/2021	Outside le bistro	RD: FW Slabs Rocking	Internal		Committed	50083318
<b>Batch:</b> 41092477 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Officer:</b> [REDACTED]	<b>Date:</b> 17/05/2021		
42069100		17/05/2021		RD: SFP Damaged Bollard	Internal		Committed	50083176
<b>Batch:</b> 41092054 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Officer:</b> [REDACTED]	<b>Date:</b> 11/05/2021		
42068581	Cat posts missing and needs replaced	11/05/2021		RD: SFP Damaged Bollard	Internal		Committed	50082714
<b>Batch:</b> 41091780 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Officer:</b> [REDACTED]	<b>Date:</b> 06/05/2021		
42068377		06/05/2021		RD: SFP Damaged Bollard	Internal		Committed	50082458
<b>Batch:</b> 41091031 - Inspection Batch	No actionable defects found		<b>Route:</b> SE_CW1_Central1		<b>Officer:</b> [REDACTED]	<b>Date:</b> 26/04/2021		
<b>Batch:</b> 41090743 - Inspection Batch	No actionable defects found		<b>Route:</b> SE_FW1_Mound1		<b>Officer:</b> [REDACTED]	<b>Date:</b> 20/04/2021		

## Site History Report

**Effective:** 01/01/2020 to 25/06/2021  
**Display Action Officer:** Yes

**Asset Number:** 1.00 to 3.00  
**Site:** George IV Bridge (7903433)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b>	Whole Street	<b>Feature Type:</b>	Road Asset		<b>Area:</b>	South East Locality
<b>Batch:</b>	41090434 - Inspection Batch			<b>Route:</b>	Ad hoc Route	<b>Officer:</b>		<b>Date:</b> 15/04/2021
42067044	Cat posts and Base need replaced	15/04/2021		RD: SFP Damaged Bollard	Internal		Committed	50081116
<b>Batch:</b>	41089583 - Inspection Batch			<b>Route:</b>	Ad hoc Route	<b>Officer:</b>		<b>Date:</b> 01/04/2021
42066381		01/04/2021		RD: SFP Damaged Bollard	Internal		Committed	50080362
<b>Batch:</b>	41089033 - Inspection Batch			<b>Route:</b>	Ad hoc Route	<b>Officer:</b>		<b>Date:</b> 26/03/2021
42065772	2 number BT manholes with loose and nosey lids one triple one one double	26/03/2021	On carriageway outside Sichuan House RU: Utility Apparatus		Internal		Uncommitted	50079709
<b>Batch:</b>	41088642 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1	<b>Officer:</b>		<b>Date:</b> 24/03/2021
	No actionable defects found							
<b>Batch:</b>	41088145 - Inspection Batch			<b>Route:</b>	SE_FW1_Mound1	<b>Officer:</b>		<b>Date:</b> 18/03/2021
	No actionable defects found							
<b>Batch:</b>	41085546 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1	<b>Officer:</b>		<b>Date:</b> 26/02/2021
	No actionable defects found							
<b>Batch:</b>	41084446 - Inspection Batch			<b>Route:</b>	SE_FW1_Mound1	<b>Officer:</b>		<b>Date:</b> 22/02/2021
	No actionable defects found							
<b>Batch:</b>	41078365 - Inspection Batch			<b>Route:</b>	SE_CF1_Mound1	<b>Officer:</b>		<b>Date:</b> 26/01/2021
	No actionable defects found							
<b>Batch:</b>	41078160 - Inspection Batch			<b>Route:</b>	SE_FW1_Mound1	<b>Officer:</b>		<b>Date:</b> 26/01/2021
42059434	3no Rocking Caithness slabs	25/01/2021	Opposite greyfriars Bobby pub	RD: FW Slabs Rocking	Internal		Uncommitted	50072810
42059459	Carriageway broken up at pedestrian crossing 0,2x4m	26/01/2021	Outside pizza paradise	RD: CW Cracked/Broken	Internal		Action Required	
42059471	1.5x4m patch required	26/01/2021	Located outside central l brary entrance, at bus stop	RD: CW Cracked/Broken	Internal		Uncommitted	50072927
42059432	Pothole/cracks. Patching required, approx 2x1m and 6x1m	25/01/2021	Opposite no 3 Greyfriars Place (Joe shop)	RD: CW Cracked/Broken	Internal		Uncommitted	50072812
42059466	Renew track. Approx 6x0.5m	26/01/2021	Southbound lane opposite Vittoria	RD: CW Cracked/Broken	Internal		Uncommitted	50072931
42059431	1no Rocking Caithness slab	25/01/2021	At bristo port	RD: FW Slabs Rocking	Internal		Uncommitted	50072813
42059436	Refresh yellow box area	25/01/2021	Southbound lane at Chambers Street	RD: Markings Refresh	Internal		Action Required	
42059474	High slab at foot of pole	26/01/2021	Opposite pizza express	RD: FW Slabs Rocking	Internal		Action Required	
42059469	Pothole. 2x0.5m	26/01/2021	Outside Villager	RD: CW Cracked/Broken	Internal		Uncommitted	50072928
42059475	2no rocking slabs	26/01/2021	Opposite phone boxes	RD: FW Slabs Rocking	Internal		Uncommitted	50072926
42059462	2x1m and 0.5x0.5m patching required	26/01/2021	Outside no 28 (near Frankenstein)	RD: CW Cracked/Broken	Internal		Uncommitted	50072933
42059435	1no damaged natural stone kerb	25/01/2021	Corner of Chambers Street outside National Museum of Scotland	RD: FW Kerbs Damaged/Missing	Internal		Action Required	
42059468	1no rocking Caithness slab	26/01/2021	Outside the cellar door restaurant	RD: FW Slabs Rocking	Internal		Uncommitted	50072929
42059461	2no rocking Caithness slab	26/01/2021	Outside nandos	RD: FW Slabs Rocking	Internal		Action Required	
42059464	2x1m and 1.5x1m patching required	26/01/2021	Outside The Elephant House	RD: CW Cracked/Broken	Internal		Uncommitted	50072932
42059433	Uneven surface. Patching required, approx 10x3m	25/01/2021	Southbound lane at Candlemakers Row	RD: CW Cracked/Broken	Internal		Uncommitted	50072811
42059467	Patch required 2.5x1m	26/01/2021	Outside no 17	RD: CW Cracked/Broken	Internal		Uncommitted	50072930

## Site History Report

**Effective:** 01/01/2020 to 25/06/2021  
**Display Action Officer:** Yes

**Asset Number:** 1.00 to 3.00  
**Site:** George IV Bridge (7903433)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street			<b>Feature Type:</b> Road Asset			<b>Area:</b> South East Locality	
<b>Batch:</b> 41077882 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 25/01/2021	
<b>Batch:</b> 41071653 - Inspection Batch No actionable defects found				<b>Route:</b> SE_FW1_Mound1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 18/12/2020	
<b>Batch:</b> 41071273 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 16/12/2020	
<b>Batch:</b> 41070130 - Inspection Batch No actionable defects found				<b>Route:</b> SE_FW1_Mound1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 01/12/2020	
<b>Batch:</b> 41069317 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 16/11/2020	
<b>Batch:</b> 41068877 - Inspection Batch No actionable defects found				<b>Route:</b> SE_FW1_Mound1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 11/11/2020	
<b>Batch:</b> 41066652 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 13/10/2020	
<b>Batch:</b> 41066412 - Inspection Batch No actionable defects found				<b>Route:</b> SE_FW1_Mound1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 09/10/2020	
<b>Batch:</b> 41062913 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 08/09/2020	
<b>Batch:</b> 41062666 - Inspection Batch No actionable defects found				<b>Route:</b> SE_FW1_Mound1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 01/09/2020	
<b>Batch:</b> 41061364 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 07/08/2020	
<b>Batch:</b> 41060336 - Inspection Batch				<b>Route:</b> SE_FW1_Mound1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 21/07/2020	
42051832 1no rocking flag	21/07/2020	Outside Nandos at bus stop	RD: FW Slabs Rocking	Internal		Committed	50058933	
<b>Batch:</b> 41059540 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 29/06/2020	
<b>Batch:</b> 41058522 - Inspection Batch No actionable defects found				<b>Route:</b> SE_FW1_Mound1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 08/06/2020	
<b>Batch:</b> 41057857 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 13/05/2020	
<b>Batch:</b> 41057068 - Inspection Batch No actionable defects found				<b>Route:</b> SE_FW1_Mound1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 23/04/2020	
<b>Batch:</b> 41056535 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 08/04/2020	
<b>Batch:</b> 41055165 - Inspection Batch No actionable defects found				<b>Route:</b> SE_CW1_Central1	<b>Officer:</b> [REDACTED]		<b>Date:</b> 10/03/2020	

## Site History Report

**Effective:** 01/01/2020 to 25/06/2021  
**Display Action Officer:** Yes

**Asset Number:** 1.00 to 3.00  
**Site:** George IV Bridge (7903433)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41054214 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 27/02/2020
42047770	1no pothole	27/02/2020	Outside The Elephant House	RD: CW Pothole	Internal		Committed	50053580
Batch: 41053389 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 24/02/2020
42047139	1no pothole	24/02/2020	Outside cafe andaluz	RD: CW Pothole	Internal		Committed	50052936
Batch: 41053386 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 24/02/2020
42047137	1no pothole	24/02/2020	Outside Mcgonagalls	RD: CW Pothole	Internal		Committed	50052934
Batch: 41051958 - Inspection Batch				Route: SE_CW1_Central1	Officer:			Date: 12/02/2020
No actionable defects found								
Batch: 41051249 - Inspection Batch				Route: SE_FW1_Mound1	Officer:			Date: 04/02/2020
42045409	1no rocking Caithness flag	04/02/2020	Outside The Cellar Door	RD: FW Slabs Rocking	Internal		Committed	50051171
42045407	4no low/rocking Caithness flags	04/02/2020	Opposite Bank of Scotland at junction with Royal Mile	RD: FW Slabs Rocking	Internal		Committed	50051169
Batch: 41050491 - Inspection Batch				Route: SE_CW1_Central1	Officer:			Date: 24/01/2020
42044679	2no potholes	24/01/2020	Northbound lane outside no15	RD: CW Pothole	Internal		Committed	50050368
42044680	1no pothole	24/01/2020	Northbound lane outside Cafe Andaluz	RD: CW Pothole	Internal		Committed	50050369
Batch: 41050100 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 21/01/2020
42044357	6no potholes	21/01/2020	At greyfriars bobby	RD: CW Pothole	Internal		Committed	50049712
Batch: 41049960 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 20/01/2020
42044203	Broken Scottish Water toby	20/01/2020	Northbound lane outside Ondine Restaurant	RU: Utility Apparatus	Internal		Uncommitted	50049891
Batch: 41049892 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 17/01/2020
42044106	1no pothole	17/01/2020	Northbound lane outside Ondine	RD: CW Pothole	Internal		Committed	50049444
Batch: 41049819 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 16/01/2020
42044025	6no potholes	16/01/2020	At greyfriars bobby	RD: CW Pothole	Internal		No Action Required	
Batch: 41049818 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 16/01/2020
42044024	1no pothole	16/01/2020	Outside Sichuan House	RD: CW Pothole	Internal		Committed	50049711
Batch: 41049583 - Inspection Batch				Route: Ad hoc Route	Officer:			Date: 14/01/2020
42043755	1no pothole	14/01/2020	Northbound lane outside Ondine	RD: CW Pothole	Internal		No Action Required	

## Site History Report

**Effective:** 01/01/2020 to 25/06/2021  
**Display Action Officer:** Yes

**Asset Number:** 1.00 to 3.00  
**Site:** George IV Bridge (7903433)

### Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street			<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality	
1000728	1no pothole 2x2 1no sml dip 1x1 (RD: Asphalt / Bitmac Surface)	Located outside library entrance, at bus stop		RD: Cat 3 - 60 Day	Job Cancelled	29/10/2014		
1001593	Dislodged kerbs put back in place do not remove also fix loose flags (RD: Kerbs)	Junction with Victoria st		Non Routine (One Off Works)	Job Cancelled	26/01/2015		
1007018	Sunken track. 5x0.3m (RD: Asphalt / Bitmac Surface)	Southbound lane opposite Bank of Scotland, near pedestrian crossing.		RD: Cat 4 - 12 Months	Job Raised	06/09/2016	05/09/2017	Est.
1007019	Depression at bus stop. 1x2m (RD: Asphalt / Bitmac Surface)	Southbound lane opposite Pizza Express. At pedestrian crossing		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	05/09/2017	Est.

## Site History Report

**Effective:** 01/01/2020 to 25/06/2021  
**Display Action Officer:** Yes

**Asset Number:** 1.00 to 3.00  
**Site:** George IV Bridge (7903433)

### Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street			<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality	
1007021	Refresh bus lane markings, bus stop markings, cycleways, central line (at Greyfriars Place), stop lines and lane markings at Bristo Place (RD: Road Marking & Studs)	Full lenght		RD: Cat 3 - 60 Day	Job Cancelled	06/09/2016	03/10/2016	Est.
1007023	Pothole. 2x0.5m (RD: Asphalt / Bitmac Surface)	Outside Villager		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	05/09/2017	Est.
1007024	Renew track. Approx 6x0.5m (RD: Asphalt / Bitmac Surface)	Southbound lane opposite Vittoria		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	05/09/2017	Est.
1007025	Refresh yellow box area (RD: Road Marking & Studs)	Southbound lane at Chambers Street		RD: Cat 3 - 60 Day	Job Cancelled	06/09/2016	03/10/2016	Est.
1007027	1no damaged natural stone kerb (RD: Kerbs)	Corner of Chambers Street outside National Museum of Scotland		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	05/09/2017	Est.
1007028	1no rocking caithness slab (RD: Paving Slabs)	Outside National Museum of Scotland and opposite Greyfriars Bobby		RD: Cat 3 - 60 Day	Job Cancelled	06/09/2016	03/10/2016	Est.
1007029	Uneven surface. Patching required, approx 10x3m (RD: Asphalt / Bitmac Surface)	Southbound lane at Candlemakers Row		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	05/09/2017	Est.
1007030	Pothole/cracks. Patching required, approx 2x1m and 6x1m (RD: Asphalt / Bitmac Surface)	Opposite no 3 Greyfriars Place (Joe shop)		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	05/09/2017	Est.
1007032	1x1m patching required (RD: Asphalt / Bitmac Surface)	Northbound lane outside G&V Hotel		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	06/09/2017	Est.
1007033	Relay approx 4x1m of setts (RD: Setts & Block Paving)	Northbound lane outside G&V Hotel at dropp off point		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	06/09/2017	Est.
1007035	1x1m patching required (RD: Asphalt / Bitmac Surface)	Outside Liquor L brary, opposite George IV bar		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	06/09/2017	Est.
1007036	2x1m and 1.5x1m patching required (RD: Asphalt / Bitmac Surface)	Outside The Elephant House		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	06/09/2017	Est.
1007037	2x1m and 0.5x0.5m patching required (RD: Asphalt / Bitmac Surface)	Outside no 28 (near Frankenstein)		RD: Cat 4 - 12 Months	Job Cancelled	06/09/2016	06/09/2017	Est.
1011194	Re-lining patching recently completed (RD: Road Marking & Studs)	Southbound on the street in the bus lane near the junction with the high street		RD: Cat 4 - 12 Months	Job Cancelled	11/12/2017	11/12/2018	Est.
50001503	3x8m patch required (RD: Asphalt / Bitmac Surface)	Located outside central library entrance, at bus stop		RD: Cat 4 - 12 Months	Job Cancelled	18/01/2018	18/01/2019	Est.
50001505	6no damaged radius kerbs 7no caithness slabs to be renewed (RD: Kerbs)	Junction with Victoria st		RD: Cat 4 - 12 Months	Job Cancelled	18/01/2018	18/01/2019	Est.
50004407	1no pothole (RD: CW Pothole)	Outside Cafe Andaluz		RD: Cat 2 - 5 Day	Job Cancelled	09/03/2018	12/03/2018	Est. ROAD/82003511
50005156	4no potholes (RD: CW Pothole)	Northbound lane at Greyfriars Bobby		RD: Cat 3 - 60 Day	Job Cancelled	19/03/2018	16/04/2018	Est. ROAD/82004136

## Site History Report

**Effective:** 01/01/2020 to 25/06/2021  
**Display Action Officer:** Yes

**Asset Number:** 1.00 to 3.00  
**Site:** George IV Bridge (7903433)

### Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b> 1.00		<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality		
50012934	1no rocking Caithness flag (RD: FW Slabs Rocking)	Outside the Bank of Scotland at the pedestrian crossing		PRIORITY: C H A N G E M E	Job Cancelled	09/07/2018		
50049444	1no pothole (RD: CW Pothole)	Northbound lane outside Ondine		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/01/2020	18/01/2020	Act. ROAD/82030539
50049711	1no pothole (RD: CW Pothole)	Outside Sichuan House		RD: Cat 3 - 60 Day	Job Complete	16/01/2020	22/01/2020	Act. ROAD/82030753
50049712	6no potholes (RD: CW Pothole)	At greyfriars bobby		RD: Cat 3 - 60 Day	Job Complete	16/01/2020	22/01/2020	Act. ROAD/82030754
50049891	Broken Scottish Water toby (RU: Utility Apparatus)	Northbound lane outside Ondine Restaurant		RU: Fail Med.Risk (Apparatus)	Job Complete	20/01/2020	21/01/2020	Act.
50050368	2no potholes (RD: CW Pothole)	Northbound lane outside no15		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2020	01/02/2020	Act. ROAD/82031262
50050369	1no pothole (RD: CW Pothole)	Northbound lane outside Cafe Andaluz		RD: Cat 3 - 60 Day	Job Complete	24/01/2020	01/02/2020	Act. ROAD/82031267
50051169	4no low/rocking Caithness flags (RD: FW Slabs Rocking)	Opposite Bank of Scotland at junction with Royal Mile		RD: Cat 3 - 60 Day	Job Complete	04/02/2020	25/02/2020	Act. ROAD/82031901
50051171	1no rocking Caithness flag (RD: FW Slabs Rocking)	Outside The Cellar Door		RD: Cat 3 - 60 Day	Job Complete	04/02/2020	25/02/2020	Act. ROAD/82031903
50052934	1no pothole (RD: CW Pothole)	Outside Mcgonagalls		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/02/2020	02/03/2020	Act. ROAD/82033485
50052936	1no pothole (RD: CW Pothole)	Outside cafe andaluz		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/02/2020	02/03/2020	Act. ROAD/82033487
50053580	1no pothole (RD: CW Pothole)	Outside The Elephant House		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	27/02/2020	17/03/2020	Act. ROAD/82034068
50058933	1no rocking flag (RD: FW Slabs Rocking)	Outside Nandos at bus stop		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/07/2020	22/07/2020	Act. ROAD/82038031
50072810	3no Rocking Caithness slabs (RD: FW Slabs Rocking)	Opposite greyfriars Bobby pub		RD: Cat 4 - 12 Months	Job Annulled	25/01/2021	25/01/2022	Est.
50072811	Uneven surface. Patching required, approx 10x3m (RD: CW Cracked/Broken)	Southbound lane at Candlemakers Row		RD: Cat 4 - 12 Months	Job Annulled	25/01/2021	25/01/2022	Est.
50072812	Pothole/cracks. Patching required, approx 2x1m and 6x1m (RD: CW Cracked/Broken)	Opposite no 3 Greyfriars Place (Joe shop)		RD: Cat 4 - 12 Months	Job Annulled	25/01/2021	25/01/2022	Est.
50072813	1no Rocking Caithness slab (RD: FW Slabs Rocking)	At bristo port		RD: Cat 4 - 12 Months	Job Annulled	25/01/2021	25/01/2022	Est.
50072926	2no rocking slabs (RD: FW Slabs Rocking)	Opposite phone boxes		RD: Cat 4 - 12 Months	Job Annulled	26/01/2021	26/01/2022	Est.
50072927	1.5x4m patch required (RD: CW Cracked/Broken)	Located outside central library entrance, at bus stop		RD: Cat 4 - 12 Months	Job Annulled	26/01/2021	26/01/2022	Est.
50072928	Pothole. 2x0.5m (RD: CW Cracked/Broken)	Outside Villager		RD: Cat 4 - 12 Months	Job Annulled	26/01/2021	26/01/2022	Est.
50072929	1no rocking Caithness slab (RD: FW Slabs Rocking)	Outside the cellar door restaurant		RD: Cat 4 - 12 Months	Job Annulled	26/01/2021	26/01/2022	Est.
50072930	Patch required 2.5x1m (RD: CW Cracked/Broken)	Outside no 17		RD: Cat 4 - 12 Months	Job Annulled	26/01/2021	26/01/2022	Est.
50072931	Renew track. Approx 6x0.5m (RD: CW Cracked/Broken)	Southbound lane opposite Vittoria		RD: Cat 4 - 12 Months	Job Annulled	26/01/2021	26/01/2022	Est.

## Site History Report

**Effective:** 01/01/2020 to 25/06/2021  
**Display Action Officer:** Yes

**Asset Number:** 1.00 to 3.00  
**Site:** George IV Bridge (7903433)

### Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b> 1.00		<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality		
50072932	2x1m and 1.5x1m patching required (RD: CW Cracked/Broken)	Outside The Elephant House		RD: Cat 4 - 12 Months	Job Annulled	26/01/2021	26/01/2022	Est.
50072933	2x1m and 0.5x0.5m patching required (RD: CW Cracked/Broken)	Outside no 28 (near Frankenstein)		RD: Cat 4 - 12 Months	Job Annulled	26/01/2021	26/01/2022	Est.
50079709	2 number BT manholes with loose and nosey lids one triple one one double (RU: Utility Apparatus)	On carriageway outside Sichuan House		RU: Fail Low Risk	Job Complete	26/03/2021	26/03/2021	Act.
50080362	RD: SFP Damaged Bollard			RD: Cat 3 - 60 Day	Job Complete	01/04/2021	24/05/2021	Act. ROAD/82048172
50081116	Cat posts and Base need replaced (RD: SFP Damaged Bollard)			RD: Cat 2 - 5 Day	Job Complete	15/04/2021	26/04/2021	Act. ROAD/82048613
50082458	RD: SFP Damaged Bollard			RD: Cat 2 - 5 Day	Job Complete	06/05/2021	12/05/2021	Act. ROAD/82049368
50082714	Cat posts missing and needs replaced (RD: SFP Damaged Bollard)			RD: Cat 2 - 5 Day	Job Complete	11/05/2021	12/05/2021	Act. ROAD/82049531
50083176	RD: SFP Damaged Bollard			RD: Cat 2 - 5 Day	Job Complete	17/05/2021	18/05/2021	Act. ROAD/82049768
50083315	1 rocking Caithness slab (RD: FW Slabs Rocking)	Opposite greyfriars bobby		RD: Cat 3 - 60 Day	Job Complete	18/05/2021	20/05/2021	Act. ROAD/82049853
50083316	2 rocking Caithness slabs (RD: FW Slabs Rocking)	At crossing outside Nando's		RD: Cat 3 - 60 Day	Job Complete	18/05/2021	19/05/2021	Act. ROAD/82049854
50083318	1 rocking Caithness slab (RD: FW Slabs Rocking)	Outside le bistro		RD: Cat 2 - 5 Day	Job Complete	18/05/2021	09/06/2021	Act. ROAD/82049856
50083479	Cat posts missing and bases need to be replaced soon as possible (RD: SFP Damaged Bollard)			RD: Cat 2 - 5 Day	Job Complete	20/05/2021	24/05/2021	Act. ROAD/82049961
50084119	Missing bollards cat posts (RD: SFP Damaged Bollard)			RD: Cat 2 - 5 Day	Job Complete	28/05/2021	03/06/2021	Act. ROAD/82050274
50084433	Missing cat Posts and missing bases on George the fourth Bridge pedestrian crossing as seen by Photos.. bases and Posts need to be replaced and phone contractor contraflow for inspection and daily maintenance checks that should be daily inspections (RD: SFP Damaged Bollard)			RD: Cat 2 - 5 Day	Job Complete	02/06/2021	03/06/2021	Act. ROAD/82050461
50084835	Missing bollards and bases at pedestrian crossing at the scan cafe outside (RD: SFP Damaged Bollard)			RD: Cat 2 - 5 Day	Job Complete	08/06/2021	30/06/2021	Act. ROAD/82050724



Site History Report

Effective: 01/01/2020 to 25/06/2021

Asset Number: 1.00 to 3.00

Display Action Officer: Yes

Site: George IV Bridge (7903433)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
50085180	Missing bollards and bases needs replaced soon as possible (RD: SFP Damaged Bollard)			RD: Cat 2 - 5 Day	Job Complete	14/06/2021	15/06/2021	Act. ROAD/82050890