

Effective: 02/04/2019 to 03/04/2021
Service: Roads General
Site: Elm Row (7903691)

Asset Number: 5.00 to 5.00
Display Action Officer: No

Site: Elm Row (7903691)

Locality: Broughton, Edinburgh, City of Edinburgh

Area: North East Locality

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|------------------------|---|--|------------|-------------------------------|---------------------------------|--------------|----------------------------------|-------------------------|
| Asset: | 5.00 | Asset - Locn.: Ward 11 - North side of roundabout at London Road (also part of) | | | Feature Type: Road Asset | | Area: North East Locality | |
| Batch: 41088756 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 24/03/2021 |
| Batch: 41085528 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 26/02/2021 |
| Batch: 41078063 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 25/01/2021 |
| Batch: 41071400 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 16/12/2020 |
| Batch: 41071225 | - Inspection Batch | | | Route: SE_CF1_LeithSt1 | | | | Date: 15/12/2020 |
| 42057518 | Sunken sett | 15/12/2020 | At Elm Row | RD: CW Setts Depression | Internal | | Action Required | |
| Batch: 41069233 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 16/11/2020 |
| Batch: 41066737 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 13/10/2020 |
| Batch: 41063008 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 08/09/2020 |
| Batch: 41061432 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 07/08/2020 |
| Batch: 41059457 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 26/06/2020 |
| Batch: 41057841 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 13/05/2020 |
| Batch: 41056624 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 09/04/2020 |
| Batch: 41055151 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 10/03/2020 |
| Batch: 41051852 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 12/02/2020 |
| Batch: 41050392 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 23/01/2020 |
| Batch: 41046660 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 27/11/2019 |
| Batch: 41044978 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 29/10/2019 |

Effective: 02/04/2019 to 03/04/2021
Service: Roads General
Site: Elm Row (7903691)

Asset Number: 5.00 to 5.00
Display Action Officer: No

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|-----------------------------|--------------------|--|----------|-------------------------------|---------------------------------|--------------|----------------------------------|-------------------------|
| Asset: | 5.00 | Asset - Locn.: Ward 11 - North side of roundabout at London Road (also part o | | | Feature Type: Road Asset | | Area: North East Locality | |
| Batch: 41041648 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 01/10/2019 |
| No actionable defects found | | | | | | | | |
| Batch: 41039130 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 02/09/2019 |
| No actionable defects found | | | | | | | | |
| Batch: 41037512 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 06/08/2019 |
| No actionable defects found | | | | | | | | |
| Batch: 41035992 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 08/07/2019 |
| No actionable defects found | | | | | | | | |
| Batch: 41034523 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 12/06/2019 |
| No actionable defects found | | | | | | | | |
| Batch: 41034224 | - Inspection Batch | | | Route: SE_CF1_LeithSt1 | | | | Date: 10/06/2019 |
| No actionable defects found | | | | | | | | |
| Batch: 41032851 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 15/05/2019 |
| No actionable defects found | | | | | | | | |
| Batch: 41030844 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 15/04/2019 |
| No actionable defects found | | | | | | | | |

Customer Services

| | | |
|---|---|--|
| Enquiry No.: 30602844 | Logged by: [REDACTED] | on: 01/07/2019 08:28 |
| Service: Roads General | Subject: Pavement: Damaged / Defective | Classification: Request for service |
| Desc.: every time the tenant is walking in and out the property the pavement slabs move | | |
| Location: | Contact: | |
| Enquiry No.: 30602448 | Logged by: [REDACTED] | on: 14/05/2019 09:27 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: Going south down Elm Row (after junction with Montgomery St) the potholes are getting deeper & deeper almost daily. You don't just ride bump over them, you clonk over them - accidents and/or claims for wheel damage are inevitable. Please can these be sorted urgently? | | |
| Location: after junction with Montgomery St | Contact: | |
| Enquiry No.: 964908 | Logged by: [REDACTED] | on: 23/02/2020 14:01 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: 23.02.2020 - Twitter - Prize for deepest hole on Leith Walk? On Elm Row leith bound at the traffic lights. @edinhelp Can you report to be fixed please before there is an accident? #LeithWalk | | |
| Location: Elm Row | Contact: | |
| Enquiry No.: 937373 | Logged by: [REDACTED] | on: 07/01/2020 13:27 |
| Service: Roads General | Subject: Covers: Damaged / Defective | Classification: Request for service |
| Desc.: Junction of elm row and Annandale street. At junction and is a collapsed manhole cover on road | | |
| Location: Junction of elm row and Annandale street. At junction and is a collapsed manhole cover on road | Contact: | |

Effective: 02/04/2019 to 03/04/2021

Service: Roads General

Site: Elm Row (7903691)

Asset Number: 5.00 to 5.00

Display Action Officer: No

Customer Services

| | | |
|--|---|--|
| Enquiry No.: 936916 | Logged by: [REDACTED] | on: 06/01/2020 19:09 |
| Service: Roads General | Subject: Covers: Missing | Classification: Customer Emergency |
| Desc.: Any chance you could sort that severely sunken drain cover that's now became a serious hazard to cars and cyclists. Been there for a cpl weeks now! Its located at the traffic lights outside cafe india at top of leith walk/elm row | | |
| Location: Any chance you could sort that severely sunken drain cover that's now became a serious hazard to cars and cyclists. Been there for a cpl weeks now! Its located at the traffic lights outside cafe india at top of leith walk/elm row | | Contact: |
| Enquiry No.: 935317 | Logged by: Verint CRM Connector | on: 03/01/2020 10:06 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: just past existing marked hole in road another 1metre sq crater has opened its half meter deep and would smash alloy wheel urgent action reqd junction of elm row edinburgh and leith walk just past montgomery st right on crossing | | Contact: |
| Enquiry No.: 930299 | Logged by: Verint CRM Connector | on: 17/12/2019 14:24 |
| Service: Roads General | Subject: Pavement: Damaged / Defective | Classification: Request for service |
| Desc.: | | |
| Location: On Sunday evening at 7:30 pm [REDACTED] was parked near 14 Elm Row which is next to Rimmer's Music Shop. Due to the area being poorly lit I didn't see a concrete slab until it was too late. [REDACTED] [REDACTED] [REDACTED] It looks like this used to be where a bin would have been previously. | | Contact: |
| Enquiry No.: 912852 | Logged by: Verint CRM Connector | on: 08/11/2019 12:00 |
| Service: Roads General | Subject: Street Furniture: Defective | Classification: Request for service |
| Desc.: | | |
| Location: near the corner of elm row and gayfield square. sign was flat down on pavement metal triangular signs do not know what was on sign. tripped over this and had nasty fall. can this please be put the sign the correct way up. | | Contact: |
| Enquiry No.: 903220 | Logged by: Verint CRM Connector | on: 18/10/2019 02:09 |
| Service: Roads General | Subject: Signs: Defective / Damaged | Classification: Request for service |
| Desc.: What type of sign is it? Road sign problem, type unlit | | |
| Location: Bus stop live departure times sign missing - bus stop for bus 7, 14, 49 etc towards Leith Street. | | Contact: |
| Enquiry No.: 891882 | Logged by: [REDACTED] | on: 24/09/2019 08:54 |
| Service: Roads General | Subject: Street Furniture: Defective | Classification: Request for service |
| Desc.: Please remove yellow cover outside number 61 as no function as manhole cover now repaired | | |
| Location: Elm Row | | Contact: |