

Effective: 02/04/2019 to 03/04/2021  
 Service: Roads General  
 Site: Antigua Street (7903686)

Asset Number: 2.00 to 2.00  
 Display Action Officer: No

Site: Antigua Street (7903686)

Locality: Albion, Edinburgh, City of Edinburgh

Area: South East Locality

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 2.00	<b>Asset - Locn.:</b> Ward 11 - From Union Street to north side of roundabout at Lonc			<b>Feature Type:</b> Road Asset			<b>Area:</b> South East Locality	
<b>Batch:</b> 41088754 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 24/03/2021
<b>Batch:</b> 41087896 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_FW1_LeithSt1				<b>Date:</b> 17/03/2021
<b>Batch:</b> 41085527 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 26/02/2021
<b>Batch:</b> 41083690 - Inspection Batch				<b>Route:</b> SE_FW1_LeithSt1				<b>Date:</b> 18/02/2021
42061708	2 x cw potholes	18/02/2021	Outside down the hatch	RD: CW Pothole	Internal		Committed	50075488
<b>Batch:</b> 41078062 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 25/01/2021
<b>Batch:</b> 41075812 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_FW1_LeithSt1				<b>Date:</b> 18/01/2021
<b>Batch:</b> 41074952 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 14/01/2021
42058833	1no pothole	14/01/2021	In the outside lane outside Mamma Roma	RD: CW Pothole	Internal		Committed	50072025
<b>Batch:</b> 41071399 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 16/12/2020
<b>Batch:</b> 41071217 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_FW1_LeithSt1				<b>Date:</b> 15/12/2020
<b>Batch:</b> 41071215 - Inspection Batch				<b>Route:</b> SE_CF1_LeithSt1				<b>Date:</b> 15/12/2020
42057511	Cracked slab and uneven area	15/12/2020	Outside 9	RD: FW Slabs Broken/Missing	Internal		Action Required	
42057509	2no grano patches cracked and broken	15/12/2020	Outside Mamma Roma	RD: FW Grano Cracked/Broken	Internal		Action Required	
42057507	4no broken 900x600 pcc flags 4no broken 600x600 pcc flags Cracked and broken grano at manhole	15/12/2020	Outside the Deep Sea	RD: FW Slabs Broken/Missing	Internal		Action Required	
42057508	Loose rocking cut half slab please lift and relay	15/12/2020	O/S Deep sea	RD: FW Slabs Rocking	Internal		Committed	50070149
42057513	Uneven area of slabs	15/12/2020	O/S Kahini restaraunt	RD: FW Slabs Rocking	Internal		Action Required	
42057505	4m of damaged pcc radius kerb	15/12/2020	Outside Pomegranate	RD: FW Kerbs Damaged/Missing	Internal		Action Required	
42057512	Cracked and broken asphalt surface approx 5 x 3	15/12/2020	Outside down the hatch	RD: CW Cracked/Broken	Internal		No Action Required	
42057510	Loose grano at water Toby remove loose and grano	15/12/2020	O/S no 9	RD: FW Grano Pothole	Internal		Committed	50070150
<b>Batch:</b> 41069263 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_FW1_LeithSt1				<b>Date:</b> 16/11/2020
<b>Batch:</b> 41069232 - Inspection Batch	No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 16/11/2020

Effective: 02/04/2019 to 03/04/2021  
 Service: Roads General  
 Site: Antigua Street (7903686)

Asset Number: 2.00 to 2.00  
 Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	2.00	<b>Asset - Locn.:</b>	Ward 11 - From Union Street to north side of roundabout at Lonc	<b>Feature Type:</b>	Road Asset		<b>Area:</b>	South East Locality
<b>Batch:</b>	41066761 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 13/10/2020
	No actionable defects found							
<b>Batch:</b>	41066738 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 13/10/2020
	No actionable defects found							
<b>Batch:</b>	41063132 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 11/09/2020
	No actionable defects found							
<b>Batch:</b>	41062954 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 08/09/2020
	No actionable defects found							
<b>Batch:</b>	41061428 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 07/08/2020
	No actionable defects found							
<b>Batch:</b>	41061135 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 05/08/2020
	No actionable defects found							
<b>Batch:</b>	41059526 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 29/06/2020
	No actionable defects found							
<b>Batch:</b>	41058534 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 09/06/2020
	No actionable defects found							
<b>Batch:</b>	41057842 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 13/05/2020
	No actionable defects found							
<b>Batch:</b>	41057081 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 24/04/2020
	No actionable defects found							
<b>Batch:</b>	41056633 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 09/04/2020
	No actionable defects found							
<b>Batch:</b>	41055678 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 18/03/2020
42049137	Cracked and broken grano at manhole needs replaced	18/03/2020	Outside the Deep Sea	RD: FW Grano Cracked/Broken	Internal		Committed	50055023
<b>Batch:</b>	41055150 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 10/03/2020
	No actionable defects found							
<b>Batch:</b>	41051851 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 12/02/2020
	No actionable defects found							
<b>Batch:</b>	41050879 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 30/01/2020
42045041	1no rocking 900x600pcc flag	30/01/2020	Outside Kahani	RD: FW Slabs Rocking	Internal		Committed	50050716
<b>Batch:</b>	41050474 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 24/01/2020
	No actionable defects found							
<b>Batch:</b>	41048608 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 30/12/2019
	No actionable defects found							

Effective: 02/04/2019 to 03/04/2021  
 Service: Roads General  
 Site: Antigua Street (7903686)

Asset Number: 2.00 to 2.00  
 Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	2.00	<b>Asset - Locn.:</b>	Ward 11 - From Union Street to north side of roundabout at Lonc	<b>Feature Type:</b>	Road Asset		<b>Area:</b>	South East Locality
<b>Batch:</b>	41046730 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 27/11/2019
	No actionable defects found							
<b>Batch:</b>	41046489 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 25/11/2019
	No actionable defects found							
<b>Batch:</b>	41044992 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 29/10/2019
	No actionable defects found							
<b>Batch:</b>	41042321 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 07/10/2019
	No actionable defects found							
<b>Batch:</b>	41041716 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 01/10/2019
	No actionable defects found							
<b>Batch:</b>	41039128 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 02/09/2019
	No actionable defects found							
<b>Batch:</b>	41038445 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 22/08/2019
	No actionable defects found							
<b>Batch:</b>	41037511 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 06/08/2019
	No actionable defects found							
<b>Batch:</b>	41036526 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 17/07/2019
	No actionable defects found							
<b>Batch:</b>	41035991 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 08/07/2019
	No actionable defects found							
<b>Batch:</b>	41034522 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 12/06/2019
	No actionable defects found							
<b>Batch:</b>	41034350 - Inspection Batch			<b>Route:</b>	SE_FW1_LeithSt1			<b>Date:</b> 11/06/2019
	No actionable defects found							
<b>Batch:</b>	41034225 - Inspection Batch			<b>Route:</b>	SE_CF1_LeithSt1			<b>Date:</b> 10/06/2019
42032287	Cracked and broken asphalt surface approx 8mx2m	10/06/2019	Outside no12	RD: CW Cracked/Broken	Internal		No Action Required	
42032308	4m of damaged pcc radius kerb	10/06/2019	Outside Pomegranate	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42032295	1no rocking 750x600 pcc flag	10/06/2019	Outside the Deep Sea	RD: FW Slabs Rocking	Internal		Committed	50035159
42032311	1no broken fantail 900x600 pcc flag	10/06/2019	Outside Pomegranate	RD: FW Slabs Broken/Missing	Internal		Committed	50035174
42032303	4no broken 900x600 pcc flags	10/06/2019	Outside the Deep Sea	RD: FW Slabs Broken/Missing	Internal		No Action Required	
	4no broken 600x600 pcc flags							
	Cracked and broken grano at manhole							
42032288	Loose manhole cover	10/06/2019	On the carriageway Outside Kahani	RU: Utility Apparatus	Internal		Uncommitted	50035141
42032291	2no grano patches cracked and broken	10/06/2019	Outside no5	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42032290	Missing grano infill	10/06/2019	Outside the Picture Framer	RD: FW Grano Pothole	Internal		Committed	50035150
42032289	13no broken 900x600 pcc flags	10/06/2019	Outside Jules Verne Restaurant	RD: FW Slabs Broken/Missing	Internal		No Action Required	
	7no broken 600x600 pcc flags							

Effective: 02/04/2019 to 03/04/2021  
 Service: Roads General  
 Site: Antigua Street (7903686)

Asset Number: 2.00 to 2.00  
 Display Action Officer: No

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	2.00	<b>Asset - Locn.:</b>	Ward 11 - From Union Street to north side of roundabout at Lonc	<b>Feature Type:</b>	Road Asset		<b>Area:</b>	South East Locality
<b>Batch:</b>	41032852 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 15/05/2019
	No actionable defects found							
<b>Batch:</b>	41030845 - Inspection Batch			<b>Route:</b>	SE_CW1_Central1			<b>Date:</b> 15/04/2019
	No actionable defects found							

**Customer Services**

**Enquiry No.:** 993581 **Logged by:** Verint CRM Connector **on:** 11/06/2020 16:24  
**Service:** Roads General **Subject:** Signs: Defective / Damaged **Classification:** Request for service  
**Desc.:** What type of sign is it? Road sign problem, type unlit  
**Location:** Large sign on corner of Antigua Street and Union Street has been hit by large vehicle and lost some fixings to sign mounting. **Contact:**

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order	
<b>Asset:</b>	2.00	<b>Asset - Locn.:</b>	Ward 11 - From Union Street to north side of roundabout at Lonc	<b>Feature Type:</b>	Road Asset		<b>Area:</b>	South East Locality
1003067	PARENT JOB - ANTIGUA STREET	Antigua Street	RD: Work Schedule (Parent)	Job Raised	08/06/2015	08/08/2015	Est.	
1003728	4 no. Rocking flags 1 no. broken flag, 1 no. Rocking grano patch next to BT chamber (RD: Paving Slabs)	Broken pavement outside chippy!	RD: Cat 3 - 60 Day	Job Cancelled	31/07/2015	28/08/2015	Est.	
1004962	Rocking 600 x300 900 grey pcc flag (RD: Paving Slabs)	On pavement outside Khushi's	Non Routine (One Off Works)	Job Cancelled	07/12/2015			
1007736	10no broken slabs Approx 6no slabs and 2no kerbs to be lifted and levels adjusted (RD: Paving Slabs)	Outside Pomegranate, at corner of Union Street	RD: Cat 3 - 60 Day	Job Cancelled	01/12/2016	29/12/2016	Est.	
50035141	Loose manhole cover (RU: Utility Apparatus)	On the carriageway Outside Kahani	RU: Fail Low Risk	Job Complete	10/06/2019	12/06/2019	Act.	
50035150	Missing grano infill (RD: FW Grano Pothole)	Outside the Picture Framer	RD: Cat 3 - 60 Day	Job Complete	10/06/2019	11/06/2019	Act. ROAD/82022283	
50035159	1no rocking 750x600 pcc flag (RD: FW Slabs Rocking)	Outside the Deep Sea	RD: Cat 3 - 60 Day	Job Complete	10/06/2019	11/06/2019	Act. ROAD/82022286	
50035174	1no broken fantail 900x600 pcc flag (RD: FW Slabs Broken/Missing)	Outside Pomegranate	RD: Cat 3 - 60 Day	Job Complete	10/06/2019	11/06/2019	Act. ROAD/82022293	
50050716	1no rocking 900x600pcc flag (RD: FW Slabs Rocking)	Outside Kahani	RD: Cat 3 - 60 Day	Job Complete	30/01/2020	03/02/2020	Act. ROAD/82031572	
50055023	Cracked and broken grano at manhole needs replaced (RD: FW Grano Cracked/Broken)	Outside the Deep Sea	RD: Cat 3 - 60 Day	Job Complete	18/03/2020	23/03/2020	Act. ROAD/82035294	

Effective: 02/04/2019 to 03/04/2021  
 Service: Roads General  
 Site: Antigua Street (7903686)

Asset Number: 2.00 to 2.00  
 Display Action Officer: No

<b>Maintenance Management</b>
-------------------------------

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 2.00	<b>Asset - Locn.:</b> Ward 11 - From Union Street to north side of roundabout at Lon		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality	
50070149	Loose rocking cut half slab please lift and relay (RD: FW Slabs Rocking)	O/S Deep sea	RD: Cat 3 - 60 Day	Job Complete	15/12/2020	22/12/2020	Act. ROAD/82042570
50070150	Loose grano at water Toby remove loose and grano (RD: FW Grano Pothole)	O/S no 9	RD: Cat 3 - 60 Day	Job Complete	15/12/2020	22/12/2020	Act. ROAD/82042571
50072025	1no pothole (RD: CW Pothole)	In the outside lane outside Mamma Roma	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/01/2021	15/01/2021	Act. ROAD/82043321
50075488	2 x cw potholes (RD: CW Pothole)	Outside down the hatch	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/02/2021	03/03/2021	Act. ROAD/82045186