

Site History Report

Effective: 24/12/2019 to 23/12/2021
Service: Roads General
Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Mcleod Street (7903443)

Locality: Gorgie, Edinburgh, City of Edinburgh

Area: South West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South West Locality
Batch:	41106529 - Inspection Batch			Route:	Ad hoc Route		Date:	03/11/2021
42082205	4no c/w potholes	03/11/2021	At lamppost no17	RD: CW Pothole	Internal		Committed	50095746
Batch:	41089760 - Inspection Batch			Route:	Ad hoc Route		Date:	06/04/2021
42066521	potholes (Enquiry 1108213)	06/04/2021	Outside 20/A	RD: CW Pothole	Internal		Committed	50080527
Batch:	41089759 - Inspection Batch			Route:	Ad hoc Route		Date:	06/04/2021
42066520	Potholes(Enquiry 1114512)	06/04/2021	At street lighting column no.MGC15	RD: CW Pothole	Internal		Committed	50080525
Batch:	41089758 - Inspection Batch			Route:	Ad hoc Route		Date:	06/04/2021
42066519	Pothole(Enquiry 1130205)	06/04/2021	At street lighting column MGC17	RD: CW Pothole	Internal		Committed	50080524
Batch:	41087824 - Inspection Batch			Route:	Ad hoc Route		Date:	17/03/2021
42064559	Road: Defective / Damaged (Enquiry 1141414)	17/03/2021	two potholes that have been missed when repairing the many potholes in this street	RD: CW Pothole	Internal		Committed	50078667
Batch:	41085957 - Inspection Batch			Route:	Ad hoc Route		Date:	02/03/2021
42062998	Multiple pot holes see attached photos	02/03/2021	From old Tynecastle school to Russel Rd	RD: CW Pothole	Internal		Committed	50076985
Batch:	41085946 - Inspection Batch			Route:	Ad hoc Route		Date:	02/03/2021
42062987	C/way pot holes	02/03/2021	At away supports gate	RD: CW Pothole	Internal		Committed	50076974
Batch:	41085943 - Inspection Batch			Route:	Ad hoc Route		Date:	02/03/2021
42062985	Multiple pot holes	02/03/2021	O/s new Hearts stand	RD: CW Pothole	Internal		Committed	50076973
Batch:	41070725 - Inspection Batch			Route:	Ad hoc Route		Date:	09/12/2020
42056930	2 x potholes	09/12/2020	Near tyncastle high school service entrance next to football pitch	RD: CW Pothole	Internal		Committed	50069568
Batch:	41070724 - Inspection Batch			Route:	Ad hoc Route		Date:	09/12/2020
42056929	Pothole on cw	09/12/2020	Across from stadium (see pics)	RD: CW Pothole	Internal		Committed	50069567
Batch:	41070723 - Inspection Batch			Route:	Ad hoc Route		Date:	09/12/2020
42056928	2 x potholes	09/12/2020	Near number 20A on cw	RD: CW Pothole	Internal		Committed	50069566
Batch:	41062173 - Inspection Batch			Route:	SW_CF2_DalrySouth1		Date:	25/08/2020
	No actionable defects found							
Batch:	41060013 - Inspection Batch			Route:	Ad hoc Route		Date:	09/07/2020
42051534	Refresh giveway markings	09/07/2020	McLeod street art Russel road	RD: Markings Refresh	Internal		Committed	50058228
Batch:	41056800 - Inspection Batch			Route:	Ad hoc Route		Date:	15/04/2020
42049797	Road: Defective / Damaged (Enquiry 980928)	15/04/2020	From school entrance to Russel roas	RD: CW Pothole	Internal		Committed	50055707
Batch:	41056799 - Inspection Batch			Route:	Ad hoc Route		Date:	15/04/2020
42049796	Road: Defective / Damaged (Enquiry 980928)	15/04/2020	From school entrance to Russel road	RD: CW Pothole	Internal		Committed	50055706

Site History Report

Effective: 24/12/2019 to 23/12/2021
Service: Roads General
Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South West Locality	
Batch: 41056798 - Inspection Batch		Route: Ad hoc Route			Date: 15/04/2020			
42049795	Potholes	15/04/2020	After bend see map	RD: CW Pothole	Internal		Committed	50055705
Batch: 41055691 - Inspection Batch		Route: Ad hoc Route			Date: 18/03/2020			
42049147	Road: Defective / Damaged - sent out claim papers From: [REDACTED] [REDACTED] Sent: 15 March 2020 21:12 To: Clarence <Clarence@edinburgh.gov.uk> Subject: Re: Tyre punctured via potholes Hi [REDACTED], [REDACTED] The Information is as follows: Name - [REDACTED] Address - [REDACTED] [REDACTED] Telephone Number - [REDACTED] Date of Incident - 16/02/2020 Street Name - Macleod Street, outside Gorgie Social Club there are several large potholes. Some directly out the front of the building and then another around the corner. [REDACTED] Kind regards, [REDACTED] [REDACTED] (Enquiry 9/5919)	18/03/2020	sent out claim papers From: [REDACTED] [REDACTED] Sent: 15 March 2020 21:12 To: Clarence <Clarence@edinburgh.gov.uk> Subject: Re: Tyre punctured via pothole: Hi [REDACTED], [REDACTED] The Information is as follows: Name - [REDACTED] Address - [REDACTED] Gorgie, [REDACTED] Telephone Number - [REDACTED] Date of Incident - 16/02/2020 Street Name - Macleod Street, outside Gorgie Social Club there are several large potholes. Some directly out the front of the building and then another around the corner. [REDACTED] Kind regards, [REDACTED] [REDACTED]	RD: CW Pothole	Internal		Committed	50055033
Batch: 41050207 - Inspection Batch		Route: Ad hoc Route			Date: 22/01/2020			
42044453	Pothole	22/01/2020	Os 20a	RD: CW Pothole	Internal		Committed	50050152

Site History Report

Effective: 24/12/2019 to 23/12/2021
Service: Roads General
Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South West Locality	
Batch: 41050205 - Inspection Batch		Route: Ad hoc Route			Date: 22/01/2020			
42044451	Potholes	22/01/2020	Os function hall	RD: CW Pothole	Internal		Committed	50050150
Batch: 41050204 - Inspection Batch		Route: Ad hoc Route			Date: 22/01/2020			
42044449	Road: Defective / Damaged (Enquiry 946524)	22/01/2020	From outside school service entrance to bend	RD: CW Pothole	Internal		Committed	50050147
Batch: 41050202 - Inspection Batch		Route: Ad hoc Route			Date: 22/01/2020			
42044447	Road: Defective / Damaged (Enquiry 946524)	22/01/2020	Near junction with Russel road	RD: CW Pothole	Internal		Committed	50050145
Batch: 41049496 - Inspection Batch		Route: Ad hoc Route			Date: 13/01/2020			
42043701	C/way pot holes	13/01/2020	O/s social Club	RD: CW Pothole	Internal		Committed	50049386
Batch: 41049495 - Inspection Batch		Route: Ad hoc Route			Date: 13/01/2020			
42043700	Road: Defective / Damaged (Enquiry 940409)	13/01/2020	pothole near 20 MCLEOD STREET, EDINBURGH, CITY OF EDINBURGH, EH11 2NH	RD: CW Pothole	Internal		Committed	50049385
Batch: 41049493 - Inspection Batch		Route: Ad hoc Route			Date: 13/01/2020			
42043698		13/01/2020	O/s school entrance	RD: CW Pothole	Internal		Committed	50049383

Customer Services

Enquiry No.: 1273687 **Logged by:** Verint CRM Connector **on:** 12/11/2021 09:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: potholes on this stretch of McLeod Street, on the road and potholes at the edges of the speed bumps, nowhere to drive to avoid them **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1268694 **Logged by:** Verint CRM Connector **on:** 02/11/2021 19:47
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: Because the pedestrian crossing zig-zags have completely worn away here, [REDACTED] can park with impunity, virtually on the crossing. [REDACTED] _ @edinhelp @fountainbridge
Location: It's on Gorgie Road, near the junction with Macleod Street. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1253731 **Logged by:** Verint CRM Connector **on:** 01/10/2021 09:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: pot holes, most of McLeod Street especially bad on the section from Russell road to the left hand turn round to Tynecastle, potholes on speed bumps also **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 24/12/2019 to 23/12/2021
Service: Roads General
Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1141414 **Logged by:** Verint CRM Connector **on:** 16/03/2021 12:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: two potholes that have been missed when repairing the many potholes in this street **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50078667 **Defect Number:** 42064559

Enquiry No.: 1133868 **Logged by:** Verint CRM Connector **on:** 03/03/2021 15:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road looks like fo k have been digging for gold. You'd need an off roader to get through it unscathed. It's been like this for at least 2 years and nothing has been done. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1131741 **Logged by:** Verint CRM Connector **on:** 28/02/2021 22:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole at location shown, not currently identified on map **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1131740 **Logged by:** Verint CRM Connector **on:** 28/02/2021 22:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole at location shown **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1131739 **Logged by:** Verint CRM Connector **on:** 28/02/2021 22:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The entire road is full of potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1130205 **Logged by:** Verint CRM Connector **on:** 26/02/2021 08:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road outside car park of Tynecastle High School is littered with deep potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50080524 **Defect Number:** 42066519

Site History Report

Effective: 24/12/2019 to 23/12/2021
Service: Roads General
Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1129949 **Logged by:** Verint CRM Connector **on:** 25/02/2021 16:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole - 5 MCLEOD STREET, EDINBURGH, CITY OF EDINBURGH, EH11 2NJ **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1129713 **Logged by:** Verint CRM Connector **on:** 25/02/2021 13:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: the whole road is full of potholes and is a nightmare to drive along with the park cars. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1123938 **Logged by:** Verint CRM Connector **on:** 18/02/2021 10:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: @edinhelp That is the absolute state of McLeod Street **Contact:**

Enquiry No.: 1122349 **Logged by:** Verint CRM Connector **on:** 16/02/2021 16:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Getting impossible to drive down as I drive a motorbike there's 26 holes that I counted on this stretch of road alone **Contact:**

Enquiry No.: 1114512 **Logged by:** Verint CRM Connector **on:** 07/02/2021 17:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Entire road is peppered in 2-3 inch deep potholes. Impossible to pass without going in one of them. Road needs majorly addressed it's embarrassing how bad it is for a road. **Contact:**


Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50080525 **Defect Number:** 42066520

Enquiry No.: 1108213 **Logged by:** Verint CRM Connector **on:** 27/01/2021 21:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: approx. 12 large pothole spread throughout the full length of this street **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50080527 **Defect Number:** 42066521



Site History Report

Effective: 24/12/2019 to 23/12/2021
Service: Roads General
Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1023183 **Logged by:** Verint CRM Connector **on:** 16/08/2020 17:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Lots of potholes which has had a negative effect on my car and caused it to need work done **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset



Enquiry No.: 980928 **Logged by:** Verint CRM Connector **on:** 14/04/2020 13:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: potholes on MCLEOD STREET, EDINBURGH, CITY OF EDINBURGH, EH11 2NH **Contact:**
near Russell road

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50055706 **Defect Number:** 42049796

Site History Report

Effective: 24/12/2019 to 23/12/2021

Service: Roads General

Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 980927 Logged by: Verint CRM Connector on: 14/04/2020 13:39
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: road full of potholes - 22B MCLEOD STREET, EDINBURGH, CITY OF EDINBURGH, EH11 2NH Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 975919 Logged by: [REDACTED] on: 17/03/2020 16:18
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.: sent out claim papers From: [REDACTED]
Sent: 15 March 2020 21:12
To: Clarence <Clarence@edinburgh.gov.uk>
Subject: Re: Tyre punctured via potholes
Hi [REDACTED],
[REDACTED] The Information is as follows:
Name - [REDACTED]
Address - [REDACTED]
Telephone Number - [REDACTED]
Date of Incident - 16/02/2020
Street Name - Macleod Street, outside Gorgie Social Club there are several large potholes. Some directly out the front of the building and then another around the corner.
[REDACTED]
Kind regards,
[REDACTED]
Location: outside Gorgie Social Club Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50055033 Defect Number: 42049147

Enquiry No.: 947959 Logged by: Verint CRM Connector on: 23/01/2020 09:50
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: The whole of McLeod street has severe problems with potholes and uneven surfaces, it ruins your car tyres. There is also one at the start of McLeod street if you are coming from Russell Road. Please look at the holes and you will see what I mean. [REDACTED]
Thank you. Contact:

Enquiry No.: 946524 Logged by: Verint CRM Connector on: 21/01/2020 09:42
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Series of potentially damaging potholes on Russell Road - 2 particularly bad ones as you approach Tynecastle. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50050145 Defect Number: 42044447

Site History Report

Effective: 24/12/2019 to 23/12/2021
Service: Roads General
Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 940409 **Logged by:** Verint CRM Connector **on:** 11/01/2020 16:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole near 22 MCLEOD STREET, EDINBURGH, CITY OF EDINBURGH, EH11 2NH **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50049385 **Defect Number:** 42043700

Enquiry No.: 940408 **Logged by:** Verint CRM Connector **on:** 11/01/2020 16:21
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: damaged pavement near 21 MCLEOD STREET, EDINBURGH, CITY OF EDINBURGH, EH11 2NQ **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
4011672	Road: Defective / Damaged (Enquiry 510314) 10 defects in c / way (RD: Asphalt / Bitmac Surface)	Between I / post no 16 & I / post no 18 mcleod Street	RD: Cat 3 - 60 Day	Job Raised	05/06/2017	03/07/2017	Est.
50043877	Road: Defective / Damaged (Enquiry 897722) (RD: CW Setts Depression)	Junction of Gorgie Rd and Mcleod St Paviers at crossing have sunk. Danger to pedestrians and car drivers Reported before	RD: Cat 4 - 12 Months	No code allocated	08/10/2019	08/10/2020	Est.
50049383	RD: CW Pothole	O/s school entrance	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/01/2020	16/01/2020	Act. ROAD/82030482
50049385	Road: Defective / Damaged (Enquiry 940409) (RD: CW Pothole)	pothole near 20 MCLEOD STREET, EDINBURGH, CITY OF EDINBURGH, EH11 2NH	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2020	24/01/2020	Act. ROAD/82030484
50049386	C/way pot holes (RD: CW Pothole)	O/s social Club	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/01/2020	16/01/2020	Act. ROAD/82030485

Site History Report

Effective: 24/12/2019 to 23/12/2021
Service: Roads General
Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50050145	Road: Defective / Damaged (Enquiry 946524) (RD: CW Pothole)	Near junction with Russel road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/01/2020	24/01/2020	Act. ROAD/82031090
50050147	Road: Defective / Damaged (Enquiry 946524) (RD: CW Pothole)	From outside school service entrance to bend	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/01/2020	24/01/2020	Act. ROAD/82031092
50050150	Potholes (RD: CW Pothole)	Os function hall	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/01/2020	24/01/2020	Act. ROAD/82031094
50050152	Pothole (RD: CW Pothole)	Os 20a	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/01/2020	24/01/2020	Act. ROAD/82031096

Site History Report

Effective: 24/12/2019 to 23/12/2021
 Service: Roads General
 Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50055033	Road: Defective / Damaged - sent out claim papers From: [REDACTED] [REDACTED] Sent: 15 March 2020 21:12 To: Clarence <Clarence@edinburgh.gov.uk> Subject: Re: Tyre punctured via potholes Hi [REDACTED], [REDACTED] The Information is as follows: Name - [REDACTED] Address - [REDACTED] [REDACTED] Telephone Number - [REDACTED] [REDACTED] Date of Incident - 16/02/2020 Street Name - Macleod Street, outside Gorgie Social Club there are several large potholes. Some directly out the front of the building and then another around the corner. [REDACTED] Kind regards, [REDACTED] [REDACTED] (Enquiry 9/5919) (RD: CW Pothole)	sent out claim papers From: [REDACTED] scott [REDACTED] Sent: 15 March 2020 21:12 To: Clarence <Clarence@edinburgh.gov.uk> Subject: Re: Tyre punctured via potholes Hi [REDACTED], [REDACTED] The Information is as follows: Name - [REDACTED] Address - [REDACTED] [REDACTED] Telephone Number - [REDACTED] [REDACTED] Date of Incident - 16/02/2020 Street Name - Macleod Street, outside Gorgie Social Club there are several large potholes. Some directly out the front of the building and then another around the corner. [REDACTED] Kind regards, [REDACTED] [REDACTED]	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/03/2020	23/03/2020	Act. ROAD/82035304
50055705	Potholes (RD: CW Pothole)	After bend see map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/04/2020	22/04/2020	Act. ROAD/82035874

Site History Report

Effective: 24/12/2019 to 23/12/2021

Service: Roads General

Site: Mcleod Street (7903443)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South West Locality		
50055706	Road: Defective / Damaged (Enquiry 980928) (RD: CW Pothole)	From school entrance to Russel road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/04/2020	22/04/2020	Act. ROAD/82035875
50055707	Road: Defective / Damaged (Enquiry 980928) (RD: CW Pothole)	From school entrance to Russel roas	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/04/2020	22/04/2020	Act. ROAD/82035876
50058228	Refresh giveway markings (RD: Markings Refresh)	McLeod street art Russel road	Non Routine (One Off Works)	Job Complete	09/07/2020	17/07/2020	Act. ROAD/82037632
50069566	2 x potholes (RD: CW Pothole)	Near number 20A on cw	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2020	14/12/2020	Act. ROAD/82042296
50069567	Pothole on cw (RD: CW Pothole)	Across from stadium (see pics)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2020	14/12/2020	Act. ROAD/82042297
50069568	2 x potholes (RD: CW Pothole)	Near tyncastle high school service entrance next to football pitch	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2020	14/12/2020	Act. ROAD/82042298
50076973	Multiple pot holes (RD: CW Pothole)	O/s new Hearts stand	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/03/2021	03/03/2021	Act. ROAD/82046071
50076974	C/way pot holes (RD: CW Pothole)	At away supports gate	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/03/2021	03/03/2021	Act. ROAD/82046072
50076985	Multiple pot holes see attached photos (RD: CW Pothole)	From old Tynecastle school to Russel Rd	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/03/2021	05/03/2021	Act. ROAD/82046082
50078667	Road: Defective / Damaged (Enquiry 1141414) (RD: CW Pothole)	two potholes that have been missed when repairing the many potholes in this street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2021	18/03/2021	Act. ROAD/82047106
50080524	Pothole(Enquiry 1130205) (RD: CW Pothole)	At street lighting column MGC17	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/04/2021	09/04/2021	Act. ROAD/82048261
50080525	Potholes(Enquiry 1114512) (RD: CW Pothole)	At street lighting column no.MGC15	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/04/2021	09/04/2021	Act. ROAD/82048262
50080527	potholes (Enquiry 1108213) (RD: CW Pothole)	Outside 20/A	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/04/2021	09/04/2021	Act. ROAD/82048263
50095746	4no c/w potholes (RD: CW Pothole)	At lamppost no17	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/11/2021	04/11/2021	Act. ROAD/82055750