

Effective: 01/02/2016 to 10/02/2022

Asset Number: 1.00 to 5.00

Display Action Officer: No

Site: Barnton Park Avenue (7900194)

Site: Barnton Park Avenue (7900194)

Locality: Barnton, Edinburgh, City of Edinburgh

Area: North West Locality

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street - excluding private access to No.s42-44			Feature Type: Road Asset		Area: North West Locality	
Batch: 41110853 - Inspection Batch		Route: NW_CF2_BarntonParkEast1				Date: 16/12/2021		
42087425	5 cw potholes.	16/12/2021	No 42 at Woodlands Court car pat entrance	RD: CW Pothole	Internal		Uncommitted	50068550
42087430	1 cw pothole	16/12/2021	No 101	RD: CW Pothole	Internal		Uncommitted	50068585
42087426	Ramp markings require to be refreshed	16/12/2021	Whole street	RD: Markings Refresh	Internal		Uncommitted	50068573
42087420	Refresh all markings	16/12/2021	Entire cw including all junctions	RD: Markings Refresh	Internal		Uncommitted	50100560
42087429	1 cw pothole	16/12/2021	No 93	RD: CW Pothole	Internal		Uncommitted	50068583
42087428	2cw potholes	16/12/2021	No 91	RD: CW Pothole	Internal		Uncommitted	50068582
Batch: 41109724 - Inspection Batch		Route: Ad hoc Route				Date: 07/12/2021		
42086185	Road: Defective / Damaged (Enquiry 1285831) Pothole on carriageway repair in hra	07/12/2021	Outside 26	RD: CW Pothole	Internal		Committed	50099497
Batch: 41105399 - Inspection Batch		Route: Ad hoc Route				Date: 26/10/2021		
42081221	Road: Defective / Damaged (Enquiry 1264323) opening on footway not completed	26/10/2021	Outside 64	RU: Utility Live Site	Internal		Uncommitted	50094812
Batch: 41098633 - Inspection Batch		Route: Ad hoc Route				Date: 20/08/2021		
42076411	Pothole on carriageway	20/08/2021	Barnton Park Avenue outside 2	RD: CW Pothole	Internal		Committed	50090101
Batch: 41080125 - Inspection Batch		Route: Ad hoc Route				Date: 01/02/2021		
42060035	Road: Defective / Damaged (Enquiry 1110191) pothole on carriageway	01/02/2021	Several large potholes on both sides of the road at the Barnton Park Drive junction	RD: CW Pothole	Internal		Committed	50073432
Batch: 41070004 - Inspection Batch		Route: NW_CF2_BarntonParkEast1				Date: 30/11/2020		
42056201	Fw breaking at kerb. 0.5 x 0.5 m	30/11/2020	No 42 junction at garages. Near no 38	RD: FW HRA Cracked/Broken	Internal		Action Required	
42056178	1 cw pothole at crossing	30/11/2020	No 98 at junction	RD: CW Pothole	Internal		Committed	50068536
42056194	2 cw potholes at crossing	30/11/2020	No 42 at junction.	RD: CW Pothole	Internal		Committed	50068549
42056179	Low fw box	30/11/2020	No 60	RU: Utility Apparatus	Internal		Uncommitted	50068537
42056226	Cw depressed 1 x 1 m	30/11/2020	No 43	RD: CW Rutting	Internal		Action Required	
42056205	Small fw pothole	30/11/2020	No 28	RD: FW HRA Pothole	Internal		Action Required	
42056218	Fw breaking up at kerb . 2 x. 0.5 m	30/11/2020	No 21 at driveway	RD: FW HRA Cracked/Broken	Internal		Action Required	
42056228	1 cw pothole	30/11/2020	No 93	RD: CW Pothole	Internal		No Action Required	
42056229	1 cw pothole	30/11/2020	No 101	RD: CW Pothole	Internal		No Action Required	
42056212	Fw depressed 0,5 x 0.5 m	30/11/2020	No 14 at driveway	RD: FW HRA Depression/Sunker	Internal		Action Required	
42056217	Ramp markings require to be refreshed	30/11/2020	Whole street	RD: Markings Refresh	Internal		No Action Required	
42056184	Cw broken/potholed 4x 1. 1 x 1 and 2 x 2 m.	30/11/2020	No 50 a	RD: CW Cracked/Broken	Internal		Committed	50068541
42056208	Fw breaking and raised. possible tree route damage. 3 x 0.5 m	30/11/2020	No 26	RD: FW HRA Cracked/Broken	Internal		Action Required	
42056197	Fw breaking at kerb. 8 x 0.5 m	30/11/2020	At 44 Woodlands Court	RD: FW HRA Cracked/Broken	Internal		Action Required	

Effective: 01/02/2016 to 10/02/2022

Asset Number: 1.00 to 5.00

Display Action Officer: No

Site: Barnton Park Avenue (7900194)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street - excluding private access to No.s42-44		Feature Type: Road Asset		Area: North West Locality		
Batch: 41070004 - Inspection Batch		Route: NW_CF2_BarntonParkEast1				Date: 30/11/2020		
42056195	5 cw potholes.	30/11/2020	No 42 at Woodlands Court car pat entrance	RD: CW Pothole	Internal		No Action Required	
42056215	Fw breaking up. 2 x. 0.5 m	30/11/2020	No 7 near no 5	RD: FW HRA Cracked/Broken	Internal		Action Required	
42056177	Cw depressed at manhole 1 x 1 m.	30/11/2020	No 76	RD: CW Subsidence/Heaving	Internal		Action Required	
42056232	Open joint in centre of cw 3 x 0.2	30/11/2020	Junction of Barnton Park Drive	RD: CW Open Joint	Internal		Action Required	
42056173	Low fw box	30/11/2020	No 104 at driveway	RU: Utility Apparatus	Internal		Uncommitted	50068518
42056213	2 cw potholes at crossing	30/11/2020	Junction of Barnton Park Drive	RD: CW Pothole	Internal		Committed	50068570
42056198	Cw broken/potholed 2 x 2 m	30/11/2020	No 42 ( Woolands Park ) at junction	RD: CW Cracked/Broken	Internal		Committed	50068552
42056193	High fw box with surround breaking up	30/11/2020	Opp no 37	RU: Utility Apparatus	Internal		Uncommitted	50068548
42056175	4 cw potholes	30/11/2020	Junction at no 98	RD: CW Pothole	Internal		Action Required	
42056222	Small fw pothole	30/11/2020	No 31	RD: FW HRA Pothole	Internal		Action Required	
42056196	Cw broken/potholed 20 x 1 m. 2 x 1. 1 x 1. And 4 x 1	30/11/2020	At No 44 Woodlands Court	RD: CW Cracked/Broken	Internal		Committed	50068551
42056227	2cw potholes	30/11/2020	No 91	RD: CW Pothole	Internal		No Action Required	
42056223	Fw breaking up at kerb . 2 x. 0.5 m	30/11/2020	No 37 at driveway	RD: FW HRA Cracked/Broken	Internal		Action Required	
42056180	5 cw potholes	30/11/2020	No 50 a	RD: CW Pothole	Internal		Action Required	
42056176	2 cw potholes	30/11/2020	No 86	RD: CW Pothole	Internal		Action Required	
Batch: 41059971 - Inspection Batch		Route: Ad hoc Route				Date: 08/07/2020		
42051489	11 Carriageway potholes. Make safe.	08/07/2020	At junction with Barnton park Drive	RD: CW Pothole	Internal		Committed	50058162
Batch: 41046987 - Inspection Batch		Route: Ad hoc Route				Date: 02/12/2019		
42041837	Carriageway potholes, make safe. Road: Defective / Damaged (Enquiry 889747)	02/12/2019	Barnton Park Avenue at junction with Barnton Park Drive	RD: CW Pothole	Internal		Committed	50046805
Batch: 41032308 - Inspection Batch		Route: Ad hoc Route				Date: 06/05/2019		
42030367	Road: Defective / Damaged (Enquiry 827956)	06/05/2019	Potholes on car park carriageway outside no 42	RD: CW Pothole	Internal		Committed	50032432
Hot temp make safe								
Batch: 41030767 - Inspection Batch		Route: Ad hoc Route				Date: 12/04/2019		
42029329	Road: Defective / Damaged (Enquiry 822201)	12/04/2019	Potholes on carriageway at junction with Barnton park drive	RD: CW Pothole	Internal		Committed	50030955
Hot temp make safe								
Batch: 41027220 - Inspection Batch		Route: Ad hoc Route				Date: 13/02/2019		
42026099	Road: Defective / Damaged (Enquiry 797080) dig out damaged carriageway and resurface in HRA	13/02/2019	Carriageway breaking up leaving uneven surface , at junction with Barton park drive	RD: CW Cracked/Broken	Internal		Action Required	

Effective: 01/02/2016 to 10/02/2022

Asset Number: 1.00 to 5.00

Display Action Officer: No

Site: Barnton Park Avenue (7900194)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Whole Street - excluding private access to No.s42-44			<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
<b>Batch:</b>	41027219 - Inspection Batch		<b>Route:</b> Ad hoc Route				<b>Date:</b> 13/02/2019	
42026098	Road: Defective / Damaged (Enquiry 797080)	13/02/2019	Potholes on carriageway at junction with Barnton park drive	RD: CW Pothole	Internal		Committed	50026013
Hot temp make safe								
<b>Batch:</b>	41015980 - Inspection Batch		<b>Route:</b> NW_CF2_BarntonParkEast1				<b>Date:</b> 04/08/2018	
42016504	Hot temp make safe	04/08/2018	Potholes on carriageway outside no 101	RD: CW Pothole	Internal		Committed	50013930
42016503	Dig out damaged carriageway & resurface in HRA	04/08/2018	Carriageway rutting outside no 103	RD: CW Rutting	Internal		Uncommitted	50013929
42016506	Hot temp make safe	04/08/2018	Potholes on carriageway outside no 42 next to l / p 25	RD: CW Pothole	Internal		Committed	50013932
42016505	Hot temp make safe	04/08/2018	Pothole on carriageway outside no 97	RD: CW Pothole	Internal		Committed	50013931
42016501	Hot temp make safe	04/08/2018	Potholes on carriageway outside no 103	RD: CW Pothole	Internal		Committed	50013927
42016502	Hot temp make safe	04/08/2018	Potholes on carriageway outside no 103	RD: CW Pothole	Internal		Committed	50013928
<b>Batch:</b>	41007567 - Inspection Batch		<b>Route:</b> Ad hoc Route				<b>Date:</b> 06/04/2018	
42007125	Road: Defective / Damaged (Enquiry 628834) bot temp make safe	06/04/2018	Pothole on carriageway outside no 42 at entrance to car park	RD: CW Pothole	Internal		Committed	50006324
<b>Batch:</b>	41004257 - Inspection Batch		<b>Route:</b> Ad hoc Route				<b>Date:</b> 20/02/2018	
42003833	Pothole	20/02/2018	93	RD: CW Pothole	Internal		Committed	50003510
<b>Batch:</b>	41004256 - Inspection Batch		<b>Route:</b> Ad hoc Route				<b>Date:</b> 20/02/2018	
42003832	Road: Defective / Damaged (Enquiry 619418) pothole	20/02/2018	Outside 112	RD: CW Pothole	Internal		Committed	50003509
<b>Batch:</b>	41004255 - Inspection Batch		<b>Route:</b> Ad hoc Route				<b>Date:</b> 20/02/2018	
42003831	Road: Defective / Damaged (Enquiry 619417) potholes x 2	20/02/2018	pothole at junction of Barnton Park Drive	RD: CW Pothole	Internal		Committed	50003508
<b>Batch:</b>	41002217 - Inspection Batch		<b>Route:</b> Ad hoc Route				<b>Date:</b> 24/01/2018	
42001901	Road: Defective / Damaged (Enquiry 606289) remove lose material and make safe	24/01/2018	This is the roadway entrance into blocks of flats at 42 and 44 Barnton Park Ave	RD: CW Pothole	Internal		Committed	50001762
<b>Batch:</b>	25008468 - Inspection Batch		<b>Route:</b> RD: Ad-Hoc Inspection North				<b>Date:</b> 23/01/2017	
25008288	Hot temp make safe	23/01/2017	Pothole on carriageway at car park eara outside no 42	RD: CLARENCE Response	Internal		Committed	5008412
<b>Batch:</b>	25008455 - Inspection Batch		<b>Route:</b> WE1_CF2_BarntonParkEast1				<b>Date:</b> 21/01/2017	
25008267	Pothole on carriageway	21/01/2017	Junction Barnton Park Drive	RD: CLARENCE Response	Internal		Committed	5008391
25008268	Pothole on carriageway	21/01/2017	Outside 42	RD: CLARENCE Response	Internal		Committed	5008392
<b>Batch:</b>	25007171 - Inspection Batch		<b>Route:</b> RD: Ad-Hoc Inspection North				<b>Date:</b> 28/10/2016	
25007203	1xdefect at gully	28/10/2016	Outside house no 93 at gully surroundings	RD: CLARENCE Response	Internal		Committed	5007329

Effective: 01/02/2016 to 10/02/2022

Asset Number: 1.00 to 5.00

Display Action Officer: No

Site: Barnton Park Avenue (7900194)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street - excluding private access to No.s42-44			Feature Type: Road Asset		Area: North West Locality	
Batch: 25005941 - Inspection Batch			Route: RD: Ad-Hoc Inspection North				Date: 15/06/2016	
25006161	Road: Defective / Damaged (Enquiry 368741)	15/06/2016	Junction of Barnton park ave at BT cover	RD: CLARENCE Response	Internal		Committed	5006284

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Whole Street - excluding private access to No.s42-44		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
5000358	Give Way faded (RD: Road Marking & Studs)	Outside 42	RD: Cat 4 - 12 Months	Job Complete	13/10/2014	22/02/2016	Act. RSTO16/59000159
5004409	Markings faded on speed ramp (RD: Road Marking & Studs)	Outside 99	RD: Cat 4 - 12 Months	Job Complete	12/12/2015	11/08/2018	Act. RSTO16/59000159
5004411	Broken kerb (RD: Kerbs)	Outside 55	RD: Cat 4 - 12 Months	Job Complete	12/12/2015	14/06/2016	Act. RSTO16/59000241
5004412	Give Way faded (RD: Road Marking & Studs)	Outside 42	RD: Cat 4 - 12 Months	Job Complete	12/12/2015	19/01/2017	Act. RSTO16/59000159
5004414	Loose kerb (RD: Kerbs)	Outside 44	RD: Cat 4 - 12 Months	Job Complete	12/12/2015	14/06/2016	Act. RSTO16/59000237
5006284	Road: Defective / Damaged (Enquiry 368741) (RD: CLARENCE Response)	Junction of Barnton park ave at BT cover	RD: Cat 2 - 5 Day	Job Complete	15/06/2016	16/06/2016	Act. RD01/50003869
5007329	1xdefect at gully (RD: CLARENCE Response)	Outside house no 93 at gully surroundings	RD: Cat 2 - 5 Day	Job Complete	28/10/2016	01/11/2016	Act. RD01/50004432
5008391	Pothole on carriageway (RD: CLARENCE Response)	Junction Barnton Park Drive	RD: Cat 2 - 5 Day	Job Complete	21/01/2017	23/01/2017	Act. RD01/50005180
5008392	Pothole on carriageway (RD: CLARENCE Response)	Outside 42	RD: Cat 2 - 5 Day	Job Complete	21/01/2017	23/01/2017	Act. RD01/50005181
5008412	Hot temp make safe (RD: CLARENCE Response)	Pothole on carriageway at car park eara outside no 42	RD: Cat 2 - 5 Day	Job Complete	23/01/2017	24/01/2017	Act. RD01/50005195
50001762	Road: Defective / Damaged (Enquiry 606289) remove lose material and make safe (RD: CW Pothole)	This is the roadway entrance into blocks of flats at 42 and 44 Barnton Park Ave	RD: Cat 3 - 60 Day	Job Complete	24/01/2018	26/01/2018	Act. ROAD/82001333
50003508	Road: Defective / Damaged (Enquiry 619417) potholes x 2 (RD: CW Pothole)	pothole at junction of Barnton Park Drive	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/02/2018	21/02/2018	Act. ROAD/82002743
50003509	Road: Defective / Damaged (Enquiry 619418) pothole (RD: CW Pothole)	Outside 112	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/02/2018	21/02/2018	Act. ROAD/82002744
50003510	Pothole (RD: CW Pothole)	93	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/02/2018	21/02/2018	Act. ROAD/82002745
50006324	Road: Defective / Damaged (Enquiry 628834) bot temp make safe (RD: CW Pothole)	Pothole on carriageway outside no 42 at entrance to car park	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/04/2018	11/04/2018	Act. ROAD/82005122
50013927	Hot temp make safe (RD: CW Pothole)	Potholes on carriageway outside no 103	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/08/2018	06/08/2018	Act. ROAD/82011056
50013928	Hot temp make safe (RD: CW Pothole)	Potholes on carriageway outside no 103	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/08/2018	06/08/2018	Act. ROAD/82011057

Effective: 01/02/2016 to 10/02/2022

Asset Number: 1.00 to 5.00

Display Action Officer: No

Site: Barnton Park Avenue (7900194)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b> 1.00		<b>Asset - Locn.:</b> Whole Street - excluding private access to No.s42-44		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50013929	Dig out damaged carriageway & resurface in HRA (RD: CW Rutting)	Carriageway rutting outside no 103	RD: Cat 4 - 12 Months	Job Cancelled	04/08/2018	04/08/2019	Est.
50013930	Hot temp make safe (RD: CW Pothole)	Potholes on carriageway outside no 101	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/08/2018	06/08/2018	Act. ROAD/82011058
50013931	Hot temp make safe (RD: CW Pothole)	Pothole on carriageway outside no 97	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/08/2018	06/08/2018	Act. ROAD/82011059
50013932	Hot temp make safe (RD: CW Pothole)	Potholes on carriageway outside no 42 next to l / p 25	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/08/2018	06/08/2018	Act. ROAD/82011060
50026013	Road: Defective / Damaged (Enquiry 797080)	Potholes on carriageway at junction with Barnton park drive	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/02/2019	14/02/2019	Act. ROAD/82017665
	Hot temp make safe (RD: CW Pothole)						
50030955	Road: Defective / Damaged (Enquiry 822201)	Potholes on carriageway at junction with Barnton park drive	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/04/2019	15/04/2019	Act. ROAD/82020093
	Hot temp make safe (RD: CW Pothole)						
50032432	Road: Defective / Damaged (Enquiry 827956)	Potholes on car park carriageway outside no 42	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/05/2019	07/05/2019	Act. ROAD/82020908
	Hot temp make safe (RD: CW Pothole)						
50046805	Carriageway potholes, make safe Road: Defective / Damaged (Enquiry 889747) (RD: CW Pothole)	Barnton Park Avenue at junction with Barnton Park Drive	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/12/2019	03/12/2019	Act. ROAD/82028804
50058162	11 Carriageway potholes. Make safe. (RD: CW Pothole)	At junction with Barnton park Drive	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/07/2020	09/07/2020	Act. ROAD/82037566
50068518	Low fw box (RU: Utility Apparatus)	No 104 at driveway	RU: Fail Med.Risk (Apparatus)	Job Complete	30/11/2020	30/11/2020	Act.
50068536	1 cw pothole at crossing (RD: CW Pothole)	No 98 at junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/11/2020	30/11/2020	Act. ROAD/82041775
50068537	Low fw box (RU: Utility Apparatus)	No 60	RU: Fail Low Risk	Job Complete	30/11/2020	30/11/2020	Act.
50068541	Cw broken/potholed 4x 1. 1 x 1 and 2 x 2 m. (RD: CW Cracked/Broken)	No 50 a	RD: Cat 4 - 12 Months	RD: Made Safe Job Complete	30/11/2020	17/06/2021	Act. ROAD/82041859
50068548	High fw box with surround breaking up (RU: Utility Apparatus)	Opp no 37	RU: Fail Low Risk	Job Complete	30/11/2020	30/11/2020	Act.
50068549	2 cw potholes at crossing (RD: CW Pothole)	No 42 at junction.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/11/2020	30/11/2020	Act. ROAD/82041782
50068550	5 cw potholes. (RD: CW Pothole)	No 42 at Woodlands Court car pat entrance	RD: Cat 4 - 12 Months	Job Annulled	30/11/2020	30/11/2021	Est.

Effective: 01/02/2016 to 10/02/2022

Asset Number: 1.00 to 5.00

Display Action Officer: No

Site: Barnton Park Avenue (7900194)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b> 1.00		<b>Asset - Locn.:</b> Whole Street - excluding private access to No.s42-44		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50068551	Cw broken/potholed 20 x 1 m. 2 x 1. 1 x 1. And 4 x 1 (RD: CW Cracked/Broken)	At No 44 Woodlands Court	RD: Cat 4 - 12 Months	RD: Made Safe Job Complete	30/11/2020	18/06/2021	Act. ROAD/82041855
50068552	Cw broken/potholed 2 x 2 m (RD: CW Cracked/Broken)	No 42 ( Woolands Park ) at junction	RD: Cat 4 - 12 Months	RD: Made Safe Job Complete	30/11/2020	18/06/2021	Act. ROAD/82041854
50068570	2 cw potholes at crossing (RD: CW Pothole)	Junction of Barnton Park Drive	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/11/2020	30/11/2020	Act. ROAD/82041792
50068573	Ramp markings require to be refreshed (RD: Markings Refresh)	Whole street	RD: Cat 4 - 12 Months	Job Annulled	30/11/2020	30/11/2021	Est.
50068582	2cw potholes (RD: CW Pothole)	No 91	RD: Cat 4 - 12 Months	Job Annulled	30/11/2020	30/11/2021	Est.
50068583	1 cw pothole (RD: CW Pothole)	No 93	RD: Cat 4 - 12 Months	Job Annulled	30/11/2020	30/11/2021	Est.
50068585	1 cw pothole (RD: CW Pothole)	No 101	RD: Cat 4 - 12 Months	Job Annulled	30/11/2020	30/11/2021	Est.
50073432	Road: Defective / Damaged (Enquiry 1110191) pothole on carriageway (RD: CW Pothole)	Several large potholes on both sides of the road at the Barnton Park Drive junction	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/02/2021	05/02/2021	Act. ROAD/82044037
50090101	Pothole on carriageway (RD: CW Pothole)	Barnton Park Avenue outside 2	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/08/2021	22/08/2021	Act. ROAD/82053470
50094812	Road: Defective / Damaged (Enquiry 1264323) opening on footway not completed (RU: Utility Live Site)	Outside 64	RU: Fail Low Risk	Job Complete	26/10/2021	26/10/2021	Act.
50099497	Road: Defective / Damaged (Enquiry 1285831) Pothole on carriageway repair in hra (RD: CW Pothole)	Outside 26	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/12/2021	08/12/2021	Act. ROAD/82057225
50100560	Refresh all markings (RD: Markings Refresh)	Entire cw including all junctions	RD: Cat 4 - 12 Months	No code allocated	16/12/2021	16/12/2022	Est.