

35929 Clerwood Park Pathway

We would be grateful if you could please provide:

Inspection, maintenance and repair records for the pathway running along the bottom of Clerwood Park, Edinburgh from 2015 – 2022.

Please refer to the 'Condition Survey' and 'Maintenance Management' sections of the attached Site History Report.

Records of any complaints made in respect of this pathway from 2015 – 2022.

Please refer to the 'Customer Services' section of the attached Site History Report.

Third party personal information has been redacted from the document provided in compliance with the Data Protection Act 2018. Further redactions have been applied where the information is not within scope of the request, i.e. where it is clear that it does not relate to the specific pathway described in the request. Where it is unclear from the description which specific area is being referred to, this has been provided.

Record of any accident occurring on this pathway.

There is no such record held.