Effective: 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Display Action Officer: Yes

Site: Edinburgh Road (7903508)

Locality: Cramond, Edinburgh, City of Edinburgh

Area: North West Locality

**Customer Services** 

Enquiry No.: 1331289 Logged by: Verint CRM Connector on: 21/02/2022 16:50 Officer: Ronnie Murray
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Drains blocked along the length of B924 Contact:

Reported a month ago.

With recent rain road is now under water and flooding through entrance and into

Newhalls Gate House

Also eroding stone wall from vehicles splashing and dangerous for vehicles to travel

through.

Similar issues on Main street to Dalmeny.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1329513 Logged by: Verint CRM Connector on: 18/02/2022 15:56 Officer: Road Ops Live Enquiries

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole northbound on road to dalmeny Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enguiry No.: 1322100 Logged by: Verint CRM Connector on: 07/02/2022 20:19 Officer: Road Ops Live Enguiries

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Huge pot hole Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

**Job Number**: 50105866 **Defect Number**: 42092460

Enquiry No.: 1301929 Logged by: Verint CRM Connector on: 06/01/2022 12:01 Officer: Road Ops Live Enquiries

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: massive pot hole - level with entrance to Leuchold gate Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

 Job Number: 50102009
 Defect Number: 42088483

 Enquiry No.: 1266792
 Logged by: Verint CRM Connector
 on: 29/10/2021 22:22
 Officer: Michael Wright

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Once again the pot hole as opened up again and I hit this tonight on my way home **Contact:** 

with some force, I'm not sure of the damage until see it in the light. This keeps getting half baked repairs and the hold just keeps coming back. Please fix thi

properly

Effective: 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Display Action Officer: Yes

<b>^</b>	•
( Tuctomoi	CARVICAC
Custome	Services

Logged by: Verint CRM Connector **Enquiry No.: 1266778** 

Subject: Road: Defective / Damaged

on: 29/10/2021 21:34

on: 29/10/2021 17:33

Officer: Michael Wright

Desc.:

Location: Gigantic pothole, difficult to see as full of water. On B924 heading towards

Queensferry. Just after the bridge crossing A90 when you come off at the

Dalmeny/Craigie exit.

Plot Number: 1.00 Feature Id - Location: Whole Street

Enquiry No.: 1266697 Logged by: Verint CRM Connector

Feature Type: Road Asset

Officer: Michael Wright

Service: Roads General

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Classification: Request for service

Feature Type: Road Asset

Feature Type: Road Asset

Feature Type: Road Asset

Desc.:

Location: Pothole

Contact:

Contact:

Contact:

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street

Logged by: Verint CRM Connector

on: 29/10/2021 12:33

Officer: Michael Wright

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Classification: Request for service

Officer: Ronnie Murray

Desc.:

Plot Number: 1.00

Plot Number: 1.00

**Enquiry No.:** 1266495

Location: Huge pothole

Feature Id - Location: Whole Street Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 14/07/2021 23:26

Officer: Ronnie Murray

Service: Roads General

Enquiry No.: 1208420 Desc.:

**Location:** Massive pothole

Contact:

Feature Id - Location: Whole Street

Job Number: 50087497 Defect Number: 42073566

> Logged by: Verint CRM Connector on: 31/05/2021 17:30

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Enquiry No.:** 1183373

Location: Large crater of a hole in the north bound lane once you leave the A90 heading for

Dalmeny on the B924.

On Sunday 30th May '21 at 13:45hrs whilst travelling home my vehicle NSF and NSR wheels hit the unavoidable hole causing visible damage to the NSF tyre.

Please advise the process for recovering the cost from

you for repairing the damage.

Please note, when the vehicle is taken to the garage for the repair a full inspection

will be carried out and the findings issued to you wrt hidden damage.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1182860 Logged by: Verint CRM Connector on: 30/05/2021 18:02 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** 1m x 0.5m pot hole. Towards Dalmeny direction. Contact:

Effective: 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Officer: Ronnie Murray

**Display Action Officer:** Yes

Custome	r Services
Gactonio	00.1.000

Enquiry No.: 1182577 Logged by: Verint CRM Connector on: 29/05/2021 19:30
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: West bound similar area to where there was an issue with people damaging there Contact:

cars

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1182399 Logged by: Verint CRM Connector on: 29/05/2021 12:17 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Huge pothole on the road. Swerving to avoid it takes you into oncoming traffic **Contact:** 

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1182317 Logged by: Verint CRM Connector on: 29/05/2021 08:59 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Huge very deep pot hole. Over one foot deep and half a meter wide **Contact:** 

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

**Job Number:** 50084174 **Defect Number:** 42069932

Enquiry No.: 1182303 Logged by: Verint CRM Connector on: 29/05/2021 07:54 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Large pothole of hit will cause serious damage to a car Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1176264 Logged by: Verint CRM Connector on: 17/05/2021 14:52 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Lots of potholes along this stretch of road Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1173482 Logged by: Verint CRM Connector on: 11/05/2021 23:41 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Potholes dotted all down this road on both sides. Been there a long time. Please fix **Contact:** 

as will damage car

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1114222 Logged by: Verint CRM Connector on: 07/02/2021 09:47 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Large pothole Contact:

Could cause an accident

Effective: 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Officer: Ronnie Murray

**Display Action Officer:** Yes

<b>^</b>	•
( Tuctomoi	CARVICAC
Custome	Services

**Enquiry No.:** 1114114 **Logged by:** Verint CRM Connector **on:** 06/02/2021 17:04

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Huge pothole. Deep and beside sivor

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1113906 Logged by: Verint CRM Connector on: 06/02/2021 10:49 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pot hole large probable vehicle damage Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1113473 Logged by: Verint CRM Connector on: 05/02/2021 12:50 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Large pot holes on road. The same pot holes that have been filled last week and the Contact:

week before very badly.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1111233 Logged by: Verint CRM Connector on: 02/02/2021 11:38 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Plot Number: 1.00

**Location:** Pot hole reported has yet to be repaired. This is significant hole and will damage **Contact:** 

tyre/car if hit and possible cause an accident

Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1110242 Logged by: Verint CRM Connector on: 31/01/2021 19:27 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Massive pothole inside lane a90 southbound c1 mile north of cramond brig Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1110167 Logged by: Verint CRM Connector on: 31/01/2021 16:39 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Deep and dangerous pothole inside lane A90 edinburgh bound just at Queensferry **Contact:** 

on ramp

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1110112 Logged by: Verint CRM Connector on: 31/01/2021 15:23 Officer: Ronnie Murray

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** huge pothole when leaving the slip road onto the A90 **Contact:** 

Effective: 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Display Action Officer: Yes

Logged by: Verint CRM Connector **Enquiry No.:** 1109919

Subject: Road: Defective / Damaged

on: 31/01/2021 08:44

Officer: Ronnie Murray

Service: Roads General Desc.:

Location: Pothole

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street

Enquiry No.: 1109913 Logged by: Verint CRM Connector on: 31/01/2021 08:11

Officer: Ronnie Murray

Officer: Ronnie Murray

Officer: Ronnie Murray

Officer: Ronnie Murray

Service: Roads General

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Classification: Request for service

Desc.:

Location: Major pot hole on slip into A90. This is main Bus route and main road from

queensferry/Dalmeny into A90.

Contact:

Feature Id - Location: Whole Street Plot Number: 1.00

> Logged by: Verint CRM Connector on: 19/01/2021 15:15

Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Enauiry No.:** 1103167

Location: Pothole in middle of road

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street

Feature Type: Road Asset on: 19/01/2021 15:11

**Enguiry No.:** 1103159

Logged by: Verint CRM Connector

Classification: Request for service

Service: Roads General Desc.:

Location: Several potholes in middle of road

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street Logged by: Verint CRM Connector

on: 06/01/2021 15:24

**Enquiry No.:** 1095769

Subject: Road: Defective / Damaged

Subject: Road: Defective / Damaged

Classification: Request for service

Service: Roads General

Desc.:

Location: Major road defect - large pothole.

Main bus route No 43 serving Sth Queensferry<>Edinburgh. Contact:

Un-lid road so no visible in non-daylight hours

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Feature Type: Road Asset

Feature Type: Road Asset

Feature Type: Road Asset

Enquiry No.: 1095228

Logged by: Verint CRM Connector

on: 05/01/2021 21:28

Officer: Ronnie Murray

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Feature Id - Location: Whole Street

Desc.:

Plot Number: 1.00

Location: Now a VERY large pot hole on north carriageway (heading into South Queensferry).

Contact:

Feature Type: Road Asset

**Enguiry No.:** 1095126

Logged by: Verint CRM Connector

on: 05/01/2021 18:20

Officer: Ronnie Murray

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Contact:

Plot Number: 1.00

Location: Massive pothole in road which may have damaged tyre.

Feature Id - Location: Whole Street Job Number: 50071355 Defect Number: 42058341

Feature Type: Road Asset

Effective: 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Feature Type: Road Asset

Display Action Officer: Yes

**Customer Services** 

Enquiry No.: 1094891

Logged by: Verint CRM Connector Subject: Road: Defective / Damaged

on: 05/01/2021 14:31 Classification: Request for service Officer: Ronnie Murray

Desc.:

Location: Large deep pothole on left-hand dude of the road coming into Dalmeny /

Queensferry. Unable to stop due to speed of traffic on road and where pothole

Feature Id - Location: Whole Street

located but would be extremely dangerous if car we to hit or end up in it.

Contact:

Plot Number: 1.00 **Enquiry No.:** 1054187

Logged by: Verint CRM Connector

on: 15/10/2020 01:19

Officer: Ronnie Murray

Service: Roads General

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: Most roads in Edinburgh are a disgrace I think you need to get a team of workers out Contact:

to look at the condition, absolutely the worst roads I've ever had the displeasure to

drive on... Come on

Enquiry No.: 1042371

Logged by: Verint CRM Connector

on: 20/09/2020 03:05

Officer: Ronnie Murray

Service: Roads General Subject: Road Markings: Defective

Classification: Request for service

**Desc.:** What type of sign is it? Road sign problem, type unlit

Location: Road markings (white lines, yellow lines, speed bump arrows) have nearly all rubbed Contact:

away and the road is essentially just tarmac and a free for all

**Enquiry No.: 996757** 

Logged by: Verint CRM Connector Subject: Road: Defective / Damaged on: 19/06/2020 22:07

Classification: Request for service

Officer: ESDO West Neighbourhood 2

Service: Roads General

Desc.:

Location: Overgrown grass by B924 road making impossible to see oncoming traffic on the

Contact:

junction with Bankhead road. Very dangerous. Large amount needs to be cut not like

last year not even a meter....

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

**Enquiry No.: 975030** 

Logged by: Verint CRM Connector

on: 15/03/2020 16:41

Officer: ESDO West Neighbourhood 2

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: Large pothole in centre of road, just before bridge

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Contact:

**Effective:** 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Display Action Officer: Yes

Customer Services

Logged by: Verint CRM Connector **Enquiry No.: 974370** 

on: 13/03/2020 09:03

Classification: Request for service

Classification: Request for service

Officer: ESDO West Neighbourhood 2

Desc.:

Location: 1mtr long pothole.15cm deep.30cm wide top of slip road before crossing bridge to

South Queensferry Category: Potholes

Hit it last night blew front near side tyre on

.Unsure how long it has

been their Location:

Service: Roads General

Easting/Northing: 316123/676991 (55.978551, -3.34572)

Nearest road to the pin placed on the map (automatically generated by Bing Maps):

A90, South Queensferry, EH30 9TR

Nearest postcode to the pin placed on the map (automatically generated): EH30

9AR (683m away)

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

**Enquiry No.:** 973859 Logged by: Verint CRM Connector on: 12/03/2020 07:01 Officer: ESDO West Neighbourhood 2 Subject: Road: Defective / Damaged

Desc.:

Service: Roads General

**Location:** cracks in middle of road becoming potholes Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Logged by: Verint CRM Connector on: 11/03/2020 07:56 Officer: ESDO West Neighbourhood 2 **Enquiry No.: 973395** 

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Subject: Road: Defective / Damaged

Desc.:

Location: Depp. sharp hole in very centre of road that is growing daily and will cause damage Contact:

to tyre/suspension if left much longer

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

on: 10/03/2020 22:35 **Enquiry No.: 973368** Logged by: Verint CRM Connector Officer: Insurance Services

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Deep pothole - cannot be seen in dark (road is unlit). Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Logged by: Verint CRM Connector on: 10/03/2020 19:53 Officer: ESDO West Neighbourhood 2 **Enquiry No.:** 973327

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Large pothole at edge of road heading towards dalmeny and Queensferry, at bottom Contact:

of hill. Lucky to see it in the daylight, however a number of cars have had their

hazards on at night in this part of the road after hitting the pothole.

Effective: 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Officer: ESDO West Neighbourhood 2

**Display Action Officer:** Yes

<b>^</b>	•
( Tuctomoi	CARVICAC
Custome	Services

**Enquiry No.:** 972653 **Logged by:** Verint CRM Connector **on:** 09/03/2020 14:26

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: On Sunday I ran over a huge pothole. The pothole caused a flat tyre and ruined alloy Contact:

wheel. I went back today and notice a chap out marking the potholes for repair

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 971568 Logged by: Verint CRM Connector on: 06/03/2020 12:04 Officer: ESDO West Neighbourhood 2

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Pothole near to gate, to left hand side of kurb

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 971566 Logged by: Verint CRM Connector on: 06/03/2020 12:02 Officer: ESDO West Neighbourhood 2

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Pothole - Middle of road before the bridge. I hit this last night and got a flat tyre **Contact:** 

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 971241 Logged by: Verint CRM Connector on: 05/03/2020 16:02 Officer: ESDO West Neighbourhood 2

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Plot Number: 1.00

**Location:** pothole in road westbound. hole is 32"x14" and approx 3" deep. i hit it and blew a **Contact:** 

Feature Id - Location: Whole Street

tyre. took pics of hole and tyre damage. how do i make claim?

Feature Type: Road Asset

Enquiry No.: 969867 Logged by: Verint CRM Connector on: 03/03/2020 10:02 Officer: ESDO West Neighbourhood 2

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Huge pothole on left side heading towards Queensferry

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 967919 Logged by: Verint CRM Connector on: 28/02/2020 10:38 Officer: ESDO West Neighbourhood 2

Contact:

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

**Location:** Pothole on the left side of the road as you approach the left turn to Dalmeny. I hit it **Contact:** 

causing irreparable damage to wheel.

and to whool

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 967502 Logged by: Verint CRM Connector on: 27/02/2020 15:19 Officer: ESDO West Neighbourhood 2

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: deep pothole Contact:

Effective: 23/02/2020 to 22/02/2022

Service: Roads General

Site: Edinburgh Road (7903508)

Asset Number: 1.00 to 999.00

Officer: ESDO West Neighbourhood 2

Display Action Officer: Yes

**Customer Services** 

Service: Roads General

Enquiry No.: 966431 Logged by: Verint CRM Connector

gged by: Verint CRM Connector on: 25/02/2020 17:52
Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Very big pothole on the left side of the westbound lane.

Contact:

Approx 24-30 inches long, at least 8 inches at its widest and it looks I ke it could be

2-3 inches deep at it's deepest point.

A car hitting this at speed could easily be pulled in to the verge. Buses have no

option but to go over it, which is quickly making it worse.

Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 966429 Logged by: Verint CRM Connector on: 25/02/2020 17:48 Officer: ESDO West Neighbourhood 2

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Plot Number: 1.00

**Location:** Pothole in the middle of the road as you approach the bridge. **Contact:** 

Approx 6-8 inches in diameter, approx 1" deep.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 965056 Logged by: Verint CRM Connector on: 23/02/2020 19:18 Officer: ESDO West Neighbourhood 2

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pot hole Contact: