

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Site: Newcraighall Road (7906128)

Locality: Newcraighall, Edinburgh, City of Edinburgh

Area: North East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type:	Road Asset		Area:	North East Locality
Batch:	41117144 - Inspection Batch		Route:	Ad hoc Route			Date:	25/02/2022
42094134	2no potholes	25/02/2022	Outside no15	RD: CW Pothole	Internal		No Action Required	
Batch:	41116351 - Inspection Batch		Route:	NE_CW1_East1			Date:	21/02/2022
42093615	Pothole	21/02/2022	Opp lamppost 15	RD: CW Pothole	Internal		Committed	50106985
42093623	Potholes x 2	21/02/2022	Opp no 1 Quarry cottages at bus stop	RD: CW Pothole	Internal		Committed	50106994
Batch:	41116309 - Inspection Batch		Route:	Ad hoc Route			Date:	21/02/2022
42093538	2 number potholes	21/02/2022	On roundabout at junction to McDonald's	RD: CW Pothole	Internal		Committed	50106914
Batch:	41116304 - Inspection Batch		Route:	Ad hoc Route			Date:	21/02/2022
42093535	1 number pothole	21/02/2022	On roundabout at junction to McDonald's	RD: CW Pothole	Internal		Committed	50106911
Batch:	41116085 - Inspection Batch		Route:	Ad hoc Route			Date:	18/02/2022
42093226	1 number pothole	18/02/2022	Opposite number 21	RD: CW Pothole	Internal		Committed	50106635
Batch:	41116083 - Inspection Batch		Route:	Ad hoc Route			Date:	18/02/2022
42093225	1 number pothole and remove debris at side of road	18/02/2022	At Lamppost number NAW52	RD: CW Pothole	Internal		Committed	50106634
Batch:	41115879 - Inspection Batch		Route:	Ad hoc Route			Date:	17/02/2022
42093074	1 number pothole	17/02/2022	Opposite Lamppost number NAW60	RD: CW Pothole	Internal		Committed	50106496
Batch:	41115513 - Inspection Batch		Route:	Ad hoc Route			Date:	14/02/2022
42092719	1 number pothole	14/02/2022	Outside number 21	RD: CW Pothole	Internal		Committed	50106170
Batch:	41114837 - Inspection Batch		Route:	NE_FW2_South			Date:	07/02/2022
42092201	cw pothole as marked	07/02/2022	O/S no 21	RD: CW Pothole	Internal		Committed	50105578
42092205	2 x potholes	07/02/2022	O/S lamppost NAW47 at roundabout 10m North of zebra crossing	RD: CW Pothole	Internal		Committed	50105582
42092204	cw pothole as marked	07/02/2022	10m west of lamppost NAW50 heading to town before roundabout	RD: CW Pothole	Internal		Committed	50105581
42092210	cw pothole as marked	07/02/2022	Opp no 15	RD: CW Pothole	Internal		Committed	50105587
42092203	cw pothole as marked	07/02/2022	5m West of lamppost NAW52 heading to town	RD: CW Pothole	Internal		Committed	50105580
42092207	cw pothole as marked	07/02/2022	15m West of lamppost NAW 15 near gully	RD: CW Pothole	Internal		Committed	50105584
42092209	3 x potholes as marked	07/02/2022	Opp no 21 heading west	RD: CW Pothole	Internal		Committed	50105586
Batch:	41113582 - Inspection Batch		Route:	NE_CW1_East1			Date:	20/01/2022
42090178	pothole	20/01/2022	O/S Bathroom Showroom	RD: CW Pothole	Internal		Committed	50103550
42090174	1 x pothole	20/01/2022	Opp 3 Quarry Cottages	RD: CW Pothole	Internal		Committed	50103546
42090177	3 x pothole's	20/01/2022	15- 20m west of lamppost NAW15	RD: CW Pothole	Internal		Committed	50103549

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell			Feature Type: Road Asset		Area: North East Locality	
Batch: 41113582 - Inspection Batch		Route: NE_CW1_East1			Date: 20/01/2022			
42090173	2 x pothole's	20/01/2022	Opp Blackchapel Close	RD: CW Pothole	Internal		Committed	50103545
42090176	1 x pothole	20/01/2022	5m west of lamppost NAW15	RD: CW Pothole	Internal		Committed	50103548
Batch: 41112932 - Inspection Batch		Route: Ad hoc Route			Date: 13/01/2022			
42089175	1no pothole	13/01/2022	Outside no9	RD: CW Pothole	Internal		Committed	50102706
Batch: 41112931 - Inspection Batch		Route: Ad hoc Route			Date: 13/01/2022			
42089174	4no potholes	13/01/2022	Opposite no9	RD: CW Pothole	Internal		Committed	50102705
Batch: 41112849 - Inspection Batch		Route: Ad hoc Route			Date: 12/01/2022			
42088937	1 number pothole	12/01/2022	On the roundabout outside McDonald's	RD: CW Pothole	Internal		Committed	50102484
Batch: 41112329 - Inspection Batch		Route: Ad hoc Route			Date: 07/01/2022			
42088443	1 number pothole	07/01/2022	Outside number 21	RD: CW Pothole	Internal		Committed	50101964
Batch: 41111509 - Inspection Batch		Route: NE_CW1_East1			Date: 21/12/2021			
No actionable defects found								
Batch: 41109491 - Inspection Batch		Route: NE_FW2_South			Date: 06/12/2021			
42086084	Pothole in middle lane	06/12/2021	10m west of lamppost NAW60 heading to town	RD: CW Pothole	Internal		Committed	50099384
42086093	Pothole	06/12/2021	O/S entrance to Safestore	RD: CW Pothole	Internal		Committed	50099392
42086095	Pothole	06/12/2021	Opp gable end of Quarry cottages at bus stop	RD: CW Pothole	Internal		Committed	50099395
42086080	Pothole	06/12/2021	O/S McDonald's in middle lane	RD: CW Pothole	Internal		Committed	50099381
42086096	Potholes x 3	06/12/2021	At lamppost NAW07	RD: CW Pothole	Internal		Committed	50099398
42086078	Pothole	06/12/2021	Opp no 60	RD: CW Pothole	Internal		Committed	50099380
Batch: 41108402 - Inspection Batch		Route: NE_CW1_East1			Date: 26/11/2021			
No actionable defects found								
Batch: 41105232 - Inspection Batch		Route: NE_CW1_East1			Date: 25/10/2021			
42081064	Potholes x 3 as marked	25/10/2021	Opp Brown mast	RD: CW Pothole	Internal		Committed	50094655
42081063	2 x Potholes as marked	25/10/2021	O/S lamppost 7	RD: CW Pothole	Internal		Committed	50094654
Batch: 41104848 - Inspection Batch		Route: Ad hoc Route			Date: 21/10/2021			
42080924	1 number pothole	21/10/2021	At roundabout At Lampost number NAW45	RD: CW Pothole	Internal		Committed	50094463
Batch: 41102816 - Inspection Batch		Route: NE_FW2_South			Date: 05/10/2021			
No actionable defects found								
Batch: 41101352 - Inspection Batch		Route: NE_CW1_East1			Date: 23/09/2021			
42079076	Pothole at manhole as marked	23/09/2021	Opp no 14 Niddrie cottages	RD: CW Pothole	Internal		Committed	50092473
Batch: 41100814 - Inspection Batch		Route: Ad hoc Route			Date: 21/09/2021			
42078717	1 number pothole	21/09/2021	Opposite number 1 at bus stop	RD: CW Pothole	Internal		Committed	50092163

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell			Feature Type: Road Asset		Area: North East Locality	
Batch: 41099208 - Inspection Batch			Route: NE_CW1_East1				Date: 30/08/2021	
No actionable defects found								
Batch: 41097633 - Inspection Batch			Route: NE_FW2_South				Date: 05/08/2021	
42075211	Pothole as marked by arrow on kerb	05/08/2021	At Cleekiminfield	RD: CW Pothole	Internal		Committed	50088978
42075208	Pothole as marked by arrow on kerb	05/08/2021	O/S exit from Self Storage	RD: CW Pothole	Internal		Committed	50088975
42075212	Melted plastic sticking up causing trip hazard please remove with pick to make safe	05/08/2021	Opp Peacocktail Close near bus stop	RD: Other Defect Type	Internal		Committed	50088979
42075214	2 x small Potholes as marked by arrows on kerb	05/08/2021	Opp no 17	RD: CW Pothole	Internal		Committed	50088981
42075207	Pothole as marked by arrow on kerb	05/08/2021	10m west of lamppost NAW50	RD: CW Pothole	Internal		Committed	50088974
42075200	Potholes x 2 marked by arrows on kerb	05/08/2021	Opp Bathroom Showroom	RD: CW Pothole	Internal		Committed	50088968
42075213	3 x Potholes as marked by arrows on kerb	05/08/2021	O/S lamppost NAW7	RD: CW Pothole	Internal		Committed	50088980
42075210	Small Pothole as marked by arrow on kerb	05/08/2021	15m west of lamppost NAW11	RD: CW Pothole	Internal		Committed	50088977
Batch: 41097093 - Inspection Batch			Route: NE_CW1_East1				Date: 28/07/2021	
No actionable defects found								
Batch: 41095092 - Inspection Batch			Route: NE_CW1_East1				Date: 29/06/2021	
42072080	3no potholes	29/06/2021	At the bus stop opposite the Quarry Cottages	RD: CW Pothole	Internal		Committed	50086105
Batch: 41093495 - Inspection Batch			Route: NE_FW2_South				Date: 01/06/2021	
42070174	Open joints	01/06/2021	O/S McDonald's on roundabout	RD: CW Open Joint	Internal		Committed	50084396
42070151	Pothole	01/06/2021	At lamppost NAW 46 just of roundabout	RD: CW Pothole	Internal		Committed	50084376
42070164	Open joints	01/06/2021	O/S McDonald's on roundabout	RD: CW Obstruction	Internal		Committed	50084387
Batch: 41093034 - Inspection Batch			Route: Ad hoc Route				Date: 26/05/2021	
42069665	3 number potholes	26/05/2021	Opposite Blackchapel Close	RD: CW Pothole	Internal		Committed	50083899
Batch: 41092948 - Inspection Batch			Route: NE_CW1_East1				Date: 27/05/2021	
42069560	Potholes x 2	25/05/2021	O/S no 15	RD: CW Pothole	Internal		Committed	50083772
42069562	Potholes x 2 as marked	25/05/2021	Opp no 9	RD: CW Pothole	Internal		Committed	50083773

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell		Feature Type: Road Asset		Area: North East Locality		
Batch: 41092447 - Inspection Batch		Route: Ad hoc Route					Date: 14/05/2021	
42069050	1 number pothole	14/05/2021	Just before bus stop at boots	RD: CW Pothole	Internal		Committed	50083130
Batch: 41092402 - Inspection Batch		Route: Ad hoc Route					Date: 14/05/2021	
42068971	3 number potholes	14/05/2021	Opposite number 1 at bus stop	RD: CW Pothole	Internal		Committed	50083060
Batch: 41092400 - Inspection Batch		Route: Ad hoc Route					Date: 14/05/2021	
42068969	2 number potholes	14/05/2021	Opposite number 2	RD: CW Pothole	Internal		Committed	50083055
Batch: 41090635 - Inspection Batch		Route: NE_CW1_East1					Date: 20/04/2021	
No actionable defects found								
Batch: 41089554 - Inspection Batch		Route: NE_FW2_South					Date: 01/04/2021	
42066362	Pothole x 3	01/04/2021	O/S lamppost NAW13 at bus stop area	RD: CW Pothole	Internal		Committed	50080343
42066350	Pothole	01/04/2021	At Roundabout	RD: CW Pothole	Internal		Committed	50080330
42066364	Pothole	01/04/2021	O/S lamppost NAW 7	RD: CW Pothole	Internal		Committed	50080345
42066363	Pothole x2	01/04/2021	Opp no 4 Quarry Cottages	RD: CW Pothole	Internal		Committed	50080344
42066349	Pothole	01/04/2021	O/S gable end of no 20 Niddrie Cottages	RD: CW Pothole	Internal		Committed	50080329
42066356	Pothole x2	01/04/2021	O/S lamppost no NAW39	RD: CW Pothole	Internal		Committed	50080335
42066354	Pothole marked by arrow on kerb	01/04/2021	O/S lamppost no NAW 48 at roundabout joint	RD: CW Pothole	Internal		Committed	50080333
42066355	Pothole marked by arrow on kerb	01/04/2021	5m west of lamppost NAW48	RD: CW Pothole	Internal		Committed	50080334
Batch: 41088871 - Inspection Batch		Route: Ad hoc Route					Date: 25/03/2021	
42065565	2 number potholes	25/03/2021	Just before the roundabout heading to pets at home	RD: CW Pothole	Internal		Committed	50079502
Batch: 41088106 - Inspection Batch		Route: NE_CW1_East1					Date: 18/03/2021	
No actionable defects found								
Batch: 41085850 - Inspection Batch		Route: Ad hoc Route					Date: 02/03/2021	
42062897	1 n	02/03/2021	At the bypass Flyover heading to Newcraighall	RD: CW Pothole	Internal		Committed	50076891
Batch: 41085844 - Inspection Batch		Route: Ad hoc Route					Date: 02/03/2021	
42062886	1 number pothole	02/03/2021	On roundabout outside McDonalds	RD: CW Pothole	Internal		Committed	50076879
Batch: 41085842 - Inspection Batch		Route: Ad hoc Route					Date: 02/03/2021	
42062881	1	02/03/2021	Opposite William Wilson	RD: CW Pothole	Internal		Committed	50076874
Batch: 41083626 - Inspection Batch		Route: NE_CW1_East1					Date: 18/02/2021	
42061666	1no pothole	18/02/2021	Outside no17	RD: CW Pothole	Internal		Committed	50075457
Batch: 41082012 - Inspection Batch		Route: Ad hoc Route					Date: 08/02/2021	
42060840	3 number potholes	08/02/2021	Outside number 15	RD: CW Pothole	Internal		Committed	50074354
Batch: 41080898 - Inspection Batch		Route: Ad hoc Route					Date: 04/02/2021	
42060523	2 number pothole	04/02/2021	Outside Boots	RD: CW Pothole	Internal		Committed	50074067

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type:	Road Asset		Area:	North East Locality
Batch:	41080342 - Inspection Batch		Route:	NE_CF1_NewcraighallRd1			Date:	01/02/2021
42060184	4 x Cw potholes	01/02/2021	From lamppost NAW5 for 15m east	RD: CW Pothole	Internal		Committed	50073624
42060174	Low track please top up with tar	01/02/2021	10m west of lamppost NAW51	RD: CW Pothole	Internal		Committed	50073617
42060182	Resurfacing required approx 80 m x 3 m	01/02/2021	At bus stop opposite 1quarry cottages	RD: CW Cracked/Broken	Internal		No Action Required	
42060176	2 x steel plates with grip	01/02/2021	There are 2 steel plates either side of the roundabout o/S McDonald's . The plates are smooth and are not ramped.Ramping and a gripy surface are requirements of the Safety at Street Works Code of Practice.2 x plates required	RD: CW Steel Plate Required	Internal		Committed	50054393
42060185	Cw pothole	01/02/2021	Opp no 9	RD: CW Pothole	Internal		Committed	50073625
42060181	Cw pothole	01/02/2021	Opp equinox garage	RD: CW Pothole	Internal		Committed	50073622
Batch:	41080287 - Inspection Batch		Route:	Ad hoc Route			Date:	01/02/2021
42060123	2 x cw pot	01/02/2021	O/S no 15	RD: CW Pothole	Internal		Committed	50073560
Batch:	41080269 - Inspection Batch		Route:	NE_FW2_South			Date:	01/02/2021
42060113	3 sections of Damaged visirail	01/02/2021	At on slip Newcraighall Road	RD: Railing Damage/Missing/New	Internal		Committed	50073526
42060108	2 sections of Damaged visirail	01/02/2021	At bottom off slip Newcraighall Road	RD: Railing Damage/Missing/New	Internal		Committed	50073515
Batch:	41080256 - Inspection Batch		Route:	Ad hoc Route			Date:	01/02/2021
42060103	Cw pothole at hydrant	01/02/2021	8m west of lamppost NAW56	RD: CW Pothole	Internal		Committed	50073512
Batch:	41080252 - Inspection Batch		Route:	Ad hoc Route			Date:	01/02/2021
42060100	2 x cw potholes	01/02/2021	At roundabout turnoff to B and M	RD: CW Pothole	Internal		Committed	50073510
Batch:	41074459 - Inspection Batch		Route:	NE_CW1_East1			Date:	12/01/2021
	No actionable defects found							
Batch:	41074115 - Inspection Batch		Route:	Ad hoc Route			Date:	11/01/2021
42058500	3 number potholes	11/01/2021	Opposite number 9	RD: CW Pothole	Internal		Committed	50071629
Batch:	41074107 - Inspection Batch		Route:	Ad hoc Route			Date:	11/01/2021
42058499	Resurfacing required approx 80 m x 3 m	11/01/2021	At bus stop opposite 1quarry cottages	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41074096 - Inspection Batch		Route:	Ad hoc Route			Date:	11/01/2021
42058498	1 number pothole	11/01/2021	Next to lamppost NAW52	RD: CW Pothole	Internal		Committed	50071621
Batch:	41072664 - Inspection Batch		Route:	Ad hoc Route			Date:	06/01/2021
42058334	1no pothole	06/01/2021	Opposite Peacocktail Close	RD: CW Pothole	Internal		Committed	50071334

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.	
Asset:	1.00	Asset - Locn.:	Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type:	Road Asset		Area:	North East Locality	
Batch:	41072659 - Inspection Batch			Route:	Ad hoc Route			Date:	06/01/2021
42058333	1no pothole	06/01/2021	Opposite no21	RD: CW Pothole	Internal		Committed		50071330
Batch:	41072657 - Inspection Batch			Route:	Ad hoc Route			Date:	06/01/2021
42058332	1no pothole	06/01/2021	Outside no13	RD: CW Pothole	Internal		Committed		50071325
Batch:	41070865 - Inspection Batch			Route:	NE_CW1_East1			Date:	11/12/2020
42057111	Cw pothole	11/12/2020	Opp lampost 15	RD: CW Pothole	Internal		Committed		50069750
Batch:	41070029 - Inspection Batch			Route:	NE_FW2_South			Date:	30/11/2020
42056247	Cw pothole	30/11/2020	10m east of lamppost NAW41	RD: CW Pothole	Internal		Committed		50068598
42056250	Cw pothole	30/11/2020	15m east of Cleekiminfield	RD: CW Pothole	Internal		Committed		50068601
42056248	Damaged visirail section and 1 x tactile required	30/11/2020	O/S old church at The Fort	RD: Railing Damage/Missing/Nev	Internal		Committed		50068599
Batch:	41068659 - Inspection Batch			Route:	NE_CW1_East1			Date:	09/11/2020
No actionable defects found									
Batch:	41066214 - Inspection Batch			Route:	NE_CW1_East1			Date:	08/10/2020
42054206	2no potholes	08/10/2020	Opposite no9	RD: CW Pothole	Internal		Committed		50064410
Batch:	41064029 - Inspection Batch			Route:	NE_FW2_South			Date:	25/09/2020
42053735	Damaged pole and missing sign	25/09/2020	Outside 21	RD: Unlit Sign Damaged/Missing	Internal		Committed		50063491
42053734	Cw pothole	25/09/2020	Opp 5 quarry cottages	RD: CW Pothole	Internal		Committed		50063490
Batch:	41063037 - Inspection Batch			Route:	Ad hoc Route			Date:	08/09/2020
42053261	Cw potholes marked on site x3	08/09/2020	Newcraighall Road east bound os 15	RD: CW Pothole	Internal		Committed		50062195
Batch:	41063036 - Inspection Batch			Route:	Ad hoc Route			Date:	08/09/2020
42053260	Cw pothole marked on site	08/09/2020	Newcraighall Road westbound opp 19	RD: CW Pothole	Internal		Committed		50062194
Batch:	41062701 - Inspection Batch			Route:	NE_CW1_East1			Date:	02/09/2020
No actionable defects found									
Batch:	41060618 - Inspection Batch			Route:	NE_CW1_East1			Date:	28/07/2020
No actionable defects found									
Batch:	41060369 - Inspection Batch			Route:	NE_FW2_South			Date:	22/07/2020
42051879	3 x cw potholes	22/07/2020	From lamppost NAW32 to entrance to Safe Store	RD: CW Pothole	Internal		Committed		50059005
42051878	Cw pothole	22/07/2020	O/S bathroom showroom	RD: CW Pothole	Internal		Committed		50059004
Batch:	41059210 - Inspection Batch			Route:	NE_CW1_East1			Date:	24/06/2020
No actionable defects found									
Asset:	2.00	Asset - Locn.:	Ward 17 - From Musselburgh Bypass east to Newcraighall Drive	Feature Type:	Road Asset		Area	North East Locality	
Batch:	41116370 - Inspection Batch			Route:	NE_CW1_East1			Date:	21/02/2022
No actionable defects found									

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive			Feature Type: Road Asset		Area North East Locality	
Batch:	41114645 - Inspection Batch			Route:	Ad hoc Route			Date: 03/02/2022
42091876	2 number potholes	03/02/2022	At traffic lights opposite fire station	RD: CW Pothole	Internal		Committed	50105273
Batch:	41113585 - Inspection Batch			Route:	NE_CW1_East1			Date: 20/01/2022
	No actionable defects found							
Batch:	41111502 - Inspection Batch			Route:	NE_CW1_East1			Date: 21/12/2021
	No actionable defects found							
Batch:	41108420 - Inspection Batch			Route:	NE_CW1_East1			Date: 26/11/2021
	No actionable defects found							
Batch:	41105761 - Inspection Batch			Route:	Ad hoc Route			Date: 28/10/2021
42081703	Blocked gully needs cleaned and flushed	28/10/2021	Outside number 109	Gully: Blocked / Flooding	Internal		No Action Required	
Batch:	41105266 - Inspection Batch			Route:	NE_CW1_East1			Date: 25/10/2021
	No actionable defects found							
Batch:	41101356 - Inspection Batch			Route:	NE_CW1_East1			Date: 23/09/2021
	No actionable defects found							
Batch:	41099191 - Inspection Batch			Route:	NE_CW1_East1			Date: 30/08/2021
	No actionable defects found							
Batch:	41097091 - Inspection Batch			Route:	NE_CW1_East1			Date: 28/07/2021
	No actionable defects found							
Batch:	41096946 - Inspection Batch			Route:	Ad hoc Route			Date: 26/07/2021
42074291	Renew 1 section of visirail	26/07/2021	Under railway bridge	RD: Railing Damage/Missing/New	Internal		Uncommitted	50088179
Batch:	41095090 - Inspection Batch			Route:	NE_CW1_East1			Date: 29/06/2021
	No actionable defects found							
Batch:	41093507 - Inspection Batch			Route:	Ad hoc Route			Date: 01/06/2021
42070159	Pothole	01/06/2021	O/S entrance to Health club	RD: CW Pothole	Internal		Committed	50084385
Batch:	41093503 - Inspection Batch			Route:	Ad hoc Route			Date: 01/06/2021
42070155	Pothole	01/06/2021	5m East of lamppost NAW73	RD: CW Pothole	Internal		Committed	50084382
Batch:	41092956 - Inspection Batch			Route:	NE_CW1_East1			Date: 25/05/2021
	No actionable defects found							
Batch:	41092482 - Inspection Batch			Route:	Ad hoc Route			Date: 17/05/2021
42069105	1	17/05/2021	Opposite Lamppost NAW86	RD: CW Pothole	Internal		Committed	50083182
Batch:	41090638 - Inspection Batch			Route:	NE_CW1_East1			Date: 20/04/2021
	No actionable defects found							
Batch:	41088107 - Inspection Batch			Route:	NE_CW1_East1			Date: 18/03/2021
	No actionable defects found							

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive			Feature Type: Road Asset		Area	North East Locality
Batch:	41085849 - Inspection Batch			Route:	Ad hoc Route			Date: 02/03/2021
42062896	1 number pothole	02/03/2021	Before the railway bridge at junction of Newcraighall Drive	RD: CW Pothole	Internal		Committed	50076889
Batch:	41083731 - Inspection Batch			Route:	NE_CW1_East1			Date: 18/02/2021
	No actionable defects found							
Batch:	41081313 - Inspection Batch			Route:	Ad hoc Route			Date: 04/02/2021
42060686	1 number pothole	04/02/2021	Outside number 97a	RD: CW Pothole	Internal		Committed	50074171
Batch:	41080333 - Inspection Batch			Route:	NE_CF1_NewcraighallRd1			Date: 01/02/2021
Batch:	41075754 - Inspection Batch			Route:	Ad hoc Route			Date: 18/01/2021
42058951	1	18/01/2021	Outside The Cuddue Brae	RD: CW Pothole	Internal		Committed	50072182
Batch:	41075743 - Inspection Batch			Route:	Ad hoc Route			Date: 18/01/2021
42058948	Sunken manhole	18/01/2021	On the carriageway outside Aroha hair salon	RU: Utility Apparatus	Internal		Uncommitted	50072175
Batch:	41074456 - Inspection Batch			Route:	NE_CW1_East1			Date: 12/01/2021
	No actionable defects found							
Batch:	41071052 - Inspection Batch			Route:	Ad hoc Route			Date: 14/12/2020
42057337	2 number potholes	14/12/2020	On carriageway Outside the cuddle brae	RD: CW Pothole	Internal		Committed	50069997
Batch:	41070888 - Inspection Batch			Route:	NE_CW1_East1			Date: 11/12/2020
42057134	Cw pothole	11/12/2020	O/S entrance to Bannanrynes	RD: CW Pothole	Internal		Committed	50069767
42057136	Cw pothole	11/12/2020	Opp fire station before lights	RD: CW Pothole	Internal		Committed	50069768
Batch:	41068667 - Inspection Batch			Route:	NE_CW1_East1			Date: 09/11/2020
	No actionable defects found							
Batch:	41068440 - Inspection Batch			Route:	Ad hoc Route			Date: 03/11/2020
42054999	1no	03/11/2020	Just north of Benhar Road	RD: CW Pothole	Internal		Committed	50066190
Batch:	41066208 - Inspection Batch			Route:	NE_CW1_East1			Date: 08/10/2020
	No actionable defects found							
Batch:	41062698 - Inspection Batch			Route:	NE_CW1_East1			Date: 02/09/2020
	No actionable defects found							
Batch:	41060614 - Inspection Batch			Route:	NE_CW1_East1			Date: 28/07/2020
	No actionable defects found							
Batch:	41059211 - Inspection Batch			Route:	NE_CW1_East1			Date: 24/06/2020
	No actionable defects found							

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Enquiry No.: 1335695	Logged by: Verint CRM Connector	on: 28/02/2022 00:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Bus stop surface just after the roundabout leaving fort Kinnaird is horrific.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Enquiry No.: 1335694	Logged by: Verint CRM Connector	on: 28/02/2022 00:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several potholes between the lights and the roundabout heading towards fort Kinnaird. Play dodge the pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Enquiry No.: 1334530	Logged by: Verint CRM Connector	on: 25/02/2022 16:22
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Very deep hole. Very dangerous for bikers. Looks sufficient to damage a car wheel. Cars Swerving to avoid. This is being logged as I was told to do so by clarence@edinburgh.gov.uk This was repaired the day after my incident.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Enquiry No.: 1334343	Logged by: Verint CRM Connector	on: 25/02/2022 13:10
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Various potholes as part of large flaw in road which needs to be fixed. This whole stretch of road on both sides is a disgrace for motorists and unsafe for cyclists.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Enquiry No.: 1328198	Logged by: Verint CRM Connector	on: 16/02/2022 21:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Surface of the road around the speed bump just before the railway bridge as you head towards fort Kinnaird is potholed, crumbled and broken.	Contact:	
Plot Number: 2.00	Feature Id - Location: Ward 17 - From Musse burgh Bypass east to Newcraighall Drive	Feature Type: Road Asset

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1327742 **Logged by:** Verint CRM Connector **on:** 16/02/2022 13:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Deep potholes **Contact:**
Category: Potholes

Very deep hole. Very dangerous for bikers. Looks sufficient to damage a car wheel.
Cars are swerving to avoid.

Location:
Easting/Northing: 331403/671725 (55.933672, -3.099559)
Nearest road to the pin placed on the map (automatically generated by Bing Maps):
80 Newcraighall Road, Edinburgh, EH15 3HS
Nearest postcode to the pin placed on the map (automatically generated): EH15
3RB (183m away)

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset
Job Number: 50106496 **Defect Number:** 42093074

Enquiry No.: 1326561 **Logged by:** Verint CRM Connector **on:** 14/02/2022 19:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Previous reported pot hole was filled quickly but it's completely fell apart again and is **Contact:**
a huge pothole once again. You can still see the white spray paint put around it to
mark for repair. The repair lasted a week!!

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Enquiry No.: 1324443 **Logged by:** Verint CRM Connector **on:** 11/02/2022 09:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Badly damaged road. Caused shock to front offside wheel. Required repair to alloy **Contact:**
wheel and new tyre as per attached receipts. Also attach photo of road section. I
wish to seek reimbursement of costs associated with repairs.

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1307006 **Logged by:** Verint CRM Connector **on:** 14/01/2022 09:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Reference: 101001073627

Contact:

Please note: I advised of this road defect yesterday as a major pot hole in the carriageway, resulting in an instant burst tyre, which has left me out of pocket of [REDACTED]. I received an email today to say that the works are complete. They are not! There is not even a cone advising drivers to avoid the area of road.

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Enquiry No.: 1306320 **Logged by:** Verint CRM Connector **on:** 13/01/2022 08:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Major pot holes in the road resulting in an instant burst tyre! This is on the inside lane just after the bus stop. There have been works carried out in this location in the past few months, however the road has not been repaired afterwards.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset
Job Number: 50102705 **Defect Number:** 42089174

Enquiry No.: 1304095 **Logged by:** Verint CRM Connector **on:** 09/01/2022 20:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Large deep pothole on NewCraighall Road , west bound from Fort Kinnaird towards the crossroads at the bottom of The Wisp

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Enquiry No.: 1302201 **Logged by:** Verint CRM Connector **on:** 06/01/2022 15:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Large pothole in middle of road

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset
Job Number: 50101964 **Defect Number:** 42088443

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services



Enquiry No.: 1248382 **Logged by:** Verint CRM Connector **on:** 20/09/2021 23:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Road has cracked in multiple places and big potholes have appeared - see attached images. It's very dangerous - it's likely a cyclist could be thrown off their bike and with cars around, it's only a matter of time before someone is seriously injured or killed on this road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset
Job Number: 50092163 **Defect Number:** 42078717

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)


Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1244493 **Logged by:** Verint CRM Connector **on:** 13/09/2021 20:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Travelling E to W, from Tony Macaronis to crossroads at the Wisp, the road condition is full of uneven tarmac, cracks, bumps and numerous potholes. The condition of the road is particularly very poor closest to the kerb. As a cyclist, naturally we need to keep to left of the lane. It is extremely dangerous because the road surface is very rough and full of potholes, and the chances of being thrown off the bike is high. There are also cars overtaking on your right which can lead to an accident.

Contact:



Plot Number: 2.00 **Feature Id - Location:** Ward 17 - From Musse burgh Bypass east to Newcraighall Drive **Feature Type:** Road Asset
Job Number: 50088179 **Defect Number:** 42074291

Enquiry No.: 1207275 **Logged by:** Verint CRM Connector **on:** 13/07/2021 08:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Road surface headed westwards from shopping centre is awful in several places. Very dangerous and uncomfortable.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Enquiry No.: 1176121 **Logged by:** Verint CRM Connector **on:** 17/05/2021 11:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole on opposite side of road just before bus stop

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Enquiry No.: 1175982 **Logged by:** Verint CRM Connector **on:** 17/05/2021 09:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: state of road surface in very bad condition causing cyclist to come off bike

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1175979 Service: Roads General Desc.: Location: very large pothole at speed hump	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 17/05/2021 09:14 Classification: Request for service Contact:
Plot Number: 2.00 Job Number: 50083182	Feature Id - Location: Ward 17 - From Musse burgh Bypass east to Newcraighall Drive Defect Number: 42069105	Feature Type: Road Asset
Enquiry No.: 1175502 Service: Roads General Desc.: Location: There are three potholes on the road.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/05/2021 18:22 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50083055	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Defect Number: 42068969	Feature Type: Road Asset
Enquiry No.: 1173979 Service: Roads General Desc.: Location: Very large pot holes that cause high distressing noise [REDACTED] and cause [REDACTED] house to shake when a bus or lorry drives into them	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/05/2021 16:38 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50083055	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Defect Number: 42068969	Feature Type: Road Asset
Enquiry No.: 1173921 Service: Roads General Desc.: Location: potholes at bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/05/2021 15:36 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50083060	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell Defect Number: 42068971	Feature Type: Road Asset
Enquiry No.: 1173578 Service: Roads General Desc.: Location: Huge pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/05/2021 09:39 Classification: Request for service Contact:
[REDACTED]		
Plot Number: 2.00 Enquiry No.: 1151453 Service: Roads General Desc.: Location: Pothole	Feature Id - Location: Ward 17 - From Musse burgh Bypass east to Newcraighall Drive Defect Number: 42068971 Subject: Road: Defective / Damaged	Feature Type: Road Asset on: 31/03/2021 18:19 Classification: Request for service Contact:
Plot Number: 2.00	Feature Id - Location: Ward 17 - From Musse burgh Bypass east to Newcraighall Drive	Feature Type: Road Asset

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1147058 **Logged by:** Verint CRM Connector **on:** 24/03/2021 13:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: SUNKIN DRAIN and more left lane towards B&Q **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset
Job Number: 50079502 **Defect Number:** 42065565

Enquiry No.: 1142027 **Logged by:** Verint CRM Connector **on:** 17/03/2021 11:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole surprised it didn't rip out my suspension. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - From Musse burgh Bypass east to Newcraighall Drive **Feature Type:** Road Asset

Enquiry No.: 1138868 **Logged by:** Verint CRM Connector **on:** 11/03/2021 15:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: The incident took place on the February 16th 2021 .time
Must been about 1-2 pm I can't remember exact time but date is definitely 16th
The road was towards fort Kinnard Edinburgh I was heading to wilko supermarket at the time
Location: The road was towards fort Kinnard Edinburgh, 30 yards before the bollard in middle **Contact:**
of road bus stop on opposite side of road 60 years after

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Enquiry No.: 1132383 **Logged by:** Verint CRM Connector **on:** 01/03/2021 17:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole heading for Newcraighall just before bypass flyover **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset
Job Number: 50076891 **Defect Number:** 42062897

Enquiry No.: 1132377 **Logged by:** Verint CRM Connector **on:** 01/03/2021 17:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole just before rail bridge heady cost to fort Kinnaird **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - From Musse burgh Bypass east to Newcraighall Drive **Feature Type:** Road Asset
Job Number: 50076889 **Defect Number:** 42062896

Enquiry No.: 1130822 **Logged by:** Verint CRM Connector **on:** 26/02/2021 19:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole heading eastbound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset
Job Number: 50076874 **Defect Number:** 42062881

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1130821 Service: Roads General Desc.: Location: Massive pothole inside lane heading towards roundabout	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 26/02/2021 19:08 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Enquiry No.: 1113627 Service: Roads General Desc.: Location: Traveling east on Newcraighall Road just before the entrance to Peacocktail Close there are 3 potholes on an already patched piece of road. There size is increasing daily. Also just after the bus stop before entering Fort shopping centre, where buses 400 and 48 terminate there is a large pothole in the middle of the carriageways.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 05/02/2021 15:11 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Job Number: 50074354	Defect Number: 42060840	
Enquiry No.: 1113318 Service: Roads General Desc.: Location: Dangerous pothole to centre of road getting worse affecting both lanes.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 05/02/2021 10:46 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Enquiry No.: 1112510 Service: Roads General Desc.: Location: sunken section of road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/02/2021 09:17 Classification: Request for service Contact:
Plot Number: 2.00	Feature Id - Location: Ward 17 - From Musse burgh Bypass east to Newcraighall Drive	Feature Type: Road Asset
Enquiry No.: 1112490 Service: Roads General Desc.: Location: large pot hole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/02/2021 08:57 Classification: Request for service Contact:
Plot Number: 2.00	Feature Id - Location: Ward 17 - From Musse burgh Bypass east to Newcraighall Drive	Feature Type: Road Asset
Job Number: 50074171	Defect Number: 42060686	
Enquiry No.: 1112432 Service: Roads General Desc.: Location: Issues between the fort and the traffic lights at the wisp in numerous places.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 03/02/2021 23:50 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell	Feature Type: Road Asset
Job Number: 50074067	Defect Number: 42060523	

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1108950 **Logged by:** Verint CRM Connector **on:** 29/01/2021 09:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in road Musselburgh bound, just before Newcraighall primary school, just before speed bump, this was repaired a month **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - From Musse burgh Bypass east to Newcraighall Drive **Feature Type:** Road Asset

Enquiry No.: 1108949 **Logged by:** Verint CRM Connector **on:** 29/01/2021 09:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in road, Musselburgh bound outside Ahora beauty **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Enquiry No.: 1101725 **Logged by:** Verint CRM Connector **on:** 16/01/2021 18:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Drain cover collapsing causing deep pothole. Outside cuddle bare at pedestrian crossing heading east **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - From Musse burgh Bypass east to Newcraighall Drive **Feature Type:** Road Asset

Job Number: 50072175 **Defect Number:** 42058948

Enquiry No.: 1097567 **Logged by:** Verint CRM Connector **on:** 08/01/2021 19:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pot holes at road edge.
I reported this earlier in week and some of the pot holes have been filled but not all on this stretch of road the ones remaining where I have marked are particularly big. if you could reattend that would be great. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Job Number: 50071629 **Defect Number:** 42058500

Enquiry No.: 1096690 **Logged by:** Verint CRM Connector **on:** 07/01/2021 16:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: various potholes near bus stop heading away from shopping centre **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Job Number: 50107867 **Defect Number:** 42094591

Enquiry No.: 1096046 **Logged by:** Verint CRM Connector **on:** 06/01/2021 20:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a very large pot hole in the left lane heading west just after the bus shelter. the hole is so deep it caused damage to my wife's rear passenger side tyre on the wheel of the tyre. Please can this be filled in ASAP **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Job Number: 50071621 **Defect Number:** 42058498

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1094657 **Logged by:** Verint CRM Connector **on:** 05/01/2021 11:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The pot holes are huge and dangerous on this stretch of road at present. They are on both sides going in both directions. There is some patch work that's deteriorating. We suffered a bad puncture and suspension damage to our car here last year and the botched patch up after this is failing again. Please fix this road it's so heavily used with buses and fort kinnaird traffic it needs urgent attention. You have to swerve to avoid them now.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset
Job Number: 50071325 **Defect Number:** 42058332

Enquiry No.: 1090443 **Logged by:** Verint CRM Connector **on:** 28/12/2020 16:12
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple Potholes and road depressions **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - From Musse burgh Bypass east to Newcraighall Drive **Feature Type:** Road Asset

Enquiry No.: 1083976 **Logged by:** Verint CRM Connector **on:** 12/12/2020 15:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes, been filled multiple times, need done properly, whole stretch from Bannatynes into Newcraighall village **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - From Musse burgh Bypass east to Newcraighall Drive **Feature Type:** Road Asset
Job Number: 50069997 **Defect Number:** 42057337

Enquiry No.: 1058411 **Logged by:** Verint CRM Connector **on:** 24/10/2020 11:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: At the side of the road where the drain is (heading from Newcraighall to Musselburgh) just past the old railway bridge there is a large and very dangerous hole around the drain which if a cyclist hit would be very sore.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 17 - From The Wisp to southbound on-ramp to A1 Mussell **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Customer Services

Enquiry No.: 1002703
Service: Roads General
Desc.:
Location: There appears to be a large metal plate that has been used as a placeholder for work needing to be carried out. Perhaps for cars this is not a problem but a large slippery surface for a Motorcycle can be deadly. I would rather a crack in the road than a large skate-like surface that can kill me.

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 03/07/2020 09:46
Classification: Request for service

Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussel		Feature Type: Road Asset		Area: North East Locality	
2001696	c/w breaking up (RD: Asphalt / Bitmac Surface)	Opp 10 niddrie cottages	RD: Cat 4 - 12 Months	Job Cancelled	27/04/2015	27/04/2016	Est.
2001904	C/w breaking up (RD: Asphalt / Bitmac Surface)	O/s 15	Non Routine (One Off Works)	Job Cancelled	01/06/2015		
2001905	C/w breaking up (RD: Asphalt / Bitmac Surface)	O/s 19	Non Routine (One Off Works)	Job Cancelled	01/06/2015		
2001906	C/w breaking up (RD: Asphalt / Bitmac Surface)	O/s 21	Non Routine (One Off Works)	Job Annulled	01/06/2015		
2008472	Cw patch required 5mx 2m (RD: Asphalt / Bitmac Surface)	Damaged road surface on the roundabout west side (outside lane)	RD: Cat 4 - 12 Months	Job Cancelled	24/11/2017	24/11/2018	Est.

Site History Report

Effective: 01/06/2020 to 28/02/2022

Service: Roads General

Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussel		Feature Type: Road Asset		Area: North East Locality	
50002741	Double gully frames have sunk.steel plate is already covering them (RD: Gully Sunken/Damaged Frame)	On roundabout opp Mcdonalds	RD: Cat 3 - 60 Day	Job Cancelled	09/02/2018	09/03/2018 Est.	ROAD/82002194
50002748	2 x sunken gullys. Steel plate is already on reset 2 x frames and branders required (RD: Gully Sunken/Damaged Frame)	On roundabout os Topps Tiles	RD: Cat 3 - 60 Day	Job Cancelled	09/02/2018	09/03/2018 Est.	ROAD/82002201

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussel	Feature Type: Road Asset		Area: North East Locality		
50015439	2 x Cw potholes (RD: FW HRA Pothole)	O/S no 15	RD: Cat 2 - 5 Day	Job Cancelled	04/09/2018	05/09/2018	Est. ROAD/82012123
50024757	Double gully frames have sunk.steel plate is already covering them - New Side Entry gully x 2 to be installed at location (drawings attached)	On roundabout opp Mcdonalds	RD: Follow Up Job	Job Raised	29/01/2019	26/02/2019	Est.
50024758	2 x sunken gullys. Steel plate is already on - 2 x New Side Entry gullies to be installed see attached documents for details.	On roundabout os Topps Tiles	RD: Follow Up Job	Job Raised	29/01/2019	26/02/2019	Est.
50054393	2 x steel plates with grip (RD: CW Steel Plate Required)	There are 2 steel plates either side of the roundabout o/S McDonald's . The plates are smooth and are not ramped.Ramping and a gripy surface are requirements of the Safety at Street Works Code of Practice.2 x plates required	RD: Cat 3 - 60 Day	Job Complete	09/03/2020	31/05/2021	Act. ROAD/82034776
50056243	Damaged pole and missing sign (RD: Other Defect Type)	Outside 21	RD: Cat 4 - 12 Months	Job Cancelled	20/05/2020	20/05/2021	Est.
50059004	Cw pothole (RD: CW Pothole)	O\S bathroom showroom	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/07/2020	23/07/2020	Act. ROAD/82038073
50059005	3 x cw potholes (RD: CW Pothole)	From lamppost NAW32 to entrance to Safe Store	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/07/2020	23/07/2020	Act. ROAD/82038074
50062194	Cw pothole marked on site (RD: CW Pothole)	Newcraighall Road westbound opp 19	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/09/2020	09/09/2020	Act. ROAD/82039287
50062195	Cw potholes marked on site x3 (RD: CW Pothole)	Newcraighall Road east bound os 15	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/09/2020	09/09/2020	Act. ROAD/82039288
50063490	Cw pothole (RD: CW Pothole)	Opp 5 quarry cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/09/2020	29/09/2020	Act. ROAD/82039730
50064410	2no potholes (RD: CW Pothole)	Opposite no9	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/10/2020	09/10/2020	Act. ROAD/82040126
50068598	Cw pothole (RD: CW Pothole)	10m east of lamppost NAW41	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041804

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussel	Feature Type: Road Asset			Area: North East Locality	
50068601	Cw pothole (RD: CW Pothole)	15m east of Cleekiminfield	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041806
50069750	Cw pothole (RD: CW Pothole)	Opp lamppost 15	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/12/2020	15/12/2020	Act. ROAD/82042389
50071325	1no pothole (RD: CW Pothole)	Outside no13	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/01/2021	06/01/2021	Act. ROAD/82043033
50071330	1no pothole (RD: CW Pothole)	Opposite no21	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/01/2021	06/01/2021	Act. ROAD/82043034
50071334	1no pothole (RD: CW Pothole)	Opposite Peacocktail Close	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/01/2021	06/01/2021	Act. ROAD/82043035
50071621	1 number pothole (RD: CW Pothole)	Next to lamppost NAW52	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/01/2021	12/01/2021	Act. ROAD/82043159
50071629	3 number potholes (RD: CW Pothole)	Opposite number 9	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/01/2021	12/01/2021	Act. ROAD/82043160
50073510	2 x cw potholes (RD: CW Pothole)	At roundabout turnoff to B and M	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/02/2021	03/02/2021	Act. ROAD/82044084
50073512	Cw pothole at hydrant (RD: CW Pothole)	8m west of lamppost NAW56	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/02/2021	03/02/2021	Act. ROAD/82044085
50073560	2 x cw pot (RD: CW Pothole)	O/S no 15	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/02/2021	03/02/2021	Act. ROAD/82044101
50073617	Low track please top up with tar (RD: CW Pothole)	10m west of lamppost NAW51	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2021	08/02/2021	Act. ROAD/82044135
50073622	Cw pothole (RD: CW Pothole)	Opp equinox garage	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2021	08/02/2021	Act. ROAD/82044140
50073624	4 x Cw potholes (RD: CW Pothole)	From lamppost NAW5 for 15m east	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2021	08/02/2021	Act. ROAD/82044142

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussel		Feature Type: Road Asset		Area: North East Locality	
50073625	Cw pothole (RD: CW Pothole)	Opp no 9	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2021	08/02/2021	Act. ROAD/82044143
50074067	2 number pothole (RD: CW Pothole)	Outside Boots	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2021	08/02/2021	Act. ROAD/82044360
50074354	3 number potholes (RD: CW Pothole)	Outside number 15	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/02/2021	16/02/2021	Act. ROAD/82044532
50075457	1no pothole (RD: CW Pothole)	Outside no17	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/02/2021	26/02/2021	Act. ROAD/82045163
50075672	C/w breaking up (RD: CW Cracked/Broken)	O/s 21	RD: Cat 4 - 12 Months	Job Annulled	19/02/2021	19/02/2022	Est.
50075739	C/w breaking up (RD: CW Cracked/Broken)	O/s 19	RD: Cat 4 - 12 Months	Job Annulled	21/02/2021	21/02/2022	Est.
50076874	1 (RD: CW Pothole)	Opposite William Wilson	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2021	03/03/2021	Act. ROAD/82045995
50076879	1 number pothole (RD: CW Pothole)	On roundabout outside McDonalds	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/03/2021	03/03/2021	Act. ROAD/82046000
50076891	1 n (RD: CW Pothole)	At the bypass Flyover heading to Newcraighall	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/03/2021	03/03/2021	Act. ROAD/82046007
50079502	2 number potholes (RD: CW Pothole)	Just before the roundabout heading to pets at home	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/03/2021	28/03/2021	Act. ROAD/82047620
50080329	Pothole (RD: CW Pothole)	O/S gable end of no 20 Niddrie Cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2021	08/04/2021	Act. ROAD/82048141
50080330	Pothole (RD: CW Pothole)	At Roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2021	08/04/2021	Act. ROAD/82048142
50080333	Pothole marked by arrow on kerb (RD: CW Pothole)	O/S lamppost no NAW 48 at roundabout joint	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2021	08/04/2021	Act. ROAD/82048144
50080334	Pothole marked by arrow on kerb (RD: CW Pothole)	5m west of lamppost NAW48	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2021	08/04/2021	Act. ROAD/82048145
50080335	Pothole x2 (RD: CW Pothole)	O/S lamppost no NAW39	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2021	08/04/2021	Act. ROAD/82048146
50080343	Pothole x 3 (RD: CW Pothole)	O/S lamppost NAW13 at bus stop area	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2021	08/04/2021	Act. ROAD/82048152
50080344	Pothole x2 (RD: CW Pothole)	Opp no 4 Quarry Cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2021	08/04/2021	Act. ROAD/82048153
50080345	Pothole (RD: CW Pothole)	O/S lamppost NAW 7	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2021	08/04/2021	Act. ROAD/82048154
50083055	2 number potholes (RD: CW Pothole)	Opposite number 2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/05/2021	17/05/2021	Act. ROAD/82049687
50083060	3 number potholes (RD: CW Pothole)	Opposite number 1 at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/05/2021	17/05/2021	Act. ROAD/82049689

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussel		Feature Type: Road Asset		Area: North East Locality	
50083130	1 number pothole (RD: CW Pothole)	Just before bus stop at boots	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/05/2021	17/05/2021	Act. ROAD/82049739
50083772	Potholes x 2 (RD: CW Pothole)	O/S no 15	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/05/2021	26/05/2021	Act. ROAD/82050083
50083773	Potholes x 2 as marked (RD: CW Pothole)	Opp no 9	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/05/2021	26/05/2021	Act. ROAD/82050084
50083899	3 number potholes (RD: CW Pothole)	Opposite Blackchapel Close	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/05/2021	27/05/2021	Act. ROAD/82050158
50084376	Pothole (RD: CW Pothole)	At lamppost NAW 46 just of roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/06/2021	04/06/2021	Act. ROAD/82050423
50084387	Open joints (RD: CW Obstruction)	O/S McDonald's on roundabout	RD: Cat 3 - 60 Day	Job Annulled	01/06/2021	24/08/2021	Est. ROAD/82050430
50084396	Open joints (RD: CW Open Joint)	O/S McDonald's on roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/06/2021	27/06/2021	Act. ROAD/82050438
50086105	3no potholes (RD: CW Pothole)	At the bus stop opposite the Quarry Cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/06/2021	30/06/2021	Act. ROAD/82051417
50088968	Potholes x 2 marked by arrows on kerb (RD: CW Pothole)	Opp Bathroom Showroom	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2021	06/08/2021	Act. ROAD/82052840
50088974	Pothole as marked by arrow on kerb (RD: CW Pothole)	10m west of lamppost NAW50	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2021	06/08/2021	Act. ROAD/82052842
50088975	Pothole as marked by arrow on kerb (RD: CW Pothole)	O/S exit from Self Storage	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2021	06/08/2021	Act. ROAD/82052843
50088977	Small Pothole as marked by arrow on kerb (RD: CW Pothole)	15m west of lamppost NAW11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2021	06/08/2021	Act. ROAD/82052844
50088978	Pothole as marked by arrow on kerb (RD: CW Pothole)	At Cleekiminfield	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2021	06/08/2021	Act. ROAD/82052845
50088979	Melted plastic sticking up causing trip hazard please remove with pick to make safe (RD: Other Defect Type)	Opp Peacocktail Close near bus stop	RD: Cat 3 - 60 Day	Job Complete	05/08/2021	10/08/2021	Act. ROAD/82052846
50088980	3 x Potholes as marked by arrows on kerb (RD: CW Pothole)	O/S lamppost NAW7	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2021	06/08/2021	Act. ROAD/82052847
50088981	2 x small Potholes as marked by arrows on kerb (RD: CW Pothole)	Opp no 17	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/08/2021	06/08/2021	Act. ROAD/82052848

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussel		Feature Type: Road Asset		Area: North East Locality	
50092163	1 number pothole (RD: CW Pothole)	Opposite number 1 at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/09/2021	22/09/2021	Act. ROAD/82054453
50092473	Pothole at manhole as marked (RD: CW Pothole)	Opp no 14 Niddrie cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/09/2021	24/09/2021	Act. ROAD/82054558
50094463	1 number pothole (RD: CW Pothole)	At roundabout At Lamppost number NAW45	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/10/2021	22/10/2021	Act. ROAD/82055218
50094654	2 x Potholes as marked (RD: CW Pothole)	O/S lamppost 7	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/10/2021	27/10/2021	Act. ROAD/82055294
50094655	Potholes x 3 as marked (RD: CW Pothole)	Opp Brown mast	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/10/2021	26/10/2021	Act. ROAD/82055295
50099380	Pothole (RD: CW Pothole)	Opp no 60	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/12/2021	07/12/2021	Act. ROAD/82057180
50099381	Pothole (RD: CW Pothole)	O/S McDonald's in middle lane	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/12/2021	08/12/2021	Act. ROAD/82057181
50099384	Pothole in middle lane (RD: CW Pothole)	10m west of lamppost NAW60 heading to town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/12/2021	08/12/2021	Act. ROAD/82057183
50099392	Pothole (RD: CW Pothole)	O/S entrance to Safestore	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/12/2021	07/12/2021	Act. ROAD/82057189
50099395	Pothole (RD: CW Pothole)	Opp gable end of Quarry cottages at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/12/2021	07/12/2021	Act. ROAD/82057192
50099398	Potholes x 3 (RD: CW Pothole)	At lamppost NAW07	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/12/2021	07/12/2021	Act. ROAD/82057195
50101964	1 number pothole (RD: CW Pothole)	Outside number 21	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/01/2022	10/01/2022	Act. ROAD/82058285
50102484	1 number pothole (RD: CW Pothole)	On the roundabout outside McDonald's	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/01/2022	13/01/2022	Act. ROAD/82058538
50102705	4no potholes (RD: CW Pothole)	Opposite no9	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2022	14/01/2022	Act. ROAD/82058667
50102706	1no pothole (RD: CW Pothole)	Outside no9	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2022	14/01/2022	Act. ROAD/82058668
50103545	2 x pothole's (RD: CW Pothole)	Opp Blackchapel Close	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2022	21/01/2022	Act. ROAD/82059004
50103546	1 x pothole (RD: CW Pothole)	Opp 3 Quarry Cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2022	21/01/2022	Act. ROAD/82059005
50103548	1 x pothole (RD: CW Pothole)	5m west of lamppost NAW15	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2022	21/01/2022	Act. ROAD/82059007
50103549	3 x pothole's (RD: CW Pothole)	15- 20m west of lamppost NAW15	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2022	21/01/2022	Act. ROAD/82059008
50103550	pothole (RD: CW Pothole)	O/S Bathroom Showroom	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/01/2022	21/01/2022	Act. ROAD/82059010
50105578	cw pothole as marked (RD: CW Pothole)	O/S no 21	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2022	08/02/2022	Act. ROAD/82059870
50105580	cw pothole as marked (RD: CW Pothole)	5m West of lamppost NAW52 heading to town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2022	08/02/2022	Act. ROAD/82059872

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 17 - From The Wisp to southbound on-ramp to A1 Mussel		Feature Type: Road Asset		Area: North East Locality	
50105581	cw pothole as marked (RD: CW Pothole)	10m west of lamppost NAW50 heading to town before roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2022	08/02/2022	Act. ROAD/82059873
50105582	2 x potholes (RD: CW Pothole)	O/S lamppost NAW47 at roundabout 10m North of zebra crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2022	08/02/2022	Act. ROAD/82059874
50105584	cw pothole as marked (RD: CW Pothole)	15m West of lamppost NAW 15 near gully	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2022	08/02/2022	Act. ROAD/82059875
50105586	3 x potholes as marked (RD: CW Pothole)	Opp no 21 heading west	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/02/2022	08/02/2022	Act. ROAD/82059877
50105587	cw pothole as marked (RD: CW Pothole)	Opp no 15	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2022	08/02/2022	Act. ROAD/82059878
50106170	1 number pothole (RD: CW Pothole)	Outside number 21	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2022	15/02/2022	Act. ROAD/82060161
50106496	1 number pothole (RD: CW Pothole)	Opposite Lamppost number NAW60	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2022	18/02/2022	Act. ROAD/82060355
50106634	1 number pothole and remove debris at side of road (RD: CW Pothole)	At Lamppost number NAW52	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/02/2022	20/02/2022	Act. ROAD/82060446
50106635	1 number pothole (RD: CW Pothole)	Opposite number 21	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/02/2022	21/02/2022	Act. ROAD/82060447
50106911	1 number pothole (RD: CW Pothole)	On roundabout at junction to McDonald's	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/02/2022	22/02/2022	Act. ROAD/82060585
50106914	2 number potholes (RD: CW Pothole)	On roundabout at junction to McDonald's	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/02/2022	22/02/2022	Act. ROAD/82060587
50106985	Pothole (RD: CW Pothole)	Opp lamppost 15	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/02/2022	22/02/2022	Act. ROAD/82060625
50106994	Potholes x 2 (RD: CW Pothole)	Opp no 1 Quarry cottages at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/02/2022	22/02/2022	Act. ROAD/82060631
50107484	2no potholes (RD: CW Pothole)	Outside no15	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/02/2022	02/03/2022	Act. ROAD/82060974
Asset: 2.00		Asset - Locn.: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive		Feature Type: Road Asset		Area: North East Locality	
2002420	C/w breaking up (RD: Asphalt / Bitmac Surface)	Opp NAW 86	RD: Cat 4 - 12 Months	Job Annulled	21/08/2015	21/08/2016	Est.
2002980	2 x c/w potholes (RD: CLARENCE Response)	20 m east of l/p Naw 100	RD: Cat 2 - 5 Day	Job Cancelled	13/11/2015	17/11/2015	Est. RD01/20001965
2003460	Cw pothole (RD: CLARENCE Response)	Between and opp.l/p NAW 100 and NAW 101 heading into town	RD: Cat 2 - 5 Day	Job Cancelled	22/01/2016	29/01/2016	Est. RD01/20002404
50066190	1no (RD: CW Pothole)	Just north of Benhar Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/11/2020	04/11/2020	Act. ROAD/82040880

Site History Report

Effective: 01/06/2020 to 28/02/2022
Service: Roads General
Site: Newcraighall Road (7906128)

Asset Number: 1.00 to 999.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 17 - From Musselburgh Bypass east to Newcraighall Drive			Feature Type: Road Asset		
					Area: North East Locality		
50069767	Cw pothole (RD: CW Pothole)	O/S entrance to Bannanrynes	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/12/2020	15/12/2020	Act. ROAD/82042398
50069768	Cw pothole (RD: CW Pothole)	Opp fire station before lights	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/12/2020	15/12/2020	Act. ROAD/82042399
50069997	2 number potholes (RD: CW Pothole)	On carriageway Outside the cuddle brae	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/12/2020	15/12/2020	Act. ROAD/82042484
50072175	Sunken manhole (RU: Utility Apparatus)	On the carriageway outside Aroha hair salon	RU: Fail Low Risk	Job Complete	18/01/2021	18/01/2021	Act.
50072182	1 (RD: CW Pothole)	Outside The Cuddue Brae	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/01/2021	18/01/2021	Act. ROAD/82043401
50074171	1 number pothole (RD: CW Pothole)	Outside number 97a	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2021	17/02/2021	Act. ROAD/82044441
50076889	1 number pothole (RD: CW Pothole)	Before the railway bridge at junction of Newcraighall Drive	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/03/2021	03/03/2021	Act. ROAD/82046006
50083182	1 (RD: CW Pothole)	Opposite Lamppost NAW86	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2021	17/05/2021	Act. ROAD/82049771
50084382	Pothole (RD: CW Pothole)	5m East of lamppost NAW73	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/06/2021	04/06/2021	Act. ROAD/82050426
50084385	Pothole (RD: CW Pothole)	O/S entrance to Health club	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/06/2021	04/06/2021	Act. ROAD/82050428
50105273	2 number potholes (RD: CW Pothole)	At traffic lights opposite fire station	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/02/2022	08/02/2022	Act. ROAD/82059753
Asset: 3.00		Asset - Locn.: Ward 17 - From Newcraighall Road south at entrance to Newcr			Feature Type: Road Asset		
					Area: North East Locality		