

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Site: Princes Street (7903151)

Locality: New Town, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

| Defect No. | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|------------------------|-----------------------------|-----------------------|--|-------------------------------|------------|--------------|----------------------------------|---------|
| Asset: | 2.00 | Asset - Locn.: | Ward 11 - From The Mound to Hanover Street | Feature Type: | Road Asset | | Area: South East Locality | |
| Batch: 41121255 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 30/03/2022 | |
| | No actionable defects found | | | | | | | |
| Batch: 41118152 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 03/03/2022 | |
| | No actionable defects found | | | | | | | |
| Batch: 41117788 | - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 02/03/2022 | |
| | No actionable defects found | | | | | | | |
| Batch: 41115028 | - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 08/02/2022 | |
| | No actionable defects found | | | | | | | |
| Batch: 41115015 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 08/02/2022 | |
| | No actionable defects found | | | | | | | |
| Batch: 41112774 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 11/01/2022 | |
| | No actionable defects found | | | | | | | |
| Batch: 41111778 | - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 29/12/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41109797 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 07/12/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41108112 | - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 23/11/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41106816 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 05/11/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41105128 | - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 22/10/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41102766 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 04/10/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41101229 | - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 22/09/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41099409 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 02/09/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41098683 | - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 20/08/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41097411 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 02/08/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41096282 | - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 14/07/2021 | |
| | No actionable defects found | | | | | | | |
| Batch: 41095427 | - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 02/07/2021 | |
| | No actionable defects found | | | | | | | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|------------------------|---|--|----------|---------------------------------|--------|----------------------------------|--------|-------------------------|
| Asset: | 2.00 | Asset - Locn.: Ward 11 - From The Mound to Hanover Street | | Feature Type: Road Asset | | Area: South East Locality | | |
| Batch: 41094528 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 17/06/2021 |
| Batch: 41094509 | - Inspection Batch No actionable defects found | | | Route: SE_CF1_PrinceSt1 | | | | Date: 17/06/2021 |
| Batch: 41093396 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 31/05/2021 |
| Batch: 41092383 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 13/05/2021 |
| Batch: 41091162 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 26/04/2021 |
| Batch: 41089745 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 06/04/2021 |
| Batch: 41088638 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 24/03/2021 |
| Batch: 41086004 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 02/03/2021 |
| Batch: 41085551 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 26/02/2021 |
| Batch: 41079605 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 28/01/2021 |
| Batch: 41078128 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 25/01/2021 |
| Batch: 41071757 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 22/12/2020 |
| Batch: 41071412 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 16/12/2020 |
| Batch: 41070192 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 02/12/2020 |
| Batch: 41069322 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 16/11/2020 |
| Batch: 41068618 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 06/11/2020 |
| Batch: 41067023 | - Inspection Batch No actionable defects found | | | Route: SE_CW1_Central1 | | | | Date: 14/10/2020 |
| Batch: 41065618 | - Inspection Batch No actionable defects found | | | Route: SE_FW1_Princes1 | | | | Date: 02/10/2020 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|----------------------------------|--|---|---------------------------------|----------|----------------------------------|-----------|-------------------------|
| Asset: | 2.00 | Asset - Locn.: Ward 11 - From The Mound to Hanover Street | | Feature Type: Road Asset | | Area: South East Locality | | |
| Batch: | 41063064 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 09/09/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41062317 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | | Date: 26/08/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41061507 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 10/08/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41060719 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | | Date: 29/07/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41059572 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 29/06/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41058797 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | | Date: 17/06/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41057862 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 13/05/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41057117 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | | Date: 27/04/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41056671 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 09/04/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41055049 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 09/03/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41054655 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | | Date: 03/03/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41051960 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 12/02/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41050494 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 24/01/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41050074 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | | Date: 21/01/2020 |
| | No actionable defects found | | | | | | | |
| Asset: | 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | | |
| Batch: | 50142487 - Inspection Batch | | | Route: RG: All Features | | | | Date: 23/02/2022 |
| 10001577 | Blocked needs cleaned and jetted | 23/02/2022 | Corner of south at Andrews street and princess street | Gully: Blocked - HP Jet Req'd | Internal | | Committed | 42707528 |
| Batch: | 50142486 - Inspection Batch | | | Route: RG: All Features | | | | Date: 23/02/2022 |
| 10001576 | At corner or princess street | 23/02/2022 | Turning from south David to princess street | Gully: Blocked - HP Jet Req'd | Internal | | Committed | 42707527 |
| Batch: | 41121257 - Inspection Batch | | | Route: SE_CW1_Central1 | | | | Date: 30/03/2022 |
| | No actionable defects found | | | | | | | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|--|-----------------------------|--------------|--------------|--------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41120441 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 24/03/2022 |
| 42097533 | 1no rocking perfecta flag | 24/03/2022 | Outside no125a Easyhotel | RD: FW Slabs Rocking | Internal | | Committed | 50110159 |
| Batch: | 41120177 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/03/2022 |
| 42097256 | 1no rocking perfecta flag | 22/03/2022 | Just east of the Wellington Statue | RD: FW Slabs Rocking | Internal | | Committed | 50109897 |
| Batch: | 41120176 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/03/2022 |
| 42097255 | 6no rocking perfecta flags | 22/03/2022 | Just west of the Wellington Statue | RD: FW Slabs Rocking | Internal | | Committed | 50109896 |
| Batch: | 41120174 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/03/2022 |
| 42097252 | 4no rocking perfecta flags | 22/03/2022 | At the pedestrian crossing outside Register House | RD: FW Slabs Rocking | Internal | | Committed | 50109892 |
| Batch: | 41120173 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/03/2022 |
| 42097251 | 5no rocking perfecta flags | 22/03/2022 | Next to the flag poles outside Register House | RD: FW Slabs Rocking | Internal | | Committed | 50109891 |
| Batch: | 41120171 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/03/2022 |
| 42097246 | 1no blocked gully needs cleaned and flushed | 22/03/2022 | Opposite Dr Martens at pedestrian crossing | Gully: Blocked / Flooding | Internal | | Committed | 50109887 |
| Batch: | 41120170 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/03/2022 |
| 42097245 | 3no rocking perfecta flags | 22/03/2022 | Just east of Great Scot | RD: FW Slabs Rocking | Internal | | Committed | 50109886 |
| Batch: | 41120160 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/03/2022 |
| 42097241 | 1no broken perfecta flag | 22/03/2022 | Outside Three | RD: FW Slabs Broken/Missing | Internal | | Committed | 50109882 |
| Batch: | 41119704 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 17/03/2022 |
| 42096590 | 1no pothole at manhole surround | 17/03/2022 | Eastbound lane outside Phonespot | RD: CW Pothole | Internal | | Committed | 50109383 |
| Batch: | 41119701 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 17/03/2022 |
| 42096588 | 1no pothole | 17/03/2022 | At the pedestrian crossing at the junction of Waverley Bridge | RD: CW Pothole | Internal | | Committed | 50109381 |
| Batch: | 41119356 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 15/03/2022 |
| 42096129 | Sunken gully frame and brander needs reset | 15/03/2022 | Westbound lane at pedestrian crossing opposite burger king | RD: Gully Damaged/Sunken | Internal | | Committed | 50109076 |
| Batch: | 41119227 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/03/2022 |
| 42095943 | 1 number pothole | 14/03/2022 | Outside Monsoon | RD: CW Pothole | Internal | | Committed | 50108923 |
| Batch: | 41119196 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/03/2022 |
| 42095924 | 2no sunken BT manholes | 14/03/2022 | Westbound lane at bus stop PP at the top of the Waverley steps | RU: Utility Apparatus | Internal | | Uncommitted | 50108909 |
| Batch: | 41118678 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 07/03/2022 |
| 42095252 | 2 x loose and rocking flags | 07/03/2022 | Between bus stop PE and boots | RD: FW Slabs Rocking | Internal | | Committed | 50108364 |
| Batch: | 41118676 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 07/03/2022 |
| 42095250 | 1no sunken and rocking perfecta flag | 07/03/2022 | Outside Boots | RD: FW Slabs Rocking | Internal | | Committed | 50108362 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|---|-----------------------------|-----------------|--------------|--------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41118469 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 05/03/2022 |
| 42094889 | Patch within a patch has failed. Area of CW appears to be moving when cars are going over it. | 05/03/2022 | At top of leith street just out with road studs. | RD: CW Cracked/Broken | Internal | | Committed | 50108139 |
| | Assessment required with scope for inspection and permanent patching. | | | | | | | |
| 42094892 | Area of CW has rutted through to binder layer, approx 20 sq/m. | 05/03/2022 | Outside royal house of Scotland at Frederick street junction. | RD: CW Rutting | Internal | | Committed | 50108142 |
| | Previous temp repairs have failed. | | | | | | | |
| 42094893 | Single service manhole cover has dislodged from CW and runs risk of collapse. | 05/03/2022 | Outside phone spot and EE on princes street. | RU: Utility Apparatus | Internal | | Uncommitted | 50108143 |
| | Vehicle impact is causing cover to move. | | | | | | | |
| 42094890 | x2 CW potholes, make safe. | 05/03/2022 | Outside Waverley gate. | RD: CW Pothole | Internal | | Committed | 50108140 |
| 42094891 | Rocking slab, lift and relay. | 05/03/2022 | Opposite Hanover street outside the art gallery. | RD: FW Slabs Rocking | Internal | | Committed | 50108141 |
| Batch: | 41118292 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 04/03/2022 |
| 42094846 | 1no rocking 900x600 pcc flag | 04/03/2022 | Outside no136 Jollibee | RD: FW Slabs Rocking | Internal | | Committed | 50108098 |
| Batch: | 41118153 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 03/03/2022 |
| 42094803 | 2no potholes | 03/03/2022 | At the pedestrian crossing outside the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50108053 |
| 42094802 | 1no pothole | 03/03/2022 | Outside the entrance to the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50108052 |
| Batch: | 41117573 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 01/03/2022 |
| 42094558 | 1no pothole | 01/03/2022 | At the junction of South St David Street | RD: CW Pothole | Internal | | Committed | 50107843 |
| Batch: | 41117097 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 25/02/2022 |
| 42094085 | 1 number pothole | 25/02/2022 | At junction of West Register Street | RD: CW Pothole | Internal | | Committed | 50107437 |
| Batch: | 41116939 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 24/02/2022 |
| 42094034 | Please clean channel and all gullies | 24/02/2022 | Full length of Princes Street (shop side) | Gully: Blocked - Hand Clear | Internal | | Committed | 50107382 |
| Batch: | 41116029 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 17/02/2022 |
| 42093203 | 2 number potholes | 17/02/2022 | At pedestrian crossing and junction of West Register street | RD: CW Pothole | Internal | | Committed | 50106606 |
| Batch: | 41116018 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 17/02/2022 |
| 42093193 | Loose and rocking flag | 17/02/2022 | Outside Fraser Hart | RD: FW Slabs Rocking | Internal | | Committed | 50106597 |
| Batch: | 41115764 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 16/02/2022 |
| 42092977 | Relay Loose and rocking flag | 16/02/2022 | Outside Topshop | RD: FW Slabs Rocking | Internal | | Committed | 50106395 |
| Batch: | 41115559 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/02/2022 |
| 42092748 | Collapsed Scottish power number one on footway | 14/02/2022 | Outside Art Gallery | RU: Utility Apparatus | Internal | | Uncommitted | 50106201 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|---|-----------------------------|-----------------|--------------|--------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41115558 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/02/2022 |
| 42092747 | Collapsed Scottish power concrete cover number one box on footway | 14/02/2022 | Outside Art Gallery | RU: Utility Apparatus | Internal | | Uncommitted | 50106200 |
| Batch: | 41115555 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/02/2022 |
| 42092744 | Damaged cover on fw | 14/02/2022 | Princess street at the mound | RU: Utility Apparatus | Internal | | Uncommitted | 50106197 |
| Batch: | 41115022 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 08/02/2022 |
| 42092295 | x2 rocking cut slabs, lift and relay. | 08/02/2022 | Opposite old Waverley hotel. | RD: FW Slabs Rocking | Internal | | Committed | 50105687 |
| Batch: | 41115014 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 08/02/2022 |
| Batch: | 41114586 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 03/02/2022 |
| 42091796 | 4 number potholes | 03/02/2022 | At junction of Fredrick Street | RD: CW Pothole | Internal | | Committed | 50105187 |
| Batch: | 41114583 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 03/02/2022 |
| 42091791 | 1no sunken and rocking perfecta flag | 03/02/2022 | Outside Chisholm Hunter | RD: FW Slabs Rocking | Internal | | Committed | 50105183 |
| Batch: | 41113626 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 20/01/2022 |
| 42090251 | 1no broken and sunken perfecta flag | 20/01/2022 | Outside no60 Marks and Spencer | RD: FW Slabs Broken/Missing | Internal | | Committed | 50103617 |
| Batch: | 41113625 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 20/01/2022 |
| 42090250 | Relay 3 rocking and 2 broken perfect flags | 20/01/2022 | Outside Zara | RD: FW Slabs Rocking | Internal | | Committed | 50103615 |
| Batch: | 41113624 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 20/01/2022 |
| 42090249 | 1no broken sunken perfecta flag | 20/01/2022 | Outside Boots | RD: FW Slabs Broken/Missing | Internal | | Committed | 50103614 |
| Batch: | 41113057 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/01/2022 |
| 42089276 | Recently reinstated Zayo manhole frame and covers very loose and extremely noisy | 14/01/2022 | Westbound lane opposite South Charlotte Street | RU: Utility Reinstatement | Internal | | Uncommitted | 50102839 |
| Batch: | 41113055 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/01/2022 |
| 42089272 | Sunken manhole with sunken lids | 14/01/2022 | Eastbound lane outside Phone Spot | RU: Utility Apparatus | Internal | | Uncommitted | 50102835 |
| Batch: | 41112776 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 11/01/2022 |
| 42088866 | 1no pothole | 11/01/2022 | At the junction of South St David Street | RD: CW Pothole | Internal | | Committed | 50102380 |
| Batch: | 41112014 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 06/01/2022 |
| 42088365 | 1 number pothole | 06/01/2022 | Outside Edinburgh Waverley | RD: CW Pothole | Internal | | Committed | 50101850 |
| Batch: | 41112013 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 06/01/2022 |
| 42088364 | 1no rocking perfecta flag | 06/01/2022 | Outside Foot Locker | RD: FW Slabs Rocking | Internal | | Committed | 50101849 |
| Batch: | 41112011 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 06/01/2022 |
| 42088363 | 4no potholes | 06/01/2022 | Westbound lane outside the entrance to the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50101848 |
| Batch: | 41112010 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 06/01/2022 |
| 42088362 | 1no pothole | 06/01/2022 | Eastbound lane at the junction of West Register Street | RD: CW Pothole | Internal | | Committed | 50101847 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|--|-------------------------------|-----------------|--------------|--------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41112008 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 06/01/2022 |
| 42088361 | 1no pothole | 06/01/2022 | On the pedestrian crossing outside the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50101846 |
| Batch: | 41111930 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 05/01/2022 |
| 42088302 | 2no broken perfecta flags 1no rocking perfecta flag 1no rocking cut perfecta flag | 05/01/2022 | Outside Clarks no81 | RD: FW Slabs Broken/Missing | Internal | | Committed | 50101730 |
| Batch: | 41111844 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 30/12/2021 |
| 42088245 | x1 rocking cut Caithness slab, lift and relay. | 30/12/2021 | Outside the balmoral. | RD: FW Slabs Rocking | Internal | | Committed | 50101603 |
| 42088244 | Manhole cover is low against existing CW and is causing damage. | 30/12/2021 | At junction of south David street. | RU: Utility Apparatus | Internal | | Uncommitted | 50101602 |
| 42088243 | x2 broken cut slabs, lift and replace. | 30/12/2021 | Opposite Debenhams. | RD: FW Slabs Broken/Missing | Internal | | Committed | 50101601 |
| Batch: | 41111573 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/12/2021 |
| 42088043 | Failed asphalt reinstatement at Scottish Water manhole surround | 22/12/2021 | Eastbound Lane at the junction of Frederick Street | RU: Utility Reinstatement | Internal | | Uncommitted | 50101297 |
| Batch: | 41110484 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/12/2021 |
| 42087036 | 1no pothole | 14/12/2021 | Outside the entrance to the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50100212 |
| Batch: | 41109918 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 08/12/2021 |
| 42086336 | 1no broken perfecta flag 1no rocking perfecta flag | 08/12/2021 | Outside Holland and Barrett | RD: FW Slabs Broken/Missing | Internal | | Committed | 50099626 |
| Batch: | 41109798 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 07/12/2021 |
| 42086208 | 1no pothole | 07/12/2021 | Eastbound lane at the junction of West Register Street | RD: CW Pothole | Internal | | Committed | 50099521 |
| 42086207 | 1no pothole | 07/12/2021 | Eastbound lane outside Monsoon | RD: CW Pothole | Internal | | Committed | 50099520 |
| Batch: | 41109088 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 02/12/2021 |
| 42085937 | Trip hazard at guardrail socket Please ramp off with grano | 02/12/2021 | Opposite Accessorize | RD: FW Grano Depression/Sunk | Internal | | Committed | 50099200 |
| Batch: | 41108455 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 26/11/2021 |
| 42085385 | x1 rocking slab, lift and relay. | 26/11/2021 | At ped crossing outside art gallery. | RD: FW Slabs Rocking | Internal | | Committed | 50098657 |
| 42085387 | x1 broken 600x600, lift and replace. | 26/11/2021 | Outside entrance to Edinburghs Christmas. | RD: FW Slabs Broken/Missing | Internal | | Committed | 50098659 |
| Batch: | 41107876 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 19/11/2021 |
| 42084570 | 1no dislodged kerb needs reset 1no broken 750x600 courtstone flag 1no rocking cut courtstone flag | 19/11/2021 | At the top of the Waverley steps | RD: FW Kerb Dislodged/Rocking | Internal | | Committed | 50097817 |
| Batch: | 41107697 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 17/11/2021 |
| 42084143 | 1no broken perfecta flag 3no rocking perfecta flags 2no rocking tactile flags | 17/11/2021 | At the pedestrian crossing outside Topshop | RD: FW Slabs Broken/Missing | Internal | | Committed | 50097496 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|---|----------------------------|-----------------|--------------|--------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41107533 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 16/11/2021 |
| 42083854 | Replaced missing bollards | 16/11/2021 | | RD: SFP Damaged Bollard | Internal | | Committed | 50097267 |
| Batch: | 41107345 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 15/11/2021 |
| 42083570 | 1no pothole | 15/11/2021 | Near the pedestrian crossing outside the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50097068 |
| Batch: | 41106858 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 08/11/2021 |
| 42082644 | 1no pothole | 08/11/2021 | Eastbound lane outside Primark | RD: CW Pothole | Internal | | Committed | 50096208 |
| Batch: | 41106817 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 05/11/2021 |
| | No actionable defects found | | | | | | | |
| Batch: | 41106601 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 04/11/2021 |
| 42082396 | Reset sunken drainage manhole | 04/11/2021 | West bound at bus stop PT | RD: CW Manhole Cover Reset | Internal | | Committed | 50095921 |
| Batch: | 41106474 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 03/11/2021 |
| 42082098 | Collapsed lid on Scottish Power box | 03/11/2021 | On the footway opposite South Charlotte Street near the pedestrian crossing Called [REDACTED] from Scottish Power no reference number given said action would be taken today | RU: Utility Apparatus | Internal | | Uncommitted | 50095657 |
| Batch: | 41106466 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 03/11/2021 |
| 42082093 | 1no pothole at manhole | 03/11/2021 | Westbound lane outside the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50095650 |
| Batch: | 41105966 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 01/11/2021 |
| 42081747 | 1 number pothole round manhole | 01/11/2021 | At junction of South St David Street | RD: CW Pothole | Internal | | Committed | 50095330 |
| Batch: | 41105951 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 01/11/2021 |
| 42081743 | 1no rocking 900x600 pcc flag | 01/11/2021 | Opposite Tesco Express | RD: FW Slabs Rocking | Internal | | Committed | 50095325 |
| Batch: | 41105392 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 26/10/2021 |
| 42081217 | Reset 4 x Loose and rocking tactile at crossing | 26/10/2021 | At crossing outside Edinburgh Gin | RD: FW Slabs Rocking | Internal | | Committed | 50094808 |
| Batch: | 41105390 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 26/10/2021 |
| 42081213 | 1no rocking 900x600 pcc flag | 26/10/2021 | At bus stop PP outside Waverley mall coffee bar | RD: FW Slabs Rocking | Internal | | Committed | 50094807 |
| Batch: | 41105125 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 22/10/2021 |
| 42081006 | Single service manhole cover is low against existing CW and is causing damage to the surrounding road structure. | 22/10/2021 | Outside the balmoral hotel. See photos. | RU: Utility Apparatus | Internal | | Uncommitted | 50094546 |
| 42081008 | Open grano joint at access chamber. | 22/10/2021 | Opposite Chisholm hunter. | RD: FW Grano Open Joint | Internal | | Committed | 50094548 |
| Batch: | 41104709 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 20/10/2021 |
| 42080827 | 1 number pothole | 20/10/2021 | Outside Barclays Bank at bus stop | RD: CW Pothole | Internal | | Committed | 50094344 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|--|-----------------------------|-----------------|--------------|--------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41102767 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 04/10/2021 |
| | No actionable defects found | | | | | | | |
| Batch: | 41101167 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 22/09/2021 |
| 42078917 | 3no rocking perfecta flags | 22/09/2021 | On the east side of the junction with south st Andrew st | RD: FW Slabs Rocking | Internal | | Uncommitted | 50085365 |
| 42078970 | Double service manhole cover has failed in one section and the frame has split. | 22/09/2021 | Opposite three shop on CW. Next to ped crossing. | RU: Utility Apparatus | Internal | | Uncommitted | 50092364 |
| | Patch surround has also failed and further deterioration is expected. | | | | | | | |
| 42078934 | x1 grano pothole at manhole. Remove loose and replace with fresh grano. | 22/09/2021 | Outside the Edinburgh gift shop. | RD: FW Grano Pothole | Internal | | Committed | 50092338 |
| 42078945 | x1 rocking cut perfecta slab, lift and relay. | 22/09/2021 | Next to bus stop outside h.samuel. | RD: FW Slabs Rocking | Internal | | Committed | 50092348 |
| 42078948 | x3 rocking perfecta slab, lift and relay. | 22/09/2021 | Outside H.samuel. | RD: FW Slabs Rocking | Internal | | Committed | 50092349 |
| 42078973 | x1 grano pothole, make safe. | 22/09/2021 | Opposite premier inn next to bus stop. | RD: FW Grano Pothole | Internal | | Committed | 50092365 |
| 42078968 | Open grano joint around NAL cover. | 22/09/2021 | Opposite 3 at ped crossing. | RD: FW Grano Open Joint | Internal | | Committed | 50092363 |
| 42078984 | SV Cover within CW is low against CW. | 22/09/2021 | Opposite monsoon within CW. | RU: Utility Apparatus | Internal | | Uncommitted | 50092372 |
| 42078943 | x1 grano pothole at manhole. Remove loose and replace with fresh grano. | 22/09/2021 | Bottom of castle street at ped crossing. | RD: FW Grano Pothole | Internal | | Committed | 50092346 |
| 42078940 | x1 rocking cut perfecta slab, lift and relay. | 22/09/2021 | Outside Ernest Jones. | RD: FW Slabs Rocking | Internal | | Committed | 50092344 |
| 42078927 | x6 rocking perfecta slabs, lift and replace. | 22/09/2021 | Outside old Vodafone shop, next to ped crossing. | RD: FW Slabs Rocking | Internal | | Committed | 50092333 |
| 42078966 | x1 rocking Caithness flag, lift and relay. | 22/09/2021 | Opposite royal bank of Scotland at the church. | RD: FW Slabs Rocking | Internal | | Committed | 50092361 |
| Batch: | 41101137 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/09/2021 |
| 42078899 | Broken gully frame and sunken brander needs replaced | 22/09/2021 | Outside no1 Prince Brasserie | RD: Gully Damaged/Sunken | Internal | | Committed | 50092321 |
| Batch: | 41099539 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 02/09/2021 |
| | No actionable defects found | | | | | | | |
| Batch: | 41099516 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 02/09/2021 |
| 42077276 | 1no broken cut perfecta flag | 02/09/2021 | Outside the old Jenners building next to the pedestrian crossing | RD: FW Slabs Broken/Missing | Internal | | Committed | 50091043 |
| Batch: | 41099515 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 02/09/2021 |
| 42077274 | 1no rocking perfecta flag | 02/09/2021 | On the corner of Hanover Street outside Fraser Hart | RD: FW Slabs Rocking | Internal | | Committed | 50091041 |
| Batch: | 41099021 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 26/08/2021 |
| 42076713 | Please hand clean blocked gully | 26/08/2021 | Opposite Primark on the crossing point at the tram stop | Gully: Blocked - Hand Clear | Internal | | Committed | 50090527 |
| Batch: | 41098645 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 20/08/2021 |
| 42076455 | Pothole | 20/08/2021 | O/S River Island | RD: CW Pothole | Internal | | Committed | 50090159 |
| 42076442 | Double manhole cover not flush | 20/08/2021 | Opp South Charlotte St | RU: Utility Apparatus | Internal | | Uncommitted | 50090146 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|--|-----------------------------|-----------------|--------------|--------------|---------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41098645 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | Date: | 20/08/2021 |
| 42076459 | 4 Broken- loose 1 cut perfecta slabs and 3 rocking | 20/08/2021 | O/S Boots beside footway manhole | RD: FW Slabs Broken/Missing | Internal | | Committed | 50090163 |
| 42076447 | Trip at footway manhole infill with grano | 20/08/2021 | O/S McDonald's | RD: FW Grano Open Joint | Internal | | Committed | 50090151 |
| 42076429 | Loose small slab needs reset | 20/08/2021 | 10m east of entrance to Livingston Statue | RD: FW Slabs Rocking | Internal | | Committed | 50090133 |
| 42076467 | Rocking slab need reset | 20/08/2021 | O/S H and M | RD: FW Slabs Rocking | Internal | | Committed | 50090171 |
| 42076468 | Rocking slabs x 3 and 1 broken causing trip | 20/08/2021 | O/S Topman near tactiles tactiles | RD: FW Slabs Rocking | Internal | | Committed | 50090172 |
| 42076466 | Pothole at manhole | 20/08/2021 | O/S Monsoon | RD: CW Pothole | Internal | | Committed | 50090170 |
| 42076464 | Rocking slab need reset | 20/08/2021 | O/S Marks And Spencer | RD: FW Slabs Rocking | Internal | | Committed | 50090168 |
| 42076446 | Broken- loose 900 x 600 needs renewed | 20/08/2021 | O/S Tesco Express | RD: FW Slabs Broken/Missing | Internal | | Committed | 50090150 |
| 42076443 | Pothole at SV CW manhole | 20/08/2021 | At Lothian Road | RD: CW Pothole | Internal | | Committed | 50090147 |
| 42076435 | Small section of slab missing please infill with grano to remove trip | 20/08/2021 | Beside corner plinth of National gallery | RD: FW Slabs Broken/Missing | Internal | | Committed | 50090139 |
| 42076452 | Rocking slabs x 5 need reset | 20/08/2021 | O/S Three shop | RD: FW Slabs Rocking | Internal | | Committed | 50090156 |
| 42076433 | Low slab at footway manhole please lift and relay to remove trip | 20/08/2021 | O/S Gable end of Mound Monument | RD: FW Slabs Rocking | Internal | | Committed | 50090137 |
| 42076469 | Rocking slabs x 2 | 20/08/2021 | 15m east of S St Andrews St | RD: FW Slabs Rocking | Internal | | Committed | 50090173 |
| 42076454 | Section of ACO channel broken and not flush leaving trip needs reset | 20/08/2021 | O/S Urban Outfitters at bus stop | RD: Polychannel Damaged | Internal | | Committed | 50090158 |
| 42076463 | Trip at ACO channel infill with tar | 20/08/2021 | O/S Fraser Hart | RD: FW HRA Pothole | Internal | | Committed | 50090167 |
| 42076462 | Rocking slab need reset | 20/08/2021 | O/S Ernest Jones beside footway manhole | RD: FW Slabs Rocking | Internal | | Committed | 50090166 |
| 42076457 | 1 Broken- loose perfecta no slab and 5 rocking | 20/08/2021 | O/S ZARA shop | RD: FW Slabs Broken/Missing | Internal | | Committed | 50090161 |
| 42076460 | Rocking slab need reset | 20/08/2021 | O/S no 80 Clark's at crossing | RD: FW Slabs Rocking | Internal | | Committed | 50090164 |
| 42076465 | Pothole at manhole | 20/08/2021 | At South St David's St | RD: CW Pothole | Internal | | Committed | 50090169 |
| 42076437 | 2 x low slabs please lift and relay to remove trips | 20/08/2021 | Opp Debenhams 5m and 7m east of bus stop | RD: FW Slabs Rocking | Internal | | Committed | 50090141 |
| 42076449 | low slab please lift and relay to remove trip | 20/08/2021 | O/S no 136 | RD: FW Slabs Rocking | Internal | | Committed | 50090153 |
| 42076440 | 2 x low slabs please lift and relay to remove trip | 20/08/2021 | Opp Poundland at bus stop | RD: FW Slabs Rocking | Internal | | Committed | 50090144 |
| 42076439 | Broken- loose 900 x 600 needs renewed | 20/08/2021 | Opp H Samuel | RD: FW Slabs Broken/Missing | Internal | | Committed | 50090143 |
| 42076427 | 2 x Loose small slabs need reset and pointed | 20/08/2021 | O/S Costa coffee | RD: FW Slabs Rocking | Internal | | Committed | 50090131 |
| 42076423 | Pothole at manhole | 20/08/2021 | O/S Balmoral | RD: CW Pothole | Internal | | Committed | 50090127 |
| Batch: | 41097417 - Inspection Batch | | | Route: | SE_CW1_Central1 | | Date: | 02/08/2021 |
| | No actionable defects found | | | | | | | |
| Batch: | 41096512 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 20/07/2021 |
| 42073769 | Loose and rocking tactile | 20/07/2021 | Outside Three | RD: FW Slabs Rocking | Internal | | Committed | 50087724 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|---|-------------------------------|------------------|--------------|-----------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41096511 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 20/07/2021 |
| 42073768 | Broken and noisy manhole frame and cover | 20/07/2021 | Westbound carriageway opposite South RU: Utility Apparatus Charlotte Street | | Internal | | Uncommitted | 50087723 |
| Batch: | 41096490 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 20/07/2021 |
| 42073750 | Loose and noisy manhole | 20/07/2021 | On the carriageway at the junction of South St David Street near Monsoon | RU: Utility Apparatus | Internal | | Uncommitted | 50087710 |
| Batch: | 41096489 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 20/07/2021 |
| 42073748 | 1no pothole | 20/07/2021 | At the junction of South St David Street | RD: CW Pothole | Internal | | Committed | 50087708 |
| Batch: | 41096315 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 15/07/2021 |
| 42073604 | Defective manhole | 15/07/2021 | Princes Street west bound at South Charlotte Street junction. | RU: Utility Apparatus | Internal | | Uncommitted | 50087514 |
| Batch: | 41096237 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 14/07/2021 |
| 42073483 | 2no rocking cut pcc flags | 14/07/2021 | Opposite the Edinburgh gift shop near to the Scots monument | RD: FW Slabs Rocking | Internal | | Committed | 50087436 |
| 42073475 | 1no rocking flag | 14/07/2021 | Next to the pedestrian crossing outside the balmoral hotel | RD: FW Slabs Rocking | Internal | | Committed | 50087430 |
| 42073479 | 3no broken 600x900 pcc flags | 14/07/2021 | Outside Costa coffee | RD: FW Slabs Broken/Missing | Internal | | Committed | 50087432 |
| 42073470 | 1no rocking flag 1no broken perfecta flag | 14/07/2021 | Outside Holland and barrett | RD: FW Slabs Rocking | Internal | | Committed | 50087428 |
| 42073466 | 3no rocking flags 1no broken perfecta flag | 14/07/2021 | At the foot of castle st 5m north of pedestrian crossing | RD: FW Slabs Rocking | Internal | | Committed | 50087423 |
| 42073497 | 1no broken 600x900 pcc flag | 14/07/2021 | Opposite boots | RD: FW Slabs Broken/Missing | Internal | | Committed | 50087444 |
| 42073467 | 2no rocking flags 1no broken perfecta flag | 14/07/2021 | At skechers doorway | RD: FW Slabs Rocking | Internal | | Committed | 50087424 |
| 42073492 | Renew grano at box | 14/07/2021 | Opposite Chisholm Hunter | RD: FW Grano Cracked/Broken | Internal | | Committed | 50087441 |
| Batch: | 41096115 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 13/07/2021 |
| 42073343 | Cw potholes x5 please make safe | 13/07/2021 | Princess street at Frederick street os royal house of Scotland | RD: CW Pothole | Internal | | Committed | 50087318 |
| Batch: | 41095428 - Inspection Batch No actionable defects found | | | Route: | SE_CW1_Central1 | | | Date: 02/07/2021 |
| Batch: | 41094628 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 21/06/2021 |
| 42071455 | 5no potholes | 21/06/2021 | At the pedestrian crossing outside the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50085569 |
| Batch: | 41094578 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 18/06/2021 |
| 42071410 | Dislodged kerb x2 | 18/06/2021 | Princess st at south st David st os Jenners | RD: FW Kerb Dislodged/Rocking | Internal | | Committed | 50085511 |
| Batch: | 41094530 - Inspection Batch No actionable defects found | | | Route: | SE_FW1_Princes1 | | | Date: 17/06/2021 |
| Batch: | 41094427 - Inspection Batch | | | Route: | SE_CF1_PrinceSt1 | | | Date: 17/06/2021 |
| 42071224 | 10no broken perfecta flags | 16/06/2021 | Outside Royal house | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071192 | 16no broken perfecta flags | 16/06/2021 | Outside Poundland | RD: FW Slabs Broken/Missing | Internal | | Action Required | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|--|-------------------------------|------------------|--------------|--------------------|---------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41094427 - Inspection Batch | | | Route: | SE_CF1_PrinceSt1 | | Date: | 17/06/2021 |
| 42071205 | 2no Heaving on asphalt surface approx 1mx1m each | 16/06/2021 | Outside Debenhams | RD: CW Subsidence/Heaving | Internal | | Action Required | |
| 42071322 | Replace grano around manhole | 17/06/2021 | Opposite Ann summers | RD: FW Grano Cracked/Broken | Internal | | Committed | 50085394 |
| 42071237 | 4no rocking flags | 16/06/2021 | At the junction with Frederick st on east side outside Chisholm hunter | RD: FW Slabs Rocking | Internal | | Committed | 50085344 |
| 42071288 | 3no asphalt patches required approx 2mx1m 2mx2m 1mx1m | 16/06/2021 | At the junction of West Register Street | RD: CW Cracked/Broken | Internal | | Action Required | |
| 42071256 | 2no rocking perfecta flags | 16/06/2021 | Outside yo sushi | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071245 | 2no rocking perfecta flags 2no broken perfecta flags | 16/06/2021 | Outside Gap | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071303 | 4no broken perfecta flags 1no sunken cut tactile flag | 16/06/2021 | On the corner of South St David Street | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071187 | 3no rocking and broken cut perfecta flags at channel | 16/06/2021 | Outside the EE shop | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071307 | 5no asphalt patches required approx 3mx2m 3mx3m 3mx2m 1mx1m 4mx3m | 17/06/2021 | Westbound lane outside the Balmoral Hotel | RD: CW Cracked/Broken | Internal | | Action Required | |
| 42071285 | 3no rocking perfecta flags | 16/06/2021 | On the east side of the junction with south st Andrew st | RD: FW Slabs Rocking | Internal | | No Action Required | |
| 42071316 | 1no sunken kerb | 17/06/2021 | Outside Costa at Waverley mall | RD: FW Kerb Dislodged/Rocking | Internal | | Action Required | |
| 42071193 | 670mm section of channel low/broken | 16/06/2021 | Outside urban outfitters | RD: FW Channel Damaged | Internal | | Action Required | |
| 42071211 | 2no broken perfecta flags | 16/06/2021 | Outside Levi's | RD: FW Slabs Broken/Missing | Internal | | Uncommitted | 50085335 |
| 42071282 | 1no rocking perfecta flag | 16/06/2021 | Outside H&M approx 5m from no40 doorway | RD: FW Slabs Rocking | Internal | | Committed | 50085363 |
| 42071248 | 4no rocking perfecta flags | 16/06/2021 | Outside Superdrug | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071252 | 1no rocking perfecta flag | 16/06/2021 | Outside Scribbler | RD: FW Slabs Rocking | Internal | | Committed | 50085352 |
| 42071180 | 9no broken 900x600 pcc grey flags 3no broken 600x600 pcc grey flags 3no broken cut flags at kerb | 16/06/2021 | Outside Tesco express | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071239 | 1no low fire hydrant also cracking and potholed asphalt in previous reinstatement | 16/06/2021 | Outside Primark on eastbound lane | RU: Utility Apparatus | Internal | | Uncommitted | 50085345 |
| 42071201 | 2no sections of aco channel low/broken approx 2m | 16/06/2021 | Outside Lush | RD: FW Channel Damaged | Internal | | Action Required | |
| 42071188 | 12no broken perfecta flags | 16/06/2021 | Outside USC | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071279 | 2no dislodged kerb | 16/06/2021 | At the junction with south st David st on west side | RD: FW Kerb Dislodged/Rocking | Internal | | Action Required | |
| 42071249 | 1no broken perfecta flag | 16/06/2021 | Outside clarks | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071206 | 7no low perfecta flags | 16/06/2021 | Outside Debenhams | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071226 | Asphalt surface cracked and broken approx 4mx1m 3mx1m | 16/06/2021 | At the junction of Frederick street | RD: CW Cracked/Broken | Internal | | Action Required | |
| 42071213 | 7no broken perfecta flags | 16/06/2021 | Outside Zara | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071290 | Cracked and broken asphalt surface approx 2mx3m | 16/06/2021 | Eastbound lane at pedestrian crossing at North Bridge | RD: CW Cracked/Broken | Internal | | Action Required | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|--|-----------------------------|------------------|--------------|----------------------------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: South East Locality | |
| Batch: | 41094427 - Inspection Batch | | | Route: | SE_CF1_PrinceSt1 | | | Date: 17/06/2021 |
| 42071313 | 17no broken 900x600 pcc grey flags 1no broken 750x600 pcc grey flags 2no broken cut flags at kerblines | 17/06/2021 | Between bus stop PP and PQ | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071219 | Area of missing perfecta flags approx 2x2.5m | 16/06/2021 | Outside Zara | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071184 | Refresh cycle box markings at traffic lights | 16/06/2021 | Outside pret at traffic lights | RD: Markings Refresh | Internal | | Action Required | |
| 42071287 | Patching required in channel approx 15mx0.4m Patch required approx 1mx2m | 16/06/2021 | From footlocker to Barclays bank | RD: CW Cracked/Broken | Internal | | Action Required | |
| 42071182 | 1no broken 600x900 pcc flag 1no rocking 600x750 pcc flag Replace broken grano at box | 16/06/2021 | Outside McDonald's | RD: FW Slabs Broken/Missing | Internal | | Committed | 50085321 |
| 42071310 | 12no broken courtstone flags | 17/06/2021 | Outside number one | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071186 | 14no broken perfecta flags | 16/06/2021 | Outside no132 | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071334 | 1no broken 600x900 pcc flag | 17/06/2021 | Opposite Swarovski | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071317 | Patching required approx 0.5mx1.5m | 17/06/2021 | Opposite jenners | RD: CW Cracked/Broken | Internal | | Action Required | |
| 42071221 | Low area of perfecta flags approx 2mx2m | 16/06/2021 | Outside boots | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071262 | Approx 10m of damaged aco channel needs replaced | 16/06/2021 | Outside Fraser Hart | RD: FW Channel Damaged | Internal | | Action Required | |
| 42071257 | 3no rocking perfecta flags | 16/06/2021 | Outside Skechers | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071197 | Grano at box cracked/broken | 16/06/2021 | At the junction with castle st | RD: FW Grano Cracked/Broken | Internal | | Action Required | |
| 42071264 | 2no rocking perfecta flags | 16/06/2021 | Outside Fraser hart | RD: FW Slabs Rocking | Internal | | Committed | 50085356 |
| 42071230 | 5no uneven perfecta flags lift and relay | 16/06/2021 | At the junction with Frederick st on west side | RD: FW Slabs Rocking | Internal | | Committed | 50085339 |
| 42071194 | 11no broken perfecta flags | 16/06/2021 | Outside HSBC | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071311 | 1no rocking pcc flag | 17/06/2021 | At bus stop PP | RD: FW Slabs Rocking | Internal | | Committed | 50085387 |
| 42071204 | 3no rocking perfecta flags | 16/06/2021 | Outside hotter | RD: FW Slabs Rocking | Internal | | Uncommitted | 50085332 |
| 42071292 | Patching required approx 0.5mx1m and 1mx1m | 16/06/2021 | On eastbound lane next to Wellington statue | RD: CW Cracked/Broken | Internal | | Action Required | |
| 42071355 | Please refresh tram only markings | 17/06/2021 | Westbound lane at the junction of the Mound | RD: Markings Refresh | Internal | | Action Required | |
| 42071270 | 2no rocking perfecta flags | 16/06/2021 | Outside Great Scot | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071324 | Sunken gully frame and brander needs reset | 17/06/2021 | Westbound lane at pedestrian crossing opposite burger king | RD: Gully Frame Damaged | Internal | | No Action Required | |
| 42071306 | 9no broken courtstone flags | 17/06/2021 | At the entrance to the Balmoral | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071289 | 5 broken perfecta flags 6no broken tactile flags | 16/06/2021 | On the corner of West Register Street | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071332 | 1no rocking pcc flag | 17/06/2021 | Opposite Chisholm hunter | RD: FW Slabs Rocking | Internal | | Committed | 50085403 |
| 42071315 | Slab at back of footpath broken replace with grano | 17/06/2021 | At costa coffee | RD: FW Grano Cracked/Broken | Internal | | Action Required | |
| 42071286 | 5 broken perfecta flags 2no rocking perfecta flags | 16/06/2021 | Outside Holland and Barrett | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071284 | 3no broken perfecta flags | 16/06/2021 | Outside Vodafone | RD: FW Slabs Broken/Missing | Internal | | Action Required | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|--|------------------------------|------------|--------------|-----------------|---------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41094427 - Inspection Batch | | Route: | SE_CF1_PrinceSt1 | | | Date: | 17/06/2021 |
| 42071335 | 1no rocking 900x600 pcc flag 1no broken cut pcc flag | 17/06/2021 | Opposite Boots | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071308 | approx 3m missing whin kerb 6no broken/missing courtstone flags | 17/06/2021 | At the junction with north bridge | RD: FW Kerbs Damaged/Missing | Internal | | Action Required | |
| 42071242 | 2no low/rocking tactile flags lift and relay | 16/06/2021 | Outside primark at pedestrian crossing | RD: FW Slabs Rocking | Internal | | Committed | 50085348 |
| 42071280 | Grano at manhole cracked/broken | 16/06/2021 | Outside the Edinburgh gift shop | RD: FW Grano Cracked/Broken | Internal | | Action Required | |
| 42071210 | 2no carriageway reinstatement's failed potholed and badly cracking | 16/06/2021 | Outside river island at bus stop PD on eastbound carriageway | RU: Utility Reinstatement | Internal | | Uncommitted | 50085334 |
| 42071281 | 5no broken perfecta flags 1no rocking perfecta flag | 16/06/2021 | Outside smiggle | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071189 | 1no rocking perfecta flag | 16/06/2021 | At mountain warehouse doorway | RD: FW Slabs Rocking | Internal | | Committed | 50085324 |
| 42071312 | 1no rocking pcc flag | 17/06/2021 | Approx 5m west of bus stop PP | RD: FW Slabs Rocking | Internal | | Committed | 50085388 |
| 42071243 | 4no rocking perfecta flags 1no broken perfecta flag | 16/06/2021 | Outside kingdom of sweets | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071217 | 2no rocking perfecta flags 2no broken perfecta flag | 16/06/2021 | Outside zara | RD: FW Slabs Rocking | Internal | | Committed | 50085336 |
| 42071196 | 4no broken perfecta flags Low small grano patch | 16/06/2021 | On the west corner of the junction with castle st at shop doorway | RD: FW Slabs Broken/Missing | Internal | | Uncommitted | 50085326 |
| 42071191 | 15no broken perfecta flags | 16/06/2021 | Outside no120b | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071223 | 1no broken perfecta flag | 16/06/2021 | Outside Swarovski | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071314 | 30no broken 900x600 pcc grey flags 15 broken cut flags at kerbline | 17/06/2021 | Outside Costa at Waverley mall | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071261 | 1no rocking perfecta flag | 16/06/2021 | On the corner of Hanover Street outside Fraser Hart | RD: FW Slabs Rocking | Internal | | Action Required | |
| 42071190 | 17no broken perfecta flags | 16/06/2021 | Outside Urban Outfitters | RD: FW Slabs Broken/Missing | Internal | | Action Required | |
| 42071275 | 2no rocking perfecta flags | 16/06/2021 | Outside the works | RD: FW Slabs Rocking | Internal | | Action Required | |
| Batch: | 41094009 - Inspection Batch | | Route: | Ad hoc Route | | | Date: | 09/06/2021 |
| 42070869 | 1no rocking perfecta flag | 09/06/2021 | Outside Gap | RD: FW Slabs Rocking | Internal | | Committed | 50084981 |
| Batch: | 41093868 - Inspection Batch | | Route: | Ad hoc Route | | | Date: | 08/06/2021 |
| 42070681 | Missing cat posts and bases needs replaced with new bases | 08/06/2021 | | RD: SFP Damaged Bollard | Internal | | Committed | 50084837 |
| Batch: | 41093562 - Inspection Batch | | Route: | Ad hoc Route | | | Date: | 02/06/2021 |
| 42070212 | Missing cat posts and bases needs replaced damaged | 02/06/2021 | | RD: SFP Damaged Bollard | Internal | | Committed | 50084456 |
| Batch: | 41093539 - Inspection Batch | | Route: | Ad hoc Route | | | Date: | 02/06/2021 |
| 42070189 | 2no rocking perfecta flags 1no rocking cut perfecta flag | 02/06/2021 | On the corner of Frederick Street outside Chisholm Hunter | RD: FW Slabs Rocking | Internal | | Committed | 50084431 |
| Batch: | 41093538 - Inspection Batch | | Route: | Ad hoc Route | | | Date: | 02/06/2021 |
| 42070188 | 1no missing perfecta flag nee | 02/06/2021 | At the entrance to Chisholm Hunter jewellers | RD: FW Slabs Broken/Missing | Internal | | Committed | 50084429 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|---|-----------------------------|-----------------|--------------|--------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41093536 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 02/06/2021 |
| 42070186 | 1no pothole | 02/06/2021 | Westbound lane outside waverleygate at the traffic lights | RD: CW Pothole | Internal | | Committed | 50084423 |
| Batch: | 41093395 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 31/05/2021 |
| 42070009 | 1no pothole | 31/05/2021 | At bus stop PK outside Mercure Hotel | RD: CW Pothole | Internal | | Committed | 50084243 |
| 42070017 | 2no potholes | 31/05/2021 | On the pedestrian crossing near the Wellington statue | RD: CW Pothole | Internal | | Committed | 50084247 |
| Batch: | 41092922 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 25/05/2021 |
| 42069537 | Missing cat posts | 25/05/2021 | | RD: SFP Damaged Bollard | Internal | | Committed | 50083747 |
| Batch: | 41092821 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 21/05/2021 |
| 42069439 | 1no pothole at manhole surround | 21/05/2021 | At the junction of South St David Street | RD: CW Pothole | Internal | | Committed | 50083559 |
| Batch: | 41092819 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 21/05/2021 |
| 42069437 | 1no pothole at manhole surround | 21/05/2021 | Outside the entrance to the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50083557 |
| Batch: | 41092374 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 13/05/2021 |
| 42068925 | Potholes x 6 | 13/05/2021 | O/S GAP in channel | RD: CW Pothole | Internal | | Committed | 50083033 |
| 42068928 | Loose / low slab please lift and relay | 13/05/2021 | O/S Ganble end of Zara next to polychannel | RD: FW Slabs Rocking | Internal | | Committed | 50083036 |
| Batch: | 41091711 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 05/05/2021 |
| 42068242 | 3no sunken 900x600 pcc flags 1no sunken broken 900x600 pcc flag 1no sunken 450x600 pcc flag | 05/05/2021 | At bus stop PY opposite no120b | RD: FW Slabs Rocking | Internal | | Uncommitted | 50082355 |
| Batch: | 41091463 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 29/04/2021 |
| 42067885 | Sunken and noisy manhole | 29/04/2021 | Westbound carriageway just east of bus stop PT | RU: Utility Apparatus | Internal | | Uncommitted | 50082002 |
| Batch: | 41091165 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 26/04/2021 |
| | No actionable defects found | | | | | | | |
| Batch: | 41089747 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 06/04/2021 |
| 42066513 | Loose and noisy manhole | 06/04/2021 | On the carriageway outside the Balmoral Hotel | RU: Utility Apparatus | Internal | | Uncommitted | 50080518 |
| Batch: | 41089746 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 06/04/2021 |
| 42066512 | 1no pothole at man | 06/04/2021 | Outside the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50080517 |
| Batch: | 41089677 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 06/04/2021 |
| 42066482 | Loose prefects slab needs reset | 06/04/2021 | O/S Mountain Warehouse near bin | RD: FW Slabs Rocking | Internal | | Committed | 50080488 |
| 42066480 | 2 loose broken perfecta slabs please renew | 06/04/2021 | O/S Card Factory | RD: FW Slabs Broken/Missing | Internal | | Committed | 50080486 |
| 42066477 | 1 loose broken perfecta slab please renew | 06/04/2021 | O/S Debenhams | RD: FW Slabs Broken/Missing | Internal | | Committed | 50080483 |
| 42066488 | Pothole marked by arrow | 06/04/2021 | Opp Burger King at gully | RD: CW Pothole | Internal | | Committed | 50080494 |
| 42066473 | 1 loose cut needs reset and 1 broken slab needs renewed | 06/04/2021 | O/S The Office (Near road side) | RD: FW Slabs Broken/Missing | Internal | | Committed | 50080479 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|--|-----------------------------|-----------------|--------------|--------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41089677 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 06/04/2021 |
| 42066481 | loose broken perfecta slab please renew | 06/04/2021 | O/S Urban Outfitters | RD: FW Slabs Broken/Missing | Internal | | Committed | 50080487 |
| 42066483 | 4 x Loose slabs need reset | 06/04/2021 | O/S Vans | RD: FW Slabs Rocking | Internal | | Committed | 50080489 |
| 42066478 | 1 loose cut broken perfecta slab please renew | 06/04/2021 | O/S HSBC next to double footway manhole | RD: FW Slabs Broken/Missing | Internal | | Committed | 50080484 |
| 42066475 | 1 loose broken perfecta slab please renew | 06/04/2021 | O/S Regus hotel | RD: FW Slabs Broken/Missing | Internal | | Committed | 50080481 |
| 42066486 | Potholes x 2 marked by arrow on slab | 06/04/2021 | Opp Frederick St | RD: CW Pothole | Internal | | Committed | 50080492 |
| 42066484 | Grano surround at footway manhole needs redone | 06/04/2021 | Opp HSBC | RD: FW Grano Open Joint | Internal | | Committed | 50080490 |
| Batch: | 41088802 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 24/03/2021 |
| 42065391 | 1no pothole | 24/03/2021 | Opposite Wittards | RD: CW Pothole | Internal | | Committed | 50079381 |
| Batch: | 41088801 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 24/03/2021 |
| 42065390 | 1 number pothole | 24/03/2021 | At traffic lights just before Costa Coffee | RD: CW Pothole | Internal | | Uncommitted | 50074563 |
| Batch: | 41086246 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 04/03/2021 |
| 42063315 | Reset 1 number 900 x 600 PCC slab | 04/03/2021 | At bus stop PP outside Waverley Mal | RD: FW Slabs Rocking | Internal | | Committed | 50077348 |
| Batch: | 41085894 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 02/03/2021 |
| 42062941 | loose cut slab and broken grano surround please lift and relay and redo grano | 02/03/2021 | Opp Levi's shop | RD: FW Slabs Rocking | Internal | | Committed | 50076929 |
| 42063002 | Broken/ Loose special courtstonel slab 750 x 600 please renew | 02/03/2021 | O/S Prince Brasserie near pedestrian crossing | RD: FW Slabs Broken/Missing | Internal | | Committed | 50076988 |
| 42063015 | 2 x loose slabs and 1 broken Prefecta slab please lift and relay and renew | 02/03/2021 | O/S Topshop (out door) | RD: FW Slabs Rocking | Internal | | Committed | 50077001 |
| 42063003 | Small cw pothole | 02/03/2021 | On pedestrian crossing opp Balmoral hotel | RD: CW Pothole | Internal | | Committed | 50076989 |
| 42062940 | Small loose cut slab please lift and relay | 02/03/2021 | Opp o2 shop next to BT footway manhole | RD: FW Slabs Rocking | Internal | | Committed | 50076928 |
| 42062939 | Damaged footway manhole | 02/03/2021 | O/S Scott Monument on footway | RU: Utility Apparatus | Internal | | Uncommitted | 50076927 |
| 42063028 | Loose/ broken cut perfecta slab please renew | 02/03/2021 | O/S Starbucks coffee | RD: FW Slabs Broken/Missing | Internal | | Committed | 50077013 |
| 42063019 | Loose cut slab please li | 02/03/2021 | O/S Chisholm Hunter/caffe nero | RD: FW Slabs Rocking | Internal | | Committed | 50077005 |
| 42063021 | 2no rocking perfecta flags | 02/03/2021 | Outside Zara | RD: FW Slabs Rocking | Internal | | Committed | 50070766 |
| 42063027 | Missing Toby cover | 02/03/2021 | O/S Tesco Express | RU: Utility Apparatus | Internal | | Uncommitted | 50077012 |
| Batch: | 41085580 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 26/02/2021 |
| 42062651 | 1no pothole at the manhole | 26/02/2021 | At the junction of South St David Street | RD: CW Pothole | Internal | | Committed | 50076608 |
| Batch: | 41084466 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/02/2021 |
| 42062050 | 1 number pothole | 22/02/2021 | At bus stop outside Barclays | RD: CW Pothole | Internal | | Committed | 50075901 |
| Batch: | 41084462 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 22/02/2021 |
| 42062044 | 2no missing cut 450x450 perfecta flags 1no rocking perfecta flag | 22/02/2021 | At the bus stop outside Holland and Barrett | RD: FW Slabs Broken/Missing | Internal | | Committed | 50075897 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|--|--------------------------------|-----------------|--------------|--------------------|---------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41082709 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 15/02/2021 |
| 42061099 | 4 number potholes | 15/02/2021 | At crossing just passed entrance to West Register Street And beside Wellington Monument | RD: CW Pothole | Internal | | Committed | 50074848 |
| Batch: | 41082708 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 15/02/2021 |
| 42061098 | 3no potholes | 15/02/2021 | At the junction of West Register Street | RD: CW Pothole | Internal | | Committed | 50074847 |
| Batch: | 41082164 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 09/02/2021 |
| 42060935 | 3 number potholes | 09/02/2021 | At junction of Frederick street | RD: CW Pothole | Internal | | Committed | 50074568 |
| Batch: | 41082162 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 09/02/2021 |
| 42060933 | 1 number pothole | 09/02/2021 | Round manhole at junction of Frederick Street | RD: CW Pothole | Internal | | Committed | 50074566 |
| Batch: | 41082161 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 09/02/2021 |
| 42060932 | 1 number pothole | 09/02/2021 | At traffic lights just before Costa Coffee | RD: CW Pothole | Internal | | No Action Required | |
| Batch: | 41082160 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 09/02/2021 |
| 42060931 | 1no rocking 900x600 pcc flag | 09/02/2021 | Outside Waverley mall at Costa | RD: FW Slabs Rocking | Internal | | Committed | 50074562 |
| Batch: | 41082159 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 09/02/2021 |
| 42060930 | 2no depressions require hra overlay | 09/02/2021 | At the pedestrian crossing on the corner of Waverley Bridge | RD: CW Pothole | Internal | | Committed | 50074561 |
| Batch: | 41082158 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 09/02/2021 |
| 42060929 | 5 number potholes | 09/02/2021 | Outside Balmoro Hotel | RD: CW Pothole | Internal | | Committed | 50074558 |
| Batch: | 41079562 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 28/01/2021 |
| 42059934 | 1no pothole and remove lumps of tar | 28/01/2021 | At west register street in outside lane | RD: CW Pothole | Internal | | Committed | 50073290 |
| Batch: | 41079328 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 28/01/2021 |
| 42059822 | Noisy and loose manhole | 28/01/2021 | At Frederick St heading East | RU: Utility Apparatus | Internal | | Uncommitted | 50073185 |
| Batch: | 41079317 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | Date: | 28/01/2021 |
| 42059817 | 6 x cw potholes | 28/01/2021 | At Frederick St | RD: CW Pothole | Internal | | Committed | 50073182 |
| 42059850 | Loose /Missing section of grano at footway box please renew | 28/01/2021 | O/S Dean Ramsay memorial next to St Johns church | RD: FW Grano Open Joint | Internal | | Committed | 50073206 |
| 42059859 | Loose/rocking cut slab please lift and relay | 28/01/2021 | Opp Halifax | RD: FW Slabs Rocking | Internal | | Committed | 50073214 |
| 42059828 | Damaged section of Arco channel 340mm long please renew | 28/01/2021 | O/S Overseas House | RD: FW Channel Miss Cover (HL) | Internal | | Committed | 50073189 |
| 42059833 | Loose cut slab please lift a | 28/01/2021 | O/S Waterstones | RD: FW Slabs Rocking | Internal | | Committed | 50073193 |
| 42059834 | Loose slab please lift and relay | 28/01/2021 | O/S Halifax | RD: FW Slabs Rocking | Internal | | Committed | 50073194 |
| Batch: | 41078140 - Inspection Batch | | | Route: | SE_CW1_Central1 | | Date: | 25/01/2021 |
| 42059408 | 1no pothole | 25/01/2021 | At the junction with West Register Street | RD: CW Pothole | Internal | | Committed | 50072794 |
| Batch: | 41077745 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 25/01/2021 |
| 42059338 | 1no pothole at manhole | 25/01/2021 | Eastbound lane at junction with South St David Street | RD: CW Pothole | Internal | | Committed | 50072704 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|---|-----------------------|--|-----------------------------|-----------------|--------------|--------------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41074948 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 14/01/2021 |
| 42058826 | 2no potholes | 14/01/2021 | Westbound lane outside the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50072020 |
| Batch: | 41071735 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 22/12/2020 |
| 42057958 | 3no rocking perfecta flags 1no rocking perfecta cut flag 1no broken perfecta flag | 22/12/2020 | Outside Poundland | RD: FW Slabs Rocking | Internal | | Committed | 50070760 |
| 42057990 | 1 low rocking 600x900 PCC flag | 22/12/2020 | Bus stop PP | RD: FW Slabs Rocking | Internal | | Committed | 50068825 |
| 42057982 | 1no rocking perfecta flag | 22/12/2020 | Outside H&M | RD: FW Slabs Rocking | Internal | | Committed | 50070780 |
| 42057948 | 1no broken cut perfecta flag | 22/12/2020 | Outside Halifax | RD: FW Slabs Broken/Missing | Internal | | Committed | 50070755 |
| 42057967 | Piece of damaged channel cover with grano | 22/12/2020 | Outside Swarovski | RD: FW Grano Pothole | Internal | | Committed | 50070768 |
| 42057964 | 1no rocking perfecta flag 1no broken perfecta flag | 22/12/2020 | Outside Zara | RD: FW Slabs Rocking | Internal | | Committed | 50070765 |
| 42057979 | 1no pothole at manhole | 22/12/2020 | At the junction with South st David st | RD: CW Pothole | Internal | | Committed | 50070777 |
| 42057953 | 1no rocking cut perfecta flag | 22/12/2020 | Outside Waterstones | RD: FW Slabs Rocking | Internal | | Committed | 50070757 |
| 42058000 | 1no rocking flag | 22/12/2020 | At bus stop PR opposite marks and spencer | RD: FW Slabs Rocking | Internal | | Committed | 50070786 |
| 42057973 | Piece of damaged channel cover with grano | 22/12/2020 | Outside Chisholm Hunter | RD: FW Grano Pothole | Internal | | Committed | 50070772 |
| 42057963 | 3no rocking perfecta flags | 22/12/2020 | Outside Next | RD: FW Slabs Rocking | Internal | | Committed | 50070764 |
| 42057965 | 2no rocking perfecta flags | 22/12/2020 | Outside Zara | RD: FW Slabs Rocking | Internal | | No Action Required | |
| Batch: | 41071634 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 18/12/2020 |
| 42057806 | Sunken and noisy manhole | 18/12/2020 | East bound at the junction of Frederick street | RU: Utility Apparatus | Internal | | Uncommitted | 50070570 |
| Batch: | 41071442 - Inspection Batch No actionable defects found | | | Route: | SE_CW1_Central1 | | | Date: 16/12/2020 |
| Batch: | 41070181 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 02/12/2020 |
| 42056397 | 1no pothole | 02/12/2020 | At the junction with South St David St | RD: CW Pothole | Internal | | Committed | 50068805 |
| Batch: | 41070157 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 02/12/2020 |
| 42056366 | 2no rocking slabs | 02/12/2020 | Outside Zara | RD: FW Slabs Rocking | Internal | | Committed | 50068782 |
| 42056358 | 3no rocking perfectas | 02/12/2020 | Outside hotter | RD: FW Slabs Rocking | Internal | | Committed | 50068774 |
| 42056332 | Renew broken grano at box | 02/12/2020 | Outside Tesco express | RD: FW Grano Cracked/Broken | Internal | | Committed | 50068750 |
| 42056413 | 1 low rocking 600x900 PCC flag | 02/12/2020 | Bus stop PP | RD: FW Slabs Rocking | Internal | | Committed | 50068822 |
| 42056384 | 1 low Rocking perfecta | 02/12/2020 | Outside sketchers | RD: FW Slabs Rocking | Internal | | Committed | 50068792 |
| 42056420 | 2 rocking 600x900 1 rocking 450x600 | 02/12/2020 | Opposite topshop | RD: FW Slabs Rocking | Internal | | Committed | 50068832 |
| 42056363 | 3 rocking slabs | 02/12/2020 | Outside 109 at channel | RD: FW Slabs Rocking | Internal | | Committed | 50068779 |
| 42056369 | Rocking perfecta Rocking cut perfecta | 02/12/2020 | Outside Zara just before boots. | RD: FW Slabs Rocking | Internal | | Committed | 50068784 |
| 42056372 | 1 rocking perfecta | 02/12/2020 | Outside boots. 5m west of bus stop PF | RD: FW Slabs Rocking | Internal | | Committed | 50068786 |
| 42056393 | Rocking perfecta | 02/12/2020 | Outside mercure hotel at channel | RD: FW Slabs Rocking | Internal | | Committed | 50068802 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---|---|--|---|--------------------------------|---------------------------------|-------------------------|----------------------------------|----------|
| Asset: | 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | | Feature Type: Road Asset | | Area: South East Locality | |
| Batch: 41070157 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 02/12/2020 | | |
| 42056343 | No3 low rocking perfecta slabs | 02/12/2020 | Outside EE | RD: FW Slabs Rocking | Internal | | Committed | 50068761 |
| 42056333 | Replace broken 600x900 PCC flag. | 02/12/2020 | Outside McDonald's | RD: FW Slabs Broken/Missing | Internal | | Committed | 50068751 |
| 42056409 | 3 Rocking perfectas | 02/12/2020 | Outside Holland and Barrett | RD: FW Slabs Rocking | Internal | | Committed | 50068817 |
| 42056394 | 3 rocking perfectas 1 rocking cut perfecta | 02/12/2020 | Outside jenners | RD: FW Slabs Rocking | Internal | | Committed | 50068803 |
| 42056392 | Rocking perfecta | 02/12/2020 | Outside Marks & Spencer | RD: FW Slabs Rocking | Internal | | Committed | 50068801 |
| 42056345 | 1no Rocking perfecta | 02/12/2020 | Outside Halifax | RD: FW Slabs Rocking | Internal | | Committed | 50068763 |
| 42056418 | 1 low rocking 600x900 PCC flag | 02/12/2020 | Top of steps at costa | RD: FW Slabs Rocking | Internal | | Committed | 50068829 |
| 42056361 | 1 broken 450x450 perfecta 1 rocking perfecta | 02/12/2020 | Outside river island | RD: FW Slabs Broken/Missing | Internal | | Committed | 50068778 |
| 42056357 | 2 rocking perfecta cuts 1 rocking perfecta cut | 02/12/2020 | Outside Vodafone | RD: FW Slabs Broken/Missing | Internal | | Committed | 50068773 |
| 42056380 | 2 rocking perfectas 1 rocking cut perfecta | 02/12/2020 | Outside regus | RD: FW Slabs Rocking | Internal | | Committed | 50068790 |
| 42056353 | 3 rocking perfectas 1 rocking cut perfecta at channel 1 broken 450x450 perfecta | 02/12/2020 | Outside Poundland | RD: FW Slabs Broken/Missing | Internal | | Committed | 50068770 |
| 42056348 | 1no Rocking cut perfecta at channel | 02/12/2020 | Outside Waterstones | RD: FW Slabs Rocking | Internal | | Committed | 50068764 |
| 42056400 | Rocking perfecta | 02/12/2020 | Outside smiggle | RD: FW Slabs Rocking | Internal | | Committed | 50068808 |
| 42056370 | 5no broken perfecta slabs 5 rocking perfecta slabs | 02/12/2020 | Outside boots | RD: FW Slabs Broken/Missing | Internal | | Committed | 50068785 |
| 42056334 | 1no low rocking 600x900 PCC 1no low rocking cut PCC | 02/12/2020 | Outside Pret A Manger at crossing | RD: FW Slabs Rocking | Internal | | Committed | 50068752 |
| 42056415 | 1 low rocking 600x900 PCC flag | 02/12/2020 | Bus stop PP | RD: FW Slabs Rocking | Internal | | No Action Required | |
| 42056341 | 6 rocking perfecta slabs 1 broken perfecta 450x450 | 02/12/2020 | Outside three | RD: FW Slabs Rocking | Internal | | Committed | 50068759 |
| 42056351 | 2no Rocking perfecta | 02/12/2020 | Outside closed new look store | RD: FW Slabs Rocking | Internal | | Committed | 50068767 |
| 42056406 | 3 broken 450x450 perfectas | 02/12/2020 | Outside closed Vodafone opp Waverley mall | RD: FW Slabs Broken/Missing | Internal | | Committed | 50068813 |
| 42056430 | Rocking slab at box Rocking cut at box | 02/12/2020 | Opposite gap | RD: FW Slabs Rocking | Internal | | Committed | 50068840 |
| 42056337 | 2 high cut tactiles need lowered to remove trips | 02/12/2020 | On centre island of crossing | RD: FW Slabs Rocking | Internal | | Committed | 50068754 |
| 42056423 | Rocking cut sandstone flag | 02/12/2020 | Pedestrian crossing opp topshop | RD: FW Slabs Rocking | Internal | | Committed | 50068835 |
| 42056365 | 2no rocking perfectas | 02/12/2020 | Outside next | RD: FW Slabs Rocking | Internal | | Committed | 50068780 |
| 42056375 | 1 broken cut perfecta | 02/12/2020 | Outside royal house of Scotland at box | RD: FW Slabs Broken/Missing | Internal | | Committed | 50068789 |
| 42056411 | Rocking scoutmore flag Renew missing grano at catv box | 02/12/2020 | Top of waverly steps | RD: FW Slabs Rocking | Internal | | Committed | 50068819 |
| 42056331 | No1 rocking slab | 02/12/2020 | Opposite the Huxley at scaffolding | RD: FW Slabs Rocking | Internal | | Committed | 50068749 |
| 42056404 | 2 rocking cut perfectas | 02/12/2020 | Outside topshop | RD: FW Slabs Rocking | Internal | | Committed | 50068810 |
| Batch: 41069786 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 24/11/2020 | | |
| 42055969 | Install white sticker as per sign background over the blue P on the sign. | 24/11/2020 | On Railings infront of Register House. | RD: Unlit Sign Damaged/Missing | Internal | | Uncommitted | 50068058 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|--|-----------------------------|-----------------|--------------|--------------------|---------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41069482 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 19/11/2020 |
| 42055781 | Please refresh tram only markings | 19/11/2020 | Westbound lane at the junction of the Mound | RD: Markings Refresh | Internal | | No Action Required | |
| Batch: | 41069346 - Inspection Batch | | | Route: | SE_CW1_Central1 | | Date: | 16/11/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41068595 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | Date: | 06/11/2020 |
| 42055173 | 3 x Bolts protruding on the footway please remove to make safe (spanner required) | 06/11/2020 | Opp Gap shop on garden side | RD: Other Defect Type | Internal | | Committed | 50066470 |
| 42055166 | 2 x Loose perfecta slabs lift and relay | 06/11/2020 | In between Topshop and HM next to tactiles | RD: FW Slabs Rocking | Internal | | Committed | 50066460 |
| 42055169 | 4 x Loose perfecta slabs(2 cuts) lift and relay | 06/11/2020 | O/S Royal House Scotland beside footway channel | RD: FW Slabs Rocking | Internal | | Committed | 50066463 |
| Batch: | 41068484 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 04/11/2020 |
| 42055057 | Various potholes as discussed with team leader | 04/11/2020 | Princes Street Gardens near the fountain | RD: CW Pothole | Internal | | Committed | 50066283 |
| Batch: | 41068205 - Inspection Batch | | | Route: | Ad hoc Route | | Date: | 29/10/2020 |
| 42054883 | 1no pothole around manhole | 29/10/2020 | At the junction with South St David St | RD: CW Pothole | Internal | | Committed | 50065883 |
| Batch: | 41067024 - Inspection Batch | | | Route: | SE_CW1_Central1 | | Date: | 14/10/2020 |
| | No actionable defects found | | | | | | | |
| Batch: | 41065556 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | Date: | 02/10/2020 |
| 42054003 | 5no rocking perfecta flags | 02/10/2020 | Outside river island | RD: FW Slabs Rocking | Internal | | Committed | 50063955 |
| 42053994 | 3no rocking perfecta flags 2no broken perfecta flags 1no rocking cut perfecta flag | 02/10/2020 | Outside top shop | RD: FW Slabs Broken/Missing | Internal | | Committed | 50063946 |
| 42053999 | 1 rocking perfecta flag | 02/10/2020 | Outside Fraser hart | RD: FW Slabs Rocking | Internal | | Committed | 50063951 |
| 42054023 | 3 broken 600x900 pcc flags 2broken 450 x600 pcc flags 1broken 600x600 pcc flag | 02/10/2020 | Opposite top shop | RD: FW Slabs Broken/Missing | Internal | | Committed | 50063973 |
| 42054008 | 3no rocking perfecta flags 2no broken perfecta flags | 02/10/2020 | Outside sports direct | RD: FW Slabs Rocking | Internal | | Committed | 50063960 |
| 42053991 | Rocking perfecta flag | 02/10/2020 | Outside Whittard | RD: FW Slabs Rocking | Internal | | Committed | 50063943 |
| 42054006 | 1no rocking perfecta flag | 02/10/2020 | Outside urban outfitters | RD: FW Slabs Rocking | Internal | | Committed | 50063958 |
| 42054001 | 1 rocking perfecta flag 2rocking cut perfecta flags Loose grano and pieces of slab remove and replace with grano | 02/10/2020 | Outside caffe nero | RD: FW Slabs Rocking | Internal | | Committed | 50063953 |
| 42053998 | 1 rocking perfecta flag | 02/10/2020 | Outside the o2 shop | RD: FW Slabs Rocking | Internal | | Committed | 50063950 |
| 42054011 | 3no broken perfecta flags | 02/10/2020 | | RD: FW Slabs Rocking | Internal | | Committed | 50063963 |
| 42053996 | 1 rocking perfecta flag | 02/10/2020 | Outside Romanes and paterson | RD: FW Slabs Rocking | Internal | | Committed | 50063948 |
| 42053992 | 4no Low perfecta flags 1no high perfecta flag | 02/10/2020 | Outside top shop | RD: FW Slabs Rocking | Internal | | Committed | 50063944 |
| 42054004 | 6no rocking perfecta flags Infill grano at box | 02/10/2020 | At the foot of castle st | RD: FW Slabs Rocking | Internal | | Committed | 50063956 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. | |
|---------------|--|-----------------------|--|--------------------------------|-----------------|--------------|--------------|---------------------|------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality | |
| Batch: | 41064598 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: | 29/09/2020 |
| 42053806 | 2no rocking pcc flags | 29/09/2020 | At bus stop PP outside Waverley mall | RD: FW Slabs Rocking | Internal | | Committed | 50063645 | |
| Batch: | 41063351 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: | 18/09/2020 |
| 42053588 | Sunken tram manhole previously overlaid needs new hra | 18/09/2020 | On the pedestrian crossing at the corner of Waverley Bridge | RD: CW Pothole | Internal | | Committed | 50062928 | |
| Batch: | 41063066 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: | 09/09/2020 |
| 42053285 | 1no pothole | 09/09/2020 | Eastbound lane at junction of South St David Street | RD: CW Pothole | Internal | | Committed | 50062266 | |
| Batch: | 41062536 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: | 31/08/2020 |
| 42053065 | 2no potholes | 31/08/2020 | Eastbound lane outside Barclays | RD: CW Pothole | Internal | | Committed | 50061660 | |
| Batch: | 41062277 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: | 26/08/2020 |
| 42052904 | Please remove 6m section of damaged railings | 26/08/2020 | Opposite South Charlotte Street | RD: Railing Damage/Missing/New | Internal | | Committed | 50061285 | |
| Batch: | 41062111 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: | 26/08/2020 |
| 42052852 | 1no broken 600x900 pcc cut flag | 24/08/2020 | Opposite topshop | RD: FW Slabs Broken/Missing | Internal | | Committed | 50061110 | |
| 42052847 | 5no rocking flags | 24/08/2020 | Outside where Vodafone shop was opposite Waverley mall | RD: FW Slabs Rocking | Internal | | Committed | 50061088 | |
| 42052843 | 1no rocking flag | 24/08/2020 | Outside topshop | RD: FW Slabs Rocking | Internal | | Committed | 50061079 | |
| 42052838 | 2no rocking flags | 24/08/2020 | Outside Debenhams | RD: FW Slabs Rocking | Internal | | Committed | 50061074 | |
| 42052937 | 10no broken perfecta flags 2no broken cut perfecta flags | 26/08/2020 | Outside halifax | RD: FW Slabs Broken/Missing | Internal | | Committed | 50061330 | |
| 42052841 | 2no rocking flags | 24/08/2020 | Outside primark | RD: FW Slabs Rocking | Internal | | Committed | 50061077 | |
| 42052850 | 1no rocking flag | 24/08/2020 | At pedestrian crossing outside Waverley mall opposite south st Andrew st | RD: FW Slabs Rocking | Internal | | Committed | 50061097 | |
| 42052932 | Renew grano at box | 26/08/2020 | Opposite superdrug | RD: FW Grano Pothole | Internal | | Committed | 50061321 | |
| 42052941 | 1no broken perfecta flag 7no rocking/low perfecta flags | 26/08/2020 | Outside sports direct | RD: FW Slabs Broken/Missing | Internal | | Committed | 50061334 | |
| 42052936 | 1no broken 600x900 cut pcc flag 1no broken 600x600 cut pcc flag | 26/08/2020 | Outside tesco | RD: FW Slabs Broken/Missing | Internal | | Committed | 50061326 | |
| Batch: | 41061508 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: | 10/08/2020 |
| | No actionable defects found | | | | | | | | |
| Batch: | 41060335 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: | 29/07/2020 |
| 42051839 | 1no broken 900x600 pcc flag | 21/07/2020 | Opposite Swarovski | RD: FW Slabs Broken/Missing | Internal | | Committed | 50058939 | |
| 42052068 | 3no rocking perfecta flags | 29/07/2020 | Outside Samsung | RD: FW Slabs Rocking | Internal | | Committed | 50059309 | |
| 42052069 | 1no broken perfecta flag 2no rocking perfecta flags | 29/07/2020 | Outside Primark | RD: FW Slabs Broken/Missing | Internal | | Committed | 50059310 | |
| 42051843 | 1no rocking 900x600 pcc flag 1no rocking cut pcc flag | 21/07/2020 | Opposite Halifax Bank | RD: FW Slabs Rocking | Internal | | Committed | 50058943 | |
| 42052071 | 1no broken perfecta flag 1no rocking perfecta flag | 29/07/2020 | Outside Next | RD: FW Slabs Broken/Missing | Internal | | Committed | 50059312 | |
| 42052084 | 9no rocking perfecta flags | 29/07/2020 | Outside no108 | RD: FW Slabs Rocking | Internal | | Committed | 50059319 | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---|---|--|---|------------------------------|---------------------------------|-------------------------|----------------------------------|----------|
| Asset: | 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | | Feature Type: Road Asset | | Area: South East Locality | |
| Batch: 41060335 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 29/07/2020 | | |
| 42052066 | 1no rocking perfecta flag | 29/07/2020 | Outside Marks and Spencer's Foodhall entrance | RD: FW Slabs Rocking | Internal | | Committed | 50059307 |
| 42052064 | 1no rocking perfecta flag | 29/07/2020 | Between smiggle and H+M | RD: FW Slabs Rocking | Internal | | Committed | 50059305 |
| 42051847 | 4no rocking perfecta flags | 21/07/2020 | Outside Halifax | RD: FW Slabs Rocking | Internal | | Committed | 50058947 |
| 42051844 | Broken grano infill | 21/07/2020 | Outside the Royal Bank of Scotland | RD: FW Grano Depression/Sunk | Internal | | Committed | 50058944 |
| 42051850 | 1no rocking perfecta flag | 21/07/2020 | Outside Hotter | RD: FW Slabs Rocking | Internal | | Committed | 50058950 |
| 42051835 | 1no rocking 450x600 pcc flag | 21/07/2020 | Opposite Marks and Spencer's | RD: FW Slabs Rocking | Internal | | Committed | 50058936 |
| 42051833 | 1no broken cut 450x600 pcc flag | 21/07/2020 | At the Scott monument | RD: FW Slabs Broken/Missing | Internal | | Committed | 50058934 |
| 42052065 | 1no rocking perfecta flag | 29/07/2020 | Outside Jenners near the pedestrian crossing | RD: FW Slabs Rocking | Internal | | Committed | 50059306 |
| 42052070 | 4no broken perfecta flags | 29/07/2020 | Outside Russell and Bromley | RD: FW Slabs Broken/Missing | Internal | | Committed | 50059311 |
| 42052087 | 11no rocking perfecta flags | 29/07/2020 | Outside River Island | RD: FW Slabs Rocking | Internal | | Committed | 50059322 |
| 42052067 | 2no rocking perfecta flags | 29/07/2020 | Outside Superdrug | RD: FW Slabs Rocking | Internal | | Committed | 50059308 |
| 42051848 | 6no broken perfecta flags 3no rocking perfecta flags | 21/07/2020 | Outside Sports Direct | RD: FW Slabs Broken/Missing | Internal | | Committed | 50058948 |
| 42051846 | 1no rocking perfecta flag 1no broken cut perfecta flag | 21/07/2020 | Outside Three | RD: FW Slabs Rocking | Internal | | Committed | 50058946 |
| 42051842 | 2no rocking tactile flags | 21/07/2020 | On the pedestrian crossing opposite Castle Street | RD: FW Slabs Rocking | Internal | | Committed | 50058942 |
| 42051840 | 2no rocking cut pcc flags | 21/07/2020 | Opposite Boots | RD: FW Slabs Rocking | Internal | | Committed | 50058940 |
| 42051831 | 2no broken scoutmoor flags 1no rocking scoutmoor flag | 21/07/2020 | Opposite the Old Waverley Hotel | RD: FW Slabs Broken/Missing | Internal | | Committed | 50058932 |
| 42051845 | 1no rocking 900x600 pcc flag 2no rocking cut pcc flags 1no broken cut 900x600 pcc flag 2no rocking tactile flags | 21/07/2020 | At the pedestrian crossing outside Pret a manger | RD: FW Slabs Rocking | Internal | | Committed | 50058945 |
| 42051841 | 3no rocking 900x600 pcc flags | 21/07/2020 | Opposite Castle Street | RD: FW Slabs Rocking | Internal | | Committed | 50058941 |
| Batch: 41059630 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 30/06/2020 | | |
| 42051214 | Cracked and broken asphalt surface approx 1.5mx1.5m | 30/06/2020 | In the centre of the carriageway opposite Holland and Barrett | RD: CW Cracked/Broken | Internal | | Committed | 50057445 |
| Batch: 41059628 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 30/06/2020 | | |
| 42051212 | Cracked and broken asphalt surface approx 3mx1m | 30/06/2020 | Westbound lane at bus stop PQ | RD: CW Cracked/Broken | Internal | | Committed | 50057443 |
| Batch: 41059627 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 30/06/2020 | | |
| 42051211 | Cracked and broken asphalt surface approx 3mx2m | 30/06/2020 | Westbound lane at pedestrian crossing outside Costa | RD: CW Cracked/Broken | Internal | | Committed | 50057442 |
| Batch: 41059573 - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 29/06/2020 | | |
| No actionable defects found | | | | | | | | |
| Batch: 41058642 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 17/06/2020 | | |
| 42050615 | 1no rocking 900x600 pcc flag | 15/06/2020 | Outside Waverley mall at bus stop PP | RD: FW Slabs Rocking | Internal | | Committed | 50056522 |
| 42050751 | 2no rocking perfecta flags | 17/06/2020 | Outside Cath Kidston | RD: FW Slabs Rocking | Internal | | Committed | 50056694 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---|---|--|---|---------------------------------|----------|----------------------------------|-----------|----------|
| Asset: | 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | | |
| Batch: 41058642 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 17/06/2020 | | |
| 42050739 | 1no broken cut 900x600 pcc flag | 17/06/2020 | Opposite Gap | RD: FW Slabs Broken/Missing | Internal | | Committed | 50056678 |
| 42050749 | 1no rocking perfecta flag | 17/06/2020 | Outside Zara | RD: FW Slabs Rocking | Internal | | Committed | 50056691 |
| 42050758 | 1no rocking perfecta flag | 17/06/2020 | Between Smiggle and H+M | RD: FW Slabs Rocking | Internal | | Committed | 50056704 |
| 42050757 | 1no rocking perfecta flag | 17/06/2020 | Outside Monsoon | RD: FW Slabs Rocking | Internal | | Committed | 50056703 |
| 42050740 | 1no rocking 900x600 pcc flag | 17/06/2020 | Opposite Chisholm H | RD: FW Slabs Rocking | Internal | | Committed | 50056679 |
| 42050755 | 4no rocking perfecta flags Missing grano infill | 17/06/2020 | On corner of Hanover Street outside Fraser Hart | RD: FW Slabs Rocking | Internal | | Committed | 50056701 |
| 42050748 | 2no rocking perfecta flags | 17/06/2020 | At Castle Street | RD: FW Slabs Rocking | Internal | | Committed | 50056689 |
| 42050746 | 1no broken perfecta flag 1no rocking perfecta flag | 17/06/2020 | Outside no131 | RD: FW Slabs Broken/Missing | Internal | | Committed | 50056686 |
| 42050745 | 1no rocking cut 900x600 pcc flag | 17/06/2020 | Outside old Fraser shop near Royal Bank | RD: FW Slabs Rocking | Internal | | Committed | 50056684 |
| 42050752 | 2no rocking perfecta flags | 17/06/2020 | Outside Chisholm Hunter | RD: FW Slabs Rocking | Internal | | Committed | 50056695 |
| 42050756 | 1no rocking perfecta flag | 17/06/2020 | Outside O2 | RD: FW Slabs Rocking | Internal | | Committed | 50056702 |
| 42050750 | 1no rocking perfecta flag | 17/06/2020 | Outside Boots | RD: FW Slabs Rocking | Internal | | Committed | 50056693 |
| 42050754 | 1no rocking perfecta flag | 17/06/2020 | Outside Ernest Jones | RD: FW Slabs Rocking | Internal | | Committed | 50056699 |
| 42050743 | 2no rocking tactile flags | 17/06/2020 | At the pedestrian crossing outside the old Fraser shop | RD: FW Slabs Rocking | Internal | | Committed | 50056682 |
| 42050747 | 2no rocking perfecta flags | 17/06/2020 | Outside Vans | RD: FW Slabs Rocking | Internal | | Committed | 50056687 |
| 42050744 | 3no sunken Caithness flags | 17/06/2020 | Outside the old Fraser shop under covered walkway | RD: FW Slabs Rocking | Internal | | Committed | 50056683 |
| 42050753 | 1no rocking perfecta flag | 17/06/2020 | Outside Kiko | RD: FW Slabs Rocking | Internal | | Committed | 50056696 |
| 42050613 | 2no potholes | 15/06/2020 | On the pedestrian crossing outside the Balmoral Hotel | RD: CW Pothole | Internal | | Committed | 50056520 |
| 42050741 | Sunken grano infill | 17/06/2020 | Opposite South Charlotte Street | RD: FW Grano Depression/Sunk | Internal | | Committed | 50056680 |
| Batch: 41057891 - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 13/05/2020 | | |
| No actionable defects found | | | | | | | | |
| Batch: 41057099 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 27/04/2020 | | |
| 42049974 | 3no broken perfecta flags | 27/04/2020 | Outside Next | RD: FW Slabs Broken/Missing | Internal | | Committed | 50055885 |
| 42049978 | 1no pothole | 27/04/2020 | At the junction of South St David Street | RD: CW Pothole | Internal | | Committed | 50055889 |
| 42049977 | 1no broken perfecta flag | 27/04/2020 | Outside Gap | RD: FW Slabs Broken/Missing | Internal | | Committed | 50055888 |
| 42049984 | 1no broken cut 900x600 pcc flag Missing grano infill | 27/04/2020 | Opposite Levi's | RD: FW Slabs Broken/Missing | Internal | | Committed | 50055895 |
| 42049976 | 1no rocking Tactile flag | 27/04/2020 | Outside Chisholm Hunter | RD: FW Slabs Rocking | Internal | | Committed | 50055887 |
| 42049975 | 1no rocking Perfecta flag | 27/04/2020 | Outside Next | RD: FW Slabs Rocking | Internal | | Committed | 50055886 |
| 42049970 | 1no rocking Caithness flag 1no broken rocking Caithness flag | 27/04/2020 | At the Bam building site outside the old Fraser shop | RD: FW Slabs Rocking | Internal | | Committed | 50055881 |
| 42049979 | 1no rocking Perfecta flag | 27/04/2020 | Outside the old Vodafone Shop opposite Waverley mall | RD: FW Slabs Rocking | Internal | | Committed | 50055890 |
| Batch: 41056672 - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 09/04/2020 | | |
| No actionable defects found | | | | | | | | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---|--|--|--|---------------------------------|----------|----------------------------------|-------------|----------|
| Asset: | 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | | |
| Batch: 41055578 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 17/03/2020 | | |
| 42049053 | 1n | 17/03/2020 | Outside Register House at Wellington Statue | RD: CW Pothole | Internal | | Committed | 50054915 |
| Batch: 41055048 - Inspection Batch | | | Route: SE_CW1_Central1 | | | Date: 09/03/2020 | | |
| 42048538 | 4no potholes | 09/03/2020 | Eastbound lane at the junction of Frederick Street | RD: CW Pothole | Internal | | Committed | 50054381 |
| 42048537 | 1no pothole | 09/03/2020 | On the pedestrian crossing outside Three | RD: CW Pothole | Internal | | Committed | 50054380 |
| 42048539 | 1no pothole | 09/03/2020 | On the pedestrian crossing at Wellington statue | RD: CW Pothole | Internal | | Committed | 50054382 |
| Batch: 41054833 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 05/03/2020 | | |
| 42048376 | Broken FH frame causing the lid to keep falling in | 05/03/2020 | Outside ISG site (old BHS store) | RU: Utility Apparatus | Internal | | Uncommitted | 50054220 |
| Batch: 41054773 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 05/03/2020 | | |
| 42048315 | 2no potholes | 05/03/2020 | On pedestrian crossing opposite the balmoral hotel | RD: CW Pothole | Internal | | Committed | 50054150 |
| Batch: 41054686 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 04/03/2020 | | |
| 42048229 | 1no pothole | 04/03/2020 | On pedestrian crossing opposite jenners | RD: CW Pothole | Internal | | Committed | 50054040 |
| Batch: 41054650 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 03/03/2020 | | |
| 42048195 | 5no rocking perfecta flags | 03/03/2020 | Outside Superdrug | RD: FW Slabs Rocking | Internal | | Committed | 50053940 |
| Batch: 41054584 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 03/03/2020 | | |
| 42048118 | 1no rocking perfecta flag | 03/03/2020 | Outside Holland and Barrett | RD: FW Slabs Rocking | Internal | | Committed | 50053927 |
| 42048161 | 3no broken perfecta flags | 03/03/2020 | Outside one two five | RD: FW Slabs Broken/Missing | Internal | | Committed | 50053970 |
| 42048147 | 1no broken cut perfecta flag | 03/03/2020 | Outside Boots | RD: FW Slabs Rocking | Internal | | Committed | 50053956 |
| 42048163 | 1no rocking perfecta flag | 03/03/2020 | Outside Vans | RD: FW Slabs Rocking | Internal | | Committed | 50053973 |
| 42048115 | 2no rocking tactile flags | 03/03/2020 | Opposite Waverley mall costa coffee at pedestrian crossing | RD: FW Slabs Rocking | Internal | | Committed | 50053923 |
| 42048117 | 1no broken 450x450 perfecta flag | 03/03/2020 | Outside Holland and Barrett | RD: FW Slabs Rocking | Internal | | Committed | 50053925 |
| 42048130 | 1no rocking cut perfecta flag | 03/03/2020 | Outside Office | RD: FW Slabs Rocking | Internal | | Committed | 50053939 |
| 42048143 | Renew sunken/cracked grano at box | 03/03/2020 | Outside Thomas Sabo | RD: FW Grano Cracked/Broken | Internal | | Committed | 50053952 |
| 42048108 | 1no rocking perfecta flag | 03/03/2020 | Outside the O2 shop | RD: FW Slabs Rocking | Internal | | Committed | 50053916 |
| 42048133 | 5no rocking perfecta flags | 03/03/2020 | Outside Samsung | RD: FW Slabs Rocking | Internal | | Committed | 50053942 |
| 42048112 | 2no rocking perfecta flags | 03/03/2020 | Outside Marks and Spencer | RD: FW Slabs Rocking | Internal | | Committed | 50053920 |
| 42048114 | Renew sunken/cracked grano at box | 03/03/2020 | Outside topshop | RD: FW Grano Pothole | Internal | | Committed | 50053922 |
| 42048175 | 1no rocking cut pcc flag | 03/03/2020 | Outside 136 | RD: FW Slabs Rocking | Internal | | Committed | 50053986 |
| 42048113 | 2no rocking perfecta flags | 03/03/2020 | Outside 54-58 Marks and Spencer | RD: FW Slabs Rocking | Internal | | Committed | 50053921 |
| 42048111 | 1no rocking perfecta flag | 03/03/2020 | Outside Marks and Spencer | RD: FW Slabs Rocking | Internal | | Committed | 50053919 |
| 42048105 | 1no rocking perfecta flag | 03/03/2020 | Outside Fraser Hart | RD: FW Slabs Rocking | Internal | | Committed | 50053913 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|---|-----------------------------|-----------------|--------------|--------------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41054584 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 03/03/2020 |
| 42048167 | 2no broken perfecta flags 4no rocking perfecta flag | 03/03/2020 | Outside Halifax | RD: FW Slabs Broken/Missing | Internal | | Committed | 50053978 |
| 42048156 | 6no rocking perfecta flags | 03/03/2020 | Outside Levis | RD: FW Slabs Rocking | Internal | | Committed | 50053965 |
| 42048151 | 3no broken perfecta flags | 03/03/2020 | Outside Next | RD: FW Slabs Broken/Missing | Internal | | Committed | 50053960 |
| 42048140 | 2no rocking perfecta flags 1no rocking tactile flag | 03/03/2020 | Outside Chisholm Hunter | RD: FW Slabs Rocking | Internal | | Committed | 50053949 |
| 42048131 | 5no rocking perfecta flags | 03/03/2020 | Outside Superdrug | RD: FW Slabs Rocking | Internal | | No Action Required | |
| 42048129 | 3no rocking perfecta flags | 03/03/2020 | Outside Skechers | RD: FW Slabs Rocking | Internal | | Committed | 50053938 |
| 42048110 | 2no rocking perfecta cut flags | 03/03/2020 | 64 princes st at building site hoarding | RD: FW Slabs Rocking | Internal | | Committed | 50053918 |
| Batch: | 41054392 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 02/03/2020 |
| 42048004 | 1no pothole | 02/03/2020 | Westbound lane on the pedestrian crossing at the Mound | RD: CW Pothole | Internal | | Committed | 50053811 |
| Batch: | 41054246 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 28/02/2020 |
| 42047802 | 1no small pothole on ped crossing | 28/02/2020 | Outside the 3 store on pedestrian crossing | RD: CW Pothole | Internal | | Committed | 50053616 |
| Batch: | 41052832 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 19/02/2020 |
| 42046635 | 1no rocking 750x600 pcc flag | 19/02/2020 | At bus stop PP outside Waverley Mall | RD: FW Slabs Rocking | Internal | | Committed | 50052400 |
| Batch: | 41052831 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 19/02/2020 |
| 42046634 | 4no rocking cut flags 1no rocking 600x900 flag | 19/02/2020 | At bus stop PQ next to waverley mall | RD: FW Slabs Rocking | Internal | | Committed | 50052399 |
| Batch: | 41052609 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 17/02/2020 |
| 42046410 | 3no po | 17/02/2020 | Just east of West Register Street | RD: CW Pothole | Internal | | Committed | 50051602 |
| Batch: | 41052046 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 13/02/2020 |
| 42046029 | 1no pothole at manhole | 13/02/2020 | Eastbound lane at the junction of Frederick Street | RD: CW Pothole | Internal | | Committed | 50051814 |
| Batch: | 41051728 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 11/02/2020 |
| 42045826 | 1no pothole | 11/02/2020 | Westbound lane outside Waverley mall in between the 2 bus stops | RD: CW Pothole | Internal | | Committed | 50051607 |
| Batch: | 41051722 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 11/02/2020 |
| 42045825 | 1no pothole | 11/02/2020 | On the pedestrian crossing outside Waverley mall | RD: CW Pothole | Internal | | Committed | 50051605 |
| Batch: | 41051718 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 11/02/2020 |
| 42045822 | 3no po | 11/02/2020 | Just east of West Register Street | RD: CW Pothole | Internal | | No Action Required | |
| Batch: | 41051602 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 07/02/2020 |
| 42045735 | 1no rocking perfecta flag | 07/02/2020 | At the bus stop outside River Island | RD: FW Slabs Rocking | Internal | | Committed | 50051501 |
| Batch: | 41051601 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 07/02/2020 |
| 42045734 | 1no broken perfecta flag | 07/02/2020 | Outside no108 | RD: FW Slabs Broken/Missing | Internal | | Committed | 50051500 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---------------|--|-----------------------|--|-----------------------------|-----------------|--------------|--------------------|-------------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | | Area: | South East Locality |
| Batch: | 41051380 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 05/02/2020 |
| 42045500 | 1no pothole | 05/02/2020 | Eastbound lane at the junction of South RD: CW Pothole St David Street | | Internal | | Committed | 50051262 |
| Batch: | 41051232 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 04/02/2020 |
| 42045388 | 2no broken perfecta flags 1no rocking perfecta flag | 04/02/2020 | Outside Poundland | RD: FW Slabs Broken/Missing | Internal | | Committed | 50051150 |
| Batch: | 41051218 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 04/02/2020 |
| 42045373 | 1no broken 900x600 pcc flag | 04/02/2020 | Outside Costa Coffee at Waverley mall | RD: FW Slabs Broken/Missing | Internal | | Committed | 50051032 |
| Batch: | 41051097 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 03/02/2020 |
| 42045266 | 1no broken 900x600 pcc flag | 03/02/2020 | Outside Costa Coffee at Waverley mall | RD: FW Slabs Broken/Missing | Internal | | No Action Required | |
| Batch: | 41050988 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 31/01/2020 |
| 42045163 | 1no rocking perfecta flag | 31/01/2020 | Outside no125 | RD: FW Slabs Rocking | Internal | | Committed | 50050906 |
| Batch: | 41050606 - Inspection Batch | | | Route: | Ad hoc Route | | | Date: 27/01/2020 |
| 42044765 | 1no pothole | 27/01/2020 | Westbound lane outside the Balmoral just west of the pedestrian crossing | RD: CW Pothole | Internal | | Committed | 50050389 |
| 42044764 | 1no pothole at manhole | 27/01/2020 | Westbound lane outside the Balmoral Hotel entrance | RD: CW Pothole | Internal | | Committed | 50050390 |
| Batch: | 41050523 - Inspection Batch | | | Route: | SE_CW1_Central1 | | | Date: 24/01/2020 |
| 42044700 | 1no pothole | 24/01/2020 | Westbound lane outside the Balmoral just west of the pedestrian crossing | RD: CW Pothole | Internal | | No Action Required | |
| 42044701 | 1no pothole at manhole | 24/01/2020 | Westbound lane outside the Balmoral Hotel entrance | RD: CW Pothole | Internal | | No Action Required | |
| 42044691 | 2no potholes | 24/01/2020 | Eastbound lane at West Register Street | RD: CW Pothole | Internal | | Committed | 50050380 |
| Batch: | 41050057 - Inspection Batch | | | Route: | SE_FW1_Princes1 | | | Date: 21/01/2020 |
| 42044312 | 1no rocking 900x600 pcc flag | 21/01/2020 | At bus stop PP outside Waverley mall | RD: FW Slabs Rocking | Internal | | Committed | 50049988 |
| 42044309 | 6no rocking perfecta flags | 21/01/2020 | Outside Holland and Barrett | RD: FW Slabs Rocking | Internal | | Committed | 50049984 |
| 42044307 | 1no rocking perfecta flag | 21/01/2020 | Outside Whittard | RD: FW Slabs Rocking | Internal | | Committed | 50049981 |
| 42044291 | 1no broken perfecta flag | 21/01/2020 | Outside Primark | RD: FW Slabs Broken/Missing | Internal | | Committed | 50049964 |
| 42044290 | 1no rocking cut perfecta flag 1no rocking perfecta flag | 21/01/2020 | Outside Chisholm Hunter | RD: FW Slabs Rocking | Internal | | Committed | 50049963 |
| 42044302 | 1no rocking perfecta flag | 21/01/2020 | At bus stop PK outside the Mercure Hotel | RD: FW Slabs Rocking | Internal | | Committed | 50049975 |
| 42044315 | 1no broken 900x600 pccflag | 21/01/2020 | Outside Costa Coffee at Waverley mall | RD: FW Slabs Broken/Missing | Internal | | Committed | 50049991 |
| 42044281 | 1no rocking 900x600 pcc flag | 21/01/2020 | Outside Tesco Express | RD: FW Slabs Rocking | Internal | | Committed | 50049954 |
| 42044285 | 1no rocking cut perfecta flag | 21/01/2020 | Outside HSBC | RD: FW Slabs Rocking | Internal | | Committed | 50049958 |
| 42044283 | 3no rocking perfecta flags | 21/01/2020 | Just west of USC | RD: FW Slabs Rocking | Internal | | Committed | 50049956 |
| 42044320 | 1no rocking cut pcc flag | 21/01/2020 | At bus stop PR opposite Mercure Hotel | RD: FW Slabs Rocking | Internal | | Committed | 50049998 |
| 42044310 | 1no rocking cut perfecta flag | 21/01/2020 | Outside Foot Locker | RD: FW Slabs Rocking | Internal | | Committed | 50049986 |
| 42044306 | 1no rocking cut perfecta flag | 21/01/2020 | Outside Topshop no30-31 | RD: FW Slabs Rocking | Internal | | Committed | 50049979 |
| 42044287 | 2no rocking perfecta flags | 21/01/2020 | Outside Levi's | RD: FW Slabs Rocking | Internal | | Committed | 50049960 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Condition Survey

| Defect No: | Description | Log Date | Location | Defect Type | Class. | Organisation | Status | Job No. |
|---|--|--|--|-----------------------------|---------------------------------|-------------------------|----------------------------------|----------|
| Asset: | 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | | Feature Type: Road Asset | | Area: South East Locality | |
| Batch: 41050057 - Inspection Batch | | | Route: SE_FW1_Princes1 | | | Date: 21/01/2020 | | |
| 42044301 | 1no rocking cut perfecta flag 1no rocking perfecta flag | 21/01/2020 | Outside Marks and Spencer's no60 | RD: FW Slabs Rocking | Internal | | Committed | 50049974 |
| 42044316 | 1no rocking scoutmoor flag | 21/01/2020 | At the corner of Waverley Bridge opposite Topshop | RD: FW Slabs Rocking | Internal | | Committed | 50049992 |
| 42044303 | 2no rocking perfecta flags | 21/01/2020 | Outside Jenners no50-52 | RD: FW Slabs Rocking | Internal | | Committed | 50049976 |
| 42044305 | 2no rocking cut tactile flags 1no rocking tactile flag | 21/01/2020 | At the pedestrian crossing at South St David Street outside Jenners | RD: FW Slabs Rocking | Internal | | Committed | 50049978 |
| 42044298 | 1no rocking perfecta flag | 21/01/2020 | Outside Great Scot | RD: FW Slabs Rocking | Internal | | Committed | 50049971 |
| 42044286 | 2no broken perfecta flags 2no rocking perfecta flags | 21/01/2020 | Outside River Island | RD: FW Slabs Broken/Missing | Internal | | Committed | 50049959 |
| 42044282 | 1no rocking cut pcc flag | 21/01/2020 | At the pedestrian crossing outside Pret A Manger | RD: FW Slabs Rocking | Internal | | Committed | 50049955 |
| 42044288 | 1no rocking cut perfecta flag 1no rocking perfecta flag | 21/01/2020 | Outside Boots at west entrance | RD: FW Slabs Rocking | Internal | | Committed | 50049961 |
| 42044319 | 1no rocking 750x600 pcc flag | 21/01/2020 | Opposite the Old Waverley | RD: FW Slabs Rocking | Internal | | Committed | 50049996 |
| 42044322 | 1no broken 900x600 pccflag 1no rocking 900x600 pcc flag | 21/01/2020 | At bus stop PX opposite Vodafone | RD: FW Slabs Broken/Missing | Internal | | Committed | 50050003 |
| 42044314 | 1no pothole | 21/01/2020 | At the pedestrian crossing outside Waverley mall | RD: CW Pothole | Internal | | Committed | 50049990 |
| 42044284 | 1no rocking cut perfecta flag | 21/01/2020 | At bus stop PB outside New Look | RD: FW Slabs Rocking | Internal | | Committed | 50049957 |
| 42044289 | 1no broken perfecta flag 1no broken cut perfecta flag | 21/01/2020 | Outside Boots | RD: FW Slabs Broken/Missing | Internal | | Committed | 50049962 |
| Batch: 41049449 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 13/01/2020 | | |
| 42043653 | 1no broken perfecta flag 3no sunken cut perfecta flags | 13/01/2020 | Between H+M and Topshop | RD: FW Slabs Broken/Missing | Internal | | Committed | 50049333 |
| Batch: 41049448 - Inspection Batch | | | Route: Ad hoc Route | | | Date: 13/01/2020 | | |
| 42043652 | 2no broken perfecta flags | 13/01/2020 | Outside nn30-31 | RD: FW Slabs Broken/Missing | Internal | | Committed | 50049332 |

Customer Services

Enquiry No.: 34004869

Logged by: [REDACTED]

on: 03/03/2022 11:42

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.: Broken concrete on pedestrian crossing causing trip hazard at tram line

Location: Opposite Three

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Enquiry No.: 34004783

Logged by: [REDACTED]

on: 14/02/2022 10:06

Service: Roads General

Subject: Drainage: General Enquiry

Classification: General Enquiry

Desc.: please inspect blocked drainage on pavement close to castle street between 113-117. please see pic attached.

Location: princess street / castle street

Contact: [REDACTED]

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

| | | |
|---|--|--|
| Enquiry No.: 34004644 | Logged by: Nightshift Squad 1 | on: 09/01/2022 05:42 |
| Service: Road Gully & Flooding | Subject: Gully: Flooding | Classification: Customer Emergency |
| Desc.: Flooding | | |
| Location: Opp Waverley Bridge | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50102067 | | |
| Enquiry No.: 34004600 | Logged by: [REDACTED] | on: 29/12/2021 13:45 |
| Service: Roads General | Subject: Street Furniture: Defective | Classification: Request for service |
| Desc.: Damaged bollard | | |
| Location: Opposite the Balmoral and Apple Store. | Contact: | |
| Enquiry No.: 34004435 | Logged by: [REDACTED] | on: 22/11/2021 10:14 |
| Service: Roads General | Subject: Pavement: Damaged / Defective | Classification: Request for service |
| Desc.: footway defects and dropped kerbs required. some of the kerbs are too high [REDACTED] | | |
| Location: | Contact: | |
| Enquiry No.: 34004270 | Logged by: Nightshift Squad 1 | on: 20/10/2021 06:34 |
| Service: Roads General | Subject: Public Utilities: General | Classification: General Enquiry |
| Desc.: Sunken Manhole and surround has disintegrated | | |
| Location: Princes St at South St David St | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 34003598 | Logged by: [REDACTED] | on: 24/05/2021 16:19 |
| Service: Roads General | Subject: Pavement: Damaged / Defective | Classification: Request for service |
| Desc.: low kerbstone type obstructions a short distance from the edge of the pavement which I must have tripped over | | |
| Location: Waverley Steps, at the pedestrian crossing to cross to Princes Street. | Contact: | |
| Enquiry No.: 34003562 | Logged by: [REDACTED] | on: 13/05/2021 14:56 |
| Service: Roads General | Subject: Pavement: General Enquiry | Classification: General Enquiry |
| Desc.: Low Street lighting or traffic signals footway manhole | | |
| Location: O/S The Mound | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 34003561 | Logged by: [REDACTED] | on: 13/05/2021 14:47 |
| Service: Roads General | Subject: Pavement: General Enquiry | Classification: General Enquiry |
| Desc.: Low Street lighting or traffic signals footway manhole | | |
| Location: O/S The Mound | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 34003026 | Logged by: [REDACTED] | on: 28/01/2021 10:10 |
| Service: Accident Claims (All Services) | Subject: Accident Claim Roads/Lighting | Classification: Accident Claim |
| Desc.: I crossed the road early in the morning (5:40 am) on my way to work. I suddenly fell [REDACTED]. | | |
| Location: Incident happened on 13.12.2018 | Contact: | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

| | | |
|--|--|--|
| Enquiry No.: 34002805 | Logged by: [REDACTED] | on: 02/12/2020 10:37 |
| Service: Roads General | Subject: Drainage: General Enquiry | Classification: General Enquiry |
| Desc.: Low broken poly channel | | |
| Location: Outside Chisholm hunter | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 34002711 | Logged by: [REDACTED] | on: 17/11/2020 13:46 |
| Service: Roads General | Subject: Road Markings: Defective | Classification: Request for service |
| Desc.: worn road markings on Princes Street at the Tram Bahn - "Tram Only" writing on the road needs repainting | | |
| Location: on the entrance into PST TS AB track | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| | Defect Number: 42071355 | |
| Enquiry No.: 34002268 | Logged by: [REDACTED] | on: 26/08/2020 10:23 |
| Service: Road Gully & Flooding | Subject: Gully: Polychannel Blocked | Classification: Request for service |
| Desc.: Clean out footway channel along entire leng | | |
| Location: Outside Chisholm Hunter and Monsoon are flooding but could the entire footway channel along Princes Street please be cleaned | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50061280 | | |
| Enquiry No.: 34002186 | Logged by: [REDACTED] | on: 16/07/2020 12:04 |
| Service: Accident Claims (All Services) | Subject: Accident Claim Roads/Lighting | Classification: Accident Claim |
| Desc.: A road tripping accident which ocured on 05.03.2020 at Princess Street.The pursuer was crossing the road, she fell to her injury on a sunken hole in the road. | | |
| Location: Pedestrian crossing by the Balmoral Hotel | Contact: | |
| Enquiry No.: 34001958 | Logged by: [REDACTED] | on: 28/02/2020 12:06 |
| Service: Accident Claims (All Services) | Subject: Accident Claim Roads/Lighting | Classification: Accident Claim |
| Desc.: Our client, a cyclist, was proceeding along Princes Street when he has fallen off his bicycle due to colliding with a tram track. | | |
| Location: Princes Street | Contact: Digby Brown | |
| Enquiry No.: 34001859 | Logged by: [REDACTED] | on: 03/02/2020 14:43 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: Potholed | | |
| Location: East bound lane at junction with West Register Street | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50051602 | Defect Number: 42046410 | |
| Enquiry No.: 34001799 | Logged by: [REDACTED] | on: 13/01/2020 09:28 |
| Service: Road Gully & Flooding | Subject: Gully: Blocked/Needs Clean | Classification: Request for service |
| Desc.: Blocked gully needs cleaned | | |
| Location: At the Wellington statue | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50049334 | | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 30110430 **Logged by:** [REDACTED] **on:** 05/03/2020 14:23
Service: Roads General **Subject:** Drainage: General Enquiry **Classification:** General Enquiry
Desc.: Drain cover broken
Location: On road at great Scot princess street **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 10065078 **Logged by:** [REDACTED] **on:** 08/06/2021 16:35
Service: Open Space Maintenance **Subject:** Street Cleaning Request **Classification:** Request for service
Desc.: Please could someone take a look at the query below and raise the issues with the relevant teams? I can send a note of acknowledgement but if someone could respond confirming the work has been actioned that would be super.
[REDACTED] | Elected Members' Officer to Councillor Adam McVey and Councillor Amy McNeese-Mechan | SNP Group | Level 9 | The City of Edinburgh Council | City Chambers | High Street, Edinburgh EH1 1YJ | [REDACTED]@edinburgh.gov.uk |
From: [REDACTED] >
Sent: 07 June 2021 15:13
To: Adam McVey <Adam.McVey@edinburgh.gov.uk>
Subject: Disgusting state of Princess Street.
Dear Councillor McVey,
Today I walked along Princess Street from The West End and I have to say I have never seen the Street in such a disgusting state. Dried fluids everywhere, trash in doorways, loose and broken paving.
Is it beyond this SNP/Labour administration to keep the main thoroughfare of Edinburgh in a clean and presentable condition? In other cities they can wash down the streets when there are dry spells, but Edinburgh seems to be the exception. What an indictment on the City Council.

Location: **Contact:**

Enquiry No.: 10061728 **Logged by:** [REDACTED] **on:** 11/01/2020 10:01
Service: RD: Road Services Out of Hours **Subject:** RD: Out of Hours Emergency **Classification:** Request for service
Desc.: Bollards blwon accross pavement leaving exposed hole in ground.
Location: Outside H&M On Princes Street **Contact:**

Effective: 01/01/2020 to 31/03/2022
 Display Action Officer: No

Asset Number: 1.00 to 3.00
 Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1352988 **Logged by:** Verint CRM Connector **on:** 29/03/2022 09:10
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Please see attached **Contact:**

Enquiry No.: 1350786 **Logged by:** Verint CRM Connector **on:** 24/03/2022 14:45
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: I write to notify you of a large pothole in the pavement of Princes Street (area detailed on the map provided). On the 11/12/21 I unknowingly walked over said pot hole and sustained injury [REDACTED]
 [REDACTED] returned to the area on 25/02/22 and was concerned to see that the hole had not been repaired. Can you please address this as a matter of urgency.
Contact:

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1350558 **Logged by:** Verint CRM Connector **on:** 24/03/2022 11:23
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: loose pavement slab outside 125 princes Street . to be attended to ASAP **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50110159 **Defect Number:** 42097533

Enquiry No.: 1348637 **Logged by:** Verint CRM Connector **on:** 21/03/2022 14:04
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Rocking slabs on pavement in front of Register House. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50109891 **Defect Number:** 42097251

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1348519 Logged by: Verint CRM Connector on: 21/03/2022 11:59

Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim

Desc.: [REDACTED]

Location: multiple broken and damaged slabs, they are raised and move around when stood on. serious trip hazard. Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Job Number: 50109886 Defect Number: 42097245

Enquiry No.: 1347164 Logged by: [REDACTED] on: 18/03/2022 08:53

Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim

Desc.: I had been Shopping today at Hotter on Princes Street. Upon leaving the shop I had only gone a few feet along when I tripped on badly uneven pavement [REDACTED]

[REDACTED] I wanted to bring this to your attention as the paving on Princes street is in very poor condition and is quite frankly a genuine danger. How on earth do you expect people with impaired vision to avoid a similar situation. Something must be done to make the area much safer for everyone. [REDACTED]

Location: at Hotter on Princes Street

Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 1347161 Logged by: Verint CRM Connector on: 18/03/2022 08:43

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: Broken slabs Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Job Number: 50109882 Defect Number: 42097241

Enquiry No.: 1347160 Logged by: Verint CRM Connector on: 18/03/2022 08:40

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: Slabs on pavement all cracked and broken, the length of princes street, trip hazard. Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 1346958 Logged by: Verint CRM Connector on: 17/03/2022 16:14

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: [REDACTED] Contact:

[REDACTED] can you please advise if you actually visited the Monsoon/Accessorize store as although the cracks on the pavement may not be classed by yourselves as a hazard for pedestrians this is causing water to leak through into the store basement staff room area which needs resolving. Please review this again and ensure you communicate with the store team on site.

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

| | | |
|---|--|--|
| Enquiry No.: 1346443 | Logged by: Verint CRM Connector | on: 16/03/2022 21:21 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: Princes St and South Charlotte st Tarmac is collapsing right next to the tram line on south side of Princes street | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 1345966 | Logged by: Verint CRM Connector | on: 16/03/2022 09:50 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: open manhole with a gap of around 500mm between tram tracks and cycle lane on princes street - cones around open manhole but NO barriers making this extremely dangerous - closest shop location Primark | Contact: | |
| Enquiry No.: 1345851 | Logged by: Verint CRM Connector | on: 15/03/2022 21:14 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: There is a huge gap between the manhole cover and the road. I barely missed it on my bike this morning. As you are going east on Princes St it is on the road outside, or just past, the 2 phone shops (Phone spot is 1 of them I think). The gap is genuinely dangerous and just the right size for a cyclist wheel. It will cause serious harm if not fixed. | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50109383 | Defect Number: 42096590 | |
| Enquiry No.: 1345415 | Logged by: Verint CRM Connector | on: 15/03/2022 10:48 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: Large pothole immediately after the painted bike box heading West on the left hand side of the road next to the traffic lights. | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50109381 | Defect Number: 42096588 | |
| Enquiry No.: 1345125 | Logged by: Verint CRM Connector | on: 14/03/2022 17:11 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: Two loose manhole covers on roadway. | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50109076 | Defect Number: 42096129 | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1344670

Logged by: [REDACTED]

on: 14/03/2022 09:01

Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Request for service

Desc.: [REDACTED] following an accident which I was involved in on 9 October 2021 on Princes Street, Edinburgh. At between 11-11.30pm on the above date, I was crossing the eastbound carriageway of Princes Street from the bus stop outside Barclays towards Waverley Station. I had taken a few steps from the pavement when my foot went into a pot hole which was filled with rain water. The pothole was a tripping hazard to pedestrians. [REDACTED]

[REDACTED] Your employees carried out inspections between 16 June 2021 and my accident on 17 June 2021, 2 July 2021, 14 July 2021, 2 August 2021, 20 August 2021, 2 September 2021, 22 September 2021 and 4 October 2021. They failed to note the defect or arrange to have it fixed. Had they done so my accident would not have occurred. The area in which my accident occurred was previously repaired by your colleagues on 23 February 2021. The repair failed by 16 June 201 and worsened further by the time my accident happened. The repair which took place on 23 February 2021 should have lasted longer. The repair by your employee was not carried out with due care and attention. [REDACTED]

Location: I was crossing the eastbound carriageway of Princes Street from the bus stop outside Barclays towards Waverley Station.

Contact:

Enquiry No.: 1344652

Logged by: Verint CRM Connector

on: 14/03/2022 08:28

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Manhole cover sinking outside 1st bus stop heading westbound at waverley steps Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Job Number: 50108909

Defect Number: 42095924

Enquiry No.: 1344065

Logged by: Aideen Collins

on: 12/03/2022 14:26

Service: RD: Road Services Out of Hours Subject: RD: Out of Hours Emergency Classification: Request for service

Desc.: Manhole cover open and sticking up, hazard to traffic

Location: Near tram stop at Frederick Street on Princes Street, East bound Contact:

Enquiry No.: 1343489

Logged by: Verint CRM Connector

on: 11/03/2022 11:54

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: Leak coming into Monsoon/Accessorize store basement staff room, believed to be related to damaged pavement to the front of the store as per photos provided
Please can this pavement be looked into asap to stop the leaks coming through
Store address = 45 Princes Street, Edinburgh, EH2 2BY Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Job Number: 50109887

Defect Number: 42097246


Effective: 01/01/2020 to 31/03/2022
 Display Action Officer: No

Asset Number: 1.00 to 3.00
 Site: Princes Street (7903151)


Customer Services

Enquiry No.: 1342049 **Logged by:** Verint CRM Connector **on:** 09/03/2022 10:21
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Gully Road lid loose **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset



Enquiry No.: 1339772 **Logged by:** Verint CRM Connector **on:** 05/03/2022 09:57
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: I am contacting you from Boots, as there is a an area of pavement outside Boots that has sunk slightly and is causing a trip hazard. **Contact:**



Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50108362 **Defect Number:** 42095250

Enquiry No.: 1339044 **Logged by:** [Redacted] **on:** 04/03/2022 09:05
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: @edinhelp any chance one of your bosses could visit princes street & take a look at how bad the loose slabs are, it's like a game of Russian roulette trying not to stand on a loose one & have half your leg soaked in manky street juice!
Location: Princes Street **Contact:**

Enquiry No.: 1337042 **Logged by:** Verint CRM Connector **on:** 01/03/2022 14:23
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: paving slab loose and tilting upwards - outside the old Santander building (136 Princes Street) needs to be made safe ASAP **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50108098 **Defect Number:** 42094846

Enquiry No.: 1336912 **Logged by:** Verint CRM Connector **on:** 01/03/2022 13:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole on eastbound carriageway on junction with West Register Street. **Contact:**

Enquiry No.: 1336910 **Logged by:** Verint CRM Connector **on:** 01/03/2022 13:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole on eastbound carriageway on Princes Street near to junction with Leith Street. Liable to cause damage to vehicles **Contact:**

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1335580 **Logged by:** Verint CRM Connector **on:** 27/02/2022 18:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Big pothole dangerous for cyclists and trip hazard
Location: Outside front entrance to waverley station **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1334576 **Logged by:** Verint CRM Connector **on:** 25/02/2022 17:12
Service: Roads General **Subject:** Signs: Defective / Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow
Location: Sort the lights at this location. It's causing stationary traffic to emit unnecessary fumes **Contact:**

Enquiry No.: 1331412 **Logged by:** Verint CRM Connector **on:** 21/02/2022 19:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: East junction of Princes St and Waverley Bridge. **Contact:**
Road surface is giving way. I was standing close by earlier today and could see the tarmac giving way as buses went over it. Large area needs to be checked.

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1329119 **Logged by:** [REDACTED] **on:** 18/02/2022 09:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: @Edinburgh_CC
Any chance of someone fixing the crators from balmoral hotel up to howies ? Roads are a disgrace .
Location: **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1328131 **Logged by:** Verint CRM Connector **on:** 16/02/2022 19:36
Service: Road Gully & Flooding **Subject:** Gully: Polychannel Blocked **Classification:** Request for service
Desc.:
Location: think someone needs to take a look at the amount of water on the pavements on princes street. Lots of very large puddles and little streams running. And that's before the storm hits ? **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50107382 **Defect Number:** 42094034

Enquiry No.: 1327518 **Logged by:** Verint CRM Connector **on:** 16/02/2022 10:28
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: loose paving slab outside Fraser Hart -77 Princes street, EH2 2DF - been reported on several occassions but nothing and pedestrians are tripping over the loose slab and complaining to the shop staff **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50106597 **Defect Number:** 42093193

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1326705 **Logged by:** Verint CRM Connector **on:** 15/02/2022 09:15
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.: The incident happened yesterday 15 February 2022 at 08:45 am
Location: raised slab outside Topshop, causing people to trip and being a danger to the public **Contact:**
needs to be repaired ASAP


Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50106395 **Defect Number:** 42092977

Enquiry No.: 1326686 **Logged by:** [REDACTED] **on:** 15/02/2022 08:38
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: @edinhelp Hello, not sure if this is a council responsibility but there's a damaged drain cover on the corner of Princes St and The Mound by the Galleries which is a bit of a trip hazard.
Location: Map attached showing location **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 11 - From The Mound to Hanover Street **Feature Type:** Road Asset

Enquiry No.: 1325432 **Logged by:** Verint CRM Connector **on:** 13/02/2022 09:48
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: There is a large hole in one of the utility pavement covers. The hole is large enough for someone's foot to go down it. It is very dangerous and an accident waiting to happen. Someone will put their foot through it and will seriously injure themselves. It's on the pavement at the art gallery right at the pedestrian crossing to cross over the bottom of the mound.
This needs looked at urgently. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
50106197 42092744



Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)


Customer Services

Enquiry No.: 1319028 **Logged by:** Verint CRM Connector **on:** 02/02/2022 15:25
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.:

Location: Location outside jewellers Chisholm hunter 97/98 princes street. I fell over an unstable slab. All along princes street there are broken and unstable slabs. That was the second time I tripped over. I didn't break anything but was battered and bruised and shaken. I'm surely not the only person who has complained about the state of the pavements
Contact:

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50105183 **Defect Number:** 42091791



Enquiry No.: 1310833 **Logged by:** Verint CRM Connector **on:** 20/01/2022 16:40
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.:

Location: Sunken and broken slab that an elderly pedestrian this morning tripped on, fell flat out, and could have been seriously injured. Similar issue in front of the galleries, at the foot of the mound.
Contact:

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1310665 **Logged by:** Verint CRM Connector **on:** 20/01/2022 13:54
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.:

Location: A customer has called into the customer hub at the High Street to report that a pavement slab has been split and is uneven at the M&S on princes street where he witnessed a woman to trip and fall.
Contact:

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1309855

Logged by: [REDACTED]

on: 19/01/2022 12:10

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.: Please see attached email.

Location: Please see attached email.

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Job Number: 50103617

Defect Number: 42090251

Enquiry No.: 1309843

Logged by: [REDACTED]

on: 19/01/2022 12:05

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.: loose paving slabs

Location: o/s Boots the chemist

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Job Number: 50103614

Defect Number: 42090249

Enquiry No.: 1306110

Logged by: Verint CRM Connector

on: 12/01/2022 16:05

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: There is a drain here which has sunken quite considerably creating a very dangerous hazard to cyclists. I almost came off my bike when cycling along here yesterday and had to swerve to avoid it.

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Job Number: 50102835

Defect Number: 42089272

Enquiry No.: 1303623

Logged by: Verint CRM Connector

on: 08/01/2022 18:46

Service: Road Gully & Flooding

Subject: Gully: Blocked/Needs Clean

Classification: Request for service

Desc.: What is the problem with the gully : blocked.

What surface is the gully on : unknown - describe it

Location: Not selectable on map. Blocked gully on edge of tram at the junction of South St Andrew St & Princes St. Outside the old Topshop. Appears full to brim and cracked concrete alongside.

Contact:

Enquiry No.: 1303008

Logged by: Verint CRM Connector

on: 07/01/2022 15:27

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: Tarmac on road at crossing point island, massive potholes, significant trip and fall hazard

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services


Enquiry No.: 1296670 Logged by: Verint CRM Connector on: 28/12/2021 12:03
 Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim
 Desc.: [REDACTED]
 Location: Raised and cracked stones outside clarks - 81 princess street Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset
 Job Number: 50101730 Defect Number: 42088302

Enquiry No.: 1296353 Logged by: [REDACTED] on: 27/12/2021 12:52
 Service: RD: Road Services Out of Hours Subject: RD: Out of Hours Emergency Classification: Request for service
 Desc.: sheveron - concrete block has been out in middle of road - half way in bus lane - holding a sign saying on unauthorised vehicles
 Location: princess street / apple store in the middle - been dragged across Contact:

Enquiry No.: 1296274 Logged by: Verint CRM Connector on: 27/12/2021 11:18
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: Pavement uneven and cracked in many places along Princes Street area. Trip Hazard or slip hazard if any puddles freeze.. Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset



Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1290155

Logged by: [REDACTED]

on: 14/12/2021 09:01

Service: Roads General


Subject: Street Furniture: Defective

Classification: Request for service

Desc.: M [REDACTED]

She was crossing the road using traffic lights! and tripped over the road dividers (not sure what the are called). Crossing over to the Wavely Market Mall.

Location:



Enquiry No.: 1288652

Logged by: Verint CRM Connector

on: 11/12/2021 08:56

Service: Open Space Maintenance

Subject: Litter


Classification: Request for service

Desc.: Which problem you would like to report? Litter complaint.

Does litter contain sharps? No

Location: A huge piece of wood lying on pavement near Tesco in princes street.

Contact:



Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1287505 Logged by: [REDACTED] on: 09/12/2021 09:01
 Service: Roads General Subject: Public Utilities: General Classification: Request for service
 Desc.: CRM Number: 101001034400
 Contact details: [REDACTED]

Location: [REDACTED] Contact: [REDACTED]

2. On Princes street just outside the Balmoral Hotel a manhole lid has been partly patched over!! Please do something about this. This is a capital city after all.
 [REDACTED]

Enquiry No.: 1287260 Logged by: Verint CRM Connector on: 08/12/2021 17:11
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: Outside Holland And Barrat, sunken and broken paving slabs. Bad trip hazard, need urgent attention Contact:

Enquiry No.: 1286160 Logged by: Verint CRM Connector on: 07/12/2021 08:41
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: Loose, cracked, sunken, wobbly paving slab directly out side Holland and Barrett shop on Princes Street. 18 Princes Street. Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset
 Job Number: 50099626 Defect Number: 42086336

Enquiry No.: 1285580 Logged by: Verint CRM Connector on: 06/12/2021 11:23
 Service: Roads General Subject: Public Utilities: General Classification: Request for service
 Desc.: Huge area of broken surface around manhole with loose cover. You can see from the photo, the road surface is breaking into blocks and some are missing, leaving bad holes. The manhole cover looks like it will fall apart soon. This is a busy junction with heavy traffic and a good number of bicycles.
 Location: Easting/Northing: 324800/673698 (55.950407, -3.205784) Contact:
 Nearest road to the pin placed on the map (automatically generated by Bing Maps):
 131-132 PRINCES, Edinburgh, EH2 4B

Enquiry No.: 1277544 Logged by: [REDACTED] on: 19/11/2021 11:26
 Service: Roads General Subject: Public Utilities: General Classification: General Enquiry
 Desc.: [REDACTED] advised that he takes deliveries in at the back of the rose street entrance however they cannot do this due to a bike rack being installed right outside the entrance. He is looking to have this removed as a matter of urgency as it is affecting him from getting deliveries into his shop
 Location: Rose Street entrance at the back of M&S Contact:

Enquiry No.: 1276628 Logged by: [REDACTED] on: 17/11/2021 19:30
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.: [REDACTED] And while they're at it can they fix this slab outside the Mercure hotel on Princes Street, right next to bus stop. [REDACTED]
 Location: Outside Mercure hotel on Princes Street, right next to bus stop Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1276496

Logged by: [REDACTED]

on: 17/11/2021 14:31

Service: Roads General

Subject: Public Utilities: General

Classification: Request for service

Desc.: missing clover

Location: Opposite PRET manhole cover at Lothian Road end

Contact:

Enquiry No.: 1275801

Logged by: Verint CRM Connector

on: 16/11/2021 13:27

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.:

Location: dangerous pavement surface has collapsed outside Topshop

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Job Number: 50097496

Defect Number: 42084143

Enquiry No.: 1274800

Logged by: Verint CRM Connector

on: 14/11/2021 21:50

Service: Open Space Maintenance

Subject: Litter

Classification: Request for service

Desc.: Which problem you would like to report? Litter complaint.

Does litter contain sharps? No

Location: Orange fences left by workmen left lying about pavements, graffiti and rubbish at west end.

Contact:

Enquiry No.: 1274536

Logged by: [REDACTED]

on: 14/11/2021 11:20

Service: RD: Road Services Out of Hours

Subject: RD: Out of Hours Emergency

Classification: Request for service

Desc.: Drain cover smashed, dangerous, sharp. Deep drop unguarded and pedestrians are walking over it

Location: opposite Three Store

74-75 Princes Street

EH2 2DF on pavement on gardens side of road.

Contact:

Enquiry No.: 1273963

Logged by: Verint CRM Connector

on: 12/11/2021 14:13

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: Potholes in the road with wires exposed.

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Job Number: 50097068

Defect Number: 42083570

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

| | | |
|---|--|--|
| Enquiry No.: 1270770 Service: Roads General Desc.: Location: On the eastbound lane, near the pavement, a bit pothole which all the buses are making worse, big bump when they over | Logged by: Verint CRM Connector Subject: Road: Defective / Damaged | on: 06/11/2021 19:01 Classification: Request for service Contact: |
| Plot Number: 3.00 Job Number: 50096208 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Defect Number: 42082644 | Feature Type: Road Asset |
| Enquiry No.: 1268660 Service: Roads General Desc.: Location: Sunken manhole cover and frame, west bound opposite old BHS store | Logged by: Verint CRM Connector Subject: Road: Defective / Damaged | on: 02/11/2021 18:33 Classification: Request for service Contact: |
| Plot Number: 3.00 Job Number: 50095921 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Defect Number: 42082396 | Feature Type: Road Asset |
| Enquiry No.: 1268657 Service: Roads General Desc.: Location: SW manhole cover and frame westbound outside NB hotel | Logged by: Verint CRM Connector Subject: Public Utilities: General | on: 02/11/2021 18:30 Classification: Request for service Contact: |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 1268262 Service: Roads General Desc.: Location: Manhole cover broken away - just saw someone fall in it! | Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective | on: 02/11/2021 10:18 Classification: Request for service Contact: |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 1268237 Service: Roads General Desc.: Location: A drain or utility cover is sinking into the road surface and the road surface has broken up around it. | Logged by: Verint CRM Connector Subject: Road: Defective / Damaged | on: 02/11/2021 10:02 Classification: Request for service Contact: |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 1268236 Service: Roads General Desc.: Location: Outside the Balmoral Hotel A drain or utility cover is sinking into the road surface and the road surface has broken up around it. | Logged by: Verint CRM Connector Subject: Road: Defective / Damaged | on: 02/11/2021 09:59 Classification: Request for service Contact: |
| Plot Number: 3.00 Job Number: 50095650 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Defect Number: 42082093 | Feature Type: Road Asset |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

| | | |
|--|--|--|
| Enquiry No.: 1268188 | Logged by: [REDACTED] | on: 02/11/2021 09:03 |
| Service: Accident Claims (All Services) | Subject: Accident Claim Roads/Lighting | Classification: Accident Claim |
| Desc.: I fell onto road due to faulty pavement [REDACTED] Re fault on pavement needs rectified it is dangerous as it is one of the square metal blocks that I think are used for when council put barriers up this one in particular is a disgrace the way it has been fitted as it is raised up higher on chunk of concrete and it won't be hard to find as it's pavement along at Scott's monument opposite Accessories store on princess street I hope this information helps if you need any further information please let me know | | |
| Location: along at Scott's monument opposite Accessories store on princess street | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50099200 | Defect Number: 42085937 | |
| Enquiry No.: 1267945 | Logged by: Verint CRM Connector | on: 01/11/2021 17:02 |
| Service: Roads General | Subject: Pavement: Damaged / Defective | Classification: Request for service |
| Desc.: | | |
| Location: Deep hole. Broken old electricity cover. Near railings. | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50095657 | Defect Number: 42082098 | |
| Enquiry No.: 1266145 | Logged by: [REDACTED] | on: 28/10/2021 16:22 |
| Service: Roads General | Subject: Pavement: Damaged / Defective | Classification: Request for service |
| Desc.: Large hole on pavement. Incident 2540 | | |
| Location: o/s St Johns Church | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50095325 | Defect Number: 42081743 | |
| Enquiry No.: 1266026 | Logged by: [REDACTED] | on: 28/10/2021 13:44 |
| Service: Roads General | Subject: Covers: Damaged / Defective | Classification: Request for service |
| Desc.: do not know what type of manhole cover this is. the cover has sunken into road...phoned this across to michael duffy roads daytime standby officer | | |
| Location: just before the tram stop at the mound heading towards haymarket...middle of road on this side of street | Contact: | |
| Enquiry No.: 1265720 | Logged by: Verint CRM Connector | on: 27/10/2021 22:38 |
| Service: Roads General | Subject: Public Utilities: General | Classification: Request for service |
| Desc.: | | |
| Location: On Princes Street, At junction with South Charlotte Street, Scottish Water manhole covers surrounded by broken up road. Especially dangerous for bikes | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 1265662 | Logged by: Verint CRM Connector | on: 27/10/2021 19:36 |
| Service: Open Space Maintenance | Subject: Litter | Classification: Request for service |
| Desc.: Which problem you would like to report? Litter complaint. Does litter contain sharps? No | | |
| Location: Orange work fence lying on payment. | Contact: | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1265280 **Logged by:** Verint CRM Connector **on:** 27/10/2021 10:24
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service

Desc.:

Location: The double chamber cover has failed and the chamber is at considerable risk of collapse. The road pavement immediately surrounding the chamber is disintegrating as a result of continued impact by HGVs and buses. If this is not repaired soon the chamber is likely to collapse and presents a considerable risk to road users.

Contact:

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1264684 **Logged by:** [REDACTED] **on:** 26/10/2021 09:49
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.: Hi @Edinburgh_CC this broken slab is placed in a really busy spot. Princes Street, just opposite Holland and Barrett. Can you fix it please? Many thanks in advance! H&B Team Princes St

Location: 18-19 Princes St**Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50094807**Defect Number:** 42081213

Enquiry No.: 1263081 **Logged by:** Verint CRM Connector **on:** 21/10/2021 18:27
Service: Open Space Maintenance **Subject:** Litter **Classification:** Request for service

Desc.: Which problem you would like to report? Litter complaint.
Does litter contain sharps? No

Location: Abandoned Traffic cones, work signs, sand bags, along princes st.**Contact:**

Enquiry No.: 1262435 **Logged by:** [REDACTED] **on:** 20/10/2021 13:33
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.: Pls inspect raised pavement before art gallery elderly gent tripped over it and fell**Location:** Between 33 bus stop and art gallery**Contact:**

Enquiry No.: 1261836 **Logged by:** Verint CRM Connector **on:** 19/10/2021 11:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:**Location:** Pothole**Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50094344**Defect Number:** 42080827

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1259213 **Logged by:** Verint CRM Connector **on:** 13/10/2021 11:45
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Road surface deteriorating around metal work which is also sunken **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1257969 **Logged by:** Verint CRM Connector **on:** 10/10/2021 22:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep crack in road outside Primark on Princes street. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1257937 **Logged by:** [REDACTED] **on:** 10/10/2021 19:44
Service: Open Space Maintenance **Subject:** OSM: Conduct **Classification:** Request for service
Desc.: CRM Number: 101000939220
Contact details: [REDACTED]
Customers Comment: I just witnessed a bin lorry on princes street at 1:35am 10/10/21, license plate [REDACTED] literally pull out the bins to empty and then drive off with a massive pile of dropped rubbish left behind including glass bottles, bags and fast food cartons. It's absolutely disgusting. It would have been reasonable if they'd even tried and just had the usual drunk people make a mess afterwards but these guys consciously left a pile of crap strewn on the street for people to walk on.
Location: **Contact:** [REDACTED]

Plot Number: 2.00 **Feature Id - Location:** Ward 11 - From The Mound to Hanover Street **Feature Type:** Road Asset

Enquiry No.: 1255769 **Logged by:** Verint CRM Connector **on:** 05/10/2021 23:42
Service: Road Gully & Flooding **Subject:** Gully: Blocked/Needs Clean **Classification:** Request for service
Desc.: What is the problem with the gully : blocked.
What surface is the gully on : footpath
Location: Acco / slot drain completely blocked and full of vegetation. Ponding water across footpath. **Contact:**

Enquiry No.: 1253199 **Logged by:** Verint CRM Connector **on:** 30/09/2021 09:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Drainage issue - massive puddle forming at the corner of Princes Street/North Bridge **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1253189 **Logged by:** [REDACTED] **on:** 30/09/2021 08:40
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.: Westbound on Princes Street, between the junctions with Lothian Road and South Charlotte Street, there is a loose manhole cover and clatters loudly any time a bus or car passes over it. There is also some degradation in the road surface surrounding the manhole.
Location: Westbound on Princes Street, between the junctions with Lothian Road and South Charlotte Street, there is a loose manhole cover and clatters loudly any time a bus or car passes over it. There is also some degradation in the road surface surrounding the manhole. **Contact:**


Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)


Customer Services



Enquiry No.: 1239316 **Logged by:** Verint CRM Connector **on:** 04/09/2021 07:03
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:
Location: Kerb stone has come away from mooring **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1238731 **Logged by:** Verint CRM Connector **on:** 02/09/2021 22:20
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Hi I tripped on a wobbly flag outside Waverley station on Princes Street, Edinburgh. **Contact:**
This was 25 August. It's quite dangerous [redacted]
[redacted] It's between 2 bus stops and steps down to the train station. My
photo is to large to send, if you email me I can send you photos to identify it.



Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00


Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1238190 Logged by: Verint CRM Connector on: 02/09/2021 09:34
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: Rocking paving slab Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset
 Job Number: 50091041 Defect Number: 42077274



Enquiry No.: 1233921 Logged by: [REDACTED] on: 25/08/2021 17:57
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.: just seen someone trip and go their length because of the dodgy paving at the top of Waverley Steps. If fixing isn't a viable solution can we at least afford to invest in some hazard tape?
 Location: top of waverly steps Contact:

Enquiry No.: 1232587 Logged by: Verint CRM Connector on: 24/08/2021 08:20
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: Broken dangerous slabs on shop side. Contact:

Enquiry No.: 1231574 Logged by: Verint CRM Connector on: 22/08/2021 08:17
 Service: Roads General Subject: Public Utilities: General Classification: Request for service
 Desc.:
 Location: Sunken manhole cover Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 1230694 Logged by: [REDACTED] on: 20/08/2021 08:43
 Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim
 Desc.: On Thursday 29th July at approximately 2:20pm whilst walking along Princes Street I had just come out of Boots walking towards the corner of Fredrick Street when I tripped and had a fall on a broken piece of pavement.
 It was a hard fall and I now have a radial head fracture in one of the bones in my elbow in my right arm. Three people came to my aid and pointed out that I had tripped on a broken piece of pavement.

Location: [REDACTED]

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1229673 **Logged by:** Verint CRM Connector **on:** 18/08/2021 15:15
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Drain cover surroundings deteriorated causing 200mm depth hole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1227644 **Logged by:** [REDACTED] **on:** 14/08/2021 17:01
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Should check your slabs on princess Street lose ones. [REDACTED] happened in April in [REDACTED] was walking along princess Street one of slabs gave away went over my foot think slight fracture again
Location: Junction of st st Andrews Street after pedestrian crossing **Contact:**

Enquiry No.: 1222791 **Logged by:** Verint CRM Connector **on:** 06/08/2021 13:54
Service: Road Gully & Flooding **Subject:** Gully: Blocked/Needs Clean **Classification:** Request for service
Desc.: What is the problem with the gully : blocked.
What surface is the gully on : footpath
Location: at the west end of the Princes tramstop, on the central island crossing point **Contact:**

Enquiry No.: 1222118 **Logged by:** Verint CRM Connector **on:** 05/08/2021 14:53
Service: Open Space Maintenance **Subject:** Graffiti (offensive/racist) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? council.
Is the graffiti offensive/racist? Yes .
Location: Graffiti on the electrical box located on the west side of the PLaza at the Waverley Mall **Contact:**

Enquiry No.: 1219619 **Logged by:** [REDACTED] **on:** 02/08/2021 08:56
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.: [REDACTED]
I slipped on the plastic pavement extender on Princes Street. It's in front of Waverley Village, in between the two bus stops. It happened on Saturday, 26.06.2021 at around 12.15.
Location: It was on Princes Street, in between bus stops PP and PQ. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1211194 **Logged by:** Verint CRM Connector **on:** 19/07/2021 18:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: canal cover loose (3 no.) in very close vicinity **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50087723 **Defect Number:** 42073768

Enquiry No.: 1211082 **Logged by:** [REDACTED] **on:** 19/07/2021 16:10
Service: Open Space Maintenance **Subject:** Street Cleaning Request **Classification:** Request for service
Desc.: I am standing at the top of Waverly steps waiting on someone coming off the train. I am horrified at the state of the pavements. They are disgustingly disgraceful. They are dirty , soiled and not welcoming for tourists. What is wrong with our council? Clean up our public spaces. Get street cleaners out there. It is totally unhygienic. Please get your act together.

Location: [REDACTED] **Contact:**

Enquiry No.: 1209919 **Logged by:** Verint CRM Connector **on:** 17/07/2021 11:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: manhole cover **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50087708 **Defect Number:** 42073748

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00


Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1208476 **Logged by:** Verint CRM Connector **on:** 15/07/2021 08:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Collapsed manhole cover west end of Princes Street west bound at South Charlotte Street junction. **Contact:**


Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50087514 **Defect Number:** 42073604



Enquiry No.: 1206036 **Logged by:** Verint CRM Connector **on:** 10/07/2021 18:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 4x, 1 foot wide, 2 inch deep potholes, north side of street, corner Princes Street & Frederick Street; What3Words reference is hoot.drunk.affair **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50087318 **Defect Number:** 42073343

Enquiry No.: 1204220 **Logged by:** Verint CRM Connector **on:** 07/07/2021 21:57
Service: Open Space Maintenance **Subject:** Litter **Classification:** Request for service
Desc.: Which problem you would like to report? Litter complaint.
Does litter contain sharps? No
Location: Orange barrier lying on pavement outside jenners, woman tripped over l. **Contact:**



Effective: 01/01/2020 to 31/03/2022
Display Action Officer: No

Asset Number: 1.00 to 3.00
Site: Princes Street (7903151)


Customer Services



Enquiry No.: 1198445 Logged by: [redacted] on: 29/06/2021 12:48
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.: Customers Comment: [redacted] tripped over some raised surface on princes street and fell [redacted]. I'm not sure what the areas are called but it's raised metal areas on the sides closest to the road. [redacted] would suggest that these be covered or highlighted in some way to reduce the chances of this happening again to others and cause more damage [redacted]
Location: [redacted] Contact:

Enquiry No.: 1197598 Logged by: Verint CRM Connector on: 28/06/2021 09:30
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: Slabs located just outside the plaza area located on top of the Waverley Mall Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset



Enquiry No.: 1193571 Logged by: Verint CRM Connector on: 19/06/2021 13:14
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Various pot holes outside hotel. Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset
Job Number: 50085569 Defect Number: 42071455

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1192850 **Logged by:** Verint CRM Connector **on:** 18/06/2021 10:37
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Guys, this is on the corner of Princes st beside Jenners, can someone fix this asap, **Contact:**
concerned that someone could hurtthemselves. its on the corner of princes street
south St David Street opposite Jenners and beside the traffic lights.

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50085511 **Defect Number:** 42071410

Enquiry No.: 1187995 **Logged by:** [REDACTED] **on:** 09/06/2021 10:19
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.: [REDACTED]
Date: Wednesday, June 9, 2021, 10:06:11 AM
To: clarence@edinburgh.gov.uk <clarence@edinburgh.gov.uk>
Subject: Accident

I was walking down princess Street on Saturday 5th June and there was a paving slab up and it came up and I lost my balance [REDACTED]
[REDACTED] it was outside the posh sweet shop 85 princess Street [REDACTED]
[REDACTED]

Location: outside the posh sweet shop 85 princess Street **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50084981 **Defect Number:** 42070869

Enquiry No.: 1185415 **Logged by:** [REDACTED] **on:** 04/06/2021 08:52
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.: Our client was walking east on Princes Street. She stepped into a pothole, lost her balance and fell to the ground.
Location: Princes Street at junction with Frederick Street **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1183835 **Logged by:** [REDACTED] **on:** 01/06/2021 14:10
Service: RD: Road Services Out of Hours **Subject:** RD: Out of Hours Emergency **Classification:** Request for service
Desc.: urgent sorry there is a paving slab which is cracked and split in two and is protruding up around 40 - 50 mls and two people already tripped over it thankfully they are ok. i left a voice mail message
for [REDACTED] about this
Location: front of number 97 - 98 **Contact:**

Enquiry No.: 1183832 **Logged by:** Verint CRM Connector **on:** 01/06/2021 14:08
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: paving stone broken and sticking up around 50mm outside jewellers @97 Princes street **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50084429 **Defect Number:** 42070188

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1181498 **Logged by:** Verint CRM Connector **on:** 27/05/2021 14:21
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Small ridge between paving slabs at 44 bus stop west bound across from former Debenham building. In 4 minutes I saw two people trip over this. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1179420 **Logged by:** Verint CRM Connector **on:** 24/05/2021 09:30
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location: Road.
Type: Foliage / Bush
Location: Low hanging branches hitting buses and possibility of hitting passengers on open top tours. **Contact:**

Enquiry No.: 1178661 **Logged by:** [REDACTED] **on:** 21/05/2021 13:56
Service: Roads General **Subject:** Roadworks: Defect **Classification:** Request for service
Desc.: Hello, the sign in the below photograph has been laying across the pavement for 2 days now. There is no local roads closed that I know of. Its a trip hazard. Thanks
Location: On Princes Street/ West register Street. Beside Apple Store. Opposite The Balmoral **Contact:**

Enquiry No.: 1177731 **Logged by:** Verint CRM Connector **on:** 20/05/2021 09:58
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: North side, outside Top Shop. Paving stone edge sticking up 1/4 inch. [REDACTED] **Contact:**
[REDACTED] This happened on Tuesday 18 May about 3.3

Enquiry No.: 1177656 **Logged by:** [REDACTED] **on:** 20/05/2021 08:31
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.: Hit one of the spaces for people bollards when cycling and injured his face.
Location: travelling westbound - passing the pedestrian crossing near the Scott Monument/Waverley Station **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1172024 **Logged by:** Verint CRM Connector **on:** 08/05/2021 15:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole where the front wheel of the bus stops, next to bus shelter 'Scott Monument PT' on south side of Princes Street; What3Words reference is sage.trips.trio **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Effective: 01/01/2020 to 31/03/2022


Asset Number: 1.00 to 3.00

Display Action Officer: No



Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1171024 Logged by: Verint CRM Connector on: 06/05/2021 12:56
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: On 27th April 2021 I had just arrived in Edinburgh when I tripped over a pavement slab near to bus stop that was badly protruding from those around it



Enquiry No.: 1170730 Logged by: Verint CRM Connector on: 05/05/2021 20:22
 Service: Open Space Maintenance Subject: Graffiti (non offensive) Classification: Request for service
 Desc.: Is the graffiti on Council or private property? not known.
 Is the graffiti offensive/racist? No .
 Location: Green grafitti on one of the planters on the Mound precinct



Enquiry No.: 1157713 Logged by: Verint CRM Connector on: 12/04/2021 10:54
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Trip Hazard. The temporary rubber thing fitted to the road needs cleaned. It's at the bus stop. I cant upload the image as it says it's to big. It tripped over it after disembarking a bus. The poles have been removed which makes it dangerously unseen.

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1153775 **Logged by:** Verint CRM Connector **on:** 06/04/2021 07:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Please see photos .There is a very loud noise any time a vehicle, especially buses, **Contact:**
travel over this manhole.

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50080517 **Defect Number:** 42066512

Enquiry No.: 1151856 **Logged by:** [REDACTED] **on:** 01/04/2021 12:38
Service: Open Space Maintenance **Subject:** Spillage of Fluids **Classification:** Request for service
Desc.: oil substance has been pored on the pavemnet
Location: outside barcleys **Contact:**

Enquiry No.: 1146826 **Logged by:** [REDACTED] **on:** 24/03/2021 10:11
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.: Raised paving slabs
Location: Bus stop on opp side of road from Card Factory shop for buses 4 and 44 **Contact:**

Enquiry No.: 1142418 **Logged by:** Verint CRM Connector **on:** 17/03/2021 15:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: a hole on side of road closest to princes mall and on opposite side of street from **Contact:**
whittards shop. hole is circular in shape around 18 inches in size and possibly
around 3 or 4 inches in depth

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50079381 **Defect Number:** 42065391

Enquiry No.: 1141773 **Logged by:** Verint CRM Connector **on:** 16/03/2021 19:57
Service: Roads General **Subject:** Roadworks: Defect **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow
Location: Between Balmoral Hotel and Apple store **Contact:**



Enquiry No.: 1138834 **Logged by:** [REDACTED] **on:** 11/03/2021 15:11
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Rasied pavement outside at the last bus stop going out of town for the 4 next to charlotte square [REDACTED] e
Location: Rasied pavement outside at the last bus stop going out of town for the 4 next to **Contact:**
charlotte square at the begging of the bus shelter

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1134343 **Logged by:** Verint CRM Connector **on:** 04/03/2021 11:15
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Located just in the middle of the bus stop you have a very loose slab that already 1 **Contact:**
member of the public has tripped on.

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50077348 **Defect Number:** 42063315

Enquiry No.: 1128734 **Logged by:** Verint CRM Connector **on:** 24/02/2021 10:58
Service: Open Space Maintenance **Subject:** Graffiti (offensive/racist) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? council.
Is the graffiti offensive/racist? Yes .
Location: graffiti on council eclectic boxes and bins. been reported a few times **Contact:**

Enquiry No.: 1126319 **Logged by:** Verint CRM Connector **on:** 21/02/2021 13:04
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:
Location: Bus stop paving stone broken & currently a trip hazard to members of the public **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50075897 **Defect Number:** 42062044

Enquiry No.: 1116897 **Logged by:** Verint CRM Connector **on:** 11/02/2021 00:49
Service: Roads General **Subject:** Road: Missing Setts / Blocks **Classification:** Customer Emergency
Desc.:
Location: **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1115803 **Logged by:** Verint CRM Connector **on:** 09/02/2021 16:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pot hole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50074847 **Defect Number:** 42061098

Enquiry No.: 1110633 **Logged by:** Verint CRM Connector **on:** 01/02/2021 13:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole at lights into Waterloo Place in direct line of traffic.already deep and breaking up **Contact:**

Enquiry No.: 1108532 **Logged by:** [REDACTED] **on:** 28/01/2021 13:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Large pothole
Location: at east end of Princes Street on right hand lane at junct with North bridge **Contact:**

Enquiry No.: 1105241 **Logged by:** Verint CRM Connector **on:** 22/01/2021 14:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Subject: Reference Number 101000536929
Please see attached pictures of broken manhole cover
Sunk manhole on junction of Sth St David Street/ Princes St
Location: road crumbling around manhole on junction between princes street and south st david street **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50072704 **Defect Number:** 42059338

Enquiry No.: 1103481 **Logged by:** Verint CRM Connector **on:** 20/01/2021 06:46
Service: Open Space Maintenance **Subject:** Graffiti (offensive/racist) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? private.
Is the graffiti offensive/racist? Yes .
Location: anti vaccination graffiti on the vodafone shop on princess street and round the corner onto the next street **Contact:**

Enquiry No.: 1097441 **Logged by:** [REDACTED] **on:** 08/01/2021 15:15
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: @edinhelp @Edinburgh_CC one of the drains is leaking quite a lot on the corner by the Scott Monument on Princes Street- just letting you know incase you didn't know! ;
Location: @edinhelp @Edinburgh_CC one of the drains is leaking quite a lot on the corner by the Scott Monument on Princes Street- just letting you know incase you didn't know! **Contact:**

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1095342 **Logged by:** [REDACTED] **on:** 06/01/2021 09:21
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: Flooding
Category: Pavements/footpaths
Flooding through the manhole cover, it'll ice over tonight as well.
Location: front of 45 - 46 princes street **Contact:**

Enquiry No.: 1087993 **Logged by:** Verint CRM Connector **on:** 21/12/2020 13:46
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Reported this last year yellow board on pavement causing tripping/sliding hazard is still there. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1086501 **Logged by:** [REDACTED] **on:** 17/12/2020 15:07
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: several manhole covers defective. please see document attached
Location: several manhole covers defective. please see document attached **Contact:**

Enquiry No.: 1084189 **Logged by:** Verint CRM Connector **on:** 13/12/2020 11:08
Service: Open Space Maintenance **Subject:** Graffiti (non offensive) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? council.
Is the graffiti offensive/racist? No .
Location: Nearly every bin on Princes Street as well as Lothian Road has been vandalised with graffiti. This was reported weeks ago. Also all of the graffiti reported has disappeared from the map without being cleaned, reinstate all reports from last month&action!! **Contact:**

Enquiry No.: 1082878 **Logged by:** [REDACTED] **on:** 10/12/2020 12:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: [REDACTED]
Location: there is a hole in the pavement she has fell over this [REDACTED] **Contact:**
[REDACTED] can we fix this asap opposite side of the road to primark

Enquiry No.: 1081346 **Logged by:** Verint CRM Connector **on:** 07/12/2020 23:32
Service: Open Space Maintenance **Subject:** Graffiti (offensive/racist) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? council.
Is the graffiti offensive/racist? Yes .
Location: West princes street gardens shelters. Covered in graffiti **Contact:**

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1079250 **Logged by:** [REDACTED] **on:** 03/12/2020 16:17
Service: Road Permits **Subject:** Permits: Road Occupation (S58) **Classification:** Request for service
Desc.: From: [REDACTED]
 Sent: 19 November 2020 13:41
 To: Customer Care <Customer.Care@edinburgh.gov.uk>
 Subject: Walkway too narrow

I think the west Princes Street walkway beside the building site at former Fraser's is too narrow for people without masks passing one another. See attached photos.
 Could something be done about this, please ?
 Thanks.

Location: [REDACTED]**Contact:**

Enquiry No.: 1078957 **Logged by:** [REDACTED] **on:** 03/12/2020 10:50
Service: Winter Response **Subject:** Gritting: Pavement / Footpath **Classification:** Request for service
Desc.: @Edinburgh_CC the paths in princess street, mound and Ramsay lane very bad this morning,hadn't been gritted at all
Location: **Contact:**

Enquiry No.: 1077593 **Logged by:** Verint CRM Connector **on:** 30/11/2020 18:38
Service: Open Space Maintenance **Subject:** Graffiti (non offensive) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? council.
 Is the graffiti offensive/racist? No .
Location: Nearly all bins on Princes St have been vandalised with graffiti. Please clean them ASAP as they're such an eyesore on the main street of the city. **Contact:**

Enquiry No.: 1071835 **Logged by:** [REDACTED] **on:** 19/11/2020 09:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: claim form sent please see document attached thanks
Location: claim form sent please see document attached thanks **Contact:**

Enquiry No.: 1071636 **Logged by:** Verint CRM Connector **on:** 19/11/2020 04:54
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
 Location:Footpath.
 Type:Grass
Location: VERINT TEST **Contact:**

Enquiry No.: 1071635 **Logged by:** Verint CRM Connector **on:** 19/11/2020 03:28
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
 Location:Pavement.
 Type:Grass
Location: VERINT TEST **Contact:**

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1071631 **Logged by:** Verint CRM Connector **on:** 19/11/2020 03:16
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
Location:Footpath.
Type:Foliage / Bush
Location: VERINT TEST **Contact:**

Enquiry No.: 1069147 **Logged by:** [REDACTED] **on:** 14/11/2020 13:24
Service: Roads General **Subject:** Signs: General Enquiry **Classification:** General Enquiry
Desc.: @Edinburgh_CC don't think this sign at the jct of North Bridge and Princes St is correct now? - Sign in question is the one that shows waverly, Parking symbol and railway sign. On fence at the junction of Nothr bridge.Princess street infront of Hm genral regsiter house
Location: Princes Street **Contact:**
Edinburgh
City of Edinburgh
EH2 2AN

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50068058 **Defect Number:** 42055969

Enquiry No.: 1067845 **Logged by:** [REDACTED] **on:** 12/11/2020 09:28
Service: Street lighting **Subject:** Light: Light out (5+ Consec.) **Classification:** Request for service
Desc.: From: [REDACTED] >
Sent: 11 November 2020 18:01
To: Customer Care <Customer.Care@edinburgh.gov.uk>
Subject: Line of lights not on in Princes Street

Hello

Given it's so many I suspect it may be a timer issue than so many bulbs not working at the one time, particularly since each other section of Princes Street had its lights on.

Walking home from work this evening at 16:40 it was dark but none of the lights on Princes Street between South St. David Street and Hanover Street were on:

- a) none of single lights on the Gardens side of the above;
- b) none of the double lights in the middle of the roadway that carries the tram electricity wire.

It was very dark on the Gardens side and the only light available was from buses.

Grateful if you could investigate and amend the timer so that all lights on Princes Street between South St. David Street and Hanover Street are on when it's dark.

Location: [REDACTED] **Contact:**

Enquiry No.: 1062655 **Logged by:** Verint CRM Connector **on:** 03/11/2020 01:52
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:
Location: VERINT TEST **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1059472

Logged by: Verint CRM Connector

on: 26/10/2020 22:27

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service


Desc.:

Location: 2 large manhole covers and 1 smaller one on princess Street outside primark are on the verge of collapsing due to constant impact from buses. Contact:

Plot Number: 1.00

Feature Id - Location: Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset



Enquiry No.: 1051086

Logged by: Verint CRM Connector

on: 08/10/2020 06:49

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service


Desc.:

Location: Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset



Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1046484 **Logged by:** [REDACTED] **on:** 28/09/2020 15:18
Service: Road Gully & Flooding **Subject:** RD: Gully Cover Damaged **Classification:** Request for service
Desc.: Gully has no lid on it customer just about fell down the hole of it which is dangerous.
Location: Right outside Primark on Princess Street **Contact:**

Enquiry No.: 1046419 **Logged by:** [REDACTED] **on:** 28/09/2020 14:00
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Large piece of metal that has been screwed into the pavement but it has only been screwed in one side of it so it moves when you walk on it. The customer nearly tripped and nearly fell which is dangerous.
Location: On the Princess Street Gardens side right opposite Superdrug **Contact:**

Enquiry No.: 1045281 **Logged by:** Verint CRM Connector **on:** 25/09/2020 10:54
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Last night I tripped on a rocking pavement slab and fell badly , this was approximately at the bus stop outside Princes Mall on Princes Street . **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50063645 **Defect Number:** 42053806

Enquiry No.: 1043731 **Logged by:** Verint CRM Connector **on:** 22/09/2020 14:08
Service: Open Space Maintenance **Subject:** Litter **Classification:** Request for service
Desc.: Which problem you would like to report? Litter complaint.
Does litter contain sharps? No
Location: Customers Comment: I am writing to complain about the build up of litter in the gutter outside The Balmoral Hotel. At a time when cleanliness and hygiene are a priority I find it deplorable that the council is allowing the build up of litter and debris that can attract vermin and cause disease, especially in a busy area designated for social distancing during a pandemic. Please respond and rectify this issue as a priority. **Contact:**

Enquiry No.: 1042450 **Logged by:** [REDACTED] **on:** 20/09/2020 11:58
Service: RD: Road Services Out of Hours **Subject:** RD: Out of Hours Emergency **Classification:** Request for service
Desc.: Description - Bench gone missing from princes street and the two brackets are on the floor with people stumbling over them.
Location: Description - Bench gone missing from princes street and the two brackets are on the floor with people stumbling over them. **Contact:**

Enquiry No.: 1041604 **Logged by:** Verint CRM Connector **on:** 18/09/2020 07:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Crossing from princess street Edinburgh to the waverly market . Very bad pot hole on the waverly side of the road crossing . I was in it at 7pm 17/9/20. Very sore and it needs seen to before its tragic . **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50062928 **Defect Number:** 42053588

Enquiry No.: 1041093 **Logged by:** [REDACTED] **on:** 17/09/2020 07:26
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Paving slab raised and customer had a fall [REDACTED]
Location: 2nd last bus stop before Lothian road on gardens side - serves buses3 and 33 slab raised at bus stop **Contact:**

Effective: 01/01/2020 to 31/03/2022


Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1040950 **Logged by:** Verint CRM Connector **on:** 16/09/2020 15:32
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Raised paving slab on gardens side of princes street. This is at the 2nd last bus stop before Lothian Road. Customer has fallen over it . The bus stop serves the 3 and 33 bus



Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1038000 **Logged by:** Verint CRM Connector **on:** 11/09/2020 07:56
Service: Open Space Maintenance **Subject:** Graffiti (non offensive) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? not known.
Is the graffiti offensive/racist? No .
Location: some graffiti **Contact:**

Enquiry No.: 1031413 **Logged by:** Verint CRM Connector **on:** 01/09/2020 03:55
Service: Roads General **Subject:** Road: Missing Setts / Blocks **Classification:** Customer Emergency
Desc.:
Location: **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1030462 **Logged by:** Verint CRM Connector **on:** 30/08/2020 11:59
Service: Roads General **Subject:** Signs: Defective / Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow
Location: At the intersection of Princes Street and Castle Street, there is a traffic light that is not facing the traffic, but in a 45-degree angle to it. It is very risky for pedestrians, who see a green light almost in front of them and tend to cross the street. **Contact:**

Enquiry No.: 1027757 **Logged by:** Verint CRM Connector **on:** 25/08/2020 12:25
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: The drainage isn't working correctly in the middle of the payment outside Chisholm Hunter. Recently with the bad weather the drain cannot keep up with the amount of water. There is consistently a puddle but recently there was so much water it flooded our store destroying thousands of pounds worth of property. We need to get the drainage sorted ASAP before anymore flooding could occur. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1027508 **Logged by:** Verint CRM Connector **on:** 25/08/2020 05:05
Service: Roads General **Subject:** Road: Missing Setts / Blocks **Classification:** Customer Emergency
Desc.:
Location: **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1025293 **Logged by:** Verint CRM Connector **on:** 19/08/2020 20:04
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: there is a hand rail broken is in this state from a year is on the path in princess street near the church **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50061285 **Defect Number:** 42052904

Enquiry No.: 1025118 **Logged by:** [REDACTED] **on:** 19/08/2020 14:43
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.: I am advised that an incident occurred on 22 December 2019 on the southside footway of Princes Street, Edinburgh.
Location: i have sent claim papers. please see two documents attached **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 1023682 **Logged by:** Verint CRM Connector **on:** 17/08/2020 13:46
Service: Open Space Maintenance **Subject:** Graffiti (non offensive) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? council.
Is the graffiti offensive/racist? No .
Location: Nearly every bin on Princes St is now covered by graffiti. Can you please clean / repaint them all ASAP **Contact:**

Enquiry No.: 1023680 **Logged by:** Verint CRM Connector **on:** 17/08/2020 13:45
Service: Open Space Maintenance **Subject:** Graffiti (offensive/racist) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? council.
Is the graffiti offensive/racist? Yes .
Location: Bin next to bus shelter at the bottom of the Mound has been covered by highly offensive 'ACAB' graffiti **Contact:**

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)


Customer Services

Enquiry No.: 1020913 Logged by: [REDACTED] on: 12/08/2020 03:55
 Service: RD: Road Services Out of Hours Subject: RD: Out of Hours Emergency Classification: Request for service
 Desc.: Road flooding into basement
 Location: 90 -Burger king Contact:
 Princes Street
 New Town
 Edinburgh
 City of Edinburgh


Enquiry No.: 1020881 Logged by: Verint CRM Connector on: 12/08/2020 00:10
 Service: Road Gully & Flooding Subject: Gully: Flooding Classification: Customer Emergency
 Desc.: What is the problem with the gully : flooding.
 What surface is the gully on : road.
 Are cars avoiding the flood : Unknown.
 Is flood affecting a property : Unknown

Location: Contact:

Plot Number: 2.00 Feature Id - Location: Ward 11 - From The Mound to Hanover Street Feature Type: Road Asset
 Job Number: 50060410



Enquiry No.: 1018671 Logged by: [REDACTED] on: 07/08/2020 10:22
 Service: Roads General Subject: Covers: Damaged / Defective Classification: Request for service
 Desc.: Can you have the two manhole covers outside Primark Princes St repaired ASAP as every time a bus hits them, it compresses them further into the ground. Thanks.
 Location: outside primark Contact:



Enquiry No.: 1016836 Logged by: Verint CRM Connector on: 04/08/2020 08:10
 Service: Roads General Subject: Road: Missing Setts / Blocks Classification: Customer Emergency
 Desc.:
 Location: Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 1015945

Logged by: Verint CRM Connector

on: 01/08/2020 22:46

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.:

Location: Raised slab just before exit under scaffolding by Frasers building hearing towards Queensferry street. Is on the left as estimating and hard to see the to poor lighting, lack of space and social distancing.

Contact:


[Redacted]

[Redacted]

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset



| |
|--|
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |


Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)


Customer Services



Enquiry No.: 999709 Logged by: [Redacted] on: 26/06/2020 14:35
 Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim
 Desc.: Accident Claim form (see attached).
 Location: Princes Street Contact:

Enquiry No.: 994537 Logged by: Verint CRM Connector on: 15/06/2020 14:59
 Service: Open Space Maintenance Subject: Dog Fouling Classification: Request for service
 Desc.: Dog fouling problem
 Location: test Contact:

Enquiry No.: 991163 Logged by: Verint CRM Connector on: 04/06/2020 09:00
 Service: Open Space Maintenance Subject: Litter Classification: Request for service
 Desc.: Which problem you would like to report? Litter complaint.
 Does litter contain sharps? No
 Location: This blanket or duvet has been lying in the street, right next to Princes St. Gardens and opposite the National Gallery for well over a month. It's a disgrace and a health-hazard. We are more concerned about this spreading disease than Coronavirus. Birds peck at it and it's a breeding-ground for mice and rats. Please arrange to have it removed immediately.
 Why should we pay Council Tax for street cleaning ? Contact:



Enquiry No.: 978242 Logged by: Verint CRM Connector on: 26/03/2020 13:30
 Service: Open Space Maintenance Subject: Graffiti (non offensive) Classification: Request for service
 Desc.: Is the graffiti on Council or private property? council.
 Is the graffiti offensive/racist? No .
 Location: CCTV camera pole (opposite entrance to Castle Street, on Princes St -- south side of the street) has been covered by a huge amount of graffiti Contact:

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 976796 **Logged by:** Verint CRM Connector **on:** 20/03/2020 07:52
Service: Open Space Maintenance **Subject:** Litter **Classification:** Request for service
Desc.: Which problem you would like to report? Litter complaint.
Does litter contain sharps? No
Location: Roof of Waverley Mall is covered in McDonalds litter **Contact:**

Enquiry No.: 976564 **Logged by:** [REDACTED] **on:** 19/03/2020 12:47
Service: Open Space Maintenance **Subject:** Bin Repair/Replace/Resite **Classification:** Request for service
Desc.: bin has been set on fire can we go out to replace
Location: outside top man **Contact:**

Enquiry No.: 975797 **Logged by:** Verint CRM Connector **on:** 17/03/2020 12:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At east end of princes street, on north side buy the traffic lights with the bridges. So big it will kill a cyclist. **Contact:**

I have a photo but cant attach it.

Yours in fear of my life.

Enquiry No.: 975771 **Logged by:** [REDACTED] **on:** 17/03/2020 11:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole east end of Princes Street, eastbound, around the point after apple shop but before Leith Street. Almost level with North Bridge on right, Iron Duke on left. **Contact:**

Enquiry No.: 975529 **Logged by:** Verint CRM Connector **on:** 17/03/2020 08:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Approx 400mm dia pothole on Waterloo Pl off North Bridge outside register house. Carriageway for turning left onto Leith street. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset
Job Number: 50054915 **Defect Number:** 42049053

Enquiry No.: 975478 **Logged by:** Verint CRM Connector **on:** 16/03/2020 15:52
Service: Accident Claims (All Services) **Subject:** Accident Claim Roads/Lighting **Classification:** Accident Claim
Desc.:
Location: there is a hole in the pavement [REDACTED] **Contact:**
[REDACTED] can we fix this asap opposite side of the road to primark

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 975464 **Logged by:** Verint CRM Connector **on:** 16/03/2020 15:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: very deep pothole outside the apple store **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 975117 Logged by: Verint CRM Connector on: 16/03/2020 01:03
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Very severe and dangerous pothole Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset



Enquiry No.: 973908 Logged by: [Redacted] on: 12/03/2020 09:06
 Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim
 Desc.: Pothole
 Location: at the bus stop between Book World and the site of the former British Home Stores (currently under reconstruction). Contact:

Enquiry No.: 973473 Logged by: Verint CRM Connector on: 11/03/2020 10:12
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: I came off my bike here due to the front wheel getting stuck in the tram track. Luckily I have only minor injuries. The people who helped me said they see this "all the time." This is a problem caused by infrastructure that is incredibly dangerous. The council needs a plan to inform the public, perhaps using signage or in partnership with local bike shops. I will never ride on a street with tram lines again, but I guarantee you others will, and some of those people will be badly hurt or killed. Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset


Enquiry No.: 972687 Logged by: [Redacted] on: 09/03/2020 15:37
 Service: Open Space Maintenance Subject: New Litter Bin Request Classification: Request for service
 Desc.: @edinhelp this bin is broken by Waverley rooftop between the bus stops, contents will be all over Princes Street by rush hour if not dealt with #littering #brokenstreetbin
 Location: by Waverley rooftop between the bus stops Contact:

Effective: 01/01/2020 to 31/03/2022

Display Action Officer: No

Asset Number: 1.00 to 3.00

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 971181 Logged by: [REDACTED] on: 05/03/2020 14:25
 Service: Roads General Subject: Covers: Damaged / Defective Classification: Request for service
 Desc.: South st david street and hanover street. Mancover fell inside on princess street.
 Location: Princes Street Contact:

Enquiry No.: 971179 Logged by: [REDACTED] on: 05/03/2020 14:26
 Service: Roads General Subject: Covers: Damaged / Defective Classification: Request for service
 Desc.: Hi @edinhelp this needs made safe asap. Princes St eastbound between Hanover St and South St David (o/s old BHS).
 Location: Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset
 Job Number: 50054220 Defect Number: 42048376

Enquiry No.: 971004 Logged by: Verint CRM Connector on: 05/03/2020 10:14
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Pothole opp statue Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 970899 Logged by: Verint CRM Connector on: 04/03/2020 23:52
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Large pothole in carriageway at traffic lights outside Apple store on Princes Street. Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset
 Job Number: 50054150 Defect Number: 42048315

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 970641 **Logged by:** [REDACTED] **on:** 04/03/2020 14:38
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: Drain cover collapsed in on itself
72-73 Princes Street, Edinburgh, EH2 2DF
Location: Nearest road to the pin placed on the map (automatically generated by Bing Maps): **Contact:**
72-73 Princes Street, Edinburgh, EH2 2DF

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 970251 **Logged by:** [REDACTED] **on:** 03/03/2020 19:02
Service: Roads General **Subject:** Covers: Missing **Classification:** Customer Emergency
Desc.: Drain cover on side of Princes St by Debenhams missing - dangerous as child could fall down drain.
Location: **Contact:**

Enquiry No.: 970014 **Logged by:** Verint CRM Connector **on:** 03/03/2020 12:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: close to number 20 princes street **Contact:**

Enquiry No.: 969567 **Logged by:** [REDACTED] **on:** 02/03/2020 16:18
Service: Open Space Maintenance **Subject:** Bin Repair/Replace/Resite **Classification:** Request for service
Desc.: Bins have gone from Princess Street and Elm Row next to bus-stops. Can these bins please be replaced as the raised concrete platforms are still in position and posing a trip hazard and littering at bus-stops is increasing due to no bins.
Location: Litter bins near bus-stops at Princes Street and Elm Row **Contact:** [REDACTED]

Enquiry No.: 969140 **Logged by:** Verint CRM Connector **on:** 02/03/2020 08:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: hole close to pedestrian crossing on princes street just close to jenners and in between prince street gardens and jenners..hole is around 2 feet in diameter and around 3 or so inches deep close to tram tracks **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50054040 **Defect Number:** 42048229

Enquiry No.: 969018 **Logged by:** Verint CRM Connector **on:** 01/03/2020 19:46
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Whilst visiting on Saturday I tripped over a seriously raised paving slab outside Superdrug on princes street. It was nearer the road than the shops. [REDACTED] **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50053940 **Defect Number:** 42048195

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

| | | |
|---|--|--|
| Enquiry No.: 968515 | Logged by: Verint CRM Connector | on: 29/02/2020 11:34 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: HAZARD TYPE: Pothole APPROX. SIZE: APPROX. DEPTH: APPROX. DISTANCE FROM KERB: DATE ENCOUNTERED: 2020-02-26 DEFECT DESCRIPTION: Multiple potholes and rutting on princes street at junction with Hanover street - lane towards Waverley station. Very dangerous for cyclists FURTHER INFORMATION: http://www.fillthathole.org.uk/hazard/174105 | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 968504 | Logged by: Verint CRM Connector | on: 29/02/2020 11:20 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: HAZARD TYPE: Unevenness due to rut or gully DATE ENCOUNTERED: 2020-02-26 Multiple potholes and rutting on princes street at junction with Fredrick street - lane towards Waverley station. Very dangerous for cyclists FURTHER INFORMATION: http://www.fillthathole.org.uk/hazard/174104 | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 968483 | Logged by: Verint CRM Connector | on: 29/02/2020 10:59 |
| Service: Roads General | Subject: Pavement: Damaged / Defective | Classification: Request for service |
| Desc.: | | |
| Location: * Princes Street, north pavement, outside Marks & Spencer (no. 60) [the westmost entrance]; - paving stone displaced leaving tripping edge. | Contact: | |
| Enquiry No.: 966855 | Logged by: Verint CRM Connector | on: 26/02/2020 14:12 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: A pothole is forming in the pedestrian crossing on the north side of Princes St. | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50053616 | Defect Number: 42047802 | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 965585

Logged by: [REDACTED]

on: 24/02/2020 14:52

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.: one of square slabs has sunken down...the photograph sent is too large to be copied into this note...From: [REDACTED] >

Sent: 20 February 2020 12:27

To: Clarence <Clarence@edinburgh.gov.uk>

Subject: Pavement Accident

[REDACTED]. This was entirely due to a loose slab on the pavement. See attached photo. The incident took place outside Marks and Spencers on the right side of the store. The incident was captured on the stores CTV cameras [REDACTED]

Location: outside Marks and Spencers on the right side of the store.

Contact:

Enquiry No.: 965451

Logged by: [REDACTED]

on: 24/02/2020 12:21

Service: Open Space Maintenance

Subject: Bin Repair/Replace/Resite

Classification: Request for service

Desc.: From: do-not-reply@edinburgh.gov.uk <do-not-reply@edinburgh.gov.uk>

Sent: 18 February 2020 18:50

To: Customer Care <Customer.Care@edinburgh.gov.uk>

Subject: Email to be generated to Customer Care Team

CRM Number: 101000134313

Reference Number:

Customer name:

Address:

Contact details: stephanie.egan@boots.com

Customers Comment: Can I ask why the bins on princes street that were removed at new year have been put back but not in place where they usually are? One seems to have appeared right in front of Boots! Stands out like an eyesore whereas the usual place next to bus stop it didn't stand out so much! Is the confirmed position for a bin directly outside Boots now or can this be moved?

Customers previous reported issue:

Any previous reference numbers linking to current complaint:

Location: Princes Street.

Contact: Ms Stephanie Egan

Enquiry No.: 963632

Logged by: [REDACTED]

on: 20/02/2020 15:00

Service: Accident Claims (All Services)

Subject: Accident Claim Roads/Lighting

Classification: Accident Claim

Desc.: Water filled barrier at West Register Street blew over a vehicle causing damage

Location: Outside BAlmoral Hotel

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Enquiry No.: 962203

Logged by: Verint CRM Connector

on: 18/02/2020 13:45

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.:

Location: Between bus stop PP & Waverley Mall - next to lamp post . V Dangerous loose slab
- imminent danger for all pedestrians , esp elderly

Contact:

Plot Number: 3.00

Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place

Feature Type: Road Asset

Job Number: 50052400

Defect Number: 42046635

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

| | | |
|--|--|--|
| Enquiry No.: 961529 | Logged by: Verint CRM Connector | on: 17/02/2020 12:45 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: Huge pothole on eastbound carriageway near to Apple shop. | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50051602 | Defect Number: 42046410 | |
| Enquiry No.: 960141 | Logged by: Verint CRM Connector | on: 14/02/2020 09:08 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: Road surface around a drain has broken up and exposed the drain cover | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Enquiry No.: 958724 | Logged by: Verint CRM Connector | on: 12/02/2020 08:51 |
| Service: Open Space Maintenance | Subject: Graffiti (non offensive) | Classification: Request for service |
| Desc.: Is the graffiti on Council or private property? council. Is the graffiti offensive/racist? No . | | |
| Location: Bus shelter opposite HSBC covered by graffiti | Contact: | |
| Enquiry No.: 958716 | Logged by: [REDACTED] | on: 12/02/2020 08:44 |
| Service: Winter Response | Subject: Gritting: Pavement / Footpath | Classification: Request for service |
| Desc.: @Edinburgh_CC do you not grit paths in centre of the city? Just slipped and fallen on Waverley Bridge and parts of Princes Stbad too. | | |
| Location: | Contact: | |
| Enquiry No.: 958383 | Logged by: Verint CRM Connector | on: 11/02/2020 16:13 |
| Service: Open Space Maintenance | Subject: Litter | Classification: Request for service |
| Desc.: Which problem you would like to report? Litter complaint. Does litter contain sharps? No | | |
| Location: On Princes Street between railings and bushes/greenery, empty bottles, plastics, cans as well as large roadwork cone in bushes. | Contact: | |
| Enquiry No.: 957970 | Logged by: Verint CRM Connector | on: 11/02/2020 08:05 |
| Service: Roads General | Subject: Road: Defective / Damaged | Classification: Request for service |
| Desc.: | | |
| Location: Hi @edinhelp Any chance this crater on Princes Street right outside the crosswalk at the Waverley Mall could be repaired before someone disappears down it or breaks a leg? ?? [REDACTED] | Contact: | |
| Plot Number: 3.00 | Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset |
| Job Number: 50051605 | Defect Number: 42045825 | |
| Enquiry No.: 957339 | Logged by: [REDACTED] | on: 10/02/2020 08:01 |
| Service: Open Space Maintenance | Subject: New Litter Bin Request | Classification: Request for service |
| Desc.: @Edinburgh_CC This on one of our beautiful city's main thoroughfares, Princes Street, near the bus stop opposite SportsDirect. Can't be picked up by a public-spirited passer-by (me, for example) and disposed of immediately because the bins near bus stops have been removed. Why? | | |
| Location: | Contact: | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 955608 **Logged by:** Verint CRM Connector **on:** 05/02/2020 16:11
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:

Location: Morrison Utility services recently repaired a electrical cable beneath the pavement and then instead of replacing the paving slabs used a cheaper method of tarmac. The result is unsightly and only too common place. We are a business at 40 Princes Street. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 954796 **Logged by:** Verint CRM Connector **on:** 04/02/2020 13:17
Service: Open Space Maintenance **Subject:** Graffiti (offensive/racist) **Classification:** Request for service
Desc.: Is the graffiti on Council or private property? council.
Is the graffiti offensive/racist? Yes .

Location: sorry for the swearing, but this is inside the playpark in Princess Street Gardens, any chance it could be covered up? **Contact:**

Enquiry No.: 954356 **Logged by:** Verint CRM Connector **on:** 03/02/2020 16:13
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Broken cracked and loose paving slabs **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50051032 **Defect Number:** 42045373

Enquiry No.: 953548 **Logged by:** Verint CRM Connector **on:** 02/02/2020 13:33
Service: Open Space Maintenance **Subject:** Litter **Classification:** Request for service
Desc.: Which problem you would like to report? Litter complaint.
Does litter contain sharps? No

Location: Princes Street Gardens. Walking along the Gardens railings, from Lothian Road to the Mound, all I could see was rubbish littered just inside the fencing. What a mess! Please have this cleared up. It is an eyesore for locals and tourists. **Contact:**

Enquiry No.: 952816 **Logged by:** Verint CRM Connector **on:** 31/01/2020 11:45
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: a cracked slab **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50051150 **Defect Number:** 42045388

Enquiry No.: 952761 **Logged by:** Verint CRM Connector **on:** 31/01/2020 11:03
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:

Location: Paving blocks badly cracked and parts missing. Deep chunks missing from paving blocks. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Effective: 01/01/2020 to 31/03/2022

Display Action Officer: No

Asset Number: 1.00 to 3.00

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 949235 **Logged by:** Verint CRM Connector **on:** 24/01/2020 16:44
Service: Open Space Maintenance **Subject:** Dumping and Fly Tipping **Classification:** Request for service
Desc.: Where has the flytipping occurred: On the street, park or beach.
 What rubbish has been dumped: Household Waste.
 How much rubbish has been dumped: cardboard and plastic
Location: At bus stop PE outside Zara on Princes S **Contact:**

Enquiry No.: 948905 **Logged by:** Verint CRM Connector **on:** 24/01/2020 11:14
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: I was walking along princes street and its a hazard as there are lots of paving slabs either broken or that are loose and move when you stand on them. The worst bit is at Waterstones.
 It also looks awful!

Plot Number: 1.00 **Feature Id - Location:** Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Enquiry No.: 948669 **Logged by:** Verint CRM Connector **on:** 24/01/2020 09:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The entire bus lane and road from The Balmoral to the Princes Mall bus stops is littered with potholes, some wide and deep. These are dangerous for cyclists in particular both if they hit one, or weave to avoid one. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** 11110 - Ward 11 - From Waterloo Place to Shandwick Place **Feature Type:** Road Asset

Job Number: 50050389**Defect Number:** 42044765

Enquiry No.: 948422 **Logged by:** [REDACTED] **on:** 23/01/2020 19:23
Service: Open Space Maintenance **Subject:** New Litter Bin Request **Classification:** Request for service
Desc.: @edinhelp Hi. I was just looking for a bin on Princes Street but couldn't find one. Had to go up Frederick Street. Why have they all gone from Princes Street?
Location: I couldn't find any on either side of Princes Street between Castle St and Hanover St. I just wanted to dispose of a banana skin before getting on a bus. **Contact:**

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Customer Services

Enquiry No.: 947935 Logged by: [REDACTED] on: 23/01/2020 09:18

Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim

Desc.: Hi,

[REDACTED] an accident I had on Friday 13 December at 18:35. I tripped on a broken paving stone on Princes Street [REDACTED].
 [REDACTED] I have reported the faulty paving stone to the council. [REDACTED] attach a photo of the broken paving stone. [REDACTED]
 [REDACTED] Can you please send me the appropriate documentation to make a claim.

Location: Princess Street

Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 945898 Logged by: Verint CRM Connector on: 20/01/2020 13:16

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: paving slab is uneven and broken into 4 lady tripped on this

Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 944492 Logged by: Verint CRM Connector on: 17/01/2020 13:10

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: at the bus stop outside Costa Coffee where the 25 bus stops

Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 942099 Logged by: Verint CRM Connector on: 14/01/2020 13:41

Service: Accident Claims (All Services) Subject: Accident Claim Roads/Lighting Classification: Accident Claim

Desc.:

Location: I telephoned two weeks ago and was advised to email. I fell over broken pavement approx 10 yards from first bus stop on Princes Street. [REDACTED]
 [REDACTED] have been unable to email until now. I was advised to request a complaint and claim form.

Contact:

Plot Number: 3.00 Feature Id - Location: 11110 - Ward 11 - From Waterloo Place to Shandwick Place Feature Type: Road Asset

Enquiry No.: 941808 Logged by: [REDACTED] on: 14/01/2020 08:11

Service: Roads General Subject: Street Furniture: General Enq Classification: General Enquiry

Desc.: please remove barrier from beside the apple shop

Location: princes st - apple shop

Contact:

Enquiry No.: 939269 Logged by: Verint CRM Connector on: 09/01/2020 18:11

Service: Open Space Maintenance Subject: Litter Classification: Request for service

Desc.: Which problem you would like to report? Litter complaint.
 Does litter contain sharps? No


Location: Lots of litter at bus stop outside Apple store

Contact:

Effective: 01/01/2020 to 31/03/2022
 Display Action Officer: No

Asset Number: 1.00 to 3.00
 Site: Princes Street (7903151)

Customer Services



Enquiry No.: 935745 **Logged by:** Verint CRM Connector **on:** 03/01/2020 20:41
Service: Open Space Maintenance **Subject:** Litter **Classification:** Request for service
Desc.: Which problem you would like to report? Litter complaint.
 Does litter contain sharps? No
Location: Princes Street, end to end. **Contact:**

Enquiry No.: 934879 **Logged by:** [REDACTED] **on:** 01/01/2020 22:51
Service: Open Space Maintenance **Subject:** Broken Glass **Classification:** Request for service
Desc.: Police Scotlad ([REDACTED]) called to report large window @ Boots the chemist on 101 Princes Street has been smashed and is all over the pavement should have been passed to
 Cleansing but n
Location: **Contact:**

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|---------|--|--|--------------------|---------------------------------|------------|----------------------------------|-------------|
| | Asset: 1.00 | Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: City Centre & Leith | |
| 1008634 | Gully frame and brander sunken and damaging surrounding area needs removed and side entry gully installed (Gully: Brander Missing) | Opposite the body shop | RD: Cat 3 - 60 Day | Job Raised | 09/03/2017 | 06/04/2017 | Est. |
| 1009693 | Flooding on footway please clear footway gully and channel (Gully: Blocked / Flooding) | Outside Chisholm and Hunter | RD: Cat 3 - 60 Day | Job Raised | 09/06/2017 | 07/07/2017 | Est. |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|---|--------------------------------|---------------------------------|------------|----------------------------------|----------------------|
| | Asset: 1.00 | Asset - Locn.: Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: City Centre & Leith | |
| 10265962 | Pavement: Damaged / Defective (Enquiry 928289) | The pavement in this area is cracked and due to the split in it, it has become dislodged from the ground when stepped on. | PRIORITY: C H A N G E M E | No code allocated | 20/12/2019 | | |
| 42421244 | Light: Light out (6+ Consec.) (Enquiry 746103) | | SL: 12 Hour Priority Repair | Job Cancelled | 14/11/2018 | 13/11/2018 | Est. |
| | Asset: 2.00 | Asset - Locn.: Ward 11 - From The Mound to Hanover Street | | Feature Type: Road Asset | | Area: South East Locality | |
| 50060410 | Gully: Flooding - What is the problem with the gully : flooding. What surface is the gully on : road. Are cars avoiding the flood : Unknown. Is flood affecting a property : Unknown (Enquiry 1020881) | | RG: Gully - High Priority | Job Complete | 17/08/2020 | 31/08/2020 | Act. RDGC14/82001127 |
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 1001459 | various rocking flags in paticularly at behind bus stops (RD: CLARENCE Response) | from the end of balmoral hotel heading west towards waverley bridge on princes st | RD: Cat 2 - 5 Day | Job Cancelled | 13/01/2015 | 26/02/2015 | Est. RD01/10000683 |
| 1002192 | Need resurfacing (RD: Capital Assessment Requird) | North br leith st junction | Non Routine (One Off Works) | Job Cancelled | 13/03/2015 | | |
| 1002911 | PARENT job. Hard Landscaping in the City Centre and Leith (Princes Street) | | Non Routine (One Off Works) | Job Raised | 22/05/2015 | | |
| 1003172 | | | Non Routine (One Off Works) | Job Raised | 24/06/2015 | | |
| 1003325 | Lift and relay 2 flags | | OSM 10 day Response | Job Raised | 08/07/2015 | 18/07/2015 | Est. |
| 1003373 | Lift and reset broken aqua drain (RG: Polychannel Damaged) | Outside H&M the manhole has sunk in and she has fallen over this. Called through to | RD: Cat 2 - 5 Day | Job Cancelled | 16/07/2015 | 23/07/2015 | Est. |
| 1003440 | 6 rocking caithness flags (RD: Paving Slabs) | Entrance to gardens at mound precinct | RD: Cat 2 - 5 Day | Job Cancelled | 21/07/2015 | 28/07/2015 | Est. |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|---------|--|--|-----------------------------|---------------------------------|------------|----------------------------------|----------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 1003545 | Renew footway. Approx 20m2 of missing slabs. Infilled with tar. (RD: Paving Slabs) | Outside House of Fraser | RD: Cat 4 - 12 Months | Job Cancelled | 24/07/2015 | 24/07/2016 | Est. |
| 1003546 | 3no damaged Caithness (RD: Paving Slabs) | Outside St Johns Church. At corner of Lothian Rd | RD: Cat 2 - 5 Day | Job Cancelled | 24/07/2015 | 31/07/2015 | Est. |
| 1003547 | 3no rocking Caithness (RD: Paving Slabs) | Outside St Johns Church. Opposite Tesco | RD: Cat 2 - 5 Day | Job Cancelled | 24/07/2015 | 31/07/2015 | Est. |
| 1003548 | 4no rocking slab grey pcc (RD: Paving Slabs) | Opposite McDonald's | RD: Cat 2 - 5 Day | Job Cancelled | 24/07/2015 | 31/07/2015 | Est. |
| 1003549 | 1no rocking slab grey pcc (RD: Paving Slabs) | Opposite O2 at South Charlotte Street | RD: Cat 2 - 5 Day | Job Cancelled | 24/07/2015 | 31/07/2015 | Est. |
| 1003916 | Fill up and level of grano area at junction with st Andrew square on rt hand side footway (RD: Grano / Concrete) | opposite the street sign the pavement has been repaired with concrete and the levels vary by over an inch and has caused me to trip causing injury. Junction with st Andrew square | Non Routine (One Off Works) | Job Cancelled | 13/08/2015 | | |
| 1005666 | Lift and relay rocking flag 600 x300 pcc at manhole at tesco express west end (RD: Paving Slabs) | on the pavement o/s tesco express the paving slabs and manhole cover wobble and moving and her mum fell hurt herself called over city road team | RD: Cat 2 - 5 Day | Job Cancelled | 22/02/2016 | 29/02/2016 | Est. |
| 1006336 | Broken slab (RD: Paving Slabs) | Opp ernest jones | RD: Cat 2 - 5 Day | Job Cancelled | 10/05/2016 | 17/05/2016 | Est. |
| 1006381 | 3 loose slabs and 6 loose part slabs (RD: Paving Slabs) | Opp pc world at and behind bus shelter | Non Routine (One Off Works) | Job Cancelled | 12/05/2016 | | |
| 1006384 | 4 loose slabs 1 loose part aoab pcc grey (RD: Paving Slabs) | Mountain warehouse | RD: Cat 3 - 60 Day | Job Cancelled | 12/05/2016 | 09/06/2016 | Est. |
| 1006386 | 1 loose slab 1 loose part slab 600x900 (RD: Paving Slabs) | Opp O2 | RD: Cat 3 - 60 Day | Job Cancelled | 12/05/2016 | 09/06/2016 | Est. |
| 1006418 | Lift and relay rocking slabs | Wellington statue heading towards st james centre | Non Routine (One Off Works) | Job Raised | 19/05/2016 | | |
| 1006610 | | | Non Routine (One Off Works) | Job Raised | 24/06/2016 | | RD01/10003006 |
| 1006636 | relay 4 perfecta flags | Outside H&M | Non Routine (One Off Works) | Job Raised | 28/06/2016 | | RD01/10003022 |
| 1006889 | Pavement: Damaged / Defective (Enquiry 390453) Relay rocking slab outside top man (RD: Paving Slabs) | Outside top man relay rocking perfect slab | RD: Cat 2 - 5 Day | Job Cancelled | 27/08/2016 | 05/09/2016 | Est. |
| 1006896 | Relay 2 rocking perfect flags (RD: Paving Slabs) | Outside old waverely hotel | RD: Cat 2 - 5 Day | Job Cancelled | 28/08/2016 | 05/09/2016 | Est. |
| 1006923 | Lift and relay 1 rocking perfeta (RD: Paving Slabs) | Outside accessorize at old waverely hotel | RD: Cat 2 - 5 Day | Job Cancelled | 31/08/2016 | 07/09/2016 | Est. |
| 1006959 | Pavement: Damaged / Defective (Enquiry 400596)lift and relay 4 broken perfect slabs and 4 rockers (RD: Paving Slabs) | Outside all saints | RD: Cat 2 - 5 Day | Job Cancelled | 02/09/2016 | 09/09/2016 | Est. RSTO16/10000024 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|---------------------------------|---------------|------------|----------------------------------|-----------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: Road Asset | | | Area: South East Locality | |
| 1007072 | Broken large York stone slabs (RD: Paving Slabs) | Just before crossing at mound | RD: Cat 2 - 5 Day | Job Cancelled | 07/09/2016 | 13/09/2016 Est. | RSTO16/10000024 |
| 1007088 | Lift and relay low trip hazard slab (RD: Paving Slabs) | Outside sisal bite cafe | RD: Cat 2 - 5 Day | Job Cancelled | 07/09/2016 | 14/09/2016 Est. | RSTO16/10000024 |
| 1007096 | 20 broken perfect slabs (RD: Paving Slabs) | Outside star bucks and currys | RD: Cat 2 - 5 Day | Job Cancelled | 07/09/2016 | 14/09/2016 Est. | RSTO16/10000024 |
| 1007140 | PARENT - princes street | | RD: Work Schedule (Parent) | Job Cancelled | 15/09/2016 | | RSTO16/10000024 |
| 1007547 | Lift rocking pcc flag | Outside boots the chemist | RD: Cat 1 - 24 Hours | Job Raised | 10/11/2016 | 11/11/2016 Est. | RD01/10003373 |
| 1008308 | 1no broken 900 x600 pcc grey flag (RD: Paving Slabs) | Opposite Levis | RD: Cat 2 - 5 Day | Job Complete | 10/02/2017 | 21/01/3201 Act. | RD01/10003723 |
| 1009064 | 1no rocking 900 x600 pcc grey flag 1no rocking cut pcc grey flag (RD: Paving Slabs) | Opposite Holland and Barret | RD: Cat 1 - 24 Hours | Job Cancelled | 10/04/2017 | 11/04/2017 Est. | RD01/10004107 |
| 1009065 | 1no broken 900 x600 pcc grey flag (RD: Paving Slabs) | Opposite EE just east of bus stop PQ | RD: Cat 1 - 24 Hours | Job Cancelled | 10/04/2017 | 11/04/2017 Est. | RD01/10004108 |
| 1009666 | 2no rocking grey pcc 600x900 (RD: Paving Slabs) | Opposite Currys PC World | RD: Cat 3 - 60 Day | Job Raised | 06/06/2017 | 30/06/2017 Est. | |
| 1011195 | Re-line where recent patching works took place (RD: Road Marking & Studs) | Junction of Waterloo place and princes street | RD: Cat 4 - 12 Months | Job Cancelled | 11/12/2017 | 11/12/2018 Est. | |
| 1011202 | 1no rocking cut tactile flag (RD: Paving Slabs) | At pedestrian crossing outside Frasers | RD: Cat 4 - 12 Months | Job Cancelled | 12/12/2017 | 12/12/2018 Est. | |
| 1011203 | 1no dislodged kerb needs reset and repointed (RD: Kerbs) | At South Charlotte Street west side | RD: Cat 3 - 60 Day | Job Cancelled | 12/12/2017 | 09/01/2018 Est. | |
| 1011204 | 8no rocking perfecta flags (RD: Paving Slabs) | Outside Three | RD: Cat 3 - 60 Day | Job Cancelled | 12/12/2017 | 09/01/2018 Est. | |
| 7800001 | | | Non Routine (One Off Works) | Job Raised | 02/04/2015 | | |
| 10074401 | Polychannel: Blocked/Flooding (Enquiry 342679) | Princes street | Non Routine (One Off Works) | Job Raised | 12/04/2016 | | |
| 42702509 | Polychannel: Blocked/Flooding - Polychannel is blocked and floods when it is raining (Enquiry 365937) | outside Holland and Barret | Non Routine (One Off Works) | Job Raised | 15/06/2016 | | |
| 42707527 | At corner or princess street (Gully: Blocked - HP Jet Req'd) | Turning from south David to princess street | RG: Gully - Standard Priority | Job Complete | 23/02/2022 | 23/02/2022 Act. | RDGC14/10006506 |
| 42707528 | Blocked needs cleaned and jetted (Gully: Blocked - HP Jet Req'd) | Corner of south at Andrews street and princess street | RG: Gully - Standard Priority | Job Complete | 23/02/2022 | 08/03/2022 Act. | RDGC14/10006507 |
| 50000263 | 3no cracked 900 x600 pcc grey flags 1no cracked cut 600 x600 pcc grey flag (RD: FW Slabs Broken/Missing) | Outside no140 | RD: Cat 4 - 12 Months | Job Cancelled | 20/12/2017 | 20/12/2018 Est. | |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-----------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50000264 | 1no rocking cut pcc grey flag at kerb (RD: FW Slabs Rocking) | Outside no139 | RD: Cat 4 - 12 Months | Job Cancelled | 20/12/2017 | 20/12/2018 | Est. |
| 50000266 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside carphone warehouse | RD: Cat 4 - 12 Months | Job Cancelled | 20/12/2017 | 20/12/2018 | Est. |
| 50000273 | 4no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Sports Direct | RD: Cat 4 - 12 Months | Job Cancelled | 20/12/2017 | 20/12/2018 | Est. |
| 50000297 | 8no rocking perfecta flags (RD: FW Slabs Rocking) | At Castle Street between HSBC and Vodafone | RD: Cat 4 - 12 Months | Job Cancelled | 20/12/2017 | 20/12/2018 | Est. |
| 50000299 | Asphalt surface needs reinstatement Approx 1mx1m (RD: CW Pothole) | Outside Debenhams on inside eastbound lane | RD: Cat 4 - 12 Months | Job Cancelled | 20/12/2017 | 20/12/2018 | Est. |
| 50000302 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Next | RD: Cat 4 - 12 Months | Job Cancelled | 20/12/2017 | 20/12/2018 | Est. |
| 50000354 | 1no rocking perfecta flag 2no rocking cut perfecta flag 1no rocking cross cut perfecta flag 2no rocking tactile flags 2no rocking cut tactile flags at box 1no broken cut charcoal tactile at kerb (RD: FW Slabs Rocking) | At Frederick Street on the east side | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000360 | 1no rocking cut perfecta flag 1no sunken perfecta flag 1no sunken cut perfecta flag (RD: FW Slabs Rocking) | Outside Ernest Jones | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000361 | 1no rocking cut perfecta flag 1no rocking perfecta flag (RD: FW Slabs Rocking) | At Hanover Street east side | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000362 | 8m missing aco channel (RD: FW Channel Damaged) | Outside Fraser Hart | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000367 | 1no rocking cut perfecta flag 1no sunken perfecta flag (RD: FW Slabs Rocking) | Outside Marks and Spencer | RD: Cat 3 - 60 Day | Job Cancelled | 21/12/2017 | 18/01/2018 | Est. ROAD/82000247 |
| 50000370 | 1no broken perfecta flag 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Jenners door no52-50 | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000375 | 1no rocking cut perfecta flag at channel (RD: FW Slabs Rocking) | Outside the Edinburgh Gift Shop | RD: Cat 3 - 60 Day | Job Cancelled | 21/12/2017 | 18/01/2018 | Est. ROAD/82000254 |
| 50000376 | 1no rocking perfecta flag 1no rocking cut perfecta flag (RD: FW Slabs Rocking) | Outside Smiggle | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000379 | 1no rocking perfecta flag 1no rocking cut perfecta flag at crossing (RD: FW Slabs Rocking) | Outside Topshop | RD: Cat 3 - 60 Day | Job Cancelled | 21/12/2017 | 18/01/2018 | Est. ROAD/82000257 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|-----------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50000380 | 1no rocking tactile flag (RD: FW Slabs Rocking) | Outside Vodafone | RD: Cat 3 - 60 Day | Job Cancelled | 21/12/2017 | 18/01/2018 | Est. ROAD/82000258 |
| 50000382 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Holland and Barrett | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000383 | Recurring pothole needs permanent asphalt reinstatement approx 2mx1m (RD: CW Pothole) | Eastbound lane outside Holland and Barrett near centre line | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000385 | 2no asphalt patches required approx 3mx2m and 3mx1m (RD: CW Pothole) | At West Register Street eastbound inside lane | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000386 | Recurring pothole needs permanent asphalt reinstatement approx 2mx1m (RD: CW Pothole) | Eastbound outside lane at West Register Street | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000388 | Recurring pothole needs permanent asphalt reinstatement approx 3mx2m (RD: CW Pothole) | On the pedestrian crossing at Wellington statue inside lane | RD: Cat 4 - 12 Months | Job Cancelled | 21/12/2017 | 21/12/2018 | Est. |
| 50000420 | Depression and cracking along footpath approx 15mx0.5m (RD: FW Depression/Sunken) | West Princes Street Gardens near fountain | RD: Cat 2 - 5 Day | Job Cancelled | 21/12/2017 | 03/01/2018 | Est. ROAD/82000280 |
| 50000537 | Broken and potholed asphalt surface approx 4mx1.5m (RD: CW Cracked/Broken) | Westbound lane outside Balmoral hotel at traffic lights | RD: Cat 4 - 12 Months | Job Cancelled | 28/12/2017 | 28/12/2018 | Est. |
| 50000538 | 2no Broken and potholed asphalt surface require patching approx 3mx1.5m and 3mx2m (RD: CW Cracked/Broken) | Outside the entrance to the Balmoral hotel | RD: Cat 4 - 12 Months | Job Cancelled | 28/12/2017 | 28/12/2018 | Est. |
| 50000539 | 1no rocking 750 x600 courtstone flag (RD: FW Slabs Rocking) | Between number one and waverley steps | RD: Cat 3 - 60 Day | Job Cancelled | 28/12/2017 | 25/01/2018 | Est. ROAD/82000384 |
| 50000547 | 13no broken 900 x600 pcc grey flags 3no broken 600 x450 pcc grey flags (RD: FW Slabs Rocking) | Outside waverley mall opposite south st andrew st | RD: Cat 4 - 12 Months | Job Cancelled | 28/12/2017 | 28/12/2018 | Est. |
| 50000558 | 1no rocking 900 x600 pcc grey flag (RD: FW Slabs Rocking) | Opposite Marks and Spencer | RD: Cat 4 - 12 Months | Job Cancelled | 28/12/2017 | 28/12/2018 | Est. |
| 50000564 | Broken and potholed asphalt surface at gully surround approx 1mx1m (RD: CW Cracked/Broken) | At pedestrian crossing opposite the body shop | RD: Cat 4 - 12 Months | Job Cancelled | 28/12/2017 | 28/12/2018 | Est. |
| 50000568 | 1no rocking 900 x600 pcc grey flag (RD: FW Slabs Rocking) | At bus stop PV opposite Debenhams | RD: Cat 4 - 12 Months | Job Cancelled | 28/12/2017 | 28/12/2018 | Est. |
| 50000569 | 4no rocking 900 x600 pcc grey flags 1no rocking 450 x600 pcc grey flag (RD: FW Slabs Rocking) | Opposite Debenhams just west of bus stop PV | RD: Cat 4 - 12 Months | Job Cancelled | 28/12/2017 | 28/12/2018 | Est. |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-----------------------------|---------------------------------|------------|----------------------------------|----------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50000572 | 2no rocking 900 x600 pcc grey flags (RD: FW Slabs Rocking) | Behind bus stop PZ opposite vans | RD: Cat 3 - 60 Day | Job Cancelled | 28/12/2017 | 25/01/2018 | Est. ROAD/82000411 |
| 50005757 | 1no pothole (RD: CW Pothole) | Eastbound outside lane at West Register Street | RD: Cat 2 - 5 Day | Job Cancelled | 27/03/2018 | 03/04/2018 | Est. ROAD/82004634 |
| 50008313 | 1no broken perfecta flag 2no rocking perfecta flags Missing grano at catv box (RD: FW Slabs Broken/Missing) | At castle street | RD: Cat 2 - 5 Day | Job Cancelled | 01/05/2018 | 08/05/2018 | Est. ROAD/82006903 |
| 50008318 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Boots | RD: Cat 2 - 5 Day | Job Cancelled | 01/05/2018 | 08/05/2018 | Est. ROAD/82006907 |
| 50008320 | 1no broken perfecta flag (RD: FW Slabs Broken/Missing) | At bus stop PF outside boots | RD: Cat 2 - 5 Day | Job Cancelled | 01/05/2018 | 08/05/2018 | Est. ROAD/82006909 |
| 50008323 | 1no broken tactile flag (RD: FW Slabs Broken/Missing) | Outside Chisholm Hunter | RD: Cat 2 - 5 Day | Job Cancelled | 01/05/2018 | 08/05/2018 | Est. ROAD/82006912 |
| 50008329 | 3no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Clarks | RD: Cat 2 - 5 Day | Job Cancelled | 01/05/2018 | 08/05/2018 | Est. ROAD/82006918 |
| 50008330 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Office | RD: Cat 2 - 5 Day | Job Cancelled | 01/05/2018 | 08/05/2018 | Est. ROAD/82006919 |
| 50008337 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Marks and Spencer's | RD: Cat 2 - 5 Day | Job Cancelled | 01/05/2018 | 08/05/2018 | Est. ROAD/82006926 |
| 50017580 | Carriageway and footway subsidence needs reinstatement approx 8mx8m Update 17.10.2018 - This is Scottish Water responsibility. Investigations into the issue are still ongoing. (RD: CW Subsidence/Heaving) | Opposite British Home Stores | RD: Cat 4 - 12 Months | Job Cancelled | 17/10/2018 | 17/10/2019 | Est. |
| 50017835 | Please refresh all bus stop markings (RD: Markings Refresh) | Full length | RD: Cat 4 - 12 Months | Job Annulled | 23/10/2018 | 23/10/2019 | Est. ROAD/82013772 |
| 50037722 | Polychannel: Blocked/Flooding - Polychannel blocked creating flooding (Enquiry 34001360) | Outside 98-99 Cath Kidston | Non Routine (One Off Works) | Job Complete | 11/07/2019 | 15/01/2020 | Act. RDGC14/82000347 |
| 50037723 | Polychannel: Blocked/Flooding - Polychannel blocked causing flooding (Enquiry 34001361) | Outside boots | Non Routine (One Off Works) | Job Complete | 11/07/2019 | 15/01/2020 | Act. RDGC14/82000348 |
| 50049332 | 2no broken perfecta flags (RD: FW Slabs Broken/Missing) | Outside nn30-31 | RD: Cat 2 - 5 Day | Job Complete | 13/01/2020 | 15/01/2020 | Act. ROAD/82030438 |
| 50049333 | 1no broken perfecta flag 3no sunken cut perfecta flags (RD: FW Slabs Broken/Missing) | Between H+M and Topshop | RD: Cat 3 - 60 Day | Job Complete | 13/01/2020 | 15/01/2020 | Act. ROAD/82030439 |
| 50049334 | Gully: Blocked / Needs Clean - Blocked gully needs cleaned (Enquiry 34001799) | At the Wellington statue | RG: Gully - High Priority | Job Complete | 13/01/2020 | 24/01/2020 | Act. RDGC14/82000624 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|--------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50049954 | 1no rocking 900x600 pcc flag (RD: FW Slabs Rocking) | Outside Tesco Express | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 23/01/2020 | Act. ROAD/82030938 |
| 50049955 | 1no rocking cut pcc flag (RD: FW Slabs Rocking) | At the pedestrian crossing outside Pret A Manger | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 23/01/2020 | Act. ROAD/82030939 |
| 50049956 | 3no rocking perfecta flags (RD: FW Slabs Rocking) | Just west of USC | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 21/01/2020 | Act. ROAD/82030940 |
| 50049957 | 1no rocking cut perfecta flag (RD: FW Slabs Rocking) | At bus stop PB outside New Look | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 21/01/2020 | Act. ROAD/82030941 |
| 50049958 | 1no rocking cut perfecta flag (RD: FW Slabs Rocking) | Outside HSBC | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 21/01/2020 | Act. ROAD/82030942 |
| 50049959 | 2no broken perfecta flags 2no rocking perfecta flags (RD: FW Slabs Broken/Missing) | Outside River Island | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 21/01/2020 | Act. ROAD/82030943 |
| 50049960 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Levi's | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 21/01/2020 | Act. ROAD/82030944 |
| 50049961 | 1no rocking cut perfecta flag 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Boots at west entrance | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 21/01/2020 | Act. ROAD/82030945 |
| 50049962 | 1no broken perfecta flag 1no broken cut perfecta flag (RD: FW Slabs Broken/Missing) | Outside Boots | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030946 |
| 50049963 | 1no rocking cut perfecta flag 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Chisholm Hunter | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030947 |
| 50049964 | 1no broken perfecta flag (RD: FW Slabs Broken/Missing) | Outside Primark | RD: Cat 3 - 60 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030948 |
| 50049971 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Great Scot | RD: Cat 2 - 5 Day | Enquiry Closed Cat 4 | 21/01/2020 | 22/01/2020 | Act. ROAD/82030955 |
| 50049974 | 1no rocking cut perfecta flag 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Marks and Spencer's no60 | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030958 |
| 50049975 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | At bus stop PK outside the Mercure Hotel | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030959 |
| 50049976 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Jenners no50-52 | RD: Cat 3 - 60 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030960 |
| 50049978 | 2no rocking cut tactile flags 1no rocking tactile flag (RD: FW Slabs Rocking) | At the pedestrian crossing at South St David Street outside Jenners | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030962 |
| 50049979 | 1no rocking cut perfecta flag (RD: FW Slabs Rocking) | Outside Topshop no30-31 | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 23/01/2020 | Act. ROAD/82030963 |
| 50049981 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Whittard | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030964 |
| 50049984 | 6no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Holland and Barrett | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030966 |
| 50049986 | 1no rocking cut perfecta flag (RD: FW Slabs Rocking) | Outside Foot Locker | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030967 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|----------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50049988 | 1no rocking 900x600 pcc flag (RD: FW Slabs Rocking) | At bus stop PP outside Waverley mall | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030969 |
| 50049990 | 1no pothole (RD: CW Pothole) | At the pedestrian crossing outside Waverley mall | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 24/01/2020 | Act. ROAD/82030971 |
| 50049991 | 1no broken 900x600 pccflag (RD: FW Slabs Broken/Missing) | Outside Costa Coffee at Waverley mall | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030972 |
| 50049992 | 1no rocking scoutmoor flag (RD: FW Slabs Rocking) | At the corner of Waverley Bridge opposite Topshop | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 23/01/2020 | Act. ROAD/82030973 |
| 50049996 | 1no rocking 750x600 pcc flag (RD: FW Slabs Rocking) | Opposite the Old Waverley | RD: Cat 3 - 60 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030975 |
| 50049998 | 1no rocking cut pcc flag (RD: FW Slabs Rocking) | At bus stop PR opposite Mercure Hotel | RD: Cat 3 - 60 Day | Job Complete | 21/01/2020 | 22/01/2020 | Act. ROAD/82030976 |
| 50050003 | 1no broken 900x600 pccflag 1no rocking 900x600 pcc flag (RD: FW Slabs Broken/Missing) | At bus stop PX opposite Vodafone | RD: Cat 2 - 5 Day | Job Complete | 21/01/2020 | 23/01/2020 | Act. ROAD/82030978 |
| 50050380 | 2no potholes (RD: CW Pothole) | Eastbound lane at West Register Street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 24/01/2020 | 31/01/2020 | Act. ROAD/82031277 |
| 50050389 | 1no pothole (RD: CW Pothole) | Westbound lane outside the Balmoral just west of the pedestrian crossing | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 24/01/2020 | 31/01/2020 | Act. ROAD/82031285 |
| 50050390 | 1no pothole at manhole (RD: CW Pothole) | Westbound lane outside the Balmoral Hotel entrance | RD: Cat 3 - 60 Day | Job Complete | 24/01/2020 | 31/01/2020 | Act. ROAD/82031286 |
| 50050906 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside no125 | RD: Cat 2 - 5 Day | Job Complete | 31/01/2020 | 04/02/2020 | Act. ROAD/82031685 |
| 50051032 | 1no broken 900x600 pcc flag (RD: FW Slabs Broken/Missing) | Outside Costa Coffee at Waverley mall | RD: Cat 3 - 60 Day | Job Complete | 03/02/2020 | 05/02/2020 | Act. ROAD/82031777 |
| 50051150 | 2no broken perfecta flags 1no rocking perfecta flag (RD: FW Slabs Broken/Missing) | Outside Poundland | RD: Cat 2 - 5 Day | Job Complete | 04/02/2020 | 05/02/2020 | Act. ROAD/82031882 |
| 50051262 | 1no pothole (RD: CW Pothole) | Eastbound lane at the junction of South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 05/02/2020 | 06/02/2020 | Act. ROAD/82031993 |
| 50051500 | 1no broken perfecta flag (RD: FW Slabs Broken/Missing) | Outside no108 | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 07/02/2020 | 14/02/2020 | Act. ROAD/82032235 |
| 50051501 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | At the bus stop outside River Island | RD: Cat 2 - 5 Day | Job Complete | 07/02/2020 | 14/02/2020 | Act. ROAD/82032236 |
| 50051602 | 3no po (RD: CW Pothole) | Just east of West Register Street | RD: Cat 2 - 5 Day | Job Complete | 11/02/2020 | 19/02/2020 | Act. ROAD/82032316 |
| 50051605 | 1no pothole (RD: CW Pothole) | On the pedestrian crossing outside Waverley mall | RD: Cat 1 - 24 Hours | RD: Made Safe Job Complete | 11/02/2020 | 11/02/2020 | Act. ROAD/82032318 |
| 50051607 | 1no pothole (RD: CW Pothole) | Westbound lane outside Waverley mall in between the 2 bus stops | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 11/02/2020 | 19/03/2020 | Act. ROAD/82032319 |
| 50051814 | 1no pothole at manhole (RD: CW Pothole) | Eastbound lane at the junction of Frederick Street | RD: Cat 2 - 5 Day | Job Complete | 13/02/2020 | 19/02/2020 | Act. ROAD/82032511 |
| 50052399 | 4no rocking cut flags 1no rocking 600x900 flag (RD: FW Slabs Rocking) | At bus stop PQ next to waverley mall | RD: Cat 3 - 60 Day | Job Complete | 19/02/2020 | 08/04/2020 | Act. ROAD/82033030 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|----------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50052400 | 1no rocking 750x600 pcc flag (RD: FW Slabs Rocking) | At bus stop PP outside Waverley Mall | RD: Cat 3 - 60 Day | Job Complete | 19/02/2020 | 13/03/2020 | Act. ROAD/82033031 |
| 50053616 | 1no small pothole on ped crossing (RD: CW Pothole) | Outside the 3 store on pedestrian crossing | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 28/02/2020 | 18/03/2020 | Act. ROAD/82034098 |
| 50053811 | 1no pothole (RD: CW Pothole) | Westbound lane on the pedestrian crossing at the Mound | RD: Cat 2 - 5 Day | Job Complete | 02/03/2020 | 19/03/2020 | Act. ROAD/82034286 |
| 50053913 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Fraser Hart | RD: Cat 2 - 5 Day | Job Complete | 03/03/2020 | 11/03/2020 | Act. ROAD/82034384 |
| 50053916 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside the O2 shop | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 16/03/2020 | Act. ROAD/82034386 |
| 50053918 | 2no rocking perfecta cut flags (RD: FW Slabs Rocking) | 64 princes st at building site hoarding | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 16/03/2020 | Act. ROAD/82034388 |
| 50053919 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Marks and Spencer | RD: Cat 1 - 24 Hours | Job Complete | 03/03/2020 | 03/03/2020 | Act. ROAD/82034389 |
| 50053920 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Marks and Spencer | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 16/03/2020 | Act. ROAD/82034390 |
| 50053921 | 2no rocking perfecta flags 1 broken 450x450 perfecta flag (RD: FW Slabs Rocking) | Outside 54-58 Marks and Spencer | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 16/03/2020 | Act. ROAD/82034391 |
| 50053922 | Renew sunken/cracked grano at box (RD: FW Grano Pothole) | Outside topshop | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 16/03/2020 | Act. ROAD/82034392 |
| 50053923 | 2no rocking tactile flags (RD: FW Slabs Rocking) | Opposite Waverley mall costa coffee at pedestrian crossing | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 17/03/2020 | Act. ROAD/82034393 |
| 50053925 | 1no broken 450x450 perfecta flag (RD: FW Slabs Rocking) | Outside Holland and Barrett | RD: Cat 2 - 5 Day | Job Complete | 03/03/2020 | 16/03/2020 | Act. ROAD/82034395 |
| 50053927 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Holland and Barrett | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 17/03/2020 | Act. ROAD/82034397 |
| 50053938 | 3no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Skechers | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 08/04/2020 | Act. ROAD/82034408 |
| 50053939 | 1no rocking cut perfecta flag (RD: FW Slabs Rocking) | Outside Office | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 08/04/2020 | Act. ROAD/82034409 |
| 50053940 | 5no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Superdrug | RD: Cat 2 - 5 Day | Job Complete | 03/03/2020 | 06/03/2020 | Act. ROAD/82034410 |
| 50053942 | 5no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Samsung | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 23/03/2020 | Act. ROAD/82034412 |
| 50053949 | 2no rocking perfecta flags 1no rocking tactile flag (RD: FW Slabs Rocking) | Outside Chisholm Hunter | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 17/03/2020 | Act. ROAD/82034419 |
| 50053952 | Renew sunken/cracked grano at box (RD: FW Grano Cracked/Broken) | Outside Thomas Sabo | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 17/03/2020 | Act. ROAD/82034422 |
| 50053956 | 1no broken cut perfecta flag 1 rocking perfecta flag (RD: FW Slabs Rocking) | Outside Boots | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 18/03/2020 | Act. ROAD/82034426 |
| 50053960 | 3no broken perfecta flags (RD: FW Slabs Broken/Missing) | Outside Next | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 18/03/2020 | Act. ROAD/82034430 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50053965 | 6no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Levis | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 17/03/2020 | Act. ROAD/82034435 |
| 50053970 | 3no broken perfecta flags 1no rocking perfecta flag (RD: FW Slabs Broken/Missing) | Outside one two five | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 18/03/2020 | Act. ROAD/82034440 |
| 50053973 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Vans | RD: Cat 2 - 5 Day | Job Complete | 03/03/2020 | 06/03/2020 | Act. ROAD/82034443 |
| 50053978 | 2no broken perfecta flags 4no rocking perfecta flag (RD: FW Slabs Broken/Missing) | Outside Halifax | RD: Cat 2 - 5 Day | Job Complete | 03/03/2020 | 06/03/2020 | Act. ROAD/82034448 |
| 50053986 | 1no rocking cut pcc flag (RD: FW Slabs Rocking) | Outside 136 | RD: Cat 3 - 60 Day | Job Complete | 03/03/2020 | 17/03/2020 | Act. ROAD/82034455 |
| 50054040 | 1no pothole (RD: CW Pothole) | On pedestrian crossing opposite jenners | RD: Cat 3 - 60 Day | Job Complete | 04/03/2020 | 19/03/2020 | Act. ROAD/82034504 |
| 50054150 | 2no potholes (RD: CW Pothole) | On pedestrian crossing opposite the balmoral hotel | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 05/03/2020 | 19/03/2020 | Act. ROAD/82034578 |
| 50054220 | Broken FH frame causing the lid to keep falling in (RU: Utility Apparatus) | Outside ISG site (old BHS store) | RU: Fail Med.Risk (Apparatus) | Job Complete | 05/03/2020 | 09/03/2020 | Act. |
| 50054380 | 1no pothole (RD: CW Pothole) | On the pedestrian crossing outside Three | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 09/03/2020 | 18/03/2020 | Act. ROAD/82034765 |
| 50054381 | 4no potholes (RD: CW Pothole) | Eastbound lane at the junction of Frederick Street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 09/03/2020 | 18/03/2020 | Act. ROAD/82034766 |
| 50054382 | 1no pothole (RD: CW Pothole) | On the pedestrian crossing at Wellington statue | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 09/03/2020 | 19/03/2020 | Act. ROAD/82034767 |
| 50054915 | 1n (RD: CW Pothole) | Outside Register House at Wellington Statue | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 17/03/2020 | 19/03/2020 | Act. ROAD/82035219 |
| 50055881 | 1no rocking Caithness flag 1no broken rocking Caithness flag (RD: FW Slabs Rocking) | At the Bam building site outside the old Fraser shop | RD: Cat 2 - 5 Day | Job Complete | 27/04/2020 | 01/05/2020 | Act. ROAD/82036011 |
| 50055885 | 3no broken perfecta flags (RD: FW Slabs Broken/Missing) | Outside Next | RD: Cat 2 - 5 Day | Job Complete | 27/04/2020 | 30/04/2020 | Act. ROAD/82036014 |
| 50055886 | 1no rocking Perfecta flag (RD: FW Slabs Rocking) | Outside Next | RD: Cat 2 - 5 Day | Job Complete | 27/04/2020 | 30/04/2020 | Act. ROAD/82036015 |
| 50055887 | 1no rocking Tactile flag (RD: FW Slabs Rocking) | Outside Chisholm Hunter | RD: Cat 2 - 5 Day | Job Complete | 27/04/2020 | 30/04/2020 | Act. ROAD/82036016 |
| 50055888 | 1no broken perfecta flag (RD: FW Slabs Broken/Missing) | Outside Gap | RD: Cat 2 - 5 Day | Job Complete | 27/04/2020 | 01/05/2020 | Act. ROAD/82036017 |
| 50055889 | 1no pothole (RD: CW Pothole) | At the junction of South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 27/04/2020 | 29/04/2020 | Act. ROAD/82036018 |
| 50055890 | 1no rocking Perfecta flag (RD: FW Slabs Rocking) | Outside the old Vodafone Shop opposite Waverley mall | RD: Cat 2 - 5 Day | Job Complete | 27/04/2020 | 01/05/2020 | Act. ROAD/82036019 |
| 50055895 | 1no broken cut 900x600 pcc flag Missing grano infill (RD: FW Slabs Broken/Missing) | Opposite Levi's | RD: Cat 2 - 5 Day | Job Complete | 27/04/2020 | 01/05/2020 | Act. ROAD/82036023 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|--------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50056520 | 2no potholes (RD: CW Pothole) | On the pedestrian crossing outside the Balmoral Hotel | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 15/06/2020 | 18/06/2020 | Act. ROAD/82036478 |
| 50056522 | 1no rocking 900x600 pcc flag (RD: FW Slabs Rocking) | Outside Waverley mall at bus stop PP | RD: Cat 2 - 5 Day | Job Complete | 15/06/2020 | 16/06/2020 | Act. ROAD/82036480 |
| 50056678 | 1no broken cut 900x600 pcc flag (RD: FW Slabs Broken/Missing) | Opposite Gap | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036591 |
| 50056679 | 1no rocking 900x600 pcc flag (RD: FW Slabs Rocking) | Opposite Chisholm H | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036592 |
| 50056680 | Sunken grano infill (RD: FW Grano Depression/Sunken) | Opposite South Charlotte Street | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036593 |
| 50056682 | 2no rocking tactile flags (RD: FW Slabs Rocking) | At the pedestrian crossing outside the old Fraser shop | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036594 |
| 50056683 | 3no sunken Caithness flags (RD: FW Slabs Rocking) | Outside the old Fraser shop under covered walkway | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 21/06/2020 | Act. ROAD/82036595 |
| 50056684 | 1no rocking cut 900x600 pcc flag (RD: FW Slabs Rocking) | Outside old Fraser shop near Royal Bank | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036596 |
| 50056686 | 1no broken perfecta flag 1no rocking perfecta flag (RD: FW Slabs Broken/Missing) | Outside no131 | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036597 |
| 50056687 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Vans | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036598 |
| 50056689 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | At Castle Street | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036599 |
| 50056691 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Zara | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036600 |
| 50056693 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Boots | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036601 |
| 50056694 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Cath Kidston | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036602 |
| 50056695 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Chisholm Hunter | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036603 |
| 50056696 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Kiko | RD: Cat 2 - 5 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036604 |
| 50056699 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Ernest Jones | RD: Cat 2 - 5 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036605 |
| 50056701 | 4no rocking perfecta flags Missing grano infill (RD: FW Slabs Rocking) | On corner of Hanover Street outside Fraser Hart | RD: Cat 3 - 60 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036606 |
| 50056702 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside O2 | RD: Cat 2 - 5 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036607 |
| 50056703 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Monsoon | RD: Cat 2 - 5 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036608 |
| 50056704 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Between Smiggle and H+M | RD: Cat 2 - 5 Day | Job Complete | 17/06/2020 | 18/06/2020 | Act. ROAD/82036609 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|--------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50057442 | Cracked and broken asphalt surface approx 3mx2m (RD: CW Cracked/Broken) | Westbound lane at pedestrian crossing outside Costa | RD: Cat 3 - 60 Day | Job Complete | 30/06/2020 | 01/07/2020 | Act. ROAD/82037072 |
| 50057443 | Cracked and broken asphalt surface approx 3mx1m (RD: CW Cracked/Broken) | Westbound lane at bus stop PQ | RD: Cat 3 - 60 Day | Job Complete | 30/06/2020 | 01/07/2020 | Act. ROAD/82037073 |
| 50057445 | Cracked and broken asphalt surface approx 1.5mx1.5m (RD: CW Cracked/Broken) | In the centre of the carriageway opposite Holland and Barrett | RD: Cat 3 - 60 Day | Job Complete | 30/06/2020 | 01/07/2020 | Act. ROAD/82037074 |
| 50058932 | 2no broken scoutmoor flags 1no rocking scoutmoor flag (RD: FW Slabs Broken/Missing) | Opposite the Old Waverley Hotel | RD: Cat 3 - 60 Day | Job Complete | 21/07/2020 | 28/08/2020 | Act. ROAD/82038030 |
| 50058934 | 1no broken cut 450x600 pcc flag (RD: FW Slabs Broken/Missing) | At the Scott monument | RD: Cat 3 - 60 Day | Job Complete | 21/07/2020 | 22/07/2020 | Act. ROAD/82038032 |
| 50058936 | 1no rocking 450x600 pcc flag (RD: FW Slabs Rocking) | Opposite Marks and Spencer's | RD: Cat 3 - 60 Day | Job Complete | 21/07/2020 | 22/07/2020 | Act. ROAD/82038034 |
| 50058939 | 1no broken 900x600 pcc flag (RD: FW Slabs Broken/Missing) | Opposite Swarovski | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/07/2020 | 23/07/2020 | Act. ROAD/82038036 |
| 50058940 | 2no rocking cut pcc flags (RD: FW Slabs Rocking) | Opposite Boots | RD: Cat 3 - 60 Day | Job Complete | 21/07/2020 | 22/07/2020 | Act. ROAD/82038037 |
| 50058941 | 3no rocking 900x600 pcc flags (RD: FW Slabs Rocking) | Opposite Castle Street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/07/2020 | 22/07/2020 | Act. ROAD/82038038 |
| 50058942 | 2no rocking tactile flags (RD: FW Slabs Rocking) | On the pedestrian crossing opposite Castle Street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/07/2020 | 24/07/2020 | Act. ROAD/82038039 |
| 50058943 | 1no rocking 900x600 pcc flag 1no rocking cut pcc flag (RD: FW Slabs Rocking) | Opposite Halifax Bank | RD: Cat 3 - 60 Day | Job Complete | 21/07/2020 | 22/07/2020 | Act. ROAD/82038040 |
| 50058944 | Broken grano infill (RD: FW Grano Depression/Sunken) | Outside the Royal Bank of Scotland | RD: Cat 2 - 5 Day | Job Complete | 21/07/2020 | 22/07/2020 | Act. ROAD/82038041 |
| 50058945 | 1no rocking 900x600 pcc flag 2no rocking cut pcc flags 1no broken cut 900x600 pcc flag 2no rocking tactile flags (RD: FW Slabs Rocking) | At the pedestrian crossing outside Pret a manger | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 21/07/2020 | 28/07/2020 | Act. ROAD/82038042 |
| 50058946 | 1no rocking perfecta flag 1no broken cut perfecta flag (RD: FW Slabs Rocking) | Outside Three | RD: Cat 3 - 60 Day | Job Complete | 21/07/2020 | 29/07/2020 | Act. ROAD/82038043 |
| 50058947 | 4no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Halifax | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/07/2020 | 24/07/2020 | Act. ROAD/82038044 |
| 50058948 | 6no broken perfecta flags 3no rocking perfecta flags (RD: FW Slabs Broken/Missing) | Outside Sports Direct | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/07/2020 | 29/07/2020 | Act. ROAD/82038045 |
| 50058950 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Hotter | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/07/2020 | 24/07/2020 | Act. ROAD/82038046 |
| 50059305 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Between smiggle and H+M | RD: Cat 2 - 5 Day | Job Complete | 29/07/2020 | 03/08/2020 | Act. ROAD/82038242 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-----------------------------|---------------------------------|------------|----------------------------------|----------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50059306 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Jenners near the pedestrian crossing | RD: Cat 3 - 60 Day | Job Complete | 29/07/2020 | 03/08/2020 | Act. ROAD/82038243 |
| 50059307 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Marks and Spencer's Foodhall entrance | RD: Cat 2 - 5 Day | Job Complete | 29/07/2020 | 04/08/2020 | Act. ROAD/82038244 |
| 50059308 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Superdrug | RD: Cat 2 - 5 Day | Job Complete | 29/07/2020 | 05/08/2020 | Act. ROAD/82038245 |
| 50059309 | 3no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Samsung | RD: Cat 3 - 60 Day | Job Complete | 29/07/2020 | 03/08/2020 | Act. ROAD/82038246 |
| 50059310 | 1no broken perfecta flag 2no rocking perfecta flags (RD: FW Slabs Broken/Missing) | Outside Primark | RD: Cat 3 - 60 Day | Job Complete | 29/07/2020 | 03/08/2020 | Act. ROAD/82038247 |
| 50059311 | 4no broken perfecta flags (RD: FW Slabs Broken/Missing) | Outside Russell and Bromley | RD: Cat 3 - 60 Day | Job Complete | 29/07/2020 | 05/08/2020 | Act. ROAD/82038248 |
| 50059312 | 1no broken perfecta flag 1no rocking perfecta flag (RD: FW Slabs Broken/Missing) | Outside Next | RD: Cat 3 - 60 Day | Job Complete | 29/07/2020 | 03/08/2020 | Act. ROAD/82038249 |
| 50059319 | 9no rocking perfecta flags (RD: FW Slabs Rocking) | Outside no108 | RD: Cat 3 - 60 Day | Job Complete | 29/07/2020 | 06/08/2020 | Act. ROAD/82038253 |
| 50059322 | 11no rocking perfecta flags (RD: FW Slabs Rocking) | Outside River Island | RD: Cat 3 - 60 Day | Job Complete | 29/07/2020 | 19/08/2020 | Act. ROAD/82038255 |
| 50061074 | 2no rocking flags (RD: FW Slabs Rocking) | Outside Debenhams | RD: Cat 3 - 60 Day | Job Complete | 24/08/2020 | 27/08/2020 | Act. ROAD/82038902 |
| 50061077 | 2no rocking flags (RD: FW Slabs Rocking) | Outside primark | RD: Cat 3 - 60 Day | Job Complete | 24/08/2020 | 27/08/2020 | Act. ROAD/82038904 |
| 50061079 | 1no rocking flag (RD: FW Slabs Rocking) | Outside topshop | RD: Cat 2 - 5 Day | Job Complete | 24/08/2020 | 27/08/2020 | Act. ROAD/82038905 |
| 50061088 | 5no rocking flags (RD: FW Slabs Rocking) | Outside where Vodafone shop was opposite Waverley mall | RD: Cat 3 - 60 Day | Job Complete | 24/08/2020 | 27/08/2020 | Act. ROAD/82038907 |
| 50061097 | 1no rocking flag (RD: FW Slabs Rocking) | At pedestrian crossing outside Waverley mall opposite south st Andrew st | RD: Cat 2 - 5 Day | Job Complete | 24/08/2020 | 27/08/2020 | Act. ROAD/82038909 |
| 50061110 | 1no broken 600x900 pcc cut flag (RD: FW Slabs Broken/Missing) | Opposite topshop | RD: Cat 3 - 60 Day | Job Complete | 24/08/2020 | 01/09/2020 | Act. ROAD/82038910 |
| 50061280 | Polychannel: Blocked/Flooding - Clean out footway channel along entire leng (Enquiry 34002268) | Outside Chisholm Hunter and Monsoon are flooding but could the entire footway channel along Princes Street please be cleaned | Non Routine (One Off Works) | Job Complete | 26/08/2020 | 16/04/2021 | Act. RDGC14/82001386 |
| 50061285 | Please remove 6m section of damaged railings (RD: Railing Damage/Missing/New) | Opposite South Charlotte Street | RD: Cat 3 - 60 Day | Job Complete | 26/08/2020 | 09/11/2020 | Act. ROAD/82038949 |
| 50061321 | Renew grano at box (RD: FW Grano Pothole) | Opposite superdrug | RD: Cat 3 - 60 Day | Job Complete | 26/08/2020 | 27/08/2020 | Act. ROAD/82038973 |
| 50061326 | 1no broken 600x900 cut pcc flag 1no broken 600x600 cut pcc flag (RD: FW Slabs Broken/Missing) | Outside tesco | RD: Cat 3 - 60 Day | Job Complete | 26/08/2020 | 28/08/2020 | Act. ROAD/82038977 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|--------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50061330 | 10no broken perfecta flags 2no broken cut perfecta flags (RD: FW Slabs Broken/Missing) | Outside halifax | RD: Cat 3 - 60 Day | Job Complete | 26/08/2020 | 31/08/2020 | Act. ROAD/82038978 |
| 50061334 | 1no broken perfecta flag 7no rocking/low perfecta flags (RD: FW Slabs Broken/Missing) | Outside sports direct | RD: Cat 3 - 60 Day | Job Complete | 26/08/2020 | 28/08/2020 | Act. ROAD/82038982 |
| 50061660 | 2no potholes (RD: CW Pothole) | Eastbound lane outside Barclays | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 31/08/2020 | 01/09/2020 | Act. ROAD/82039100 |
| 50062266 | 1no pothole (RD: CW Pothole) | Eastbound lane at junction of South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 09/09/2020 | 11/09/2020 | Act. ROAD/82039314 |
| 50062928 | Sunken tram manhole previously overlaid needs new hra (RD: CW Pothole) | On the pedestrian crossing at the corner of Waverley Bridge | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 18/09/2020 | 20/09/2020 | Act. ROAD/82039609 |
| 50063645 | 2no rocking pcc flags (RD: FW Slabs Rocking) | At bus stop PP outside Waverley mall | RD: Cat 3 - 60 Day | Job Complete | 29/09/2020 | 01/10/2020 | Act. ROAD/82039792 |
| 50063943 | Rocking perfecta flag (RD: FW Slabs Rocking) | Outside Whittard | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 06/10/2020 | Act. ROAD/82039954 |
| 50063944 | 4no Low perfecta flags 1no high perfecta flag (RD: FW Slabs Rocking) | Outside top shop | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 26/10/2020 | Act. ROAD/82039955 |
| 50063946 | 3no rocking perfecta flags 2no broken perfecta flags 1no rocking cut perfecta flag (RD: FW Slabs Broken/Missing) | Outside top shop | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 07/10/2020 | Act. ROAD/82039956 |
| 50063948 | 1 rocking perfecta flag (RD: FW Slabs Rocking) | Outside Romanes and paterson | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 06/10/2020 | Act. ROAD/82039958 |
| 50063950 | 1 rocking perfecta flag (RD: FW Slabs Rocking) | Outside the o2 shop | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 05/10/2020 | Act. ROAD/82039960 |
| 50063951 | 1 rocking perfecta flag (RD: FW Slabs Rocking) | Outside Fraser hart | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 05/10/2020 | Act. ROAD/82039961 |
| 50063953 | 1 rocking perfecta flag 2rocking cut perfecta flags Loose grano and pieces of slab remove and replace with grano (RD: FW Slabs Rocking) | Outside caffe nero | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 05/10/2020 | Act. ROAD/82039963 |
| 50063955 | 5no rocking perfecta flags (RD: FW Slabs Rocking) | Outside river island | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 05/10/2020 | Act. ROAD/82039965 |
| 50063956 | 6no rocking perfecta flags Infill grano at box (RD: FW Slabs Rocking) | At the foot of castle st | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 05/10/2020 | Act. ROAD/82039966 |
| 50063958 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside urban outfitters | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 05/10/2020 | Act. ROAD/82039968 |
| 50063960 | 3no rocking perfecta flags 2no broken perfecta flags (RD: FW Slabs Rocking) | Outside sports direct | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 07/10/2020 | Act. ROAD/82039970 |
| 50063963 | 3no broken perfecta flags (RD: FW Slabs Rocking) | | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 26/10/2020 | Act. ROAD/82039973 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|-----------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50063973 | 3 broken 600x900 pcc flags 2broken 450 x600 pcc flags 1broken 600x600 pcc flag (RD: FW Slabs Broken/Missing) | Opposite top shop | RD: Cat 3 - 60 Day | Job Complete | 02/10/2020 | 08/10/2020 | Act. ROAD/82039982 |
| 50065883 | 1no pothole around manhole (RD: CW Pothole) | At the junction with South St David St | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 29/10/2020 | 30/10/2020 | Act. ROAD/82040787 |
| 50066283 | Various potholes as discussed with team leader (RD: CW Pothole) | Princes Street Gardens near the fountain | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 04/11/2020 | 06/11/2020 | Act. ROAD/82040930 |
| 50066460 | 2 x Loose perfecta slabs lift and relay (RD: FW Slabs Rocking) | In between Topshop and HM next to tactiles | RD: Cat 2 - 5 Day | Job Complete | 06/11/2020 | 10/11/2020 | Act. ROAD/82041017 |
| 50066463 | 4 x Loose perfecta slabs(2 cuts) lift and relay (RD: FW Slabs Rocking) | O/S Royal House Scotland beside footway channel | RD: Cat 2 - 5 Day | Job Complete | 06/11/2020 | 10/11/2020 | Act. ROAD/82041020 |
| 50066470 | 3 x Bolts protruding on the footway please remove to make safe (spanner required) (RD: Other Defect Type) | Opp Gap shop on garden side | RD: Cat 3 - 60 Day | Job Complete | 06/11/2020 | 09/11/2020 | Act. ROAD/82041024 |
| 50068058 | Install white sticker as per sign background over the blue P on the sign. (RD: Unlit Sign Damaged/Missing) | On Railings infront of Register House. | RD: Cat 4 - 12 Months | No code allocated | 24/11/2020 | 24/11/2021 | Est. |
| 50068749 | No1 rocking slab (RD: FW Slabs Rocking) | Opposite the Huxley at scaffolding | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 16/12/2020 | Act. ROAD/82041909 |
| 50068750 | Renew broken grano at box (RD: FW Grano Cracked/Broken) | Outside Tesco express | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041910 |
| 50068751 | Replace broken 600x900 PCC flag. (RD: FW Slabs Broken/Missing) | Outside McDonald's | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041911 |
| 50068752 | 1no low rocking 600x900 PCC 1no low rocking cut PCC (RD: FW Slabs Rocking) | Outside Pret A Manger at crossing | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041912 |
| 50068754 | 2 high cut tactiles need lowered to remove trips (RD: FW Slabs Rocking) | On centre island of crossing | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041914 |
| 50068759 | 6 rocking perfecta slabs 1 broken perfecta 450x450 (RD: FW Slabs Rocking) | Outside three | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041916 |
| 50068761 | No3 low rocking perfecta slabs (RD: FW Slabs Rocking) | Outside EE | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041918 |
| 50068763 | 1no Rocking perfecta (RD: FW Slabs Rocking) | Outside Halifax | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041919 |
| 50068764 | 1no Rocking cut perfecta at channel (RD: FW Slabs Rocking) | Outside Waterstones | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041920 |
| 50068767 | 2no Rocking perfecta (RD: FW Slabs Rocking) | Outside closed new look store | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041923 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|--------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50068770 | 3 rocking perfectas 1 rocking cut perfecta at channel 1 broken 450x450 perfecta (RD: FW Slabs Broken/Missing) | Outside Poundland | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 18/12/2020 | Act. ROAD/82041925 |
| 50068773 | 2 rocking perfecta cuts 1 rocking perfecta cut (RD: FW Slabs Broken/Missing) | Outside Vodafone | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041928 |
| 50068774 | 3no rocking perfectas (RD: FW Slabs Rocking) | Outside hotter | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041929 |
| 50068778 | 1 broken 450x450 perfecta 1 rocking perfecta (RD: FW Slabs Broken/Missing) | Outside river island | RD: Cat 2 - 5 Day | Job Complete | 02/12/2020 | 08/12/2020 | Act. ROAD/82041931 |
| 50068779 | 3 rocking slabs (RD: FW Slabs Rocking) | Outside 109 at channel | RD: Cat 2 - 5 Day | Job Complete | 02/12/2020 | 08/12/2020 | Act. ROAD/82041932 |
| 50068780 | 2no rocking perfectas (RD: FW Slabs Rocking) | Outside next | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041933 |
| 50068782 | 2no rocking slabs (RD: FW Slabs Rocking) | Outside Zara | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 16/12/2020 | Act. ROAD/82041934 |
| 50068784 | Rocking perfecta Rocking cut perfecta (RD: FW Slabs Rocking) | Outside Zara just before boots. | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041936 |
| 50068785 | 5no broken perfecta slabs 5 rocking perfecta slabs (RD: FW Slabs Broken/Missing) | Outside boots | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 16/12/2020 | Act. ROAD/82041937 |
| 50068786 | 1 rocking perfecta (RD: FW Slabs Rocking) | Outside boots. 5m west of bus stop PF | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041938 |
| 50068789 | 1 broken cut perfecta (RD: FW Slabs Broken/Missing) | Outside royal house of Scotland at box | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 14/12/2020 | Act. ROAD/82041940 |
| 50068790 | 2 rocking perfectas 1 rocking cut perfecta (RD: FW Slabs Rocking) | Outside regus | RD: Cat 2 - 5 Day | Job Complete | 02/12/2020 | 08/12/2020 | Act. ROAD/82041942 |
| 50068792 | 1 low Rocking perfecta (RD: FW Slabs Rocking) | Outside sketchers | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041943 |
| 50068801 | Rocking perfecta (RD: FW Slabs Rocking) | Outside Marks & Spencer | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041946 |
| 50068802 | Rocking perfecta (RD: FW Slabs Rocking) | Outside mercure hotel at channel | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041947 |
| 50068803 | 3 rocking perfectas 1 rocking cut perfecta (RD: FW Slabs Rocking) | Outside jenners | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041948 |
| 50068805 | 1no pothole (RD: CW Pothole) | At the junction with South St David St | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 02/12/2020 | 03/12/2020 | Act. ROAD/82041950 |
| 50068808 | Rocking perfecta (RD: FW Slabs Rocking) | Outside smiggle | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041952 |
| 50068810 | 2 rocking cut perfectas (RD: FW Slabs Rocking) | Outside topshop | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041954 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50068813 | 3 broken 450x450 perfectas (RD: FW Slabs Broken/Missing) | Outside closed Vodafone opp Waverley mall | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041956 |
| 50068817 | 3 Rocking perfectas (RD: FW Slabs Rocking) | Outside Holland and Barrett | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041960 |
| 50068819 | Rocking scoutmore flag Renew missing grano at catv box (RD: FW Slabs Rocking) | Top of waverly steps | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 15/12/2020 | Act. ROAD/82041961 |
| 50068822 | 1 low rocking 600x900 PCC flag (RD: FW Slabs Rocking) | Bus stop PP | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 10/03/2021 | Act. ROAD/82041963 |
| 50068825 | 1 low rocking 600x900 PCC flag (RD: FW Slabs Rocking) | Bus stop PP | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 10/03/2021 | Act. ROAD/82041965 |
| 50068829 | 1 low rocking 600x900 PCC flag (RD: FW Slabs Rocking) | Top of steps at costa | RD: Cat 2 - 5 Day | Job Complete | 02/12/2020 | 08/12/2020 | Act. ROAD/82041968 |
| 50068832 | 2 rocking 600x900 1 rocking 450x600 (RD: FW Slabs Rocking) | Opposite topshop | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 18/12/2020 | Act. ROAD/82041970 |
| 50068835 | Rocking cut sandstone flag (RD: FW Slabs Rocking) | Pedestrian crossing opp topshop | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 18/12/2020 | Act. ROAD/82041973 |
| 50068840 | Rocking slab at box Rocking cut at box (RD: FW Slabs Rocking) | Opposite gap | RD: Cat 3 - 60 Day | Job Complete | 02/12/2020 | 10/03/2021 | Act. ROAD/82041977 |
| 50070570 | Sunken and noisy manhole (RU: Utility Apparatus) | East bound at the junction of Frederick street | RU: Fail Med.Risk (Apparatus) | Job Complete | 18/12/2020 | 22/12/2020 | Act. |
| 50070755 | 1no broken cut perfecta flag (RD: FW Slabs Broken/Missing) | Outside Halifax | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 27/02/2021 | Act. ROAD/82042817 |
| 50070757 | 1no rocking cut perfecta flag (RD: FW Slabs Rocking) | Outside Waterstones | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 27/02/2021 | Act. ROAD/82042818 |
| 50070760 | 3no rocking perfecta flags 1no rocking perfecta cut flag 1no broken perfecta flag (RD: FW Slabs Rocking) | Outside Poundland | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 27/02/2021 | Act. ROAD/82042819 |
| 50070764 | 3no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Next | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 27/02/2021 | Act. ROAD/82042821 |
| 50070765 | 1no rocking perfecta flag 1no broken perfecta flag (RD: FW Slabs Rocking) | Outside Zara | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 04/03/2021 | Act. ROAD/82042822 |
| 50070766 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Zara | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 04/03/2021 | Act. ROAD/82042823 |
| 50070768 | Piece of damaged channel cover with grano (RD: FW Grano Pothole) | Outside Swarovski | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 27/02/2021 | Act. ROAD/82042824 |
| 50070772 | Piece of damaged channel cover with grano (RD: FW Grano Pothole) | Outside Chisholm Hunter | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 27/02/2021 | Act. ROAD/82042827 |
| 50070777 | 1no pothole at manhole (RD: CW Pothole) | At the junction with South st David st | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 22/12/2020 | 22/12/2020 | Act. ROAD/82042829 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50070780 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside H&M | RD: Cat 2 - 5 Day | Job Complete | 22/12/2020 | 23/12/2020 | Act. ROAD/82042831 |
| 50070786 | 1no rocking flag (RD: FW Slabs Rocking) | At bus stop PR opposite marks and spencer | RD: Cat 3 - 60 Day | Job Complete | 22/12/2020 | 04/03/2021 | Act. ROAD/82042835 |
| 50072020 | 2no potholes (RD: CW Pothole) | Westbound lane outside the Balmoral Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 14/01/2021 | 15/01/2021 | Act. ROAD/82043317 |
| 50072704 | 1no pothole at manhole (RD: CW Pothole) | Eastbound lane at junction with South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 25/01/2021 | 26/01/2021 | Act. ROAD/82043636 |
| 50072794 | 1no pothole (RD: CW Pothole) | At the junction with West Register Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 25/01/2021 | 26/01/2021 | Act. ROAD/82043678 |
| 50073182 | 6 x cw potholes (RD: CW Pothole) | At Frederick St | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 28/01/2021 | 29/01/2021 | Act. ROAD/82043893 |
| 50073185 | Noisy and loose manhole (RU: Utility Apparatus) | At Frederick St heading East | RU: Fail Med.Risk (Apparatus) | Job Complete | 28/01/2021 | 29/01/2021 | Act. |
| 50073189 | Damaged section of Arco channel 340mm long please renew (RD: FW Channel Miss Cover (HL)) | O/S Overseas House | RD: Cat 3 - 60 Day | Job Complete | 28/01/2021 | 04/03/2021 | Act. ROAD/82043898 |
| 50073193 | Loose cut slab please lift a (RD: FW Slabs Rocking) | O/S Waterstones | RD: Cat 3 - 60 Day | Job Complete | 28/01/2021 | 04/03/2021 | Act. ROAD/82043901 |
| 50073194 | Loose slab please lift and relay (RD: FW Slabs Rocking) | O/S Halifax | RD: Cat 3 - 60 Day | Job Complete | 28/01/2021 | 09/03/2021 | Act. ROAD/82043902 |
| 50073206 | Loose /Missing section of grano at footway box please renew (RD: FW Grano Open Joint) | O/S Dean Ramsay memorial next to St Johns church | RD: Cat 3 - 60 Day | Job Complete | 28/01/2021 | 08/03/2021 | Act. ROAD/82043912 |
| 50073214 | Loose/rocking cut slab please lift and relay (RD: FW Slabs Rocking) | Opp Halifax | RD: Cat 3 - 60 Day | Job Complete | 28/01/2021 | 08/03/2021 | Act. ROAD/82043918 |
| 50073290 | 1no pothole and remove lumps of tar (RD: CW Pothole) | At west register street in outside lane | RD: Cat 1 - 24 Hours | RD: Made Safe Job Complete | 28/01/2021 | 28/01/2021 | Act. ROAD/82043961 |
| 50074558 | 5 number potholes (RD: CW Pothole) | Outside Balmoro Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 09/02/2021 | 15/02/2021 | Act. ROAD/82044616 |
| 50074561 | 2no depressions require hra overlay (RD: CW Pothole) | At the pedestrian crossing on the corner of Waverley Bridge | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 09/02/2021 | 15/02/2021 | Act. ROAD/82044617 |
| 50074562 | 1no rocking 900x600 pcc flag (RD: FW Slabs Rocking) | Outside Waverley mall at Costa | RD: Cat 2 - 5 Day | Job Complete | 09/02/2021 | 16/02/2021 | Act. ROAD/82044618 |
| 50074563 | 1 number pothole (RD: CW Pothole) | At traffic lights just before Costa Coffee | OSM Rectification | Job Annulled | 09/02/2021 | | |
| 50074566 | 1 number pothole (RD: CW Pothole) | Round manhole at junction of Frederick Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 09/02/2021 | 11/02/2021 | Act. ROAD/82044619 |
| 50074568 | 3 number potholes (RD: CW Pothole) | At junction of Frederick street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 09/02/2021 | 15/02/2021 | Act. ROAD/82044621 |
| 50074847 | 3no potholes (RD: CW Pothole) | At the junction of West Register Street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 15/02/2021 | 23/02/2021 | Act. ROAD/82044783 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|---|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50074848 | 4 number potholes (RD: CW Pothole) | At crossing just passed entrance to West Register Street And beside Wellington Monument | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 15/02/2021 | 23/02/2021 | Act. ROAD/82044784 |
| 50075897 | 2no missing cut 450x450 perfecta flags 1no rocking perfecta flag (RD: FW Slabs Broken/Missing) | At the bus stop outside Holland and Barrett | RD: Cat 2 - 5 Day | Job Complete | 22/02/2021 | 25/02/2021 | Act. ROAD/82045373 |
| 50075901 | 1 number pothole (RD: CW Pothole) | At bus stop outside Barclays | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 22/02/2021 | 23/02/2021 | Act. ROAD/82045376 |
| 50076608 | 1no pothole at the manhole (RD: CW Pothole) | At the junction of South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 26/02/2021 | 02/03/2021 | Act. ROAD/82045823 |
| 50076927 | Damaged footway manhole (RU: Utility Apparatus) | O/S Scott Monument on footway | RU: Fail Med.Risk (Apparatus) | Job Complete | 02/03/2021 | 02/03/2021 | Act. |
| 50076928 | Small loose cut slab please lift and relay (RD: FW Slabs Rocking) | Opp o2 shop next to BT footway manhole | RD: Cat 3 - 60 Day | Job Complete | 02/03/2021 | 08/03/2021 | Act. ROAD/82046032 |
| 50076929 | loose cut slab and broken grano surround please lift and relay and redo grano (RD: FW Slabs Rocking) | Opp Levi's shop | RD: Cat 3 - 60 Day | Job Complete | 02/03/2021 | 08/03/2021 | Act. ROAD/82046033 |
| 50076988 | Broken/ Loose special courtstonel slab 750 x 600 please renew (RD: FW Slabs Broken/Missing) | O/S Prince Brasserie near pedestrian crossing | RD: Cat 2 - 5 Day | Job Complete | 02/03/2021 | 09/03/2021 | Act. ROAD/82046085 |
| 50076989 | Small cw pothole (RD: CW Pothole) | On pedestrian crossing opp Balmoral hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 02/03/2021 | 04/03/2021 | Act. ROAD/82046086 |
| 50077001 | 2 x loose slabs and 1 broken Prefecta slab please lift and relay and renew (RD: FW Slabs Rocking) | O/S Topshop (out door) | RD: Cat 2 - 5 Day | Job Complete | 02/03/2021 | 09/03/2021 | Act. ROAD/82046098 |
| 50077005 | Loose cut slab please li (RD: FW Slabs Rocking) | O/S Chisholm Hunter/caffe nero | RD: Cat 2 - 5 Day | Job Complete | 02/03/2021 | 08/03/2021 | Act. ROAD/82046102 |
| 50077012 | Missing Toby cover (RU: Utility Apparatus) | O/S Tesco Express | RU: Fail Med.Risk (Apparatus) | Job Complete | 02/03/2021 | 04/03/2021 | Act. |
| 50077013 | Loose/ broken cut pefecta slab please renew (RD: FW Slabs Broken/Missing) | O/S Starbucks coffee | RD: Cat 3 - 60 Day | Job Complete | 02/03/2021 | 09/03/2021 | Act. ROAD/82046109 |
| 50077348 | Reset 1 number 900 x 600 PCC slab (RD: FW Slabs Rocking) | At bus stop PP outside Waverley Mal | RD: Cat 2 - 5 Day | Job Complete | 04/03/2021 | 08/03/2021 | Act. ROAD/82046340 |
| 50079381 | 1no pothole (RD: CW Pothole) | Opposite Wittards | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 24/03/2021 | 26/03/2021 | Act. ROAD/82047531 |
| 50080479 | 1 loose cut needs reset and 1 broken slab needs renewed (RD: FW Slabs Broken/Missing) | O/S The Office (Near road side) | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 26/04/2021 | Act. ROAD/82048229 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50080481 | 1 loose broken perfecta slab please renew (RD: FW Slabs Broken/Missing) | O/S Regus hotel | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 26/04/2021 | Act. ROAD/82048231 |
| 50080483 | 1 loose broken perfecta slab please renew (RD: FW Slabs Broken/Missing) | O/S Debenhams | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 26/04/2021 | Act. ROAD/82048233 |
| 50080484 | 1 loose cut broken perfecta slab please renew (RD: FW Slabs Broken/Missing) | O/S HSBC next to double footway manhole | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 26/04/2021 | Act. ROAD/82048234 |
| 50080486 | 2 loose broken perfecta slabs please renew (RD: FW Slabs Broken/Missing) | O/S Card Factory | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 28/04/2021 | Act. ROAD/82048236 |
| 50080487 | loose broken perfecta slab please renew (RD: FW Slabs Broken/Missing) | O/S Urban Outfitters | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 29/04/2021 | Act. ROAD/82048237 |
| 50080488 | Loose perfects slab needs reset (RD: FW Slabs Rocking) | O/S Mountain Warehouse near bin | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 28/04/2021 | Act. ROAD/82048238 |
| 50080489 | 4 x Loose slabs need reset (RD: FW Slabs Rocking) | O/S Vans | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 29/04/2021 | Act. ROAD/82048239 |
| 50080490 | Grano surround at footway manhole needs redone (RD: FW Grano Open Joint) | Opp HSBC | RD: Cat 3 - 60 Day | Job Complete | 06/04/2021 | 28/04/2021 | Act. ROAD/82048240 |
| 50080492 | Potholes x 2 marked by arrow on slab (RD: CW Pothole) | Opp Frederick St | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 06/04/2021 | 08/04/2021 | Act. ROAD/82048242 |
| 50080494 | Pothole marked by arrow (RD: CW Pothole) | Opp Burger King at gully | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 06/04/2021 | 08/04/2021 | Act. ROAD/82048244 |
| 50080517 | 1no pothole at man (RD: CW Pothole) | Outside the Balmoral Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 06/04/2021 | 08/04/2021 | Act. ROAD/82048257 |
| 50080518 | Loose and noisy manhole (RU: Utility Apparatus) | On the carriageway outside the Balmoral Hotel | RU: Fail Med.Risk (Apparatus) | Job Complete | 06/04/2021 | 08/04/2021 | Act. |
| 50082002 | Sunken and noisy manhole (RU: Utility Apparatus) | Westbound carriageway just east of bus stop PT | RU: Fail Med.Risk (Apparatus) | Job Complete | 29/04/2021 | 05/05/2021 | Act. |
| 50082355 | 3no sunken 900x600 pcc flags 1no sunken broken 900x600 pcc flag 1no sunken 450x600 pcc flag (RD: FW Slabs Rocking) | At bus stop PY opposite no120b | RD: Cat 4 - 12 Months | No code allocated | 05/05/2021 | 05/05/2022 | Est. |
| 50083033 | Potholes x 6 (RD: CW Pothole) | O/S GAP in channel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 13/05/2021 | 14/05/2021 | Act. ROAD/82049675 |
| 50083036 | Loose / low slab please lift and relay (RD: FW Slabs Rocking) | O/S Ganble end of Zara next to polychannel | RD: Cat 3 - 60 Day | Job Complete | 13/05/2021 | 26/05/2021 | Act. ROAD/82049678 |
| 50083557 | 1no pothole at manhole surround (RD: CW Pothole) | Outside the entrance to the Balmoral Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/05/2021 | 24/05/2021 | Act. ROAD/82049998 |
| 50083559 | 1no pothole at manhole surround (RD: CW Pothole) | At the junction of South St David Street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/05/2021 | 24/05/2021 | Act. ROAD/82050000 |
| 50083747 | Missing cat posts (RD: SFP Damaged Bollard) | | RD: Cat 2 - 5 Day | Job Complete | 25/05/2021 | 03/06/2021 | Act. ROAD/82050071 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50084243 | 1no pothole (RD: CW Pothole) | At bus stop PK outside Mercure Hotel | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 31/05/2021 | 01/06/2021 | Act. ROAD/82050354 |
| 50084247 | 2no potholes (RD: CW Pothole) | On the pedestrian crossing near the Wellington statue | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 31/05/2021 | 02/06/2021 | Act. ROAD/82050358 |
| 50084423 | 1no pothole (RD: CW Pothole) | Westbound lane outside waverleygate at the traffic lights | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 02/06/2021 | 03/06/2021 | Act. ROAD/82050452 |
| 50084429 | 1no missing perfecta flag nee (RD: FW Slabs Broken/Missing) | At the entrance to Chisholm Hunter jewellers | RD: Cat 3 - 60 Day | Job Complete | 02/06/2021 | 02/06/2021 | Act. ROAD/82050457 |
| 50084431 | 2no rocking perfecta flags 1no rocking cut perfecta flag (RD: FW Slabs Rocking) | On the corner of Frederick Street outside Chisholm Hunter | RD: Cat 3 - 60 Day | Job Complete | 02/06/2021 | 24/06/2021 | Act. ROAD/82050458 |
| 50084456 | Missing cat posts and bases needs replaced damaged (RD: SFP Damaged Bollard) | | RD: Cat 2 - 5 Day | Job Complete | 02/06/2021 | 03/06/2021 | Act. ROAD/82050483 |
| 50084837 | Missing cat posts and bases needs replaced with new bases (RD: SFP Damaged Bollard) | | RD: Cat 2 - 5 Day | Job Complete | 08/06/2021 | 30/06/2021 | Act. ROAD/82050725 |
| 50084981 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Gap | RD: Cat 3 - 60 Day | Job Complete | 09/06/2021 | 23/06/2021 | Act. ROAD/82050809 |
| 50085321 | 1no broken 600x900 pcc flag 1no rocking 600x750 pcc flag Replace broken grano at box (RD: FW Slabs Broken/Missing) | Outside McDonald's | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 08/07/2021 | Act. ROAD/82050978 |
| 50085324 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | At mountain warehouse doorway | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 01/07/2021 | Act. ROAD/82050980 |
| 50085326 | 4no broken perfecta flags Low small grano patch (RD: FW Slabs Broken/Missing) | On the west corner of the junction with castle st at shop doorway | RD: Cat 4 - 12 Months | No code allocated | 16/06/2021 | 16/06/2022 | Est. |
| 50085332 | 3no rocking perfecta flags (RD: FW Slabs Rocking) | Outside hotter | RD: Cat 4 - 12 Months | No code allocated | 16/06/2021 | 16/06/2022 | Est. |
| 50085334 | 2no carriageway reinstatement's failed potholed and badly cracking (RU: Utility Reinstatement) | Outside river island at bus stop PD on eastbound carriageway | RU: Fail Med.Risk (Apparatus) | Job Complete | 16/06/2021 | 16/06/2021 | Act. |
| 50085335 | 2no broken perfecta flags (RD: FW Slabs Broken/Missing) | Outside Levi's | RD: Cat 4 - 12 Months | No code allocated | 16/06/2021 | 16/06/2022 | Est. |
| 50085336 | 2no rocking perfecta flags 2no broken perfecta flag (RD: FW Slabs Rocking) | Outside zara | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 01/07/2021 | Act. ROAD/82050987 |
| 50085339 | 5no uneven perfecta flags lift and relay (RD: FW Slabs Rocking) | At the junction with Frederick st on west side | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 01/07/2021 | Act. ROAD/82050990 |
| 50085344 | 4no rocking flags (RD: FW Slabs Rocking) | At the junction with Frederick st on east side outside Chisholm hunter | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 01/07/2021 | Act. ROAD/82050994 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50085345 | 1no low fire hydrant also cracking and potholed asphalt in previous reinstatement (RU: Utility Apparatus) | Outside Primark on eastbound lane | RU: Fail Med.Risk (Apparatus) | Job Complete | 16/06/2021 | 16/06/2021 | Act. |
| 50085348 | 2no low/rocking tactile flags lift and relay (RD: FW Slabs Rocking) | Outside primark at pedestrian crossing | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 01/07/2021 | Act. ROAD/82050997 |
| 50085352 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Scribbler | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 02/07/2021 | Act. ROAD/82051001 |
| 50085356 | 2no rocking perfecta flags (RD: FW Slabs Rocking) | Outside Fraser hart | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 08/07/2021 | Act. ROAD/82051004 |
| 50085363 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside H&M approx 5m from no40 doorway | RD: Cat 3 - 60 Day | Job Complete | 16/06/2021 | 08/07/2021 | Act. ROAD/82051009 |
| 50085365 | 3no rocking perfecta flags (RD: FW Slabs Rocking) | On the east side of the junction with south st Andrew st | RD: Cat 4 - 12 Months | No code allocated | 16/06/2021 | 16/06/2022 | Est. |
| 50085382 | 1no rocking Caithness flag (RD: FW Slabs Rocking) | Outside Frasers entrance | RD: Cat 4 - 12 Months | Job Annulled | 16/06/2021 | 16/06/2022 | Est. |
| 50085387 | 1no rocking pcc flag (RD: FW Slabs Rocking) | At bus stop PP | RD: Cat 3 - 60 Day | Job Complete | 17/06/2021 | 02/07/2021 | Act. ROAD/82051022 |
| 50085388 | 1no rocking pcc flag (RD: FW Slabs Rocking) | Approx 5m west of bus stop PP | RD: Cat 3 - 60 Day | Job Complete | 17/06/2021 | 02/07/2021 | Act. ROAD/82051023 |
| 50085394 | Replace grano around manhole (RD: FW Grano Cracked/Broken) | Opposite Ann summers | RD: Cat 3 - 60 Day | Job Complete | 17/06/2021 | 01/07/2021 | Act. ROAD/82051026 |
| 50085403 | 1no rocking pcc flag (RD: FW Slabs Rocking) | Opposite Chisholm hunter | RD: Cat 3 - 60 Day | Job Complete | 17/06/2021 | 02/07/2021 | Act. ROAD/82051030 |
| 50085511 | Dislodged kerb x2 (RD: FW Kerb Dislodged/Rocking) | Princess st at south st David st os Jenners | RD: Cat 2 - 5 Day | Job Complete | 18/06/2021 | 24/06/2021 | Act. ROAD/82051095 |
| 50085569 | 5no potholes (RD: CW Pothole) | At the pedestrian crossing outside the Balmoral Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 21/06/2021 | 23/06/2021 | Act. ROAD/82051133 |
| 50087318 | Cw potholes x5 please make safe (RD: CW Pothole) | Princess street at Frederick street os royal house of Scotland | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 13/07/2021 | 15/07/2021 | Act. ROAD/82051952 |
| 50087423 | 3no rocking flags 1no broken perfecta flag (RD: FW Slabs Rocking) | At the foot of castle st 5m north of pedestrian crossing | RD: Cat 3 - 60 Day | Job Complete | 14/07/2021 | 26/07/2021 | Act. ROAD/82052004 |
| 50087424 | 2no rocking flags 1no broken perfecta flag (RD: FW Slabs Rocking) | At skechers doorway | RD: Cat 3 - 60 Day | Job Complete | 14/07/2021 | 30/07/2021 | Act. ROAD/82052005 |
| 50087428 | 1no rocking flag 1no broken perfecta flag (RD: FW Slabs Rocking) | Outside Holland and barrett | RD: Cat 3 - 60 Day | Job Complete | 14/07/2021 | 30/07/2021 | Act. ROAD/82052008 |
| 50087430 | 1no rocking flag (RD: FW Slabs Rocking) | Next to the pedestrian crossing outside the balmoral hotel | RD: Cat 3 - 60 Day | Job Complete | 14/07/2021 | 26/07/2021 | Act. ROAD/82052009 |
| 50087432 | 3no broken 600x900 pcc flags (RD: FW Slabs Broken/Missing) | Outside Costa coffee | RD: Cat 3 - 60 Day | Job Complete | 14/07/2021 | 03/08/2021 | Act. ROAD/82052010 |
| 50087436 | 2no rocking cut pcc flags (RD: FW Slabs Rocking) | Opposite the Edinburgh gift shop near to the Scots monument | RD: Cat 3 - 60 Day | Job Complete | 14/07/2021 | 26/07/2021 | Act. ROAD/82052012 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50087441 | Renew grano at box (RD: FW Grano Cracked/Broken) | Opposite Chisholm Hunter | RD: Cat 3 - 60 Day | Job Complete | 14/07/2021 | 26/07/2021 | Act. ROAD/82052014 |
| 50087444 | 1no broken 600x900 pcc flag (RD: FW Slabs Broken/Missing) | Opposite boots | RD: Cat 3 - 60 Day | Job Complete | 14/07/2021 | 30/07/2021 | Act. ROAD/82052016 |
| 50087514 | Defective manhole (RU: Utility Apparatus) | Princes Street west bound at South Charlotte Street junction. | RU: Fail High Risk | Job Complete | 15/07/2021 | 15/07/2021 | Act. |
| 50087708 | 1no pothole (RD: CW Pothole) | At the junction of South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 20/07/2021 | 22/07/2021 | Act. ROAD/82052130 |
| 50087710 | Loose and noisy manhole (RU: Utility Apparatus) | On the carriageway at the junction of South St David Street near Monsoon | RU: Fail Med.Risk (Apparatus) | Job Complete | 20/07/2021 | 20/07/2021 | Act. |
| 50087723 | Broken and noisy manhole frame and cover (RU: Utility Apparatus) | Westbound carriageway opposite South Charlotte Street | RU: Fail Med.Risk (Apparatus) | Job Complete | 20/07/2021 | 20/07/2021 | Act. |
| 50087724 | Loose and rocking tactile (RD: FW Slabs Rocking) | Outside Three | RD: Cat 3 - 60 Day | Job Complete | 20/07/2021 | 26/07/2021 | Act. ROAD/82052144 |
| 50090127 | Pothole at manhole (RD: CW Pothole) | O/S Balmoral | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053492 |
| 50090131 | 2 x Loose small slabs need reset and pointed (RD: FW Slabs Rocking) | O/S Costa coffee | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053494 |
| 50090133 | Loose small slab needs reset (RD: FW Slabs Rocking) | 10m east of entrance to Livingston Statue | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053496 |
| 50090137 | Low slab at footway manhole please lift and relay to remove trip (RD: FW Slabs Rocking) | O/S Gable end of Mound Monument | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053499 |
| 50090139 | Small section of slab missing please infill with grano to remove trip (RD: FW Slabs Broken/Missing) | Beside corner plinth of National gallery | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053501 |
| 50090141 | 2 x low slabs please lift and relay to remove trips (RD: FW Slabs Rocking) | Opp Debenhams 5m and 7m east of bus stop | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053503 |
| 50090143 | Broken- loose 900 x 600 needs renewed (RD: FW Slabs Broken/Missing) | Opp H Samuel | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 24/08/2021 | Act. ROAD/82053505 |
| 50090144 | 2 x low slabs please lift and relay to remove trip (RD: FW Slabs Rocking) | Opp Poundland at bus stop | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 05/10/2021 | Act. ROAD/82053506 |
| 50090146 | Double manhole cover not flush (RU: Utility Apparatus) | Opp South Charlotte St | RU: Fail Med.Risk (Apparatus) | Job Complete | 20/08/2021 | 23/08/2021 | Act. |
| 50090147 | Pothole at SV CW manhole (RD: CW Pothole) | At Lothian Road | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 20/08/2021 | 24/08/2021 | Act. ROAD/82053507 |
| 50090150 | Broken- loose 900 x 600 needs renewed (RD: FW Slabs Broken/Missing) | O/S Tesco Express | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053510 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|--|----------------------------|------------|------------|---------------------|
| Asset: | 3.00 | Asset - Locn.: | 11110 - Ward 11 - From Waterloo Place to Shandwick Place | Feature Type: | Road Asset | Area: | South East Locality |
| 50090151 | Trip at footway manhole infill with grano (RD: FW Grano Open Joint) | O/S McDonald's | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053511 |
| 50090153 | low slab please lift and relay to remove trip (RD: FW Slabs Rocking) | O/S no 136 | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053513 |
| 50090156 | Rocking slabs x 5 need reset (RD: FW Slabs Rocking) | O/S Three shop | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 24/08/2021 | Act. ROAD/82053514 |
| 50090158 | Section of ACO channel broken and not flush leaving trip needs reset (RD: Polychannel Damaged) | O/S Urban Outfitters at bus stop | RD: Cat 2 - 5 Day | Job Complete | 20/08/2021 | 16/09/2021 | Act. ROAD/82053515 |
| 50090159 | Pothole (RD: CW Pothole) | O/S River Island | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053516 |
| 50090161 | 1 Broken- loose perfecta no slab and 5 rocking (RD: FW Slabs Broken/Missing) | O/S ZARA shop | RD: Cat 2 - 5 Day | Job Complete | 20/08/2021 | 24/08/2021 | Act. ROAD/82053517 |
| 50090163 | 4 Broken- loose 1 cut perfecta slabs and 3 rocking (RD: FW Slabs Broken/Missing) | O/S Boots beside footway manhole | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 31/08/2021 | Act. ROAD/82053518 |
| 50090164 | Rocking slab need reset (RD: FW Slabs Rocking) | O/S no 80 Clark's at crossing | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053519 |
| 50090166 | Rocking slab need reset (RD: FW Slabs Rocking) | O/S Ernest Jones beside footway manhole | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053521 |
| 50090167 | Trip at ACO channel infill with tar (RD: FW HRA Pothole) | O/S Fraser Hart | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053522 |
| 50090168 | Rocking slab need reset (RD: FW Slabs Rocking) | O/S Marks And Spencer | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053523 |
| 50090169 | Pothole at manhole (RD: CW Pothole) | At South St David's St | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053524 |
| 50090170 | Pothole at manhole (RD: CW Pothole) | O/S Monsoon | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053525 |
| 50090171 | Rocking slab need reset (RD: FW Slabs Rocking) | O/S H and M | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 23/08/2021 | Act. ROAD/82053526 |
| 50090172 | Rocking slabs x 3 and 1 broken causing trip (RD: FW Slabs Rocking) | O/S Topman near tactiles tactiles | RD: Cat 3 - 60 Day | Job Complete | 20/08/2021 | 25/08/2021 | Act. ROAD/82053527 |
| 50090173 | Rocking slabs x 2 (RD: FW Slabs Rocking) | 15m east of S St Andrews St | RD: Cat 2 - 5 Day | Job Complete | 20/08/2021 | 24/08/2021 | Act. ROAD/82053528 |
| 50090527 | Please hand clean blocked gully (Gully: Blocked - Hand Clear) | Opposite Primark on the crossing point at the tram stop | RG: Gully - Standard Priority | Gully: Hand Crew Required | 26/08/2021 | 26/11/2021 | Est. ROAD/82053713 |
| 50091041 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | On the corner of Hanover Street outside Fraser Hart | RD: Cat 2 - 5 Day | Job Complete | 02/09/2021 | 03/09/2021 | Act. ROAD/82054033 |
| 50091043 | 1no broken cut perfecta flag (RD: FW Slabs Broken/Missing) | Outside the old Jenners building next to the pedestrian crossing | RD: Cat 2 - 5 Day | Job Complete | 02/09/2021 | 03/09/2021 | Act. ROAD/82054035 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|--|--|-------------------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50092321 | Broken gully frame and sunken brander needs replaced (RD: Gully Damaged/Sunken) | Outside no1 Prince Brasserie | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 04/11/2021 | Act. ROAD/82054485 |
| 50092333 | x6 rocking perfecta slabs, lift and replace. (RD: FW Slabs Rocking) | Outside old Vodafone shop, next to ped crossing. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 24/09/2021 | Act. ROAD/82054494 |
| 50092338 | x1 grano pothole at manhole. Remove loose and replace with fresh grano. (RD: FW Grano Pothole) | Outside the Edinburgh gift shop. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 24/09/2021 | Act. ROAD/82054496 |
| 50092344 | x1 rocking cut perfecta slab, lift and relay. (RD: FW Slabs Rocking) | Outside Ernest Jones. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 24/09/2021 | Act. ROAD/82054501 |
| 50092346 | x1 grano pothole at manhole. Remove loose and replace with fresh grano. (RD: FW Grano Pothole) | Bottom of castle street at ped crossing. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 23/09/2021 | Act. ROAD/82054503 |
| 50092348 | x1 rocking cut perfecta slab, lift and relay. (RD: FW Slabs Rocking) | Next to bus stop outside h.samuel. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 24/09/2021 | Act. ROAD/82054505 |
| 50092349 | x3 rocking perfecta slab, lift and relay. (RD: FW Slabs Rocking) | Outside H.samuel. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 24/09/2021 | Act. ROAD/82054506 |
| 50092361 | x1 rocking Caithness flag, lift and relay. (RD: FW Slabs Rocking) | Opposite royal bank of Scotland at the church. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 29/09/2021 | Act. ROAD/82054510 |
| 50092363 | Open grano joint around NAL cover. (RD: FW Grano Open Joint) | Opposite 3 at ped crossing. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 23/09/2021 | Act. ROAD/82054511 |
| 50092364 | Double service manhole cover has failed in one section and the frame has split. Patch surround has also failed and further deterioration is expected. (RU: Utility Apparatus) | Opposite three shop on CW. Next to ped crossing. | RU: Fail Med.Risk (Apparatus) | Job Complete | 22/09/2021 | 24/09/2021 | Act. |
| 50092365 | x1 grano pothole, make safe. (RD: FW Grano Pothole) | Opposite premier inn next to bus stop. | RD: Cat 3 - 60 Day | Job Complete | 22/09/2021 | 23/09/2021 | Act. ROAD/82054512 |
| 50092372 | SV Cover within CW is low against CW. (RU: Utility Apparatus) | Opposite monsoon within CW. | RU: Fail Low Risk | Job Complete | 22/09/2021 | 24/09/2021 | Act. |
| 50094344 | 1 number pothole (RD: CW Pothole) | Outside Barclays Bank at bus stop | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 20/10/2021 | 21/10/2021 | Act. ROAD/82055179 |
| 50094546 | Single service manhole cover is low against existing CW and is causing damage to the surrounding road structure. (RU: Utility Apparatus) | Outside the balmoral hotel. See photos. | RU: Fail Med.Risk (Apparatus) | Job Complete | 22/10/2021 | 22/10/2021 | Act. |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|---|--------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50094548 | Open grano joint at access chamber. (RD: FW Grano Open Joint) | Opposite Chisholm hunter. | RD: Cat 3 - 60 Day | Job Complete | 22/10/2021 | 26/10/2021 | Act. ROAD/82055268 |
| 50094807 | 1no rocking 900x600 pcc flag (RD: FW Slabs Rocking) | At bus stop PP outside Waverley mall coffee bar | RD: Cat 2 - 5 Day | Job Complete | 26/10/2021 | 27/10/2021 | Act. ROAD/82055341 |
| 50094808 | Reset 4 x Loose and rocking tactile at crossing (RD: FW Slabs Rocking) | At crossing outside Edinburgh Gin | RD: Cat 2 - 5 Day | Job Complete | 26/10/2021 | 27/10/2021 | Act. ROAD/82055342 |
| 50095325 | 1no rocking 900x600 pcc flag (RD: FW Slabs Rocking) | Opposite Tesco Express | RD: Cat 3 - 60 Day | Job Complete | 01/11/2021 | 09/11/2021 | Act. ROAD/82055522 |
| 50095330 | 1 number pothole round manhole (RD: CW Pothole) | At junction of South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 01/11/2021 | 02/11/2021 | Act. ROAD/82055526 |
| 50095650 | 1no pothole at manhole (RD: CW Pothole) | Westbound lane outside the Balmoral Hotel | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 03/11/2021 | 04/11/2021 | Act. ROAD/82055700 |
| 50095657 | Collapsed lid on Scottish Power box (RU: Utility Apparatus) | On the footway opposite South Charlotte Street near the pedestrian crossing Called Lorraine Jones from Scottish Power no reference number given said action would be taken today | RU: Fail High Risk | Job Complete | 03/11/2021 | 09/11/2021 | Act. |
| 50095921 | Reset sunken drainage manhole (RD: CW Manhole Cover Reset) | West bound at bus stop PT | RD: Cat 3 - 60 Day | Job Complete | 04/11/2021 | 14/11/2021 | Act. ROAD/82055803 |
| 50096208 | 1no pothole (RD: CW Pothole) | Eastbound lane outside Primark | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 08/11/2021 | 09/11/2021 | Act. ROAD/82055932 |
| 50097068 | 1no pothole (RD: CW Pothole) | Near the pedestrian crossing outside the Balmoral Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 15/11/2021 | 16/11/2021 | Act. ROAD/82056253 |
| 50097267 | Replaced missing bollards (RD: SFP Damaged Bollard) | | RD: Cat 2 - 5 Day | Job Complete | 16/11/2021 | 16/11/2021 | Act. ROAD/82056355 |
| 50097496 | 1no broken perfecta flag 3no rocking perfecta flags 2no rocking tactile flags (RD: FW Slabs Broken/Missing) | At the pedestrian crossing outside Topshop | RD: Cat 2 - 5 Day | Job Complete | 17/11/2021 | 15/01/2022 | Act. ROAD/82056451 |
| 50097817 | 1no dislodged kerb needs reset 1no broken 750x600 courtstone flag 1no rocking cut courtstone flag (RD: FW Kerb Dislodged/Rocking) | At the top of the Waverley steps | RD: Cat 2 - 5 Day | Job Complete | 19/11/2021 | 22/11/2021 | Act. ROAD/82056568 |
| 50098657 | x1 rocking slab, lift and relay. (RD: FW Slabs Rocking) | At ped crossing outside art gallery. | RD: Cat 2 - 5 Day | Job Complete | 26/11/2021 | 30/11/2021 | Act. ROAD/82056920 |
| 50098659 | x1 broken 600x600, lift and replace. (RD: FW Slabs Broken/Missing) | Outside entrance to Edinburghs Christmas. | RD: Cat 3 - 60 Day | Job Complete | 26/11/2021 | 07/12/2021 | Act. ROAD/82056921 |
| 50099200 | Trip hazard at guardrail socket Please ramp off with grano (RD: FW Grano Depression/Sunken) | Opposite Accessorize | RD: Cat 3 - 60 Day | Job Complete | 02/12/2021 | 07/12/2021 | Act. ROAD/82057099 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|-------------------------------|---------------------------------|------------|----------------------------------|-----------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50099520 | 1no pothole (RD: CW Pothole) | Eastbound lane outside Monsoon | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 07/12/2021 | 08/12/2021 | Act. ROAD/82057240 |
| 50099521 | 1no pothole (RD: CW Pothole) | Eastbound lane at the junction of West Register Street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 07/12/2021 | 08/12/2021 | Act. ROAD/82057241 |
| 50099626 | 1no broken perfecta flag 1no rocking perfecta flag (RD: FW Slabs Broken/Missing) | Outside Holland and Barrett | RD: Cat 2 - 5 Day | Job Complete | 08/12/2021 | 15/12/2021 | Act. ROAD/82057296 |
| 50100212 | 1no pothole (RD: CW Pothole) | Outside the entrance to the Balmoral Hotel | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 14/12/2021 | 15/12/2021 | Act. ROAD/82057571 |
| 50101297 | Failed asphalt reinstatement at Scottish Water manhole surround (RU: Utility Reinstatement) | Eastbound Lane at the junction of Frederick Street | RU: Fail Med.Risk (Apparatus) | Job Complete | 22/12/2021 | 22/12/2021 | Act. |
| 50101601 | x2 broken cut slabs, lift and replace. (RD: FW Slabs Broken/Missing) | Opposite Debenhams. | RD: Cat 3 - 60 Day | Job Complete | 30/12/2021 | 19/01/2022 | Act. ROAD/82058109 |
| 50101602 | Manhole cover is low against existing CW and is causing damage. (RU: Utility Apparatus) | At junction of south David street. | RU: Fail Med.Risk (Apparatus) | Job Complete | 30/12/2021 | 05/01/2022 | Act. |
| 50101603 | x1 rocking cut Caithness slab, lift and relay. (RD: FW Slabs Rocking) | Outside the balmoral. | RD: Cat 3 - 60 Day | Job Complete | 30/12/2021 | 19/01/2022 | Act. ROAD/82058113 |
| 50101730 | 2no broken perfecta flags 1no rocking perfecta flag 1no rocking cut perfecta flag (RD: FW Slabs Broken/Missing) | Outside Clarks no81 | RD: Cat 2 - 5 Day | Job Complete | 05/01/2022 | 15/01/2022 | Act. ROAD/82058161 |
| 50101846 | 1no pothole (RD: CW Pothole) | On the pedestrian crossing outside the Balmoral Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 06/01/2022 | 07/01/2022 | Act. ROAD/82058211 |
| 50101847 | 1no pothole (RD: CW Pothole) | Eastbound lane at the junction of West Register Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 06/01/2022 | 06/01/2022 | Act. ROAD/82058212 |
| 50101848 | 4no potholes (RD: CW Pothole) | Westbound lane outside the entrance to the Balmoral Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 06/01/2022 | 07/01/2022 | Act. ROAD/82058213 |
| 50101849 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside Foot Locker | RD: Cat 2 - 5 Day | Job Complete | 06/01/2022 | 11/01/2022 | Act. ROAD/82058214 |
| 50101850 | 1 number pothole (RD: CW Pothole) | Outside Edinburgh Waverley | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 06/01/2022 | 07/01/2022 | Act. ROAD/82058215 |
| 50102067 | Gully: Flooding - Flooding (Enquiry 34004644) | Opp Waverley Bridge | RG: Gully - High Priority | Job Complete | 09/01/2022 | 08/03/2022 | Act. RDGC/14/82004297 |
| 50102380 | 1no pothole (RD: CW Pothole) | At the junction of South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 11/01/2022 | 12/01/2022 | Act. ROAD/82058505 |
| 50102835 | Sunken manhole with sunken lids (RU: Utility Apparatus) | Eastbound lane outside Phone Spot | RU: Fail Med.Risk (Apparatus) | Job Complete | 14/01/2022 | 24/01/2022 | Act. |
| 50102839 | Recently reinstated Zayo manhole frame and covers very loose and extremely noisy (RU: Utility Reinstatement) | Westbound lane opposite South Charlotte Street | RU: Fail Med.Risk (Apparatus) | Job Complete | 14/01/2022 | 18/01/2022 | Act. |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|-------------------------------|---------------------------------|------------|----------------------------------|----------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50103614 | 1no broken sunken perfecta flag (RD: FW Slabs Broken/Missing) | Outside Boots | RD: Cat 3 - 60 Day | Job Complete | 20/01/2022 | 25/01/2022 | Act. ROAD/82059052 |
| 50103615 | Relay 3 rocking and 2 broken perfect flags (RD: FW Slabs Rocking) | Outside Zara | RD: Cat 2 - 5 Day | Job Complete | 20/01/2022 | 21/01/2022 | Act. ROAD/82059053 |
| 50103617 | 1no broken and sunken perfecta flag (RD: FW Slabs Broken/Missing) | Outside no60 Marks and Spencer | RD: Cat 2 - 5 Day | Job Complete | 20/01/2022 | 21/01/2022 | Act. ROAD/82059054 |
| 50105183 | 1no sunken and rocking perfecta flag (RD: FW Slabs Rocking) | Outside Chisholm Hunter | RD: Cat 2 - 5 Day | Job Complete | 03/02/2022 | 04/02/2022 | Act. ROAD/82059711 |
| 50105187 | 4 number potholes (RD: CW Pothole) | At junction of Fredrick Street | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 03/02/2022 | 11/02/2022 | Act. ROAD/82059712 |
| 50105687 | x2 rocking cut slabs, lift and relay. (RD: FW Slabs Rocking) | Opposite old Waverley hotel. | RD: Cat 3 - 60 Day | Job Complete | 08/02/2022 | 21/02/2022 | Act. ROAD/82059929 |
| 50106197 | Damaged cover on fw (RU: Utility Apparatus) | Princess street at the mound | RU: Fail High Risk | Job Complete | 14/02/2022 | 21/02/2022 | Act. |
| 50106200 | Collapsed Scottish power concrete cover number one box on footway (RU: Utility Apparatus) | Outside Art Gallery | RU: Fail High Risk | Job Complete | 14/02/2022 | 22/02/2022 | Act. |
| 50106201 | Collapsed Scottish power number one on footway (RU: Utility Apparatus) | Outside Art Gallery | RU: Fail High Risk | Job Complete | 14/02/2022 | 23/02/2022 | Act. |
| 50106395 | Relay Loose and rocking flag (RD: FW Slabs Rocking) | Outside Topshop | RD: Cat 2 - 5 Day | Job Complete | 16/02/2022 | 21/02/2022 | Act. ROAD/82060299 |
| 50106597 | Loose and rocking flag (RD: FW Slabs Rocking) | Outside Fraser Hart | RD: Cat 2 - 5 Day | Job Complete | 17/02/2022 | 21/02/2022 | Act. ROAD/82060419 |
| 50106606 | 2 number potholes (RD: CW Pothole) | At pedestrian crossing and junction of West Register street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 17/02/2022 | 20/02/2022 | Act. ROAD/82060426 |
| 50107382 | Please clean channel and all gullys (Gully: Blocked - Hand Clear) | Full length of Princes Street (shop side) | RG: Gully - Standard Priority | Job Committed | 24/02/2022 | 24/05/2022 | Est. RDGC14/82004437 |
| 50107437 | 1 number pothole (RD: CW Pothole) | At junction of West Register Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 25/02/2022 | 01/03/2022 | Act. ROAD/82060939 |
| 50107843 | 1no pothole (RD: CW Pothole) | At the junction of South St David Street | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 01/03/2022 | 02/03/2022 | Act. ROAD/82061145 |
| 50108052 | 1no pothole (RD: CW Pothole) | Outside the entrance to the Balmoral Hotel | RD: Cat 2 - 5 Day | RD: Made Safe Job Complete | 03/03/2022 | 04/03/2022 | Act. ROAD/82061253 |
| 50108053 | 2no potholes (RD: CW Pothole) | At the pedestrian crossing outside the Balmoral Hotel | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 03/03/2022 | 04/03/2022 | Act. ROAD/82061254 |
| 50108098 | 1no rocking 900x600 pcc flag (RD: FW Slabs Rocking) | Outside no136 Jollibee | RD: Cat 2 - 5 Day | Job Complete | 04/03/2022 | 07/03/2022 | Act. ROAD/82061274 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|-------------------------------|---------------------------------|------------|----------------------------------|----------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50108139 | Patch within a patch has failed. Area of CW appears to be moving when cars are going over it. | At top of leith street just out with road studs. | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 05/03/2022 | 13/03/2022 | Act. ROAD/82061305 |
| | Assessment required with scope for inspection and permanent patching. (RD: CW Cracked/Broken) | | | | | | |
| 50108140 | x2 CW potholes, make safe. (RD: CW Pothole) | Outside Waverley gate. | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 05/03/2022 | 07/03/2022 | Act. ROAD/82061306 |
| 50108141 | Rocking slab, lift and relay. (RD: FW Slabs Rocking) | Opposite Hanover street outside the art gallery. | RD: Cat 2 - 5 Day | Job Complete | 05/03/2022 | 07/03/2022 | Act. ROAD/82061307 |
| 50108142 | Area of CW has rutted through to binder layer, approx 20 sq/m. | Outside royal house of Scotland at Frederick street junction. | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 05/03/2022 | 13/03/2022 | Act. ROAD/82061308 |
| | Previous temp repairs have failed. (RD: CW Rutting) | | | | | | |
| 50108143 | Single service manhole cover has dislodged from CW and runs risk of collapsation. | Outside phone spot and EE on princes street. | RU: Fail Med.Risk (Apparatus) | Job Complete | 05/03/2022 | 07/03/2022 | Act. |
| | Vehicle impact is causing cover to move. (RU: Utility Apparatus) | | | | | | |
| 50108362 | 1no sunken and rocking perfecta flag (RD: FW Slabs Rocking) | Outside Boots | RD: Cat 2 - 5 Day | Job Complete | 07/03/2022 | 10/03/2022 | Act. ROAD/82061396 |
| 50108364 | 2 x loose and rocking flags (RD: FW Slabs Rocking) | Between bus stop PE and boots | RD: Cat 2 - 5 Day | Job Complete | 07/03/2022 | 10/03/2022 | Act. ROAD/82061398 |
| 50108909 | 2no sunken BT manholes (RU: Utility Apparatus) | Westbound lane at bus stop PP at the top of the Waverley steps | RU: Fail Med.Risk (Apparatus) | Job Complete | 14/03/2022 | 14/03/2022 | Act. |
| 50108923 | 1 number pothole (RD: CW Pothole) | Outside Monsoon | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 14/03/2022 | 15/03/2022 | Act. ROAD/82061658 |
| 50109076 | Sunken gully frame and brander needs reset (RD: Gully Damaged/Sunken) | Westbound lane at pedestrian crossing opposite burger king | RD: Cat 3 - 60 Day | Job Scheduled | 15/03/2022 | 07/06/2022 | Est. RDGC14/82004488 |
| 50109381 | 1no pothole (RD: CW Pothole) | At the pedestrian crossing at the junction of Waverley Bridge | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 17/03/2022 | 18/03/2022 | Act. ROAD/82061897 |
| 50109383 | 1no pothole at manhole surround (RD: CW Pothole) | Eastbound lane outside Phonespot | RD: Cat 3 - 60 Day | RD: Made Safe Job Complete | 17/03/2022 | 18/03/2022 | Act. ROAD/82061898 |
| 50109882 | 1no broken perfecta flag (RD: FW Slabs Broken/Missing) | Outside Three | RD: Cat 3 - 60 Day | Job Complete | 22/03/2022 | 23/03/2022 | Act. ROAD/82062107 |
| 50109886 | 3no rocking perfecta flags (RD: FW Slabs Rocking) | Just east of Great Scot | RD: Cat 3 - 60 Day | Job Complete | 22/03/2022 | 23/03/2022 | Act. ROAD/82062109 |
| 50109887 | 1no blocked gully needs cleaned and flushed (Gully: Blocked / Flooding) | Opposite Dr Martens at pedestrian crossing | RG: Gully - Standard Priority | Job Committed | 22/03/2022 | 22/06/2022 | Est. RDGC14/82004526 |

Effective: 01/01/2020 to 31/03/2022

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: Princes Street (7903151)

Maintenance Management

| Job No. | Description | Location | Priority | Job Status | Entered | Completion | Works Order |
|----------|---|--|--------------------|---------------------------------|------------|----------------------------------|--------------------|
| | Asset: 3.00 | Asset - Locn.: 11110 - Ward 11 - From Waterloo Place to Shandwick Place | | Feature Type: Road Asset | | Area: South East Locality | |
| 50109891 | 5no rocking perfecta flags (RD: FW Slabs Rocking) | Next to the flag poles outside Register House | RD: Cat 2 - 5 Day | Job Complete | 22/03/2022 | 23/03/2022 | Act. ROAD/82062112 |
| 50109892 | 4no rocking perfecta flags (RD: FW Slabs Rocking) | At the pedestrian crossing outside Register House | RD: Cat 2 - 5 Day | Job Complete | 22/03/2022 | 23/03/2022 | Act. ROAD/82062113 |
| 50109896 | 6no rocking perfecta flags (RD: FW Slabs Rocking) | Just west of the Wellington Statue | RD: Cat 3 - 60 Day | Job Complete | 22/03/2022 | 25/03/2022 | Act. ROAD/82062115 |
| 50109897 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Just east of the Wellington Statue | RD: Cat 3 - 60 Day | Job Complete | 22/03/2022 | 25/03/2022 | Act. ROAD/82062116 |
| 50110159 | 1no rocking perfecta flag (RD: FW Slabs Rocking) | Outside no125a Easyhotel | RD: Cat 3 - 60 Day | Job Complete | 24/03/2022 | 29/03/2022 | Act. ROAD/82062292 |