

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Site: George Street (7901802)

Locality: New Town, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41121237 - Inspection Batch			Route:	Ad hoc Route		Date:	30/03/2022
42098163	1no pothole	30/03/2022	On the zebra crossing outside NatWest	RD: CW Pothole	Internal		Committed	50110709
Batch:	41121233 - Inspection Batch			Route:	SE_CW1_Central1		Date:	30/03/2022
42098160	1no pothole	30/03/2022	Outside no29	RD: CW Pothole	Internal		Committed	50110706
Batch:	41120189 - Inspection Batch			Route:	SE_FW1_GeorgeSt1		Date:	22/03/2022
42097265	x2 broken 900x600 pcc slabs, lift and replace.	22/03/2022	Outside le monde.	RD: FW Slabs Rocking	Internal		Committed	50109908
42097302	x1 broken 900x600 pcc slab next to service cover, lift and replace.	22/03/2022	Outside candy bar.	RD: FW Slabs Broken/Missing	Internal		Committed	50109944
42097295	x1 rocking tactile and cut within recessed cover, relay or replace with new charcoal tactile.	22/03/2022	Outside fat face.	RD: FW Slabs Rocking	Internal		Committed	50109937
	x1 broken cut slab within cover, lift and relay.							
	Repair any Grano surround where required.							
42097308	x1 Grano pothole/open joint. Make safe.	22/03/2022	Outside 108 and Fred's next to tactile paving.	RD: FW Grano Pothole	Internal		Committed	50109950
42097305	x3 Grano potholes/open joints. Make safe.	22/03/2022	Outside Eden Locke.	RD: FW Grano Pothole	Internal		Committed	50109947
42097301	x1 broken 600x600 pcc slab, lift and replace.	22/03/2022	Outside 101.	RD: FW Slabs Broken/Missing	Internal		Committed	50109943
42097293	Grano open joint next to Toby, make safe.	22/03/2022	Outside 69a.	RD: FW Grano Open Joint	Internal		Committed	50109935
42097297	Grano open joint next to NAL service cover and double service box, make safe.	22/03/2022	Outside fat face.	RD: FW Grano Open Joint	Internal		Committed	50109939
Batch:	41118895 - Inspection Batch			Route:	Ad hoc Route		Date:	10/03/2022
42095708	1no rocking 600x600 pcc flag	10/03/2022	Outside the Dome	RD: FW Slabs Rocking	Internal		Committed	50108713
Batch:	41118136 - Inspection Batch			Route:	SE_CW1_Central1		Date:	03/03/2022
	No actionable defects found							
Batch:	41117148 - Inspection Batch			Route:	SE_CF1_GeorgeSt1		Date:	25/02/2022
	No actionable defects found							
Batch:	41117143 - Inspection Batch			Route:	SE_FW1_GeorgeSt1		Date:	25/02/2022
42094133	Pothole at Frederick street junction, make safe.	25/02/2022	At junction of Fredrick street.	RD: CW Pothole	Internal		Committed	50107483
Batch:	41114991 - Inspection Batch			Route:	SE_CW1_Central1		Date:	08/02/2022
	No actionable defects found							
Batch:	41114050 - Inspection Batch			Route:	SE_FW1_GeorgeSt1		Date:	26/01/2022
42090914	Open grano joint at box.	25/01/2022	Outside why not.	RD: FW Grano Open Joint	Internal		Committed	50104248

Site History Report

Effective: 05/08/2020 to 06/04/2022
 Service: Roads General
 Site: George Street (7901802)

Asset Number: 1.00 to 3.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41114050 - Inspection Batch				Route: SE_FW1_GeorgeSt1		Date: 26/01/2022		
42090913	x1 rocking pcc, lift and relay.	25/01/2022	Outside old NatWest next to the dome.	RD: FW Slabs Rocking	Internal		Committed	50104247
Batch: 41112773 - Inspection Batch				Route: SE_CW1_Central1		Date: 11/01/2022		
No actionable defects found								
Batch: 41111713 - Inspection Batch				Route: SE_FW1_GeorgeSt1		Date: 24/12/2021		
42088125	x1 rocking tactiles, lift and relay.	24/12/2021	Outside Lakeland.	RD: FW Slabs Rocking	Internal		Committed	50101434
42088123	x3 rocking tactiles, lift and relay.	24/12/2021	Opposite Charlotte square at ped crossing.	RD: FW Slabs Rocking	Internal		Committed	50101432
Infill grano pothole with mortar mix.								
42088119	x2 broken 900x600 pcc, lift and replace.	24/12/2021	Opposite old nationwide offices.	RD: FW Slabs Broken/Missing	Internal		Committed	50101429
42088122	x4 CW pothole, make safe.	24/12/2021	At junction of north castle street.	RD: CW Pothole	Internal		Committed	50101431
42088120	x2 broken 900x600 pcc, lift and replace.	24/12/2021	Opposite the dome.	RD: FW Slabs Broken/Missing	Internal		Committed	50101430
Batch: 41110498 - Inspection Batch				Route: Ad hoc Route		Date: 14/12/2021		
42087067	1no rocking 900x600 pcc flag	14/12/2021	Outside the Intercontinental Hotel	RD: FW Slabs Rocking	Internal		Committed	50100233
Batch: 41109776 - Inspection Batch				Route: SE_CW1_Central1		Date: 07/12/2021		
No actionable defects found								
Batch: 41108515 - Inspection Batch				Route: SE_FW1_GeorgeSt1		Date: 29/11/2021		
No actionable defects found								
Batch: 41106799 - Inspection Batch				Route: SE_CW1_Central1		Date: 05/11/2021		
No actionable defects found								
Batch: 41104745 - Inspection Batch				Route: SE_FW1_GeorgeSt1		Date: 20/10/2021		
No actionable defects found								
Batch: 41102756 - Inspection Batch				Route: SE_CW1_Central1		Date: 04/10/2021		
No actionable defects found								
Batch: 41101065 - Inspection Batch				Route: SE_FW1_GeorgeSt1		Date: 21/09/2021		
No actionable defects found								
Batch: 41099531 - Inspection Batch				Route: SE_CW1_Central1		Date: 02/09/2021		
No actionable defects found								
Batch: 41099269 - Inspection Batch				Route: SE_FW1_GeorgeSt1		Date: 31/08/2021		
No actionable defects found								
Batch: 41098548 - Inspection Batch				Route: Ad hoc Route		Date: 19/08/2021		
42076311	Broken coal chute cover on footway make safe with wal board and cones And remove pallet	19/08/2021	Outside number 22 and 24	RD: CW Covers Make Safe	Internal		Committed	50090031
Batch: 41097598 - Inspection Batch				Route: Ad hoc Route		Date: 05/08/2021		
42075180	Sunken catv manhole	05/08/2021	Eastbound carriageway outside no69A	RU: Utility Apparatus	Internal		Uncommitted	50088937

Site History Report

Effective: 05/08/2020 to 06/04/2022
 Service: Roads General
 Site: George Street (7901802)

Asset Number: 1.00 to 3.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch:	41097394 - Inspection Batch			Route: SE_CW1_Central1		Date: 02/08/2021		
	No actionable defects found							
Batch:	41097278 - Inspection Batch			Route: SE_FW1_GeorgeSt1		Date: 30/07/2021		
	No actionable defects found							
Batch:	41096108 - Inspection Batch			Route: Ad hoc Route		Date: 13/07/2021		
42073337	Rocking slab please make safe	13/07/2021	George street os 95	RD: FW Slabs Rocking	Internal		Committed	50087316
Batch:	41095863 - Inspection Batch			Route: SE_FW1_GeorgeSt1		Date: 09/07/2021		
42073148	x1 broken cut 900x600 pcc.	09/07/2021	Outside all saints at ped crossing.	RD: FW Slabs Broken/Missing	Internal		Committed	50087096
	x3 rocking cut 900x600 pcc.							
Batch:	41095411 - Inspection Batch			Route: SE_CW1_Central1		Date: 02/07/2021		
	No actionable defects found							
Batch:	41094413 - Inspection Batch			Route: SE_FW1_GeorgeSt1		Date: 15/06/2021		
	No actionable defects found							
Batch:	41093373 - Inspection Batch			Route: SE_CW1_Central1		Date: 31/05/2021		
	No actionable defects found							
Batch:	41092500 - Inspection Batch			Route: SE_FW1_GeorgeSt1		Date: 17/05/2021		
42069156	1 rocking cut at kerb edge	17/05/2021	Junction with Frederick at	RD: FW Slabs Rocking	Internal		Committed	50083231
	2 no rocking cross cut 600x900s Renew grano							
42069161	1 broken 600x900	17/05/2021	Junction at north castle st	RD: FW Slabs Broken/Missing	Internal		Committed	50083235
42069150	1 low and rocking 600x900 pcc slab	17/05/2021	Outside lululemon atletica	RD: FW Slabs Rocking	Internal		Committed	50083229
42069159	1 rocking 600x600	17/05/2021	Outside cafe andaluz	RD: FW Slabs Rocking	Internal		Committed	50083234
42069134	2 broken 600x900 pcc slabs	17/05/2021	Outside fazenda	RD: FW Slabs Broken/Missing	Internal		Committed	50083217
	1 rocking 600x900							
42069136	1 broken cut at manhole	17/05/2021	Outside the white company	RD: FW Slabs Broken/Missing	Internal		Committed	50083219
	1 rocking cut at manhole							
42069146	1 broken 600x900	17/05/2021	Outside burr & co	RD: FW Slabs Broken/Missing	Internal		Committed	50083227
Batch:	41091778 - Inspection Batch			Route: Ad hoc Route		Date: 06/05/2021		
42068375	Missing cat post	06/05/2021		RD: SFP Damaged Bollard	Internal		Committed	50082455
Batch:	41091144 - Inspection Batch			Route: SE_CW1_Central1		Date: 26/04/2021		
	No actionable defects found							
Batch:	41090737 - Inspection Batch			Route: SE_FW1_GeorgeSt1		Date: 20/04/2021		
42067342	x1 rocking 600x600 PCC slabs. Lift and relay.	20/04/2021	Opposite NatWest at the old Starbucks.	RD: FW Slabs Rocking	Internal		Committed	50081405
42067341	x4 rocking PCC slabs. Lift and relay.	20/04/2021	At all bar one at junction of Hanover street.	RD: FW Slabs Rocking	Internal		Committed	50081404

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41089573 - Inspection Batch				Route: Ad hoc Route		Date: 01/04/2021		
42066373	Collapsed coal chute cover please make safe with walkboard	01/04/2021	Outside no22	RD: FW Cover Make Safe	Internal		Committed	50080353
Batch: 41088783 - Inspection Batch No actionable defects found				Route: SE_CW1_Central1		Date: 24/03/2021		
Batch: 41088462 - Inspection Batch No actionable defects found				Route: SE_FW1_GeorgeSt1		Date: 22/03/2021		
Batch: 41085597 - Inspection Batch No actionable defects found				Route: SE_FW1_GeorgeSt1		Date: 26/02/2021		
Batch: 41085555 - Inspection Batch No actionable defects found				Route: SE_CW1_Central1		Date: 26/02/2021		
Batch: 41085090 - Inspection Batch				Route: SE_CF1_GeorgeSt1		Date: 26/02/2021		
42062484	Rocking red 600x600 PCC slab. Lift and relay.	24/02/2021	Oustide 114.	RD: FW Slabs Rocking	Internal		Committed	50076379
42062478	x4 missing PCC which has been replaced with deteriorating grano. Lift grano and replace with slabs.	24/02/2021	Next to browns.	RD: FW Slabs Broken/Missing	Internal		Committed	50076374
42062566	x6 broken PCC slab 900x600. Lift and replace with grey PCC.	25/02/2021	Between hawes & Curtis and British study centres.	RD: FW Slabs Broken/Missing	Internal		Committed	50076495
42062659	Missing setts/depression which has left a small trip hazard on 3 setts. Make safe with HRA until proper reinstatement is carried out with cobbles.	26/02/2021	In central parking area across from 10 George street.	RD: CW Setts Depression	Internal		Committed	50076621
42062558	x1 broken buff PCC slab. Lift and replace.	25/02/2021	Oustide the royal society of Edinburgh.	RD: FW Slabs Rocking	Internal		Committed	50076489
42062556	x15 broken and damaged PCC slabs. Lift and replace with PCC.	25/02/2021	Oustide the dome.	RD: FW Slabs Broken/Missing	Internal		Action Required	
42062574	x1 rocking 600x600 pcc slab, lift and replace.	25/02/2021	Oustide 91.	RD: FW Slabs Rocking	Internal		Committed	50076502
42062665	Significant cracking on transverse track. Overlay with HRA.	26/02/2021	Outside Starbucks's.	RD: CW Cracked/Broken	Internal		Committed	50076623
42062663	Slight CW cracking around double service manhole.	26/02/2021	Outside cashmere & tweeds.	RD: CW Cracked/Broken	Internal		Action Required	
42062467	1 rocking 600x900 pcc flag 1 rocking 450x600 pcc flag	24/02/2021	Outside All Bar One	RD: FW Slabs Rocking	Internal		Committed	50070517
42062662	Slight CW cracking around double service manhole and the transverse track running just out with the road studs is showing signs of failure.	26/02/2021	Between road studs on ped crossing outside Lakeland.	RD: CW Cracked/Broken	Internal		Action Required	
42062564	x1 broken red PCC slab 900x600. Lift and replace.	25/02/2021	Outside lowdown coffee.	RD: FW Slabs Broken/Missing	Internal		Committed	50076493

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch:	41085090 - Inspection Batch			Route: SE_CF1_GeorgeSt1		Date: 26/02/2021		
42062563	Setts missing from central parking bays. Make safe with HRA in the interim.	25/02/2021	Outside burr & co.	RD: CW Setts Damaged/Missing	Internal		Committed	50076492
42062485	x1 rocking buff PCC slab. Lift and relay.	24/02/2021	Outside knight property group.	RD: FW Slabs Rocking	Internal		Committed	50076380
42062481	x2 rocking red tactile paving slab. Lift and replace.	24/02/2021	At ped crossing in junction of Charlotte square.	RD: FW Slabs Rocking	Internal		Uncommitted	50076377
42062576	CW next ped crossing has deteriorated significantly. Overlay with HRA and remove any loose HRA prior to overlay. Approx 4x2m overlay. Strengthening/deeper patching is required at a later date.	25/02/2021	At ped crossing outside fat face.	RD: CW Cracked/Broken	Internal		Committed	50076504
42062479	Low manhole cover which has resulted in numerous trip hazards in the surrounding area.	24/02/2021	Next to parking meter just along from Hadeel	RU: Utility Apparatus	Internal		Uncommitted	50076375
42062668	CW is showing signs of deeper cracking which may be penetrating the DBM layer. Overlay with HRA in the interim. Requires deeper/strengthening patching at time of final repair.	26/02/2021	At ped crossing on junction of Frederick street outside fatface.	RD: CW Cracked/Broken	Internal		Committed	50076626
42062577	x8 broken PCC slab 900x600. Lift and replace with grey PCC.	25/02/2021	Outside anthropologie.	RD: FW Slabs Broken/Missing	Internal		Committed	50076505
42062557	Deteriorating grano and a small open joint next to service cover. Remove and reinstate with fresh grano.	25/02/2021	Outside Hard Rock Cafe.	RD: FW Grano Open Joint	Internal		Action Required	
42062483	Open joint on grano section of footway leaving a safety hazard. Ponding on CW where the kerb are substantially low. Kerb require raising and poss ble re-profiling of the CW to push water into the gully which is situated right next to ponding area. Requires further assessment.	24/02/2021	Next to bus stop at Edinburgh Charlotte square building.	RD: FW Grano Open Joint	Internal		Action Required	
42062476	x2 Broken 900mm PCC.	24/02/2021	Outside gusto.	RD: FW Slabs Broken/Missing	Internal		Committed	50076372

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch:	41085090 - Inspection Batch			Route: SE_CF1_GeorgeSt1		Date: 26/02/2021		
42062487	Area of setts missing which has been patched in with asphalt that is beginning to deteriorate. Remove asphalt and reinstate with fresh setts, using correct bedding materials and grout.	24/02/2021	Next to SOLO M/CS outside gusto.	RD: CW Setts Damaged/Missing	Internal		Action Required	
42062477	Red PCC cut damaged around manhole.	24/02/2021	Next to browns.	RD: FW Slabs Broken/Missing	Internal		Committed	50076373
42062568	Grano has failed around service cover, remove and reinstate. Replace x4 broken PCC around manhole.	25/02/2021		RD: FW Grano Cracked/Broken	Internal		Action Required	
42062670	CW pothole requires deeper patch.	26/02/2021	At junction of frederick street outside 71 George street.	RD: CW Pothole	Internal		Action Required	
42062667	CW around double service cover is cracking and is showing signs of further deterioration. Make safe with HRA in the interim. At time of full repair deeper patching should be taken into consideration and the patch should also be stepped around double service cover.	26/02/2021		RU: Utility Apparatus	Internal		Committed	50081140
42062666	x1 rocking 900x600 grey pcc slab. Lift and replace.	26/02/2021	Outside phase eight and Hobbs.	RD: FW Slabs Broken/Missing	Internal		Committed	50076624
42062660	CW around double service cover is cracking and showing signs of deterioration. At time of repair deeper patching should be taken into consideration and the patch should also be stepped around double service cover.	26/02/2021	Oustide 10 George street.	RD: CW Cracked/Broken	Internal		Action Required	
42062580	x4 broken PCC slab 900x600. Lift and replace with grey PCC.	25/02/2021	Central ped crossing outside all saints.	RD: FW Slabs Broken/Missing	Internal		Committed	50076509
42062573	x1 broken PCC slab 900x600. Lift and replace with grey PCC.	25/02/2021	Oustide ESPC.	RD: FW Slabs Broken/Missing	Internal		Committed	50076501
42062572	Small pcc cut adjacent which is rocking, lift and relay. CW pothole next to service cover, make safe with HRA.	25/02/2021	At junction of north castle street next to George street monument.	RD: CW Pothole	Internal		Committed	50076500
42062562	CW pothole, make safe with HRA.	25/02/2021	Outside the dome/why not.	RD: CW Pothole	Internal		Committed	50076491

Site History Report

Effective: 05/08/2020 to 06/04/2022
 Service: Roads General
 Site: George Street (7901802)

Asset Number: 1.00 to 3.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41085090 - Inspection Batch				Route: SE_CF1_GeorgeSt1		Date: 26/02/2021		
42062486	Missing slabs next to pedestrian crossing. Cold tar is showing signs of deterioration, lift tar and replace with PCC slabs. x5 damaged PCC slabs within the area, lift and replace with PCX.	24/02/2021	At junction of castle street.	RD: FW Slabs Broken/Missing	Internal		Action Required	
42062561	Grano has failed around fire hydrant, remove and reinstate. Replace broken cut PCC slab adjacent to fire hydrant at time of repair.	25/02/2021	At junction of St Andrews square next to ped crossing.	RD: FW Grano Cracked/Broken	Internal		Action Required	
42062560	Surface course is deteriorating around fire hydrant.	25/02/2021	In parking bau outside standard life next FH.	RD: CW Cracked/Broken	Internal		Action Required	
42062468	2no broken 400 x400 charcoal tactile flags	24/02/2021	On the traffic island at the junction of Hanover Street opposite Jones bootmakers	RD: FW Slabs Broken/Missing	Internal		Uncommitted	1008835
42062465	7no broken 900 x600 pcc grey flag 5no broken 600 x600 pcc grey flags 1no rocking 900 x600 yellow flag	24/02/2021	Just west of bus stop GL	RD: FW Slabs Broken/Missing	Internal		Uncommitted	1008828
42062570	x3 loose/dislodged blocks within central pedestrian crossing.	25/02/2021	Opposite ESPC.	RD: FW Blocks Dislodged/Loose	Internal		Committed	50076498
42062569	Lift and relay. Small section of grano which ha broke away leaving an open joint. Make safe with fresh grano.	25/02/2021	Outside Freemasons hall.	RD: FW Grano Open Joint	Internal		Committed	50076497
Batch: 41078823 - Inspection Batch				Route: SE_FW1_GeorgeSt1		Date: 27/01/2021		
42059585	Broken/Loose 900 x 600 please renew	27/01/2021	O/S The Dome(Nearest west exit)	RD: FW Slabs Broken/Missing	Internal		Committed	50072993
42059616	Loose / broken slab needs renewed and loose cut needs reset	27/01/2021	At North Castle St. (ESPC)	RD: FW Slabs Broken/Missing	Internal		Committed	50073022
42059591	Broken/Loose 900 x 600 please renew	27/01/2021	O/S no 22	RD: FW Slabs Broken/Missing	Internal		Committed	50072998
42059622	Loose / broken slab needs renewed	27/01/2021	Approx 10m west of 1Standard Life main door	RD: FW Slabs Broken/Missing	Internal		Committed	50073027
42059612	2 x Broken/Loose 900 x 600 please renew also remove cold tar and replace with a slab	27/01/2021	O/S Church Of Scotland offices	RD: FW Slabs Broken/Missing	Internal		Committed	50073017
Batch: 41078083 - Inspection Batch				Route: SE_CW1_Central1		Date: 25/01/2021		
No actionable defects found								
Batch: 41077748 - Inspection Batch				Route: Ad hoc Route		Date: 25/01/2021		
42059339	1no pothole	25/01/2021	Outside the Dom	RD: CW Pothole	Internal		Committed	50072705

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41071601 - Inspection Batch			Route: SE_FW1_GeorgeSt1			Date: 18/12/2020		
42057769	4no broken 600x900 pcc flags	18/12/2020	Outside British Study Centres next to bus stop GS	RD: FW Slabs Broken/Missing	Internal		Committed	50070524
42057765	2no broken 600x900 pcc flags 1no rocking 600x900 pcc flag	18/12/2020	Approx 5m east of The Dome	RD: FW Slabs Broken/Missing	Internal		Committed	50070522
42057757	1 rocking 600x900 pcc flag 1 rocking 450x600 pcc flag	18/12/2020	Outside All Bar One	RD: FW Slabs Rocking	Internal		No Action Required	
42057754	1 rocking 600x900 pcc flag 1 broken 600x750 pcc flag 1rocking 600x600 pcc flag	18/12/2020	Outside no91	RD: FW Slabs Rocking	Internal		Committed	50070516
Batch: 41071420 - Inspection Batch			Route: SE_CW1_Central1			Date: 16/12/2020		
No actionable defects found								
Batch: 41070460 - Inspection Batch			Route: Ad hoc Route			Date: 08/12/2020		
42056739	1 broken cut 600x900 1 rocking 600x900 and renew grano at box 1 broken 600x900 at entrance	08/12/2020	Outside victor hugo deli	RD: FW Slabs Broken/Missing	Internal		Committed	50069315
Batch: 41070014 - Inspection Batch			Route: SE_FW1_GeorgeSt1			Date: 30/11/2020		
42056219	1no broken 600x900 pcc flag	30/11/2020	Outside Anthropologie	RD: FW Slabs Broken/Missing	Internal		Committed	50068574
42056209	1no broken 600x900 PCC flag	30/11/2020	Outside no100	RD: FW Slabs Broken/Missing	Internal		Committed	50068563
42056202	Renew broken grano at box	30/11/2020	Outside All Saints	RD: FW Grano Cracked/Broken	Internal		Committed	50068555
42056214	1no broken 600x900 cut pcc flag	30/11/2020	Outside Slug & lettuce	RD: FW Slabs Broken/Missing	Internal		Committed	50068571
42056221	1no rocking flag	30/11/2020	Outside no37	RD: FW Slabs Rocking	Internal		Committed	50068576
42056210	1no broken 600x900 PCC flag	30/11/2020	Outside Fazenda	RD: FW Slabs Broken/Missing	Internal		Committed	50068564
42056207	1no rocking flag	30/11/2020	Outside no84	RD: FW Slabs Rocking	Internal		Committed	50068560
Batch: 41069321 - Inspection Batch			Route: SE_CW1_Central1			Date: 16/11/2020		
No actionable defects found								
Batch: 41068361 - Inspection Batch			Route: SE_FW1_GeorgeSt1			Date: 02/11/2020		
42054939	Low manhole cover causing damage to surround.	02/11/2020	At the pedestrian crossing next to 'Baba' on the junction of charlotte square.	RU: Utility Apparatus	Internal		Uncommitted	50066087
42054942	Sunken broken grano at tact tiles and 2 no rocking slabs	02/11/2020	Outside victor hugo deli at tact tiles	RD: FW Grano Depression/Sunk	Internal		Committed	50066090
Batch: 41066832 - Inspection Batch			Route: SE_CW1_Central1			Date: 13/10/2020		
No actionable defects found								
Batch: 41064843 - Inspection Batch			Route: SE_FW1_GeorgeSt1			Date: 30/09/2020		
42053846	Relay dislodged kerb Relay slab and renew granite	30/09/2020	At the junction with Saint Andrew square	RD: FW Kerb Dislodged/Rocking	Internal		Committed	50063713
42053860	Renew broken grano	30/09/2020	Outside 112	RD: FW Grano Cracked/Broken	Internal		Committed	50063727
42053862	1no broken 600x900 pcc flag	30/09/2020	Outside The Alexander Graham Bell	RD: FW Slabs Broken/Missing	Internal		Committed	50063729
42053856	1no broken cut pcc flag 300x600 1no rocking 300x600 pcc flag	30/09/2020	Centre island outside all saints	RD: FW Slabs Broken/Missing	Internal		Committed	50063723

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41064843 - Inspection Batch			Route: SE_FW1_GeorgeSt1			Date: 30/09/2020		
42053849	1no broken 600x900 pcc flag 1no rocking 600x600 pcc flag	30/09/2020	Outside 24	RD: FW Slabs Broken/Missing	Internal		Committed	50063716
42053858	Trip at Toby infill with grano	30/09/2020	Outside 79	RD: FW Grano Pothole	Internal		Committed	50063725
42053851	Rocking 600x900 pcc flag	30/09/2020	Outside no80 Hobart house	RD: FW Slabs Rocking	Internal		Committed	50063718
42053854	Remove broken grano and slab Replace with grano	30/09/2020	Outside the standing order	RD: FW Grano Cracked/Broken	Internal		Committed	50063721
42053853	Rocking tactile flag	30/09/2020	East side of Hanover st at the junction with queen st	RD: FW Slabs Rocking	Internal		Committed	50063720
Batch: 41063023 - Inspection Batch			Route: SE_CW1_Central1			Date: 08/09/2020		
No actionable defects found								
Batch: 41062043 - Inspection Batch			Route: Ad hoc Route			Date: 21/08/2020		
42052797	1no pothole	21/08/2020	Opposite the Slug and Lettuce in central parking bays	RD: CW Pothole	Internal		Committed	50060948
Batch: 41061831 - Inspection Batch			Route: SE_FW1_GeorgeSt1			Date: 19/08/2020		
42052632	2no broken 600x900 pcc flags 1no broken 600x600 pcc flags	18/08/2020	Outside 127	RD: FW Slabs Broken/Missing	Internal		Committed	50060624
Batch: 41061608 - Inspection Batch			Route: Ad hoc Route			Date: 13/08/2020		
42052523	1no pothole	13/08/2020	Outside Lakeland on pedestrian crossing	RD: CW Pothole	Internal		Committed	50060249
Batch: 41061453 - Inspection Batch			Route: SE_CW1_Central1			Date: 07/08/2020		
No actionable defects found								

Customer Services

Enquiry No.: 34003994	Logged by: [REDACTED]	on: 04/08/2021 13:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Low virgin media box - Could be brick chamber is starting to fail.		
Location: 69	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50088937	Defect Number: 42075180	
Enquiry No.: 34003080	Logged by: [REDACTED]	on: 04/02/2021 16:34
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: private coal Shute manhole cover missing on footway		
Location: O/S no 22	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 1353542 Service: Roads General Desc.: Location: Huge hole in the zebra crossing	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 29/03/2022 20:53 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50110709	Feature Id - Location: Whole Street Defect Number: 42098163	Feature Type: Road Asset	
Enquiry No.: 1342710 Service: Roads General Desc.: Location: Raised slab - all render has gone and it has become a trip hazard.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 10/03/2022 09:29 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50108713	Feature Id - Location: Whole Street Defect Number: 42095708	Feature Type: Road Asset	
Enquiry No.: 1341552 Service: Roads General Desc.: Location: At the pedestrian crossing there is a square plastic hole cover in the road (north side). It's badly cracked and looks as though a car wheel or pedestrian could soon go right through it	Logged by: Verint CRM Connector Subject: Public Utilities: General	on: 08/03/2022 13:59 Classification: Request for service	Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset	
Enquiry No.: 1336049 Service: Roads General Desc.: for over a month this taxi driver has not been able to access this area to go down hanover street to the waverley station. there are no roadworks there at all and driver is having to make a U turn and go round by york place on to queen street and left on to hanover street. can you please advise why barrier are there causing large obstruction Location: at corner of george street and hanover street travelling west outside the door lakeland plastics	Logged by: Subject: Roadworks: General Enquiry	on: 28/02/2022 12:55 Classification: General Enquiry	Contact:
Enquiry No.: 1325618 Service: Roads General Desc.: Location: 50mm gap between paving stone and drain cover on pavement outside Dome restaurant in George street Edinburgh. A photo can be provided.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 13/02/2022 14:08 Classification: Request for service	Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset	
Enquiry No.: 1322717 Service: Roads General Desc.: What type of sign is it? Road sign problem, type dontknow Location:	Logged by: Verint CRM Connector Subject: Roadworks: Defect	on: 08/02/2022 17:13 Classification: Request for service	Contact:

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 1300365 Logged by: Verint CRM Connector on: 04/01/2022 11:10
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:

Location: On 28th Dec 2021 I tripped on George St pavement at the approx location shown on the map. The paving slabs around the area I tripped were loose, raised and uneven. Contact:

[REDACTED]
[REDACTED] This pavement is dangerous and needs urgent attention.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1288237 Logged by: Verint CRM Connector on: 10/12/2021 11:59
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:

Location: raised slab on pavement outside to the LHS of the front door of the George Hotel - accident on this already reported and needs to be attended to ASAP Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Job Number: 50100233 Defect Number: 42087067

Enquiry No.: 1279860 Logged by: Verint CRM Connector on: 24/11/2021 12:43
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:

Location: Exposed drain. Dangerous. [REDACTED] tripped and fell onto roadway and was injured. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1277291 Logged by: Verint CRM Connector on: 18/11/2021 21:28
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:

Location: Road is blocked for cyclists even though it is supposed to be open for them during the ice rink construction. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1244814 Logged by: Verint CRM Connector on: 14/09/2021 13:42
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:

Location: pot hole after junction that resulted in two wheel bike puncture at 4.45pm on 13 September. result was narrowly avoided run over by car following. Highly dangerous moment. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1227946 Logged by: Verint CRM Connector on: 15/08/2021 16:57
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:

Location: Broken manhole cover outside 22. Looks to be a five foot or more drop. Someone has covered with a wooden palette for time being. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Job Number: 50090031 Defect Number: 42076311

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 1227219 **Logged by:** [REDACTED] **on:** 13/08/2021 12:28
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: Damaged man hole cover the customer has placed a wooden pallet over it for now
Location: Outside of the hard rock cafe **Contact:**

Enquiry No.: 1211202 **Logged by:** Verint CRM Connector **on:** 19/07/2021 19:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: more potholes in the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1204633 **Logged by:** Verint CRM Connector **on:** 08/07/2021 14:13
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Loose paving stone outside Whistles store in George Street. [REDACTED] had a nasty fall on 30/6/21, tripping on the loose paving stone. Passerby who came to [REDACTED] aid reported stone loose and wobbled when stood on. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50087316 **Defect Number:** 42073337

Enquiry No.: 1202684 **Logged by:** Verint CRM Connector **on:** 06/07/2021 00:33
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Hi there's a wee plastic cover in the pavement thst doesn't close properly. Quite a bad trip hazard. Location Outside the door of 111 George st. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1172693 **Logged by:** [REDACTED] **on:** 10/05/2021 13:47
Service: Roads General **Subject:** Street Furniture: General Enq **Classification:** General Enquiry
Desc.: Caller advises new fencing was put up at 120 George Street as an old fence fell down and caller claims CEC put cones and sandbags up around this time. The new fence is there and cones and sandbags are still there. Please arrange for removal.
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1152651 **Logged by:** Verint CRM Connector **on:** 02/04/2021 22:03
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Manhole cover completely bashed in in front of Lakeland on george street **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1151862 **Logged by:** [REDACTED] **on:** 01/04/2021 13:00
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: Hi. Broken manhole cover on George Street.
Location: It's at the Hard Rock Cafe, 20 George St. **Contact:**

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 1151759 **Logged by:** [REDACTED] **on:** 01/04/2021 10:47
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.: [REDACTED] - CEC parking attendant called to say that a lorry drove over a manhole cover and has smashed it to bits leaving a very large hole in the road. I will call Road ops to advise
Location: Outside The Royal Society of Edinburgh on George Street - 22 George street **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50080353 **Defect Number:** 42066373

Enquiry No.: 1140430 **Logged by:** Verint CRM Connector **on:** 15/03/2021 08:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge trench opening on pedestrian crossing **Contact:**
Category: Roads/highways
Another typical Edinburgh crossing, huge trench now opening up on the road.
Location:
Easting/Northing: 325143/673962 (55.952829, -3.200357)
Nearest road to the pin placed on the map (automatically generated by Bing Maps):
Edinburgh, EH2 2JR, GB
Nearest postcode to the pin placed on the map (automatically generated): EH2 3BX
(15m away)

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1138188 **Logged by:** [REDACTED] **on:** 10/03/2021 16:35
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** General Enquiry
Desc.: Anon caller reporting roadwork signs blown over by high winds - signs are located opposite assembly rooms
Location: **Contact:**

Enquiry No.: 1105304 **Logged by:** Verint CRM Connector **on:** 22/01/2021 15:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large deep pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50072705 **Defect Number:** 42059339

Enquiry No.: 1096418 **Logged by:** Verint CRM Connector **on:** 07/01/2021 12:04
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Footpath sunken next to bus stop, creates a large puddle at the waiting area for the bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1051121 **Logged by:** [REDACTED] **on:** 08/10/2020 09:05
Service: Roads General **Subject:** Street Furniture: General Enq **Classification:** General Enquiry
Desc.: Dumped road sign on George Street between Hanover Street and Fedrick Street.
Location: George Street between Hanover Street and Fedrick Street. **Contact:** [REDACTED]

Site History Report

Effective: 05/08/2020 to 06/04/2022
 Service: Roads General
 Site: George Street (7901802)

Asset Number: 1.00 to 3.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1045335 **Logged by:** [REDACTED] **on:** 25/09/2020 12:00
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: outside num ber 63 there is one glass slab broken safety hazard
Location: outside num ber 63 there is one glass slab broken safety hazard **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50064299

Enquiry No.: 1044872 **Logged by:** [REDACTED] **on:** 24/09/2020 13:18
Service: Roads General **Subject:** Roadworks: Defect **Classification:** Request for service
Desc.: is this abandoned sign going to adorn the George Street pavement for ever? There are two of them
Location: Block between Frederick st and Hanover Street north side. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1028560 **Logged by:** Verint CRM Connector **on:** 26/08/2020 15:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1025690 **Logged by:** [REDACTED] **on:** 20/08/2020 14:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: From: do-not-reply@edinburgh.gov.uk <do-not-reply@edinburgh.gov.uk>
 Sent: 20 August 2020 13:45
 To: Customer Care <Customer.Care@edinburgh.gov.uk>
 Subject: Email to be generated to Customer Care Team

CRM Number: 101000324126
 Reference Number:
 Customer name:
 Address:

Contact details: [REDACTED]

Customers Comment: On Monday 17th August, we parked in a bay on George St, directly opposite the Slug and Lettuce bar. The weather was wet with heavy rain. When I opened the passenger door and stepped out of the car, my foot went into a hole amongst the sett stones which had filled with water and not immediately detectable, resulting in a heavy fall, [REDACTED]. I have pictures of the hole [REDACTED]

Customers previous reported issue:
 Any previous reference numbers linking to current complaint:

Location: George Street. **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50060948 **Defect Number:** 42052797

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
1006360	Pavement: Damaged / Defective (Enquiry 352672) out side st Andrews church (RD: Paving Slabs)	dangerous paving slab outside St Andrews Church just a the bus stop . Called over [REDACTED]	RD: Cat 2 - 5 Day	Job Cancelled	11/05/2016	18/05/2016	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
1008114	3no broken and low cut flags causing trip (RD: Paving Slabs)	At Charlotte Square at pedestrian crossing on the north side	RD: Cat 3 - 60 Day	Job Cancelled	30/01/2017	27/02/2017	Est.
1008689	Loose grano at manhole (RD: Grano / Concrete)	Outside Amarone west of the phone boxes	RD: Cat 3 - 60 Day	Job Raised	16/03/2017	13/04/2017	Est.
1008691	1no high 600 x600 flag 2no broken 900 x600 pcc grey flag 1no broken 600 x600 pcc grey flag 1no low and broken cut flag (RD: Paving Slabs)	Outside no10 at the west end of taxi rank	RD: Cat 3 - 60 Day	Job Annulled	16/03/2017	13/04/2017	Est.
1008693	1no rocking 900 x600 pcc grey flag 3no broken 900 x600 pcc grey flag 3no broken 600 x600 pcc grey flag 1no low and broken cut flag at toby (RD: Paving Slabs)	At disabled access to the dome	RD: Cat 3 - 60 Day	Job Annulled	16/03/2017	13/04/2017	Est.
1008694	10no cracked 900 x600 pcc grey flags 1no cracked 600 x600 pcc grey flag (RD: Paving Slabs)	In front of the dome steps	RD: Cat 4 - 12 Months	Job Annulled	16/03/2017	16/03/2018	Est.
1008695	5no broken 900 x600 pcc grey flag 2no broken 600 x600 pcc grey flag 1no broken cut flag at box (RD: Paving Slabs)	At whynot	RD: Cat 3 - 60 Day	Job Annulled	16/03/2017	13/04/2017	Est.
1008704	4no broken 900 x600 pcc grey flags 2no broken 600 x600 pcc grey flags (RD: Paving Slabs)	Outside mint velvet	RD: Cat 3 - 60 Day	Job Cancelled	16/03/2017	13/04/2017	Est.
1008707	4no cracked 900 x600 pcc grey flags (RD: Paving Slabs)	Outside lowdown coffee	RD: Cat 4 - 12 Months	Job Annulled	16/03/2017	16/03/2018	Est.
1008708	1no cracked 600 x600 pcc grey flag 4no cracked 900 x600 pcc grey flags 1no low cut flag at box (RD: Paving Slabs)	Outside cheynes	RD: Cat 4 - 12 Months	Job Annulled	16/03/2017	16/03/2018	Est.
1008709	2no cracked 600 x600 pcc grey flags 1no cracked 900 x600 pcc grey flag 1no cracked 600 x300 pcc grey flag (RD: Paving Slabs)	Outside no66	RD: Cat 3 - 60 Day	Job Annulled	16/03/2017	13/04/2017	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
1008717	2no broken 900 x600 pcc grey flags 1no broken 600 x600 pcc grey flag (RD: Paving Slabs)	Outside no74	RD: Cat 3 - 60 Day	Job Raised	17/03/2017	14/04/2017	Est.
1008718	1no broken 900 x600 pcc grey flag (RD: Paving Slabs) 1no broken 600 x600 pcc grey flag (RD: Paving Slabs)	Outside Hollister	RD: Cat 4 - 12 Months	Job Annulled	17/03/2017	17/03/2018	Est.
1008720	4no cracked 600 x600 pcc grey flags 8no cracked 900 x600 pcc grey flag (RD: Paving Slabs)	Outside no80	RD: Cat 3 - 60 Day	Job Cancelled	17/03/2017	14/04/2017	Est.
1008722	4no cracked 600 x600 pcc grey flags 13no cracked 900 x600 pcc grey flag (RD: Paving Slabs)	Between rohan and Hackett	RD: Cat 4 - 12 Months	Job Annulled	17/03/2017	17/03/2018	Est.
1008724	5no cracked 600 x600 pcc grey flags 10no cracked 900 x600 pcc grey flag (RD: Paving Slabs)	Between the white company and no90	RD: Cat 4 - 12 Months	Job Annulled	17/03/2017	17/03/2018	Est.
1008725	Metal plate covering damaged manhole causing trip hazard (RD: Street Furniture)	Outside the white company	RD: Cat 2 - 5 Day	Job Cancelled	17/03/2017	24/03/2017	Est. RD01/10003945
1008728	1no cracked 600 x600 pcc grey flags 8no cracked 900 x600 pcc grey flag (RD: Paving Slabs)	Outside Cruise	RD: Cat 3 - 60 Day	Job Cancelled	17/03/2017	14/04/2017	Est.
1008729	1no broken 900 x600 cut pcc grey flag 1no broken 600 x600 pcc grey flag (RD: Paving Slabs)	Just east of the freemasons hall	RD: Cat 3 - 60 Day	Job Annulled	17/03/2017	14/04/2017	Est.
1008731	1no cracked 600 x600 pcc grey flags 7no cracked 900 x600 pcc grey flag (RD: Paving Slabs)	At the east side of Austin Reed	RD: Cat 3 - 60 Day	Job Cancelled	17/03/2017	14/04/2017	Est.
1008770	22no cracked 900 x600 pcc grey flags 9no cracked 600 x600 pcc grey flags 4m2 missing pcc grey flags (RD: Paving Slabs)	Outside no106	RD: Cat 4 - 12 Months	Job Annulled	28/03/2017	28/03/2018	Est.
1008771	11no cracked 900 x600 pcc grey flags 2no cracked 600 x600 pcc grey flags (RD: Paving Slabs)	Outside no108	RD: Cat 3 - 60 Day	Job Cancelled	28/03/2017	25/04/2017	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
1008774	11no cracked 900 x600 pcc grey flags 1no cracked 600 x600 pcc grey flag (RD: Paving Slabs)	Outside the Alexander Graham Bell	RD: Cat 3 - 60 Day	Job Cancelled	28/03/2017	25/04/2017	Est.
1008776	18no cracked 900 x600 pcc grey flags 5no cracked 600 x600 pcc grey flag Low grano at manhole (RD: Paving Slabs)	Outside no130	RD: Cat 4 - 12 Months	Job Annulled	28/03/2017	28/03/2018	Est.
1008780	6no cracked 900 x600 pcc grey flags 1no cracked 600 x600 pcc grey flag (RD: Paving Slabs)	Outside Las iguanas west door	RD: Cat 4 - 12 Months	Job Annulled	28/03/2017	28/03/2018	Est.
1008784	Missing flags infilled with deteriorating grano remove and replace with flags (RD: Grano / Concrete)	Just east of Brown's	RD: Cat 3 - 60 Day	Job Annulled	28/03/2017	25/04/2017	Est.
1008785	3no cracked 900 x600 pcc grey flags 3no cracked 600 x600 pcc grey flags 2no cracked cut flags (RD: Paving Slabs)	Between no127 and tiger lily	RD: Cat 4 - 12 Months	Job Annulled	28/03/2017	28/03/2018	Est.
1008787	Missing flags infilled with deteriorating grano remove and replace with flags (RD: Grano / Concrete)	Outside the church of Scotland offices	RD: Cat 4 - 12 Months	Job Annulled	28/03/2017	28/03/2018	Est.
1008788	4no cracked 900 x600 pcc grey flags 3no cracked 600 x600 pcc grey flags 5m of low kerb needs raised (RD: Paving Slabs)	Outside Anta	RD: Cat 3 - 60 Day	Job Cancelled	28/03/2017	25/04/2017	Est.
1008796	3no cracked 900 x600 pcc grey flags 2no cracked 600 x600 pcc grey flags 1no rocking cut flag next to box (RD: Paving Slabs)	Outside no101	RD: Cat 3 - 60 Day	Job Cancelled	28/03/2017	25/04/2017	Est.
1008797	Missing flags infilled with deteriorating grano remove and replace with flags (RD: Grano / Concrete)	Outside no95	RD: Cat 3 - 60 Day	Job Cancelled	28/03/2017	25/04/2017	Est.
1008805	Missing flags infilled with deteriorating grano remove and replace with flags 4no broken 900 x600 pcc grey flags (RD: Grano / Concrete)	Outside no79	RD: Cat 4 - 12 Months	Job Raised	28/03/2017	28/03/2018	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
 Service: Roads General
 Site: George Street (7901802)

Asset Number: 1.00 to 3.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
1008815	2no cracked 900 x600 pcc grey flags (RD: Paving Slabs)	Outside lululemon athletica	RD: Cat 4 - 12 Months	Job Raised	28/03/2017	28/03/2018	Est.
1008816	Missing flags infilled with deteriorating grano remove and replace with flags 11no broken 900 x600 pcc grey flags 4no 600 x600 pcc grey flags (RD: Grano / Concrete)	Outside phase eight	RD: Cat 4 - 12 Months	Job Raised	28/03/2017	28/03/2018	Est.
1008817	5no broken 900 x600 pcc grey flags 3no broken 600 x600 pcc grey flags 2no missing 900 x600 flags and 1no 600 x600 flag needs replaced (RD: Paving Slabs)	Outside no43	RD: Cat 3 - 60 Day	Job Raised	28/03/2017	25/04/2017	Est.
1008819	3no cracked cut pcc grey flags Broken grano at water toby (RD: Paving Slabs)	Outside Brian Drumm	RD: Cat 3 - 60 Day	Job Raised	28/03/2017	25/04/2017	Est.
1008825	7no broken 900 x600 pcc grey flags 2no broken 600 x600 pcc grey flags (RD: Paving Slabs)	Just east of Principal at ticket machine	RD: Cat 3 - 60 Day	Job Cancelled	28/03/2017	25/04/2017	Est.
1008826	6no cracked 900 x600 pcc grey flags 3no cracked 600 x600 pcc grey flags (RD: Paving Slabs)	Outside st andrews and st georges west	RD: Cat 4 - 12 Months	Job Raised	28/03/2017	28/03/2018	Est.
1008828	7no broken 900 x600 pcc grey flags 5no broken 600 x600 pcc grey flags 1no rocking 900 x600 yellow flag (RD: Paving Slabs)	Just west of bus stop GL	RD: Cat 3 - 60 Day	Job Annulled	28/03/2017	25/04/2017	Est.
1008829	3no broken 900 x600 pcc grey flags 1no rocking 900 x600 flag (RD: Paving Slabs)	8m east of bus stop GL	RD: Cat 3 - 60 Day	Job Cancelled	28/03/2017	25/04/2017	Est.
1008831	11no broken 900 x600 pcc grey flags 4no broken 600 x600 pcc grey flags (RD: Paving Slabs)	Between standard life door and traffic lights	RD: Cat 3 - 60 Day	Job Cancelled	28/03/2017	25/04/2017	Est.
1008835	2no broken 400 x400 charcoal tactile flags (RD: Paving Slabs)	On the traffic island at the junction of Hanover Street opposite Jones bootmakers	RD: Cat 3 - 60 Day	Job Annulled	29/03/2017	26/04/2017	Est.
1008837	2no rocking tactile flags 2no broken and low cut flags 2no broken cross cut flags Missing grano at box (RD: Paving Slabs)	On the traffic island at junction of Frederick Street opposite french connection	RD: Cat 3 - 60 Day	Job Raised	29/03/2017	26/04/2017	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
1008839	Missing grano at bollard and grey cabinet 1no missing 900 x600 pcc grey flag (RD: Grano / Concrete)	On the traffic island at junction of Frederick Street opposite Laing	RD: Cat 3 - 60 Day	Job Cancelled	29/03/2017	26/04/2017	Est.
1008844	Missing grano at toby 4no cracked 900 x600 pcc grey flags 3no cracked cut pcc grey flags (RD: Paving Slabs)	On the traffic island at junction of Charlotte Square	RD: Cat 3 - 60 Day	Job Raised	29/03/2017	26/04/2017	Est.
1009527	1no rocking 600 x600 pcc flag 1no broken cut flag (RD: Paving Slabs)	Behind bus stop GL at the ramp to undercroft cafe	RD: Cat 3 - 60 Day	Job Cancelled	16/05/2017	13/06/2017	Est.
1009678	1no rocking 900 x600 pcc grey flag (RD: Paving Slabs)	Outside Hamilton and Inches	RD: Cat 3 - 60 Day	Job Cancelled	07/06/2017	05/07/2017	Est.
1011121	Missing pole cover on nal socket (RD: Street Furniture)	Outside no116	RD: Cat 2 - 5 Day	Job Cancelled	29/11/2017	06/12/2017	Est. RD01/10005113
1011128	Missing pole cover on nal socket (RD: Street Furniture)	Outside no115	RD: Cat 2 - 5 Day	Job Cancelled	29/11/2017	06/12/2017	Est. RD01/10005120
50006278	7no broken 900 x600 pcc flags 1no broken cut 900 x600 pcc flag 2no sunken 900 x600 pcc flags 1no rocking 600x600 grey pcc flag (RD: FW Slabs Broken/Missing)	Outside no102	RD: Cat 3 - 60 Day	Job Cancelled	06/04/2018	04/05/2018	Est. ROAD/82005078
50060249	1no pothole (RD: CW Pothole)	Outside Lakeland on pedestrian crossing	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/08/2020	13/08/2020	Act. ROAD/82038668
50060624	2no broken 600x900 pcc flags 1no broken 600x600 pcc flags (RD: FW Slabs Broken/Missing)	Outside 127	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/08/2020	20/08/2020	Act. ROAD/82038745
50060948	1no pothole (RD: CW Pothole)	Opposite the Slug and Lettuce in central parking bays	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/08/2020	24/08/2020	Act. ROAD/82038854
50063713	Relay dislodged kerb Relay slab and renew granite (RD: FW Kerb Dislodged/Rocking)	At the junction with Saint Andrew square	RD: Cat 2 - 5 Day	Job Complete	30/09/2020	01/10/2020	Act. ROAD/82039823
50063716	1no broken 600x900 pcc flag 1no rocking 600x600 pcc flag (RD: FW Slabs Broken/Missing)	Outside 24	RD: Cat 3 - 60 Day	Job Complete	30/09/2020	01/10/2020	Act. ROAD/82039826
50063718	Rocking 600x900 pcc flag (RD: FW Slabs Rocking)	Outside no80 Hobart house	RD: Cat 3 - 60 Day	Job Complete	30/09/2020	01/10/2020	Act. ROAD/82039828

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50063720	Rocking tactile flag (RD: FW Slabs Rocking)	East side of Hanover st at the junction with queen st	RD: Cat 3 - 60 Day	Job Complete	30/09/2020	01/10/2020	Act. ROAD/82039830
50063721	Remove broken grano and slab Replace with grano (RD: FW Grano Cracked/Broken)	Outside the standing order	RD: Cat 3 - 60 Day	Job Complete	30/09/2020	01/10/2020	Act. ROAD/82039831
50063723	1no broken cut pcc flag 300x600 1no rocking 300x600 pcc flag (RD: FW Slabs Broken/Missing)	Centre island outside all saints	RD: Cat 3 - 60 Day	Job Complete	30/09/2020	10/10/2020	Act. ROAD/82039833
50063725	Trip at Toby infill with grano (RD: FW Grano Pothole)	Outside 79	RD: Cat 3 - 60 Day	Job Complete	30/09/2020	10/10/2020	Act. ROAD/82039835
50063727	Renew broken grano (RD: FW Grano Cracked/Broken)	Outside 112	RD: Cat 3 - 60 Day	Job Complete	30/09/2020	01/10/2020	Act. ROAD/82039837
50063729	1no broken 600x900 pcc flag (RD: FW Slabs Broken/Missing)	Outside The Alexander Graham Bell	RD: Cat 3 - 60 Day	Job Complete	30/09/2020	01/10/2020	Act. ROAD/82039839
50064299	Pavement: Damaged / Defective - Place wa kboard outside No. 63 (Enquiry 1045335)	outside num ber 63 there is one glass slab broken safety hazard	RD: Cat 2 - 5 Day	Job Complete	07/10/2020	09/10/2020	Act. ROAD/82040084
50066087	Low manhole cover causing damage to surround. (RU: Utility Apparatus)	At the pedestrian crossing next to 'Baba' on the junction of charlotte square.	RU: Fail Med.Risk (Apparatus)	Job Complete	02/11/2020	29/12/2020	Act.
50066090	Sunken broken grano at tact tiles and 2 no rocking slabs (RD: FW Grano Depression/Sunken)	Outside victor hugo deli at tact tiles	RD: Cat 3 - 60 Day	Job Complete	02/11/2020	05/11/2020	Act. ROAD/82040828
50068555	Renew broken grano at box (RD: FW Grano Cracked/Broken)	Outside All Saints	RD: Cat 3 - 60 Day	Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041785
50068560	1no rocking flag (RD: FW Slabs Rocking)	Outside no84	RD: Cat 3 - 60 Day	Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041788
50068563	1no broken 600x900 PCC flag (RD: FW Slabs Broken/Missing)	Outside no100	RD: Cat 3 - 60 Day	Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041789
50068564	1no broken 600x900 PCC flag (RD: FW Slabs Broken/Missing)	Outside Fazenda	RD: Cat 3 - 60 Day	Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041790
50068571	1no broken 600x900 cut pcc flag (RD: FW Slabs Broken/Missing)	Outside Slug & lettuce	RD: Cat 3 - 60 Day	Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041793
50068574	1no broken 600x900 pcc flag (RD: FW Slabs Broken/Missing)	Outside Anthropologie	RD: Cat 3 - 60 Day	Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041795
50068576	1no rocking flag (RD: FW Slabs Rocking)	Outside no37	RD: Cat 3 - 60 Day	Job Complete	30/11/2020	01/12/2020	Act. ROAD/82041797
50069315	1 broken cut 600x900 1 rocking 600x900 and renew grano at box 1 broken 600x900 at entrance (RD: FW Slabs Broken/Missing)	Outside victor hugo deli	RD: Cat 3 - 60 Day	Job Complete	08/12/2020	17/12/2020	Act. ROAD/82042177
50070516	1 rocking 600x900 pcc flag 1 broken 600x750 pcc flag 1rocking 600x600 pcc flag (RD: FW Slabs Rocking)	Outside no91	RD: Cat 3 - 60 Day	Job Complete	18/12/2020	05/03/2021	Act. ROAD/82042722

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50070517	1 rocking 600x900 pcc flag 1 rocking 450x600 pcc flag (RD: FW Slabs Rocking)	Outside All Bar One	RD: Cat 3 - 60 Day	Job Annulled	18/12/2020	12/03/2021	Est. ROAD/82042723
50070522	2no broken 600x900 pcc flags 1no rocking 600x900 pcc flag (RD: FW Slabs Broken/Missing)	Approx 5m east of The Dome	RD: Cat 3 - 60 Day	Job Complete	18/12/2020	27/02/2021	Act. ROAD/82042728
50070524	4no broken 600x900 pcc flags (RD: FW Slabs Broken/Missing)	Outside British Study Centres next to bus stop GS	RD: Cat 3 - 60 Day	Job Complete	18/12/2020	09/03/2021	Act. ROAD/82042731
50072705	1no pothole (RD: CW Pothole)	Outside the Dom	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/01/2021	26/01/2021	Act. ROAD/82043637
50072993	Broken/Loose 900 x 600 please renew (RD: FW Slabs Broken/Missing)	O/S The Dome(Nearest west exit)	RD: Cat 3 - 60 Day	Job Complete	27/01/2021	15/03/2021	Act. ROAD/82043797
50072998	Broken/Loose 900 x 600 please renew (RD: FW Slabs Broken/Missing)	O/S no 22	RD: Cat 3 - 60 Day	Job Complete	27/01/2021	10/03/2021	Act. ROAD/82043801
50073017	2 x Broken/Loose 900 x 600 please renew also remove cold tar and replace with a slab (RD: FW Slabs Broken/Missing)	O/S Church Of Scotland offices	RD: Cat 3 - 60 Day	Job Complete	27/01/2021	17/03/2021	Act. ROAD/82043813
50073022	Loose / broken slab needs renewed and loose cut needs reset (RD: FW Slabs Broken/Missing)	At North Castle St. (ESPC)	RD: Cat 3 - 60 Day	Job Complete	27/01/2021	10/03/2021	Act. ROAD/82043817
50073027	Loose / broken slab needs renewed (RD: FW Slabs Broken/Missing)	Approx 10m west of 1Standard Life main door	RD: Cat 3 - 60 Day	Job Complete	27/01/2021	10/03/2021	Act. ROAD/82043821
50076372	x2 Broken 900mm PCC. (RD: FW Slabs Broken/Missing)	Outside gusto.	RD: Cat 3 - 60 Day	Job Complete	24/02/2021	23/03/2021	Act. ROAD/82045681
50076373	Red PCC cut damaged around manhole. (RD: FW Slabs Broken/Missing)	Next to browns.	RD: Cat 3 - 60 Day	Job Complete	24/02/2021	24/03/2021	Act. ROAD/82045682
50076374	x4 missing PCC which has been replaced with deteriorating grano. Lift grano and replace with slabs. (RD: FW Slabs Broken/Missing)	Next to browns.	RD: Cat 3 - 60 Day	Job Complete	24/02/2021	23/03/2021	Act. ROAD/82045683
50076375	Low manhole cover which has resulted in numerous trip hazards in the surrounding area. (RU: Utility Apparatus)	Next to parking meter just along from Hadeel	RU: Fail Med.Risk (Apparatus)	Job Complete	24/02/2021	26/02/2021	Act.
50076377	x2 rocking red tactile paving slab. Lift and replace. (RD: FW Slabs Rocking)	At ped crossing in junction of Charlotte square.	RD: Cat 4 - 12 Months	No code allocated	24/02/2021	24/02/2022	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
 Service: Roads General
 Site: George Street (7901802)

Asset Number: 1.00 to 3.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50076379	Rocking red 600x600 PCC slab. Lift and relay. (RD: FW Slabs Rocking)	Oustide 114.	RD: Cat 3 - 60 Day	Job Complete	24/02/2021	12/03/2021	Act. ROAD/82045686
50076380	x1 rocking buff PCC slab. Lift and relay. (RD: FW Slabs Rocking)	Oustide knight property group.	RD: Cat 3 - 60 Day	Job Complete	24/02/2021	24/03/2021	Act. ROAD/82045687
50076489	x1 broken buff PCC slab. Lift and replace. (RD: FW Slabs Rocking)	Oustide the royal society of Edinburgh.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	24/03/2021	Act. ROAD/82045746
50076491	CW pothole, make safe with HRA. (RD: CW Pothole)	Outside the dome/why not.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/02/2021	26/02/2021	Act. ROAD/82045747
50076492	Setts missing from central parking bays. Make safe with HRA in the interim. (RD: CW Setts Damaged/Missing)	Outside burr & co.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/02/2021	24/03/2021	Act. ROAD/82045748
50076493	x1 broken red PCC slab 900x600. Lift and replace. (RD: FW Slabs Broken/Missing)	Outside lowdown coffee.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	24/03/2021	Act. ROAD/82045749
50076495	x6 broken PCC slab 900x600. Lift and replace with grey PCC. (RD: FW Slabs Broken/Missing)	Between hawes & Curtis and British study centres.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	24/03/2021	Act. ROAD/82045750
50076497	Small section of grano which ha broke away leaving an open joint. Make safe with fresh grano. (RD: FW Grano Open Joint)	Outside Freemasons hall.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	24/03/2021	Act. ROAD/82045751
50076498	x3 loose/dislodged blocks within central pedestrian crossing. Lift and relay. (RD: FW Blocks Dislodged/Loose)	Opposite ESPC.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	24/03/2021	Act. ROAD/82045752
50076500	CW pothole next to service cover, make safe with HRA. (RD: CW Pothole)	At junction of north castle street next to George street monument.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/02/2021	26/02/2021	Act. ROAD/82045754
50076501	x1 broken PCC slab 900x600. Lift and replace with grey PCC. Small pcc cut adjacent which is rocking, lift and relay. (RD: FW Slabs Broken/Missing)	Oustide ESPC.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	24/03/2021	Act. ROAD/82045755
50076502	x1 rocking 600x600 pcc slab, lift and replace. (RD: FW Slabs Rocking)	Oustide 91.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	24/03/2021	Act. ROAD/82045756

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50076504	CW next ped crossing has deteriorated significantly. Overlay with HRA and remove any loose HRA prior to overlay. Approx 4x2m overlay. Strengthening/deeper patching is required at a later date. (RD: CW Cracked/Broken)	At ped crossing outside fat face.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	18/04/2021	Act. ROAD/82045758
50076505	x8 broken PCC slab 900x600. Lift and replace with grey PCC. (RD: FW Slabs Broken/Missing)	Outside anthropologie.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	26/03/2021	Act. ROAD/82045759
50076509	x4 broken PCC slab 900x600. Lift and replace with grey PCC. (RD: FW Slabs Broken/Missing)	Central ped crossing outside all saints.	RD: Cat 3 - 60 Day	Job Complete	25/02/2021	30/03/2021	Act. ROAD/82045760
50076621	Missing setts/depression which has left a small trip hazard on 3 setts. Make safe with HRA until proper reinstatement is carried out with cobbles. (RD: CW Setts Depression)	In central parking area across from 10 George street.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/02/2021	19/04/2021	Act. ROAD/82045831
50076623	Significant cracking on transverse track. Overlay with HRA. (RD: CW Cracked/Broken)	Outside Starbucks's.	RD: Cat 3 - 60 Day	Job Complete	26/02/2021	18/04/2021	Act. ROAD/82045833
50076624	x1 rocking 900x600 grey pcc slab Lift and replace. (RD: FW Slabs Broken/Missing)	Outside phase eight and Hobbs.	RD: Cat 3 - 60 Day	Job Complete	26/02/2021	31/03/2021	Act. ROAD/82045834
50076625	CW around double service cover is cracking and is showing signs of further deterioration. Make safe with HRA in the interim. At time of full repair deeper patching should be taken into consideration and the patch should also be stepped around double service cover. (RD: CW Cracked/Broken)		RD: Cat 3 - 60 Day	Job Annulled	26/02/2021	21/05/2021	Est. ROAD/82045835

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50076626	CW is showing signs of deeper cracking which may be penetrating the DBM layer. Overlay with HRA in the interim. Requires deeper/strengthening patching at time of final repair. (RD: CW Cracked/Broken)	At ped crossing on junction of Frederick street outside fatface.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/02/2021	18/04/2021	Act. ROAD/82045836
50079716	1no rocking 900x600 pcc grey flag (RD: FW Slabs Rocking)	Outside no10	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079717	2no broken 900x600 pcc grey flags 4no rocking 900x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside the Dome	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079718	2no broken 900x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside whynot	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079719	10no broken 900x600 pcc grey flags 1no rocking 900x600 pcc grey flag (RD: FW Slabs Broken/Missing)	Outside le monde	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079720	1no broken 600x600 pcc grey flag 2no broken 900x600 pcc grey flag (RD: FW Slabs Broken/Missing)	Outside Hard Rock Cafe	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079721	5no broken 900x600 pcc grey flags 1no rocking 900x600 pcc grey flag (RD: FW Slabs Broken/Missing)	Between no22 and no24	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079724	7no broken 900x600 pcc grey flags 3no rocking 900x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Lakeland	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079725	15no broken 900x600 pcc grey flags 5no rocking 900x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between no36-38	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50079727	5no broken 900x600 pcc grey flags 1no broken 750x600 pc grey flag (RD: FW Slabs Broken/Missing)	Outside Charles Tyrwhitt	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079731	1no broken 900x600 pcc grey flag (RD: FW Slabs Broken/Missing)	Outside finisterre	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079732	1no broken 600x600 pcc grey flag (RD: FW Slabs Broken/Missing)	Outside the Standing Order	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079733	2no broken 900x600 pcc grey flags 1no sunken 900x600 pcc grey flag 1no rocking cross cut flag (RD: FW Slabs Broken/Missing)	Outside All Saints	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079734	2no broken 900x600 pcc flags 1no broken cut 450x600 pcc flags (RD: FW Slabs Broken/Missing)	Outside no76	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079735	4no cracked 600 x600 pcc grey flags 8no cracked 900 x600 pcc grey flag (RD: FW Slabs Broken/Missing)	Outside no80	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079736	8no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Gant	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079737	5no broken 900x600 pc grey flags 3no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Xile	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079739	1no cracked 600 x600 pcc grey flags 8no cracked 900 x600 pcc grey flag (RD: FW Slabs Broken/Missing)	Outside Cruise	RD: Cat 4 - 12 Months	No code allocated	26/03/2021	26/03/2022	Est.
50079740	1no cracked 600 x600 pcc grey flags 7no cracked 900 x600 pcc grey flag (RD: FW Slabs Broken/Missing)	At the east side of Austin Reed	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50079741	4no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags 1no rocking 900x600 pc red flag (RD: FW Slabs Broken/Missing)	Between fazenda and no102	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079742	24no broken 900x600 pc grey flags 8no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside no110	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079743	6no broken 900x600 pc grey flags 1no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between TSB and no106	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079744	11no cracked 900 x600 pcc grey flags 1no cracked 600 x600 pcc grey flag (RD: FW Slabs Broken/Missing)	Outside the Alexander Graham Bell	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079745	14no broken 900x600 pc grey flags 6no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between Alexander Graham Bell and Baba	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079746	9no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between Baba and Charlotte Square	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079747	Carriageway cracked and overlaid approx 5mx3m (RD: CW Cracked/Broken)	Westbound lane at junction of Charlotte Square	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079748	11no broken 900x600 pc grey flags 3no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside las iguanas	RD: Cat 4 - 12 Months	Job Annulled	26/03/2021	26/03/2022	Est.
50079876	6no broken 900x600 pc grey flags 1no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside no137A	RD: Cat 4 - 12 Months	No code allocated	29/03/2021	29/03/2022	Est.
50079877	8no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Browns	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
 Service: Roads General
 Site: George Street (7901802)

Asset Number: 1.00 to 3.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50079878	1no broken 900x600 pc grey flags broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Tigerlily	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079879	5no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between Hadeel and parking machine	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079880	4no cracked 900 x600 pcc grey flags 3no cracked 600 x600 pcc grey flags 5m of low kerb needs raised (RD: FW Slabs Broken/Missing)	Outside Anta	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079881	17no broken 900x600 pc grey flags 5no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between no115 and the slug and lettuce	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079882	11no broken 900x600 pc grey flags 3no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside slug and lettuce between phone box and no111	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079883	1no broken 900x600 pc grey flags 4no sunken 900x600 pc grey flags (RD: FW Slabs Broken/Missing)	At the east corner of North Castle Street	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079884	6no broken 900x600 pc grey flags 3no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Space NK	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079885	11no broken 900x600 pc grey flags 6no broken 600x600 pcc grey flags 2no cut 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Contini	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079886	7no broken 900x600 pc grey flags 5no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Whistles	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079887	Missing flags infilled with deteriorating grano remove and replace with flags (RD: CW Cracked/Broken)	Outside no95	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50079888	3no broken 900x600 pc grey flags broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Jo Malone	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079889	9no broken 900x600 pc grey flags (RD: FW Slabs Broken/Missing)	Outside no91	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079890	7no broken 900x600 pc grey flags 3no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Joules	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079891	4no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Clydesdale bank	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079892	1no sunken kerb (RD: FW Kerb Dislodged/Rocking)	Outside Clydesdale bank	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079893	4no broken 900x600 pc grey flags (RD: FW Slabs Broken/Missing)	Outside Cafe Andaluz	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079894	1no broken 900x600 pc grey flag 3no cut 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside the Bank of Scotland	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079895	10no broken 900x600 pc grey flags 1no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Nationwide	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079896	4no broken 900x600 pc grey flags 3no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	On the east corner of Hanover Street at fatface	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079897	Overlaid broken area of asphalt needs patching approx 4mx2m (RD: CW Cracked/Broken)	Eastbound lane on zebra crossing outside fatface	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079898	8no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside sweaty betty	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079899	6no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Jack Wills	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079900	3no broken 900x600 pc grey flags (RD: FW Slabs Broken/Missing)	Outside lyle and scott	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50079901	11no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Coast and Churchs	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079902	21no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between luluemon athletica and Karen millen	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079903	11no broken 900x600 pc grey flags 7no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between Laura Ashley and Jigsaw	RD: Cat 4 - 12 Months	No code allocated	29/03/2021	29/03/2022	Est.
50079905	6no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Hobbs	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079906	5no broken 900x600 pc grey flags 1no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside no45a	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079907	11no broken 900 x600 pcc grey flags 4no broken 600 x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between standard life door and traffic lights	RD: Cat 4 - 12 Months	Job Annulled	29/03/2021	29/03/2022	Est.
50079931	21no broken 900x600 pc grey flags 2no broken cut 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between the entrance to Aberdeen standard investments and the black bin	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50079933	2no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside standard life just west of black bin	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50079936	3no broken 900 x600 pcc grey flags 1no rocking 900 x600 flag (RD: FW Slabs Broken/Missing)	8m east of bus stop GL	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50079937	7no broken 900 x600 pcc grey flags 2no broken 600 x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Just east of Principal at ticket machine	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50079939	10no broken 900x600 pc grey flags 3no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside the Principal George Street	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50079940	3no broken 900x600 pc grey flags 3no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside Burr and co	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50079946	2no broken 900x600 pc grey flags 2no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Outside the printing press	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50079948	5no broken 900x600 pc grey flags (RD: FW Slabs Broken/Missing)	Between sta travel and Hanover Street	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50079949	14no broken 900x600 pc grey flags 10no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between no37 and sta travel	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50079954	10no broken 900x600 pc grey flags 4no broken 600x600 pcc grey flags (RD: FW Slabs Broken/Missing)	Between no39 and Bobbi Brown	RD: Cat 4 - 12 Months	Job Annulled	30/03/2021	30/03/2022	Est.
50080353	Collapsed coal chute cover please make safe with walkboard (RD: FW Cover Make Safe)	Outside no22	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	01/04/2021	01/04/2021	Act. ROAD/82048164
50081140	CW around double service cover is cracking and is showing signs of further deterioration. Make safe with HRA in the interim. At time of full repair deeper patching should be taken into consideration and the patch should also be stepped around double service cover. (RU: Utility Apparatus)		RU: Fail Low Risk	Job Complete	15/04/2021	16/04/2021	Act. ROAD/82048623
50081404	x4 rocking PCC slabs. Lift and relay. (RD: FW Slabs Rocking)	At all bar one at junction of Hanover street.	RD: Cat 3 - 60 Day	Job Complete	20/04/2021	28/04/2021	Act. ROAD/82048760

Site History Report

Effective: 05/08/2020 to 06/04/2022

Service: Roads General

Site: George Street (7901802)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50081405	x1 rocking 600x600 PCC slabs. Lift and relay. (RD: FW Slabs Rocking)	Opposite NatWest at the old Starbucks.	RD: Cat 3 - 60 Day	Job Complete	20/04/2021	28/04/2021	Act. ROAD/82048761
50082455	Missing cat post (RD: SFP Damaged Bollard)		RD: Cat 3 - 60 Day	Job Complete	06/05/2021	03/06/2021	Act. ROAD/82049366
50083217	2 broken 600x900 pcc slabs 1 rocking 600x900 (RD: FW Slabs Broken/Missing)	Outside fazenda	RD: Cat 3 - 60 Day	Job Complete	17/05/2021	25/05/2021	Act. ROAD/82049796
50083219	1 broken cut at manhole 1 rocking cut at manhole (RD: FW Slabs Broken/Missing)	Outside the white company	RD: Cat 3 - 60 Day	Job Complete	17/05/2021	26/05/2021	Act. ROAD/82049798
50083227	1 broken 600x900 (RD: FW Slabs Broken/Missing)	Outside burr & co	RD: Cat 3 - 60 Day	Job Complete	17/05/2021	08/07/2021	Act. ROAD/82049801
50083229	1 low and rocking 600x900 pcc slab (RD: FW Slabs Rocking)	Outside lululemon athletica	RD: Cat 3 - 60 Day	Job Complete	17/05/2021	19/05/2021	Act. ROAD/82049803
50083231	1 rocking cut at kerb edge 2 no rocking cross cut 600x900s Renew grano (RD: FW Slabs Rocking)	Junction with Frederick at	RD: Cat 3 - 60 Day	Job Complete	17/05/2021	26/05/2021	Act. ROAD/82049804
50083234	1 rocking 600x600 (RD: FW Slabs Rocking)	Outside cafe andaluz	RD: Cat 3 - 60 Day	Job Complete	17/05/2021	19/05/2021	Act. ROAD/82049807
50083235	1 broken 600x900 (RD: FW Slabs Broken/Missing)	Junction at north castle st	RD: Cat 3 - 60 Day	Job Complete	17/05/2021	26/05/2021	Act. ROAD/82049808
50087096	x1 broken cut 900x600 pcc. x3 rocking cut 900x600 pcc. (RD: FW Slabs Broken/Missing)	Outside all saints at ped crossing.	RD: Cat 3 - 60 Day	Job Complete	09/07/2021	23/07/2021	Act. ROAD/82051870
50087316	Rocking slab please make safe (RD: FW Slabs Rocking)	George street os 95	RD: Cat 3 - 60 Day	Job Complete	13/07/2021	23/07/2021	Act. ROAD/82051950
50088937	Sunken catv manhole (RU: Utility Apparatus)	Eastbound carriageway outside no69A	RU: Fail Med.Risk (Apparatus)	Job Complete	05/08/2021	06/08/2021	Act.
50090031	Broken coal chute cover on footway make safe with wallboard and cones And remove pallet (RD: CW Covers Make Safe)	Outside number 22 and 24	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/08/2021	19/08/2021	Act. ROAD/82053400
50100233	1no rocking 900x600 pcc flag (RD: FW Slabs Rocking)	Outside the Intercontinental Hotel	RD: Cat 2 - 5 Day	Job Complete	14/12/2021	15/12/2021	Act. ROAD/82057579
50101429	x2 broken 900x600 pcc, lift and replace. (RD: FW Slabs Broken/Missing)	Opposite old nationwide offices.	RD: Cat 3 - 60 Day	Job Complete	24/12/2021	10/01/2022	Act. ROAD/82058004
50101430	x2 broken 900x600 pcc, lift and replace. (RD: FW Slabs Broken/Missing)	Opposite the dome.	RD: Cat 3 - 60 Day	Job Complete	24/12/2021	10/01/2022	Act. ROAD/82058005
50101431	x4 CW pothole, make safe. (RD: CW Pothole)	At junction of north castle street.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/12/2021	29/12/2021	Act. ROAD/82058006

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50101432	x3 rocking tactiles, lift and relay. Infill grano pothole with mortar mix. (RD: FW Slabs Rocking)	Opposite Charlotte square at ped crossing.	RD: Cat 3 - 60 Day	Job Complete	24/12/2021	10/01/2022	Act. ROAD/82058007
50101434	x1 rocking tactiles, lift and relay. (RD: FW Slabs Rocking)	Outside Lakeland.	RD: Cat 3 - 60 Day	Job Complete	24/12/2021	11/01/2022	Act. ROAD/82058009
50104247	x1 rocking pcc, lift and relay. (RD: FW Slabs Rocking)	Outside old NatWest next to the dome.	RD: Cat 3 - 60 Day	Job Complete	25/01/2022	27/01/2022	Act. ROAD/82059318
50104248	Open grano joint at box. (RD: FW Grano Open Joint)	Outside why not.	RD: Cat 3 - 60 Day	Job Complete	25/01/2022	27/01/2022	Act. ROAD/82059319
50107483	Pothole at Frederick street junction, make safe. (RD: CW Pothole)	At junction of Fredrick street.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/02/2022	01/03/2022	Act. ROAD/82060973
50108713	1no rocking 600x600 pcc flag (RD: FW Slabs Rocking)	Outside the Dome	RD: Cat 2 - 5 Day	Job Complete	10/03/2022	11/03/2022	Act. ROAD/82061549
50109908	x2 broken 900x600 pcc slabs, lift and replace. (RD: FW Slabs Rocking)	Outside le monde.	RD: Cat 3 - 60 Day	Job Complete	22/03/2022	28/03/2022	Act. ROAD/82062124
50109935	Grano open joint next to Toby, make safe. (RD: FW Grano Open Joint)	Outside 69a.	RD: Cat 3 - 60 Day	Job Complete	22/03/2022	24/03/2022	Act. ROAD/82062139
50109937	x1 rocking tactile and cut within recessed cover, relay or replace with new charcoal tactile. x1 broken cut slab within cover, lift and relay. Repair any Grano surround where required. (RD: FW Slabs Rocking)	Outside fat face.	RD: Cat 3 - 60 Day	Job Complete	22/03/2022	24/03/2022	Act. ROAD/82062141
50109939	Grano open joint next to NAL service cover and double service box, make safe. (RD: FW Grano Open Joint)	Outside fat face.	RD: Cat 3 - 60 Day	Job Complete	22/03/2022	24/03/2022	Act. ROAD/82062142
50109943	x1 broken 600x600 pcc slab, lift and replace. (RD: FW Slabs Broken/Missing)	Outside 101.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/03/2022	24/03/2022	Act. ROAD/82062146
50109944	x1 broken 900x600 pcc slab next to service cover, lift and replace. (RD: FW Slabs Broken/Missing)	Outside candy bar.	RD: Cat 3 - 60 Day	Job Complete	22/03/2022	28/03/2022	Act. ROAD/82062147
50109947	x3 Grano potholes/open joints. Make safe. (RD: FW Grano Pothole)	Outside Eden Locke.	RD: Cat 3 - 60 Day	Job Complete	22/03/2022	28/03/2022	Act. ROAD/82062149

Site History Report

Effective: 05/08/2020 to 06/04/2022
Service: Roads General
Site: George Street (7901802)

Asset Number: 1.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50109950	x1 Grano pothole/open joint. Make safe. (RD: FW Grano Pothole)	Outside 108 and Fred's next to tactile paving.	RD: Cat 3 - 60 Day	Job Complete	22/03/2022	24/03/2022	Act. ROAD/82062151
50110706	1no pothole (RD: CW Pothole)	Outside no29	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/03/2022	31/03/2022	Act. ROAD/82062539
50110709	1no pothole (RD: CW Pothole)	On the zebra crossing outside NatWest	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/03/2022	30/03/2022	Act. ROAD/82062542