

36706

The gates at the bottom of the Italian Garden in Lauriston Castle have recently been painted by the firm P1.

Please provide the:

specific specifications given/presented to P1 to carry out the work – This work was commissioned due to the condition of the gate.

The specification for this work was to paint using Hammerite black gloss direct to rust.

dates between which the work was carried out

The contractor was on site between 14 and 21 February 2022.

specific type of paint used and whether it addressed/combated the rust that was on the gate

As above. The formulation of paint designed for use in these circumstances is a durable, corrosion resistant decorative coating for ferrous and non-ferrous metals.

quality assurance post work carried out – the undersides have not been fully painted.

The work was inspected following completion and it was noted that the underside was painted where the ground levels allowed.

cost of work carried out separating between the cost of materials, labour and other costs

This work was completed at no cost to the Council.