

36719 Trams to Newhaven – Vibration

Where were vibration monitors located during the period of construction / works from November 2019 – end of November 2020.

There is one permanently located noise and vibration monitor at 119 Constitution Street.

Did the four photographs received as part of EDIR:35277 constitute the external survey of non-listed buildings which the Council's public documentation refers to?

Yes, the four photographs constitute the photographic record of the outside of the building.