

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Site: Queensferry Road (7902503)

Locality: Edinburgh, City of Edinburgh

Area: North West Locality

Customer Services

Enquiry No.: 34004921 **Logged by:** [REDACTED] **on:** 08/03/2022 11:05
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: lack of road marking on the Queensferry Road A90 between the main junction between Maybury Road heading west towards the Forth Road bridge iit's particularly bad for about 2 miles from the junction.
Location: Queensferry road A90 **Contact:** [REDACTED]

Enquiry No.: 1349195 **Logged by:** Verint CRM Connector **on:** 22/03/2022 11:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Manholes x 2 Queensferry Road eh4 7qd - between 501-507 main road outside lane. **Contact:**
Across from sign of Parkgrove Shopping Centre .

Eh4 7qd- between 497-501
Gully grates dropped down

All buses and juggernaut thundering across them constantly therefore the weight bearing of said vehicle ,load causing a constant exploding sound
Road usage should be considered when replacing old for new, as Queensferry Road Edinburgh is a road that's like an airport 24/7. No rest.

Regards
[REDACTED]

Plot Number: 2.00

Feature Id - Location: Ward 1 - From Craigcrook Road to Barnton Junction

Feature Type: Road Asset

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Customer Services

Enquiry No.: 1347265 **Logged by:** [REDACTED] **on:** 18/03/2022 11:16
Service: Roads General **Subject:** Spill: Oil / Petrol / Diesel **Classification:** Customer Emergency
Desc.: From: [REDACTED]
Date: Friday, March 18, 2022, 8:10:23 AM
To: customer.care@edinburgh.gov.uk <customer.care@edinburgh.gov.uk>
Subject: diesel fuel spill-Queensferry Road

PUBLIC

Dear Sirs

We have had the following report from a member of the public regarding a spill.

If someone could have a look and see if any think could be done that would be appreciated.

Edinburgh, Queensferry Road.

From Dean Bridge (at Water of Leith) for some distance.

"continued for perhaps a mile until [he] turned off, heading towards the Forth Bridge"

Area that he saw appeared to run from Dean Bridge to lights at Craigleith shopping centre/Craigleith Road.

That is approximately 1.9KM, but is not a watercourse – nearest approach is obviously at Dean Bridge but thereafter distance from w/c increases, at furthest extent seen (Craigleith/Queensferry Road junctions) it is >1KM to the Water of Leith and c.800m to the u/n w/c at Orchard Brae Gardens.

Customer's concern is that it will go to drains/etcetera and we have advised that surface water in the area is likely to go to Scottish Water treatment, SEPA's role is for w/c. As there is some at the bridge have taken a report but have advised to contact City of Edinburgh and gave (or at least attempted to) contact details for that.

Regards

[REDACTED]

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Customer Services

Environment Protection Officer

Disclaimer

The information contained in this email and any attachments may be confidential and is intended solely for the use of the intended recipients.

Access, copying or re-use of the information in it by any other is not authorised. If you are not the intended recipient please notify us

immediately by return email to postmaster@sepa.org.uk.

Registered office: Strathallan House, Castle Business Park, Stirling FK9 4TZ. Under the Regulation of Investigatory Powers Act 2000, the email

system at SEPA may be subject to mon

Location: From:

Date: Friday, March 18, 2022, 8:10:23 AM

To: customer.care@edinburgh.gov.uk <customer.care@edinburgh.gov.uk>

Subject: diesel fuel spill-Queensferry Road

Contact:

PUBLIC

Dear Sirs

We have had the following report from a member of the public regarding a spill.

If someone could have a look and see if any think could be done that would be appreciated.

Edinburgh, Queensferry Road.

From Dean Bridge (at Water of Leith) for some distance.

“continued for perhaps a mile until [he] turned off, heading towards the Forth Bridge”

Area that he saw appeared to run from Dean Bridge to lights at Craigleith shopping centre/Craigleith Road.

That is approximately 1.9KM, but is not a watercourse – nearest approach is obviously at Dean Bridge but thereafter distance from w/c increases, at furthest extent seen (Craigleith/Queensferry Road junctions) it is >1KM to the Water of Leith

Site History Report

Effective: 13/02/2022 to 31/03/2022

Service: Roads General

Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00

Display Action Officer: No

and c.100m to the u/n w/c at Orchard Brae Gardens.

Customer Services

Customer's concern is that it will go to drains/etcetera and we have advised that surface water in the area is likely to go to Scottish Water treatment, SEPA's role is for w/c. As there is some at the bridge have taken a report but have advised to contact City of Edinburgh and gave (or at least attempted to) contact details for that.

Regards

[Redacted]

Environment Protection Officer

Disclaimer

The information contained in this email and any attachments may be confidential and is intended solely for the use of the intended recipients.

Access, copying or re-use of the information in it by any other is not authorised. If you are not the intended recipient please notify us

immediately by return email to postmaster@sepa.org.uk.

Registered office: Strathallan House, Castle Business Park, Stirling FK9 4TZ. Under the Regulation of Investigatory Powers Act 2000, the email

system at SEPA may be subject to mon

[Redacted]

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Customer Services

Enquiry No.: 1339603 Service: Roads General Desc.: Location: Large pot hole on the road on the south carriageway	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/03/2022 17:10 Classification: Request for service	Contact:
Plot Number: 2.00 Job Number: 50108280	Feature Id - Location: Ward 1 - From Craigcrook Road to Barnton Junction Defect Number: 42095149	Feature Type: Road Asset	
Enquiry No.: 1335360 Service: Roads General Desc.: Location: Pot hole/ cracked surface around drain. Which also fills with water and pedestrians at risk from water and loose rumble within area	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/02/2022 13:14 Classification: Request for service	Contact:
Plot Number: 2.00	Feature Id - Location: Ward 1 - From Craigcrook Road to Barnton Junction	Feature Type: Road Asset	
Enquiry No.: 1335096 Service: Roads General Desc.: Location: Pot hole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 26/02/2022 17:12 Classification: Request for service	Contact:
Plot Number: 2.00	Feature Id - Location: Ward 1 - From Craigcrook Road to Barnton Junction	Feature Type: Road Asset	



Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Customer Services

Enquiry No.: 1333787 **Logged by:** [REDACTED] **on:** 24/02/2022 16:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.: claim form not sent please see two documents attached

From: [REDACTED]
Date: Wednesday, February 23, 2022, 11:20:34 PM
To: <Clarence@edinburgh.gov.uk>
Subject: Pothole damage

Good evening.

I know you're aware of the massive pothole on Queensferry Road at the junction at Orchard Road South as you came out and filled it while I was waiting for a recovery truck to come and pick me up and take me home due to your incompetence in keeping the roads safe for users.

I unfortunately wasn't a lucky person and burst my tyre, buckled my alloy [REDACTED] due to this pothole.

Please find attached photos of the pothole and also damage.

I hope you can see the inconvenience this has caused and reimburse me to show for it.

Time of impact was roughly 19:48

Yours sincerely

[REDACTED]

Location: claim form not sent please see two documents attached

Contact:

From: [REDACTED]
Date: Wednesday, February 23, 2022, 11:20:34 PM
To: <Clarence@edinburgh.gov.uk>
Subject: Pothole damage

Good evening.

I know you're aware of the massive pothole on Queensferry Road at the junction at Orchard Road South as you came out and filled it while I was waiting for a recovery truck to come and pick me up and take me home due to your incompetence in keeping the roads safe for users.

I unfortunately wasn't a lucky person and burst my tyre, buckled my alloy [REDACTED] due to this pothole.

Please find attached photos of the pothole and also damage.

I hope you can see the inconvenience this has caused and reimburse me to show for it.

Time of impact was roughly 19:48

Yours sincerely

[REDACTED]

Enquiry No.: 1332182 **Logged by:** [REDACTED] **on:** 22/02/2022 16:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.: Large Pothole junction Drum Brae

Location: Queensferry Road

Contact:

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Job Number: 50107334 **Defect Number:** 42093985

Enquiry No.: 1331290 **Logged by:** Verint CRM Connector **on:** 21/02/2022 16:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Pothole on the left lane

Contact:

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Customer Services

Enquiry No.: 1331287 **Logged by:** Verint CRM Connector **on:** 21/02/2022 16:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Yet again the lane for turning right into Drumbrae from the A90 Queensferry Road has several deep potholes. One could certainly damage vehicles. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Enquiry No.: 1330362 **Logged by:** Verint CRM Connector **on:** 20/02/2022 12:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole around drain. This was filled in about 2 weeks ago with the rubbish, waste of money soft tar being used. Needs a proper fix. Photo attached shows it full of water, but the hole is about 6 inches deep. The soft tar used is now splattered all over the pavement, sticking to peoples shoes as they walk to and from the shops. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Enquiry No.: 1330360 **Logged by:** Verint CRM Connector **on:** 20/02/2022 12:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big pothole, westbound just at traffic lights. Can't avoid. Whole road not much better. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Enquiry No.: 1329509 **Logged by:** Verint CRM Connector **on:** 18/02/2022 15:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pot hole northbound before junction **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Enquiry No.: 1328892 **Logged by:** Verint CRM Connector **on:** 17/02/2022 17:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole/sunken drain near kerb on city bound side **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Enquiry No.: 1327694 **Logged by:** [REDACTED] **on:** 16/02/2022 11:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: [REDACTED] called as he was driving on Queensferry Road. He stopped at the traffic lights at the bottom of Drum Brae North. When the lights turned green he proceeded to drive and was only going about 15mph when his car hit a pot hole at the junction. Right away a warning came up on his dash advising of low tyre pressure. He says in his [REDACTED] years of driving this is the worst pothole he has ever seen and is concerned for the safety of other drivers. He has also said that he understands it may not be quick fix to the road but was wondering if a cover could be put over it to prevent others from having a nasty accident
Location: Junction of Queensferry Road/Drum Brae North **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Customer Services

Enquiry No.: 1326630 **Logged by:** Verint CRM Connector **on:** 15/02/2022 00:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: An extremely large and deep pothole in the road. It has blown the side wall of my offside front tyre. Causing me to have to wait 2 hours for a recovery truck to take my vehicle back to Dunfermline and purchase a new tyre. [REDACTED]. I have attached photos below and feel this should be investigated and this is not my fault. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Enquiry No.: 1325576 **Logged by:** Verint CRM Connector **on:** 13/02/2022 13:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Two large potholes at traffic lights. Will cause severe damage to suspension as this is a 40 mph main road and cars unable to miss these unless swerving into other lane **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 1 - From Craigcrook Road to Barnton Junction **Feature Type:** Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2.00	Asset - Locn.: Ward 1 - From Craigcrook Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	
5000323	Ultracrete (RD: CLARENCE Response)	Queensferry road inside lane north bound at the junction of Drumbrae North	RD: Cat 4 - 12 Months	Job Archived (no commitment)	18/09/2014		
5001985	brander hinge broken, brander keeps dislodging from frame. Needs replaced (Gully: Brander Damaged)	Queensferry rd city bound opposite Drumbrae north	Non Routine (One Off Works)	Job Archived (no commitment)	17/04/2015		
5001989	Reset brander and resurface surround (Gully: Brander Damaged)	Opposite tesco towards town.	Non Routine (One Off Works)	Job Annulled	17/04/2015		
5001990	14 x 1 patch (RD: Asphalt / Bitmac Surface)	Going from barnton to edinburgh. Old road repair now failing with sunken profile. Near side lane (nearest the wall) located in the right hand side of the inside lane. 4-5 metres long. Oposite 497	Non Routine (One Off Works)	Job Annulled	17/04/2015		
5001991	Replace brander (Gully: Brander Damaged)	Outside 463 northbound	Non Routine (One Off Works)	Job Annulled	17/04/2015		
5001992	replace brander and surround (Gully: Brander Damaged)	Outside 469	Non Routine (One Off Works)	Job Annulled	17/04/2015		
5001994	Carriagewaypatch required 1.4 x 3.3 (RD: Asphalt / Bitmac Surface)	Outside 543	Non Routine (One Off Works)	Job Annulled	17/04/2015		

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	2.00	Asset - Locn.: Ward 1 - From Craigcrook Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	



5004255	Keep Clear faded (RD: Road Marking & Studs)	Junction Parkgrove Street	RD: Cat 3 - 60 Day	Job Annulled	28/11/2015	26/12/2015	Est.
5004258	Bus Bays and yellow box hatchings faded, except Drum Brae North. (RD: Road Marking & Studs)	Whole Street	RD: Cat 4 - 12 Months	Job Annulled	28/11/2015	28/11/2016	Est.
5004262	Low carriageway gully frame (Gully: Brander Damaged)	Opposite Ipost 195	RD: Cat 4 - 12 Months	Job Annulled	28/11/2015	28/11/2016	Est.



Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
---------	-------------	----------	----------	------------	---------	------------	-------------

Asset: 2.00		Asset - Locn.: Ward 1 - From Craigcrook Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	
5004871	Replace damaged 10 bar brander and reset frame (Gully: Brander Damaged)	Outside oaktree veterinary centre	RD: Cat 3 - 60 Day	Job Annulled	21/01/2016	18/02/2016	Est. RSTO16/59000253
5005056	Repla e gully brander and repair carriage way 1.2 x 1.5m (Gully: Brander Damaged)	Old junction clermiston drive	RD: Cat 3 - 60 Day	Job Annulled	04/02/2016	03/03/2016	Est.



5010514	Reset sunken gully (Gully: Brander Damaged)	533 QUEENSFERRY ROAD	Non Routine (One Off Works)	Job Annulled	29/04/2017		
---------	--	----------------------	--------------------------------	--------------	------------	--	--



Site History Report

Effective: 13/02/2022 to 31/03/2022
 Service: Roads General
 Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 1 - From Craigcrook Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	
5011750	Reset gully to level (Gully: Brander Damaged)	Queensferry Road east bound carriageway slow lane at junction with drumbrae north ,	Non Routine (One Off Works)	Job Annulled	18/07/2017		
5011841	Re sett gully to level (Gully: Brander Damaged)	Sunk gully on east bound carriageway opposite no469,	Non Routine (One Off Works)	Job Annulled	24/07/2017		
5012396	Refresh road markings at junction with maybury road (RD: Road Marking & Studs)	I have never liked the junction from Maybury Road (going north) to turn west onto Queensferry Road. A green light shows but there is a give-way sign painted on the road, (this sign is becoming indistinct and worn). I had even more reason to dislike this junction yesterday when travelling on my motor-cycle from Queensferry Road (having come east towards the city) and waiting to turn right to travel west-bound on Maybury Road. A camper van (possibly a tourist) went through the green light (most likely unaware that they should give way) while a car was travelling west down Queensferry Road. The car had to quickly slow and veer a bit to avoid the camper van - just as well they did since I was at risk since I could have been hit by one of the vehicles. Please will you look at this problem since there is a risk there that needs to be addressed.	Non Routine (One Off Works)	Job Annulled	23/08/2017		
5013332	Yellow hatch box required at entrance/exit to parkgrove shopping centre (RD: Road Marking & Studs)	Queensferry Road / parkgrove shooping centre	RD: Cat 4 - 12 Months	Job Annulled	07/11/2017	07/11/2018	Est.
5013617	Outside tony macaroni (RD: Asphalt / Bitmac Surface)	Patching on west bound carriageway slow lane	RD: Cat 4 - 12 Months	Job Annulled	03/12/2017	03/12/2018	Est.



Site History Report

Effective: 13/02/2022 to 31/03/2022
 Service: Roads General
 Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 1 - From Craigcrook Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	
5013637	Faded bus stop markings west bound carriageway outside no 401 (RD: Road Marking & Studs)	Refresh bus stop road markings	RD: Cat 4 - 12 Months	Job Annulled	03/12/2017	03/12/2018	Est.
4100018	Road: Defective / Damaged (Enquiry 53591)	On the corner of Queensferry Road coming from the city turning left onto Drum Brae North at traffic lights	Non Routine (One Off Works)	Job Cancelled	11/09/2014		
50000947	Pothole at gully (RD: CW Pothole)	City bound opposite Tesco express	PRIORITY: C H A N G E M E	Job Annulled	09/01/2018		
50001544	Pothole (RD: CW Pothole)	North bound inside lane 100m before Barnton depot.	RW: Grit Bin - 5 Day	Job Annulled	20/01/2018	29/01/2018	Est.
50047902	Sunken gully and depression in Carriageway. Reset gully and patch Carriageway. Approx 5m x 1.5m (RD: Gully Sunken/Damaged Frame)	Westbound lane. Just East of junction with Drum Brae North	RD: Cat 4 - 12 Months	Job Annulled	16/12/2019	16/12/2020	Est.
50047904	Carriageway pothole. Dig out and relay. 3m x 2m (RD: CW Pothole)	559	RD: Cat 4 - 12 Months	Job Annulled	16/12/2019	16/12/2020	Est.
50047913	Sunken gully. Reset. (RD: Gully Sunken/Damaged Frame)	Opp 473 on city bound side.	RD: Cat 4 - 12 Months	Job Annulled	16/12/2019	16/12/2020	Est.
50052475	Refresh yellow junction box. Road: Defective / Damaged (Enquiry 956370) (RD: Markings Refresh)	Queensferry road/Clermiston Road North	RD: Cat 4 - 12 Months	Job Annulled	19/02/2020	19/02/2021	Est.

Site History Report

Effective: 13/02/2022 to 31/03/2022
 Service: Roads General
 Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2.00	Asset - Locn.: Ward 1 - From Craiggrook Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	
50061785	Road: Defective / Damaged (Enquiry 1031970)refresh yellow boxes (RD: Markings Refresh)	I had a crash with my car on 28/08/20 at the junction of craiggrook road, quality street and queensferry road. I was driving from craiggrook road over to quality street as I had right of way . In the middle of queensferry road at this junction there used to be a large yellow hatch box. Because of this drivers coming up quality street onto queensferry road are jumping the lights only a matter of time before a really serious accident occurs	RD: Cat 4 - 12 Months	Job Annulled	02/09/2020	02/09/2021	Est.
50071443	Road Markings: Defective - Line painting refresh required (Enquiry 34002952) (RD: Markings Refresh)	Queensferry Road at Clermiston Road and Drumbrae	RD: Cat 4 - 12 Months	Job Annulled	07/01/2021	07/01/2022	Est.
[REDACTED]							
50078846	Crack on cw patch required approximately 56 x 1 sqm (RD: CW Cracked/Broken)	Between number 425 and 433 on cw city bound	RD: Cat 4 - 12 Months	No code allocated	18/03/2021	18/03/2022	Est.
50078850	Rutting on cw 2x2 patch required on anti skid surface (RD: CW Rutting)	At junction with clermiston road north city bound	RD: Cat 4 - 12 Months	No code allocated	18/03/2021	18/03/2022	Est.
50078859	Pothole (RD: CW Pothole)	Adjacent to number 399 on opposite side of cw	RD: Cat 4 - 12 Months	No code allocated	18/03/2021	18/03/2022	Est.
50078862	Pothole in centre cw see pics (RD: CW Pothole)	At junction with quality street	RD: Cat 4 - 12 Months	No code allocated	18/03/2021	18/03/2022	Est.
50078885	Gully surround 2x1 patch (RD: CW Pothole)	At junction with Craig crook road west bound	RD: Cat 4 - 12 Months	No code allocated	18/03/2021	18/03/2022	Est.
50078892	Patch required for cracked/broken surface 4x2 sqm (RD: CW Cracked/Broken)	West bound approximately 200m past junction with quality street	RD: Cat 4 - 12 Months	No code allocated	18/03/2021	18/03/2022	Est.
50078902	Gully surround needs patched 1x1 (RD: CW Cracked/Broken)	Outside 437	RD: Cat 4 - 12 Months	No code allocated	18/03/2021	18/03/2022	Est.
50078917	Gully frame damaged needs replaced (RD: Gully Sunken/Damaged Frame)	Outside 559 on cw west bound	RD: Cat 4 - 12 Months	No code allocated	18/03/2021	18/03/2022	Est.

Site History Report

Effective: 13/02/2022 to 31/03/2022
 Service: Roads General
 Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	2.00	Asset - Locn.: Ward 1 - From Craigmack Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	
50091074	Road: Defective / Damaged (Enquiry 1238511) refresh carriageway junction markings (RD: Markings Refresh)	Queensferry Road junction Whitehouse Road/Maybury Road	RD: Cat 4 - 12 Months	No code allocated	03/09/2021	03/09/2022	Est.
50102731	Road: Defective / Damaged (Enquiry 1306309) raise carriageway gully frame and reinstate carriageway (RD: Gully Damaged/Sunken)	Heading west at Drum Brae North	RD: Cat 3 - 60 Day	Job Committed	13/01/2022	07/04/2022	Est. ROAD/82058683
50104880	Relay loose carriageway gully frames and reinstate carriageway in hra (RD: Gully Damaged/Sunken)	Outside 431,437,455,467,473,479,499,53 Drum Brae North	RD: Cat 3 - 60 Day	Job Committed	01/02/2022	26/04/2022	Est. ROAD/82059585
50105968	Road: Defective / Damaged (Enquiry 1323590) pothole on carriageway inside lane (RD: CW Pothole)	Junction Drum Brae North heading east	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/02/2022	14/02/2022	Act. ROAD/82060086
50106446	6 carriageway potholes (RD: CW Pothole)	West bound lane approx between 2-15m from drum brae junction	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/02/2022	22/02/2022	Act. ROAD/82060330
50107331	Pothole on carriageway inside lane at gully (RD: CW Pothole)	Outside 497	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/02/2022	25/02/2022	Act. ROAD/82060852
50107334	Road: Defective / Damaged - Large Pothole junction Drum Brae (Enquiry 1332182) pothole on carriageway inside lane (RD: CW Pothole)	Heading west junction Drum Brae North	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/02/2022	26/02/2022	Act. ROAD/82060855
50107336	Road: Defective / Damaged - Large Pothole junction Drum Brae (Enquiry 1332182) pothole on carriageway outside lane (RD: CW Pothole)	Heading east junction Drum Brae North	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/02/2022	26/02/2022	Act. ROAD/82060857
50107341	1 carriageway pothole (RD: CW Pothole)	Outside 499	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/02/2022	25/02/2022	Act. ROAD/82060859
50107346	2 carriageway potholes (RD: CW Pothole)	In yellow box at junction of drum brae north in the west bound lane	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/02/2022	26/02/2022	Act. ROAD/82060863
50107347	1 carriageway pothole (RD: CW Pothole)	East bound lane opposite lamppost 213	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/02/2022	08/03/2022	Act. ROAD/82060864
50107348	1 carriageway pothole (RD: CW Pothole)	At lamppost 215	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/02/2022	27/02/2022	Act. ROAD/82060865

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2.00	Asset - Locn.: Ward 1 - From Craigcrook Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	
50107447	1 carriageway pothole (RD: CW Pothole)	Opposite 56	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/02/2022	27/02/2022	Act. ROAD/82060948
50107901	Road: Defective / Damaged (Enquiry 1336903) pothole on carriageway inside lane (RD: CW Pothole)	Outside 431	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2022	03/03/2022	Act. ROAD/82061168
50107902	Noisy carriageway manhole (RU: Utility Apparatus)	Outside 419	RU: Fail Med.Risk (Apparatus)	Job Complete	02/03/2022	02/03/2022	Act.
50107903	Low carriageway manhole (RU: Utility Apparatus)	Outside 425	RU: Fail Med.Risk (Apparatus)	Job Complete	02/03/2022	02/03/2022	Act.
50108280	Road: Defective / Damaged (Enquiry 1339603) pothole on carriageway inside lane (RD: CW Pothole)	Outside 385	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/03/2022	08/03/2022	Act. ROAD/82061355
50109541	Road: Defective / Damaged (Enquiry 1345983) pothole on carriageway inside lane (RD: CW Pothole)	Outside Barnton depot	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/03/2022	22/03/2022	Act. ROAD/82061946
50109542	Pothole on carriageway inside lane (RD: CW Pothole)	Outside 409	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/03/2022	22/03/2022	Act. ROAD/82061947
50109706	Patch required approx 1x2m (RD: CW Cracked/Broken)	At th the junction with Craigcrook rd	RD: Cat 4 - 12 Months	No code allocated	20/03/2022	20/03/2023	Est.
50109708	Road: Defective / Damaged (Enquiry 750462) at junction with Clermiston road (RD: Markings Refresh)	Refresh yellow hatch box	RD: Cat 4 - 12 Months	Job Annulled	20/03/2022	20/03/2023	Est.
50109711	1no noisy Scottish water manhole also damaged surround (RU: Utility Apparatus)	Next to Clermiston drive bus stop in westbound lane near no419	RU: Fail Low Risk	Job Complete	20/03/2022	21/03/2022	Act.
50109714	Patch required at gully surround (RD: CW Cracked/Broken)	Outside no 563	RD: Cat 4 - 12 Months	No code allocated	20/03/2022	20/03/2023	Est.
50109715	Patch required approx 1x2m (RD: CW Cracked/Broken)	Outside queens manor residential home	RD: Cat 4 - 12 Months	No code allocated	20/03/2022	20/03/2023	Est.
50109719	Reinstate weebol and HRA surround (RD: Weebol Damage/Missing/New)	At the junction with Whitehouse rd	RD: Cat 3 - 60 Day	Job Complete	20/03/2022	22/03/2022	Act. ROAD/82062012
50109720	Sunken gully and hra surround (RD: Gully Damaged/Sunken)	Opposite no559	RD: Cat 4 - 12 Months	No code allocated	20/03/2022	20/03/2023	Est.
50109721	Patch required approx 1x8m (RD: CW Cracked/Broken)	In lane turning right onto Drumbrae north	RD: Cat 4 - 12 Months	No code allocated	20/03/2022	20/03/2023	Est.
50109722	Sunken gully and broken hra surround (RD: Gully Damaged/Sunken)	Opposite no499 at bus stop	RD: Cat 4 - 12 Months	No code allocated	20/03/2022	20/03/2023	Est.
50109723	Sunken gully and broken hra surround (RD: Gully Damaged/Sunken)	Opposite no463	RD: Cat 4 - 12 Months	No code allocated	20/03/2022	20/03/2023	Est.

Site History Report

Effective: 13/02/2022 to 31/03/2022
Service: Roads General
Site: Queensferry Road (7902503)

Asset Number: 2.00 to 2.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2.00	Asset - Locn.: Ward 1 - From Craigcrook Road to Barnton Junction		Feature Type: Road Asset		Area: North West Locality	
50110034	1 carriageway pothole (RD: CW Pothole)	At bus stop outside queens manor	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/03/2022	25/03/2022	Act. ROAD/82062211
50110036	Noisy carriageway manhole (RU: Utility Apparatus)	Lpost 199	RU: Fail Med.Risk (Apparatus)	Job Complete	23/03/2022	23/03/2022	Act.