

Effective: 01/04/2020 to 31/03/2022

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: West Register Street (7902281)

Site: West Register Street (7902281)

Locality: New Town, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41121448 - Inspection Batch			Route:	Ad hoc Route		Date:	31/03/2022
42098291	6no rocking scoutmoor flags 1no broken scoutmoor flag need replaced (600x400) will require fantailed on site 1no dislodged kerb needs reset	31/03/2022	On the corner opposite the Guildford Arms	RD: FW Slabs Rocking	Internal		Committed	50110818
Batch:	41121442 - Inspection Batch			Route:	Ad hoc Route		Date:	31/03/2022
42098288	6no rocking scoutmoor flags 2no broken scoutmoor flags need replaced (400x620) (500x800)	31/03/2022	Opposite the Guildford Arms	RD: FW Slabs Rocking	Internal		Committed	50110815
Batch:	41121435 - Inspection Batch			Route:	Ad hoc Route		Date:	31/03/2022
42098280	1no rocking cross cut scoutmoor flag	31/03/2022	Opposite backpackers hostel	RD: FW Slabs Rocking	Internal		Committed	50110807
Batch:	41121430 - Inspection Batch			Route:	Ad hoc Route		Date:	31/03/2022
42098276	2no rocking scoutmoor flags 1no rocking whin kerb needs reset	31/03/2022	Opposite no7	RD: FW Slabs Rocking	Internal		Committed	50110804
Batch:	41114370 - Inspection Batch			Route:	Ad hoc Route		Date:	01/02/2022
42091598	1no rocking scoutmoor flag	01/02/2022	Outside Nationwide	RD: FW Slabs Rocking	Internal		Committed	50104952
Batch:	41110493 - Inspection Batch			Route:	Ad hoc Route		Date:	14/12/2021
42087056	Badly sunken lids on manhole	14/12/2021	On the footway outside no20	RU: Utility Apparatus	Internal		Uncommitted	50100230
Batch:	41093872 - Inspection Batch			Route:	SE_CF2_StAndrew1		Date:	08/06/2021
42070699	40m dislodged kerb needs relaid	08/06/2021	From the Guildford to the corner	RD: FW Kerb Dislodged/Rocking	Internal		Action Required	
42070706	Missing and depressed setts approx 20mx3m	08/06/2021	Opposite Apple store	RD: CW Setts Damaged/Missing	Internal		Action Required	
42070705	3no dislodged kerb	08/06/2021	Opposite Apple store	RD: FW Kerb Dislodged/Rocking	Internal		Action Required	
42070703	Cracked and broken grano surface approx 6mx2m	08/06/2021	Opposite Motel One	RD: FW Grano Cracked/Broken	Internal		Action Required	
42070702	21no rocking scoutmoor flags 1no dislodged kerb	08/06/2021	On the corner outside Motel One	RD: FW Slabs Rocking	Internal		Action Required	
42070698	Depression in setts approx 2mx2m	08/06/2021	Outside no7	RD: CW Setts Depression	Internal		Action Required	
42070701	Potholed footway surface approx 20mx2m	08/06/2021	From the Guildford entrance to princes street backpackers	RD: FW HRA Cracked/Broken	Internal		Action Required	
42070697	x1 rocking natural stone channel.	08/06/2021	Opposite voodoo rooms.	RD: CW Channel Rocking	Internal		Action Required	
42070695	Double service footway manhole cover is showing signs of failure.	08/06/2021	Outside 20.	RU: Utility Apparatus	Internal		Uncommitted	50084842
	Inspected within the manhole and the stakka boxes are caving in.							
	Mediocre risk but potential of somebody tripping up.							
42070704	Cracked and broken asphalt surface approx 6mx6m	08/06/2021	At the junction of Princes Street	RD: CW Cracked/Broken	Internal		Action Required	

Effective: 01/04/2020 to 31/03/2022

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: West Register Street (7902281)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset			Area: South East Locality	
Batch: 41093872 - Inspection Batch				Route: SE_CF2_StAndrew1				Date: 08/06/2021
42070696	Potholed footway surface approx 6mx2m	08/06/2021	Outside the Cafe Royal Oyster bar entrance	RD: FW HRA Cracked/Broken	Internal		Action Required	
Batch: 41092370 - Inspection Batch				Route: Ad hoc Route				Date: 13/05/2021
42068921	Pothole	13/05/2021	3m North of Princes St next to give way marking	RD: CW Pothole	Internal		Committed	50083029
Batch: 41063270 - Inspection Batch				Route: Ad hoc Route				Date: 16/09/2020
42053496	21no rocking scoutmoor flags 1no dislodged kerb	16/09/2020	On the corner outside Motel One	RD: FW Slabs Rocking	Internal		No Action Required	

Customer Services

Enquiry No.: 34005032	Logged by: Kinga Urban	on: 28/03/2022 11:55
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: PAPC - on 05.01.2022 our client fell due to a damaged flagstone		
Location:	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 34004242	Logged by: [REDACTED]	on: 15/10/2021 11:02
Service: Roads General	Subject: Drainage: General Enquiry	Classification: General Enquiry
Desc.: please inspect drains at the back of west register street.		
Location: back of west register street	Contact: [REDACTED]	
Enquiry No.: 1354777	Logged by: Verint CRM Connector	on: 31/03/2022 18:41
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The pavement is shocking from the corner of Princess Street at General Register House up to New Register House. There are bits of the pavement actually broken and loose. Having tripped this morning after standing on a bit of the loose pavement I have decided to report this, however it has been like this for years.		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1321681	Logged by: [REDACTED]	on: 07/02/2022 12:33
Service: Open Space Maintenance	Subject: Litter	Classification: Request for service
Desc.: Some gloriously polite citizen of Edinburgh has dumped a bag of used kitty litter on West Register Streett was dumped weeks ago Street cleansing have removed the bag, but not the contents		
Location: West Register Street	Contact:	
Enquiry No.: 1315649	Logged by: Verint CRM Connector	on: 28/01/2022 14:01
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: lose and moving paving slab in middle of pavement which rocks and sticks up causing trip hazard		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50104952	Defect Number: 42091598	

Effective: 01/04/2020 to 31/03/2022

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: West Register Street (7902281)

Customer Services

Enquiry No.: 1313505 Logged by: Verint CRM Connector on: 25/01/2022 13:33
 Service: Roads General Subject: Public Utilities: General Classification: Request for service
 Desc.:

Location: There is a sunken number of slabs that make up a cover for bt lines i believe. WE have previously reported this but still it has not been repaired and is a trip hazard and is causing people to trip. we had placed cones over it but they keep being stolen by youths. Contact:

This needs to be repaired as a matter of urgency

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1289862 Logged by: [REDACTED] on: 13/12/2021 14:18
 Service: Roads General Subject: Covers: Damaged / Defective Classification: Request for service

Desc.: Reason for this email is to report a problem with the pavement/grid cover just outside the entrance to Hawksmoor restaurant towards St Andrews Gardens. there is an uneven gap between the pavement and the grid cover. Happened [REDACTED] 1/12/22 [REDACTED]

Thank you
 [REDACTED]

Location: It's West Register Street outside the entrance to Hawksmoor restaurant towards St Andrews Gardens. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Job Number: 50100230 Defect Number: 42087056

Enquiry No.: 1289810 Logged by: Verint CRM Connector on: 13/12/2021 13:47
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.: Severe washout under this gully stone on West Register Street. EH2 2AA. between Snax cafe and The Chinese restaurant. Its going to break someone's ankle Contact:

Enquiry No.: 1288651 Logged by: Verint CRM Connector on: 11/12/2021 08:53
 Service: Open Space Maintenance Subject: Litter Classification: Request for service

Desc.: Which problem you would like to report? Litter complaint.
 Does litter contain sharps? No

Location: Outside McDonald's, street is constantly covered in McDonald's waste. Contact:

Enquiry No.: 1257033 Logged by: Verint CRM Connector on: 08/10/2021 11:27
 Service: Open Space Maintenance Subject: Dumping and Fly Tipping Classification: Request for service

Desc.: Where has the flytipping occurred: On the street, park or beach.
 What rubbish has been dumped: Commercial Waste.

How much rubbish has been dumped: large wooden pallets

Location: wooden pallets very large c.8 have been dumped by fire escape door behind O2 store - please remove Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Effective: 01/04/2020 to 31/03/2022

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: West Register Street (7902281)

Customer Services

Enquiry No.: 1244798 **Logged by:** [REDACTED] **on:** 14/09/2021 13:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: [REDACTED] fall on loose cobblestones which move several inches when stepped in
Location: Tweet - Hi, something needs to be done about the paving and kerbs on West Register Street, near the Guildford Arms. **Contact:** [REDACTED]

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1040560 **Logged by:** Verint CRM Connector **on:** 16/09/2020 07:19
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: pavement is in awful, unsafe condition. paving slabs seesaw, rock, and raise up providing trip hazards. curb stones are loose due to lorries driving over them **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Defect Number: 42070702

Enquiry No.: 987679 **Logged by:** Verint CRM Connector **on:** 22/05/2020 21:53
Service: Open Space Maintenance **Subject:** Dumping and Fly Tipping **Classification:** Request for service
Desc.: Where has the flytipping occurred: On the street, park or beach.
 What rubbish has been dumped: Household Waste.
 How much rubbish has been dumped: There is an overflowing skip and around 10 other bags of rubbish in immediate area of skip
Location: On West Register Street Lane. **Contact:**
 Overflowing skip with multiple types of waste has been sitting in the lane and has more rubbish surrounding the skip. It has been there for over 2 months. With warming weather it may start attracting pests.
 May be responsibility of Hotel Indigo (20 Princes St) as they have had skips there before.

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
1000998	relay 18 kerb stones which have been knocked out (RD: Kerbs)	on corner back of motel 1 apple store	RD: Cat 2 - 5 Day	Job Cancelled	25/11/2014	02/12/2014	Est. RD01/10000408
1004046	39mtrs of kerb need re layed (RD: Capital Assessment Requird)		RD: Cat 4 - 12 Months	Job Cancelled	08/09/2015	08/09/2016	Est.
50083029	Pothole (RD: CW Pothole)	3m North of Princes St next to give way marking	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2021	14/05/2021	Act. ROAD/82049672
50084842	Double service footway manhole cover is showing signs of failure. Inspected within the manhole and the stakka boxes are caving in. Mediocre risk but potential of somebody tripping up. (RU: Utility Apparatus)	Outside 20.	RU: Fail Med.Risk (Apparatus)	Job Complete	08/06/2021	09/06/2021	Act.
50100230	Badly sunken lids on manhole (RU: Utility Apparatus)	On the footway outside no20	RU: Fail Med.Risk (Apparatus)	Job Complete	14/12/2021	16/12/2021	Act.

Effective: 01/04/2020 to 31/03/2022

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: West Register Street (7902281)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50104952	1no rocking scoutmoor flag (RD: FW Slabs Rocking)	Outside Nationwide	RD: Cat 3 - 60 Day	Job Complete	01/02/2022	02/02/2022	Act. ROAD/82059622
50110804	2no rocking scoutmoor flags 1no rocking whin kerb needs reset (RD: FW Slabs Rocking)	Opposite no7	RD: Cat 3 - 60 Day	Job Complete	31/03/2022	04/04/2022	Act. ROAD/82062570
50110807	1no rocking cross cut scoutmoor flag (RD: FW Slabs Rocking)	Opposite backpackers hostel	RD: Cat 3 - 60 Day	Job Complete	31/03/2022	04/04/2022	Act. ROAD/82062572
50110815	6no rocking scoutmoor flags 2no broken scoutmoor flags need replaced (400x620) (500x800) (RD: FW Slabs Rocking)	Opposite the Guildford Arms	RD: Cat 3 - 60 Day	Job Complete	31/03/2022	04/04/2022	Act. ROAD/82062574
50110818	6no rocking scoutmoor flags 1no broken scoutmoor flag need replaced (600x400) will require fantailed on site 1no dislodged kerb needs reset (RD: FW Slabs Rocking)	On the corner opposite the Guildford Arms	RD: Cat 3 - 60 Day	Job Complete	31/03/2022	04/04/2022	Act. ROAD/82062577