

36972 Gilmore Place, Edinburgh, EH3

Accident Date: 02/02/2022

Accident Location: Gilmore Place, Edinburgh, EH3

What height or depth does a defect have to be for it to be actionable and required to be repaired by the council on this footpath? What type of defect does it have to be?

[Please refer to the attached guidance – ‘Road Safety Inspection and Defect Categorisation April 2016’.](#)

What inspection interval has the Council identified as being appropriate for this footpath?

[Annually. All routes should be inspected within an 18-month period.](#)

What factors were used in assessing the inspection interval?

How is this footpath inspected (for example by foot)?

[Please refer to the attached guidance – ‘Road Safety Inspection and Defect Categorisation April 2016’.](#)

Please send us all the inspection records for this footpath, for the period 1 January 2020 to the present date (03/05/2022).

[Please refer to the ‘Condition Survey’ section of the attached Site History Report.](#)

Maintenance records including records of independent contractors working on this footpath for the period 1 January 2020 to the present date (03/05/2022).

Repair records for this footpath for the period 1 January 2020 to the present date (03/05/2022).

[Please refer to the ‘Maintenance Management’ section of the attached Site History Report and to the document ‘36972 Utilities Works’.](#)

Details of any complaints made in relation to this footpath in the period of 1 January 2018 to the present date (03/05/2022).

[Please refer to the following attached document – ‘36972 Site History Report - Gilmore Place\\_Q8’.](#)

Details of your policy or guidance which demonstrates the timescale within which repairs to defects on this footpath are to be completed, in the period of 1 January 2020 to the present date.

[Please refer to the attached guidance – ‘Road Safety Inspection and Defect Categorisation April 2016’.](#)

All correspondence to independent contractors or requests for inspections to any other party relating to work carried out on this footpath, for the period 1 January 2020 to the present date.

[There is no such correspondence held. Any information regarding Utilities and third parties are held on the Scottish Road Works Register which belongs to the Scottish Road Works Commissioner. We cannot provide this information on their behalf.](#)

Please confirm details of the relevant code of practice for this footpath and defect?

Please send us a copy of the relevant code of practice for this footpath and defect.

Please refer to the attached guidance – ‘Road Safety Inspection and Defect Categorisation April 2016’.

Third party personal information has been redacted from the Site History Reports provided. Further redactions have been applied where the information is not within scope of the request, i.e., where it is clear that it does not relate to the footway described in the request.