

37016 Lauriston Place, Edinburgh

Regarding previous correspondence in respect of Lauriston Place, Edinburgh:

In respect of Job Number 1010485, please confirm full measurements of the defect, specifically including the height of the defect.

Please confirm the current status of the job/defect.

The status as at 11/08/21 read "Job Annulled" – please can you clarify what is the meaning of annulment in this situation.

The full measurements are not held.

Current status – Job Annulled.

Meaning of "Job Annulled" – A full safety inspection was carried out on 11/08/2021. All actionable defects were raised.

In respect of Job Number 3001042, please confirm full measurements of the defect, specifically including the height of the defect.

Please confirm the current status of the job/defect.

The full measurements are not held.

Current status – Job Cancelled.

In respect of Job Number 3001044, please confirm full measurements of the defect, specifically including the height of the defect.

Please confirm the current status of the job/defect.

The full measurements are not held.

Current status – Job Cancelled.

In respect of Job Number 3006984, please confirm full measurements of the defect, specifically including the height of the defect.

The status as at 11/08/21 read "Job Annulled" – please can you clarify what is the meaning of annulment in this situation.

Please confirm the current status of the job/defect.

Please provide any drawings in your possession.

The full measurements are not held.

Meaning of "Job Annulled" – A full safety inspection was carried out on 11/08/2021. All actionable defects were raised.

Current status – Job Annulled.

Drawings – There are no drawings available.

In respect of Job Number 3011399, please confirm full measurements of the defect, specifically including the height of the defect.

The status as at 11/08/21 read "Job Annulled" – please can you clarify what is the meaning of annulment in this situation.

Please confirm the current status of the job/defect.

The full measurements are not held.

Meaning of "Job Annulled" – A full safety inspection was carried out on 11/08/2021. All actionable defects were raised.

Current status – Job Annulled.

In respect of Job Number 3011402, please confirm full measurements of the defect, specifically including its height.

The status as at 11/08/21 read "Job Annulled" – please can you clarify what is the meaning of annulment in this situation.

Please confirm the current status of the job/defect.

The full measurements are not held.

Meaning of "Job Annulled" – A full safety inspection was carried out on 11/08/2021. All actionable defects were raised.

Current status – Job Annulled.

In respect of Job Number 3011403, please confirm full measurements of the defect, specifically including its height.

The defect type was changed on 19/09/19 and please confirm the defect type.

Please confirm the current status of the job/defect.

The full measurements are not held.

Defect Type - RD22 RD: FW Slabs Broken/Missing

Current status – Cat 4 Defect

In respect of Job Number 3012826, please confirm full measurements of the defect, specifically including its height.

Please confirm the current status of the job/defect.

The full measurements are not held.

Current status – Job Cancelled.

In respect of Job Number 50056294, please confirm full measurements of the defect, specifically including its height.

The full measurements are not held.

Please provide inspection record in respect of Lauriston Place, Edinburgh, for the period February 2018 to February 2020 (you previously provided inspection record for the period February 2020 to August 2020).

Please refer to the attached Site History Report.

Third party personal information has been redacted from the documents provided in compliance with the Data Protection Act 2018.

With reference to point 10 above, please confirm the route/extent of the inspections.

From Forrest Road to Brougham Street.