

# Site History Report

**Effective:** 01/02/2018 to 31/01/2020  
**Display Action Officer:** No

**Asset Number:** 1.00 to 9.00  
**Site:** Lauriston Place (7902983)

**Site:** Lauriston Place (7902983)

**Locality:** Tollcross, Edinburgh, City of Edinburgh

**Area:** South East Locality

## Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Ward 11 - From Forrest Road to Brougham Street			<b>Feature Type:</b> Road Asset			<b>Area:</b> South East Locality	
<b>Batch:</b> 50044562	- Inspection Batch No actionable defects found			<b>Route:</b> RG: All Features				<b>Date:</b> 13/07/2018
<b>Batch:</b> 41050371	- Inspection Batch No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 23/01/2020
<b>Batch:</b> 41046635	- Inspection Batch No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 27/11/2019
<b>Batch:</b> 41044850	- Inspection Batch No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 29/10/2019
<b>Batch:</b> 41042389	- Inspection Batch			<b>Route:</b> Ad hoc Route				<b>Date:</b> 07/10/2019
42039541	Refresh cycle box markings on both sides	07/10/2019	@ tollcross junction	RD: Markings Refresh	Internal		No Action Required	
<b>Batch:</b> 41041611	- Inspection Batch No actionable defects found			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 01/10/2019
<b>Batch:</b> 41040242	- Inspection Batch			<b>Route:</b> SE_CF1_Lauriston1				<b>Date:</b> 30/09/2019
42038741	Make safe pothole with grano Ramp off at toby	19/09/2019	Outside bar burrito	RD: FW Grano Pothole	Internal		Committed	50042630
42038617	Approx 2mx3m grano needs relaid	18/09/2019	@junction with lauriston park	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42038609	Pavement: Damaged / Defective (Enquiry 399521) broken slabs	18/09/2019	Lauriston place opposite Novotel to opp art school	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038605	3no broken 600x900 pcc flags	18/09/2019	@ west side of junction with Chalmers st	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038572	21no broken 600x900 pcc flags 10no broken 600x750 pcc flags 4no broken 600x600 pcc flags	18/09/2019	@entrance to Edinburgh university futures institute	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038603	1no broken 600x900 pcc flag	18/09/2019	@ East side of junction with Chalmers st next to railing	RD: FW Slabs Broken/Missing	Internal		Committed	50042558
42038767	1no missing tactile slabs been made safe and 1no missing cut pcc flag	19/09/2019	East side of junction with lady Lawson st	RD: FW Slabs Broken/Missing	Internal		Uncommitted	50089358
42038756	3no broken 600x750 pcc flags 2no broken 600x600 pcc flags	19/09/2019	Outside 22	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038588	Approx 90m2 pcc flags needs relaid	18/09/2019	Better no 23 and 37	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038581	Taxi Rank and centre line markings need refreshed	18/09/2019	Taxi Rank to the West of the entrance to George heriots	RD: Markings Refresh	Internal		Uncommitted	50089348
42038768	4no broken 600x900 pcc flags 5no broken 600x750 pcc flags 4no broken cut pcc flags 1no low pcc flag Grano broken at kerb	19/09/2019	West side of junction with lauriston st	RD: FW Slabs Broken/Missing	Internal		Uncommitted	50089357
42038583	1no low slab	18/09/2019	@ lauriston terrace	RD: FW Slabs Rocking	Internal		Uncommitted	50089354
42038764	14no broken 600x900 pcc flags 7no broken 600x600 pcc flags	19/09/2019	East side of junction with lady Lawson st	RD: FW Slabs Broken/Missing	Internal		No Action Required	

## Site History Report

Effective: 01/02/2018 to 31/01/2020

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Lauriston Place (7902983)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Ward 11 - From Forrest Road to Brougham Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality		
<b>Batch:</b>	41040242 - Inspection Batch		<b>Route:</b> SE_CF1_Lauriston1			<b>Date:</b> 30/09/2019		
42038596	Reinstate 2no bollards +reinstate setts as req	18/09/2019	Lauriston place near blood donors centre	RD: Bollard Damage/Missing/Neve	Internal		No Action Required	
42038747	1no broken 600x600 pcc flag 1no broken 600x750 pcc flags Missing section of flags 1.35mx1.8m 2no low whin kerb	19/09/2019	Opposite nightingale way	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038619	2no broken cut 600x900 grey pcc flags	18/09/2019	Outside littlejohns letting agent	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038752	Form kerb with grano	19/09/2019	Outside no8	RD: FW Kerbs Damaged/Missing	Internal		Committed	50042634
42038612	6no kerb low/ dislodged need relaid	18/09/2019	Outside Chalmers centre	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42038620	4no low/rocking pcc flags 2no broken 600x900 pcc flags 1no broken cut pcc flag 600x350	18/09/2019	Outside no 123	RD: FW Slabs Broken/Missing	Internal		Committed	50042561
42038616	48no broken 600x900 pcc flags 35no broken 600x750 pcc flags	18/09/2019	Between lauriston gardens and lauriston park	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038614	1no low/sunken kerb	18/09/2019	Opposite premier inn	RD: FW Kerb Dislodged/Rocking	Internal		Uncommitted	50089355
42038765	Renew grano at manhole 1no broken 600x600 pcc flag Relay 1no rocking 600x900 pcc flag	19/09/2019	East side of junction with lady Lawson st	RD: FW Grano Cracked/Broken	Internal		Committed	50042640
42038622	1no broken 600x900 pcc flag	18/09/2019	Outside no139	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038779	2no broken 600x900 pcc flags 2 broken 450x600 pcc flags	19/09/2019	Opposite 131	RD: FW Slabs Broken/Missing	Internal		Uncommitted	50089341
42038599	10no broken/missing 600x900 pcc flags 2no rocking 600x900 pcc flags	18/09/2019	@blood donor centre	RD: FW Slabs Broken/Missing	Internal		Uncommitted	50089359
42038576	Asphalt patch required 1mx1m	18/09/2019	Next to pedestrian crossing @George heriots school main gate	RD: CW Cracked/Broken	Internal		Uncommitted	50089352
42038759	Renew grano at box 1no low whin kerb	19/09/2019	Opposite Chalmers st	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42038761	2no small potholes on crossing	19/09/2019	Opposite Chalmers centre	RD: CW Pothole	Internal		Committed	50042637
42038774	3no rocking 450x450 chamfered slabs 5no missing chamfered slabs Replace with perfecta slabs Infill pothole at catv box with grano	19/09/2019	Opposite Glen st	RD: FW Slabs Broken/Missing	Internal		Committed	50042644
42038757	3no low whin kerbs 1no broken 600x750 pcc flag	19/09/2019	Outside 36	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42038750	9no broken 600x600 pcc flags 5no broken 600x600 pcc flags 5no rocking tactile flags 1no missing cut tactile flag	19/09/2019	East side of junction with heriot place	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42038745	1no low whin kerb 2no broken 600x900 pcc flags 2no broken 600x750 pcc flags	19/09/2019	West side of George heriots school main gate	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42038590	Depression in flagged footway approx 8.4mx5.4m	18/09/2019	Outside the Lauriston building near Archibald Place	RD: FW Slabs Rocking	Internal		Uncommitted	50089360
42038618	17no broken 600x750 pcc flags 16no broken 600x900 pcc flags	18/09/2019	Between lauriston park and glen st	RD: FW Slabs Broken/Missing	Internal		No Action Required	

## Site History Report

Effective: 01/02/2018 to 31/01/2020

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Lauriston Place (7902983)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Ward 11 - From Forrest Road to Brougham Street			<b>Feature Type:</b> Road Asset			<b>Area:</b> South East Locality	
<b>Batch:</b> 41040242	- Inspection Batch			<b>Route:</b> SE_CF1_Lauriston1				<b>Date:</b> 30/09/2019
42038760	2no small potholes on crossing	19/09/2019	At car park entrance to hunter building	RD: CW Pothole	Internal		Committed	50042636
42038744	1no small pothole	19/09/2019	East side of George heriots school gate next to pedestrian crossing	RD: CW Pothole	Internal		Committed	50042631
<b>Batch:</b> 41039326	- Inspection Batch			<b>Route:</b> Ad hoc Route				<b>Date:</b> 04/09/2019
42037601	2no potholes	04/09/2019	Approx15m east of george heriots main gate	RD: CW Pothole	Internal		Committed	50041560
<b>Batch:</b> 41039116	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 02/09/2019
	No actionable defects found							
<b>Batch:</b> 41038266	- Inspection Batch			<b>Route:</b> Ad hoc Route				<b>Date:</b> 19/08/2019
42036677	Bollard knocked over Reinstate bollard and relay 1no sett	19/08/2019	Outside NHS lauriston building	RD: Bollard Damage/Missing/Neve	Internal		Committed	50040243
<b>Batch:</b> 41037538	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 06/08/2019
	No actionable defects found							
<b>Batch:</b> 41035905	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 08/07/2019
	No actionable defects found							
<b>Batch:</b> 41034628	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 13/06/2019
	No actionable defects found							
<b>Batch:</b> 41032920	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 15/05/2019
	No actionable defects found							
<b>Batch:</b> 41030931	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 16/04/2019
	No actionable defects found							
<b>Batch:</b> 41029443	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 20/03/2019
	No actionable defects found							
<b>Batch:</b> 41027782	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 20/02/2019
	No actionable defects found							
<b>Batch:</b> 41025796	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 21/01/2019
	No actionable defects found							
<b>Batch:</b> 41024616	- Inspection Batch			<b>Route:</b> SE_CW1_Central1				<b>Date:</b> 28/12/2018
	No actionable defects found							
<b>Batch:</b> 41024116	- Inspection Batch			<b>Route:</b> Ad hoc Route				<b>Date:</b> 13/12/2018
42023544	Noisy City Fibre manhole cover	13/12/2018	On the southbound carriageway outside RU no131	Utility Apparatus	Internal		Uncommitted	50021145
<b>Batch:</b> 41023507	- Inspection Batch			<b>Route:</b> Ad hoc Route				<b>Date:</b> 03/12/2018
42023040	Gap in kerline please infill with grano	03/12/2018	Outside no20	RD: FW Grano Open Joint	Internal		Committed	50019879
<b>Batch:</b> 41023237	- Inspection Batch			<b>Route:</b> Ad hoc Route				<b>Date:</b> 27/11/2018
42022844	Missing water toby cover	27/11/2018	On the pedestrian crossing at the corner of Brougham Street	RU: Utility Apparatus	Internal		Uncommitted	50019621

## Site History Report

Effective: 01/02/2018 to 31/01/2020

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Lauriston Place (7902983)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Ward 11 - From Forrest Road to Brougham Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality		
<b>Batch:</b>	41023053 - Inspection Batch			<b>Route:</b> SE_CW1_Central1		<b>Date:</b> 26/11/2018		
	No actionable defects found							
<b>Batch:</b>	41021929 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Date:</b> 12/11/2018		
42022042	1no broken 900x600pcc flag 2no rocking 900x600 pcc flags	12/11/2018	Outside the blood donor centre	RD: FW Slabs Broken/Missing	Internal		Committed	50018869
<b>Batch:</b>	41021284 - Inspection Batch			<b>Route:</b> SE_CW1_Central1		<b>Date:</b> 31/10/2018		
	No actionable defects found							
<b>Batch:</b>	41019618 - Inspection Batch			<b>Route:</b> SE_CW1_Central1		<b>Date:</b> 02/10/2018		
	No actionable defects found							
<b>Batch:</b>	41018566 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Date:</b> 12/09/2018		
42018746	Signs: Defective / Damaged - What type of sign is it?: red triangle sign (Enquiry 709420)give way pole on island bent over replace pole added to defect list	12/09/2018	Junction of Lothian St with Bristo St, pavement S side of Lothian St. I hit sign with my car 4.30 pm 9th September. Sign is now at an angle. Reported to insurance company, also to police incident no [redacted] at 10 .45 today. [redacted].checked location actually teviot place jct bristo Square	RD: Other Defect Type	Internal		Committed	50015908
<b>Batch:</b>	41018227 - Inspection Batch			<b>Route:</b> SE_CW1_Central1		<b>Date:</b> 06/09/2018		
	No actionable defects found							
<b>Batch:</b>	41016094 - Inspection Batch			<b>Route:</b> SE_CW1_Central1		<b>Date:</b> 06/08/2018		
	No actionable defects found							
<b>Batch:</b>	41014876 - Inspection Batch			<b>Route:</b> SE_CW1_Central1		<b>Date:</b> 10/07/2018		
	No actionable defects found							
<b>Batch:</b>	41012024 - Inspection Batch			<b>Route:</b> SE_CW1_Central1		<b>Date:</b> 24/05/2018		
42011862	1no pothole	24/05/2018	Westbound west of pedestrian crossing at school entrance	RD: CW Pothole	Internal		Committed	50010362
<b>Batch:</b>	41010570 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Date:</b> 07/05/2018		
42010093	1no broken cut buff tactile flag	07/05/2018	On the east corner of Archibald Place	RD: FW Slabs Broken/Missing	Internal		Committed	50008955
<b>Batch:</b>	41010569 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Date:</b> 07/05/2018		
42010092	1no rocking 900x600 pcc grey flag 3no sunken cut tactile flags 1no sunken cut 600x600 pc grey flag 1no broken cut 750x600 pc grey flag	07/05/2018	On the west corner at Archibald Place	RD: FW Slabs Rocking	Internal		Committed	50008954
<b>Batch:</b>	41010548 - Inspection Batch			<b>Route:</b> Ad hoc Route		<b>Date:</b> 07/05/2018		
42010091	1no rocking 900x600 pcc grey flag 1no rocking cut 600x600 pcc grey flag 1no missing cut 600x600 pcc grey flag	07/05/2018	On the west corner of Archibald Place	RD: FW Slabs Rocking	Internal		Committed	50008953

## Site History Report

Effective: 01/02/2018 to 31/01/2020

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Lauriston Place (7902983)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 1.00		<b>Asset - Locn.:</b> Ward 11 - From Forrest Road to Brougham Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality		
<b>Batch:</b> 41009339 - Inspection Batch				<b>Route:</b> SE_CW1_Central1		<b>Date:</b> 26/04/2018		
42009074	1no pothole	26/04/2018	Westbound lane at the pedestrian crossing outside entrance to George Heriot school	RD: CW Pothole	Internal		Committed	50006544
<b>Batch:</b> 41007856 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 09/04/2018		
42007349	1no pothole	09/04/2018	Westbound lane at the pedestrian crossing outside entrance to George Heriot school	RD: CW Pothole	Internal		No Action Required	
<b>Batch:</b> 41007420 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 05/04/2018		
42006967	1no broken 900 x600 pcc grey flag 1no broken and sunken 750x600 pcc grey flag 1no broken cut 600x600 pcc grey flag	05/04/2018	Outside no101	RD: FW Slabs Broken/Missing	Internal		Committed	50006167
<b>Batch:</b> 41006516 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 22/03/2018		
42006125	3no potholes	22/03/2018	On the yellow box junction travelling westbound towards West Tollcross	RD: CW Pothole	Internal		Committed	50005467
<b>Batch:</b> 41006513 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 22/03/2018		
42006122	1no pothole	22/03/2018	On the pedestrian crossing at the corner of Earl Grey Street	RD: CW Pothole	Internal		Committed	50005464
<b>Batch:</b> 41006512 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 22/03/2018		
42006121	1no pothole	22/03/2018	At the junction at Earl Grey Street	RD: CW Pothole	Internal		Committed	50005463
<b>Batch:</b> 41006510 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 22/03/2018		
42006119	1no pothole	22/03/2018	On the pedestrian crossing at the junction of Brougham Street	RD: CW Pothole	Internal		Committed	50005461
<b>Batch:</b> 41006180 - Inspection Batch				<b>Route:</b> SE_CW1_North1		<b>Date:</b> 18/03/2018		
No actionable defects found								
<b>Batch:</b> 41004989 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 06/03/2018		
42004615	1no pothole	06/03/2018	On the pedestrian crossing at Middle Meadow Walk	RD: CW Pothole	Internal		Committed	50004133
<b>Batch:</b> 41004807 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 27/02/2018		
42004517	1no sml pothole	27/02/2018	Outside Electron Wheels on straight ahead lane	RD: CW Pothole	Internal		Committed	50004035
<b>Batch:</b> 41004802 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 27/02/2018		
42004512	3no potholes	27/02/2018	On left turn from Earl Grey Street into Lauriston Place, at edge of yellow box	RD: CW Pothole	Internal		Committed	50004030
<b>Batch:</b> 41003814 - Inspection Batch				<b>Route:</b> SE_CW1_North1		<b>Date:</b> 15/02/2018		
No actionable defects found								

## Site History Report

**Effective:** 01/02/2018 to 31/01/2020

**Asset Number:** 1.00 to 9.00

**Display Action Officer:** No

**Site:** Lauriston Place (7902983)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 2.00		<b>Asset - Locn.:</b> Ward 11 - Loop road on south side outside Lauriston Building			<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality	
<b>Batch:</b> 41049166 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 09/01/2020
42043532	1no rocking flag	09/01/2020	On right hand side of doorway to Lauriston building	RD: FW Slabs Rocking	Internal		Committed	50049199
<b>Batch:</b> 41039271 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 03/09/2019
42037536	3no broken 600x900 pcc flags	03/09/2019	Outside the lauriston building	RD: FW Slabs Broken/Missing	Internal		Committed	50041482
<b>Batch:</b> 41031466 - Inspection Batch				<b>Route:</b> SE_CF2_Lauriston1				<b>Date:</b> 24/04/2019
42029717	Area of dislodged setts approx 8mx4m	24/04/2019	At the exit to the service road	RD: CW Setts Dislodged	Internal		No Action Required	
42029714	Area of dislodged setts approx 8mx4m	24/04/2019	At the entrance to the Lauriston Building	RD: CW Setts Dislodged	Internal		No Action Required	
42029711	2no loose setts	24/04/2019	Near lit pole 68BZ	RD: CW Setts Dislodged	Internal		No Action Required	
42029715	Area of dislodged setts approx 6mx4m	24/04/2019	Just west of the entrance to the Lauriston building	RD: CW Setts Dislodged	Internal		No Action Required	
42029719	Remove 3no setts causing trip hazard and infill with hra	24/04/2019	On the service road outside the blood donor centre	RD: CW Pothole	Internal		Committed	50031574
<b>Batch:</b> 41021927 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 12/11/2018
42022040	1no bollard and 1no channel stone needs reset	12/11/2018	Outside the blood donor centre	RD: Bollard Damage/Missing/Neve	Internal		Committed	50018867