

37358 West Register Street

We would be grateful if you could please provide the following for the period Jan 2020 to May 2022:

Your inspection and repair policy documents

Any reports from you to the relevant party in respect of apparatus requiring repair on West Register Street.

Please refer to the attached operational guidance. Please note that utility apparatus is inspected as per the NRSWA Code of Practice available at:

<https://roadworks.scot/sites/default/files/publications/248/Code%20Practice%20for%20Inspections%20-%202001%20April%202020.pdf>

There were two defects recorded in this period for defective utility apparatus as per the attached Defect Report.

Please also refer to the attached Damaged Apparatus Report.

Damaged utility companies' apparatus is reported by the Council through the Scottish Road Works Register who then identify and correspond with the relevant utility company. Any information regarding utility companies and third parties is therefore held by the Scottish Road Works Commissioner and we cannot provide this information on their behalf.