

## Site History Report

**Effective:** 01/09/2021 to 31/05/2022  
**Display Action Officer:** No

**Asset Number:** 3.00 to 3.00  
**Site:** Lanark Road (7906108)

**Site:** Lanark Road (7906108)

**Locality:** Kingsknowe, Edinburgh, City of Edinburgh

**Area:** South West Locality

### Condition Survey

Defect No.	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 3.00	<b>Asset - Locn.:</b> Ward 9 - From the Water of Leith north-east to Slateford Road a			<b>Feature Type:</b> Road Asset			<b>Area:</b> South West Locality	
<b>Batch:</b> 41125207 - Inspection Batch	No actionable defects found			<b>Route:</b> SW_CW1_North1				<b>Date:</b> 31/05/2022
<b>Batch:</b> 41125204 - Inspection Batch	No actionable defects found			<b>Route:</b> SW_CW1_East1				<b>Date:</b> 31/05/2022
<b>Batch:</b> 41123515 - Inspection Batch	No actionable defects found			<b>Route:</b> SW_CW1_North1				<b>Date:</b> 04/05/2022
<b>Batch:</b> 41123512 - Inspection Batch	No actionable defects found			<b>Route:</b> SW_CW1_East1				<b>Date:</b> 04/05/2022
<b>Batch:</b> 41122852 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 26/04/2022
42099854	Patch required approx 1.5mx3m	26/04/2022	Outside fairbairn & Laing hairdresser	RD: CW Cracked/Broken	Internal		Committed	50112404
<b>Batch:</b> 41122851 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 26/04/2022
42099853	Patch required approx 2mx4m	26/04/2022	Opposite craiglockhart avenue at traffic lights	RD: CW Cracked/Broken	Internal		Committed	50112403
<b>Batch:</b> 41121777 - Inspection Batch	No actionable defects found			<b>Route:</b> SW_CW1_East1				<b>Date:</b> 05/04/2022
<b>Batch:</b> 41121569 - Inspection Batch	No actionable defects found			<b>Route:</b> SW_CW1_North1				<b>Date:</b> 01/04/2022
<b>Batch:</b> 41117836 - Inspection Batch	No actionable defects found			<b>Route:</b> SW_CW1_North1				<b>Date:</b> 02/03/2022
<b>Batch:</b> 41117833 - Inspection Batch	No actionable defects found			<b>Route:</b> SW_CW1_East1				<b>Date:</b> 02/03/2022
<b>Batch:</b> 41117156 - Inspection Batch				<b>Route:</b> SW_CF1_LanarkRoad1				<b>Date:</b> 26/02/2022
42094167	Temp repair needs patched	26/02/2022	Outside water of leith visitors centre	RD: CW Cracked/Broken	Internal		Uncommitted	50086227
42094173	Damaged manhole cover	26/02/2022	Outside number 8	RU: Utility Apparatus	Internal		Uncommitted	50107512
42094170	Damaged utility cover	26/02/2022	Outside number 8	RU: Utility Apparatus	Internal		No Action Required	
42094169	Pothole on cw	26/02/2022	At traffic lights heading towards Chesser just before junction with craiglockhart avenue	RD: CW Pothole	Internal		Uncommitted	50086230
42094168	Broken cracked fw	26/02/2022	Outside number 22	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50107511
42094172	Refresh all the markings including all junctions	26/02/2022	Entire cw including all junctions	RD: Markings Refresh	Internal		Uncommitted	50107514
<b>Batch:</b> 41116676 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 22/02/2022
42093877	C/way pot hole	22/02/2022	Just after traffic lights east bound	RD: CW Pothole	Internal		Committed	50107201
<b>Batch:</b> 41116591 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 22/02/2022
42093827	Cw pothole marked on site	22/02/2022	Lanark rd east bound at bus stop before water of leith	RD: CW Pothole	Internal		Committed	50107165

## Site History Report

Effective: 01/09/2021 to 31/05/2022

Asset Number: 3.00 to 3.00

Display Action Officer: No

Site: Lanark Road (7906108)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	3.00	<b>Asset - Locn.:</b>	Ward 9 - From the Water of Leith north-east to Slateford Road a		<b>Feature Type:</b>	Road Asset	<b>Area:</b>	South West Locality
<b>Batch:</b>	41116584 - Inspection Batch		<b>Route:</b>		Ad hoc Route		<b>Date:</b>	22/02/2022
42093815	Cw pothole marked on site	22/02/2022	Lanark rd at stateford rd traffic lights	RD: CW Pothole	Internal		Committed	50107153
<b>Batch:</b>	41115863 - Inspection Batch		<b>Route:</b>		Ad hoc Route		<b>Date:</b>	16/02/2022
42093061	1.5mx2m permanent patch required	16/02/2022	Bottom of craiglockhart avenue outside browns body services	RD: CW Pothole	Internal		Committed	50106474
<b>Batch:</b>	41115182 - Inspection Batch		<b>Route:</b>		Ad hoc Route		<b>Date:</b>	10/02/2022
42092467	Road: Defective / Damaged (Enquiry 1322920)	10/02/2022	Collapsed manhole in Lane two eastbound o/s No 8	RU: Utility Apparatus	Internal		Uncommitted	50105873
<b>Batch:</b>	41114869 - Inspection Batch		<b>Route:</b>		Ad hoc Route		<b>Date:</b>	08/02/2022
42092249	C/way pot hole	08/02/2022	Slateford Rd junction	RD: CW Pothole	Internal		Committed	50105645
<b>Batch:</b>	41114506 - Inspection Batch		<b>Route:</b>		SW_CW1_East1		<b>Date:</b>	02/02/2022
No actionable defects found								
<b>Batch:</b>	41114468 - Inspection Batch		<b>Route:</b>		SW_CW1_North1		<b>Date:</b>	02/02/2022
No actionable defects found								
<b>Batch:</b>	41113531 - Inspection Batch		<b>Route:</b>		Ad hoc Route		<b>Date:</b>	19/01/2022
42090041	Pothole as marked	19/01/2022	Opp Craiglockhart Avenue heading to town	RD: CW Pothole	Internal		Committed	50103431
<b>Batch:</b>	41112388 - Inspection Batch		<b>Route:</b>		SW_CW1_East1		<b>Date:</b>	07/01/2022
No actionable defects found								
<b>Batch:</b>	41112078 - Inspection Batch		<b>Route:</b>		SW_CW1_North1		<b>Date:</b>	06/01/2022
42088414	Pothole	06/01/2022	O/S entrance to Water of Leth centre	RD: CW Pothole	Internal		Committed	50101908
42088416	Damaged carriageway manhole	06/01/2022	O/S no 8	RU: Utility Apparatus	Internal		Uncommitted	50101910
42088384	Pothole	06/01/2022	Near Craiglochart Avenue at lights heading west	RD: CW Pothole	Internal		Committed	50101873
<b>Batch:</b>	41109309 - Inspection Batch		<b>Route:</b>		SW_CW1_East1		<b>Date:</b>	03/12/2021
42085978	Rocking and noisy manhole, cover low in the frame	03/12/2021	City bound, before junction with Craiglockhart Avenue. Outside no 8	RU: Utility Apparatus	Internal		Uncommitted	50099251
42085976	1no CW pothole	03/12/2021	Outside no4	RD: CW Pothole	Internal		Committed	50099250
<b>Batch:</b>	41109171 - Inspection Batch		<b>Route:</b>		SW_CW1_North1		<b>Date:</b>	02/12/2021
No actionable defects found								
<b>Batch:</b>	41109033 - Inspection Batch		<b>Route:</b>		Ad hoc Route		<b>Date:</b>	02/12/2021
42085905	Pothole on cw	02/12/2021	Lanark road at traffick lights near junction with craiglockhart avenue	RD: CW Pothole	Internal		Committed	50099159
<b>Batch:</b>	41106369 - Inspection Batch		<b>Route:</b>		SW_CW1_East1		<b>Date:</b>	02/11/2021
No actionable defects found								
<b>Batch:</b>	41106088 - Inspection Batch		<b>Route:</b>		SW_CW1_North1		<b>Date:</b>	01/11/2021
No actionable defects found								
<b>Batch:</b>	41102118 - Inspection Batch		<b>Route:</b>		SW_CW1_East1		<b>Date:</b>	30/09/2021
No actionable defects found								

## Site History Report

Effective: 01/09/2021 to 31/05/2022

Asset Number: 3.00 to 3.00

Display Action Officer: No

Site: Lanark Road (7906108)

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	3.00	<b>Asset - Locn.:</b>	Ward 9 - From the Water of Leith north-east to Slateford Road a	<b>Feature Type:</b>	Road Asset		<b>Area:</b>	South West Locality
<b>Batch:</b>	41101841 - Inspection Batch			<b>Route:</b>	SW_CW1_North1			<b>Date:</b> 28/09/2021
	No actionable defects found							
<b>Batch:</b>	41100261 - Inspection Batch			<b>Route:</b>	Ad hoc Route			<b>Date:</b> 15/09/2021
42078368	Manhole cover was lifted by water during the storm on 4/7/21	15/09/2021	Outside number 1 old Landrover garage at junction Craiglockhart Avenue	RU: Utility Apparatus	Internal		Uncommitted	50091828

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order	
<b>Asset:</b>	3.00	<b>Asset - Locn.:</b>	Ward 9 - From the Water of Leith north-east to Slateford Road a	<b>Feature Type:</b>	Road Asset		<b>Area:</b>	South West Locality
4004672	c/way breking up lane closure temp Bus stop req (RD: Asphalt / Bitmac Surface)	O/sNo 11 on greenways before Bus stop	RD: Cat 3 - 60 Day	Job Annulled	24/11/2015	22/12/2015	Est.	
4010950	Chocked gully (Gully: Blocked / Flooding)	O/s garage junction	Non Routine (One Off Works)	Job Annulled	23/03/2017			
50086227	Temp repair needs patched (RD: CW Cracked/Broken)	Outside water of leith visitors centre	RD: Cat 4 - 12 Months	No code allocated	30/06/2021	30/06/2022	Est.	
50086230	Pothole on cw (RD: CW Pothole)	At traffic lights heading towards Chesser just before junction with craiglockhart avenue	RD: Cat 4 - 12 Months	Job Annulled	30/06/2021	30/06/2022	Est.	
50091828	Manhole cover was lifted by water during the storm on 4/7/21 (RU: Utility Apparatus)	Outside number 1 old Landrover garage at junction Craiglockhart Avenue	RU: Fail High Risk	Job Complete	15/09/2021	15/09/2021	Act.	
50099159	Pothole on cw (RD: CW Pothole)	Lanark road at traffick lights near junction with craiglockhart avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/12/2021	03/12/2021	Act. ROAD/82057077	
50099250	1no CW pothole (RD: CW Pothole)	Outside no4	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/12/2021	06/12/2021	Act. ROAD/82057118	
50099251	Rocking and noisy manhole, cover low in the frame (RU: Utility Apparatus)	City bound, before junction with Craiglockhart Avenue. Outside no 8	RU: Fail Med.Risk (Apparatus)	Job Complete	03/12/2021	03/12/2021	Act.	
50101873	Pothole (RD: CW Pothole)	Near Craiglochart Avenue at lights heading west	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/01/2022	07/01/2022	Act. ROAD/82058231	
50101908	Pothole (RD: CW Pothole)	O/S entrance to Water of Letlh centre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/01/2022	07/01/2022	Act. ROAD/82058260	
50101910	Damaged carriageway manhole (RU: Utility Apparatus)	O/S no 8	RU: Fail Med.Risk (Apparatus)	Job Complete	06/01/2022	06/01/2022	Act.	
50103431	Pothole as marked (RD: CW Pothole)	Opp Craiglockhart Avenue heading to town	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/01/2022	20/01/2022	Act. ROAD/82058955	
50105645	C/way pot hole (RD: CW Pothole)	Slateford Rd junction	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	08/02/2022	08/02/2022	Act. ROAD/82059905	
50105873	Road: Defective / Damaged (Enquiry 1322920) (RU: Utility Apparatus)	Collapsed manhole in Lane two eastbound o/s No 8	RU: Fail Med.Risk (Apparatus)	Job Complete	10/02/2022	10/02/2022	Act.	
50106474	1.5mx2m permanent patch required (RD: CW Pothole)	Bottom of craiglockhart avenue outside browns body services	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/02/2022	17/02/2022	Act. ROAD/82060346	

## Site History Report

Effective: 01/09/2021 to 31/05/2022

Asset Number: 3.00 to 3.00

Display Action Officer: No

Site: Lanark Road (7906108)

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 3.00	<b>Asset - Locn.:</b> Ward 9 - From the Water of Leith north-east to Slateford Road a		<b>Feature Type:</b> Road Asset		<b>Area:</b> South West Locality	
50107153	Cw pothole marked on site (RD: CW Pothole)	Lanark rd at stateford rd traffic lights	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/02/2022	23/02/2022	Act. ROAD/82060744
50107165	Cw pothole marked on site (RD: CW Pothole)	Lanark rd east bound at bus stop before water of leith	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2022	23/02/2022	Act. ROAD/82060755
50107201	C/way pot hole (RD: CW Pothole)	Just after traffic lights east bound	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/02/2022	23/02/2022	Act. ROAD/82060775
50107511	Broken cracked fw (RD: FW HRA Cracked/Broken)	Outside number 22	RD: Cat 4 - 12 Months	No code allocated	26/02/2022	26/02/2023	Est.
50107512	Damaged utility cover (RU: Utility Apparatus)	Outside number 8	RU: Fail Med.Risk (Apparatus)	Job Complete	26/02/2022	28/02/2022	Act.
50107514	Refresh all the markings including all junctions (RD: Markings Refresh)	Entire cw including all junctions	RD: Cat 4 - 12 Months	No code allocated	26/02/2022	26/02/2023	Est.
50112403	Patch required approx 2mx4m (RD: CW Cracked/Broken)	Opposite craiglockhart avenue at traffic lights	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/04/2022	01/05/2022	Act. ROAD/82063404
50112404	Patch required approx 1.5mx3m (RD: CW Cracked/Broken)	Outside fairbairn & Laing hairdresser	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/04/2022	01/05/2022	Act. ROAD/82063406