

Site History Report

Effective: 01/12/2021 to 01/04/2022
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Balgreen Road (7902555)

Site: Balgreen Road (7902555)

Locality: Saughtonhall, Edinburgh, City of Edinburgh

Area: South West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 6 - From Corstorphine Road south to railway		Feature Type: Road Asset		Area: North West Locality		
Batch: 41120247 - Inspection Batch				Route: Ad hoc Route		Date: 23/03/2022		
42097373	Road: Defective / Damaged (Enquiry 1349636)	23/03/2022	Collapsed water valve cover under rail bridge	RU: Utility Apparatus	Internal		Uncommitted	50110004
Batch: 41120215 - Inspection Batch				Route: Ad hoc Route		Date: 22/03/2022		
42097314	Road: Defective / Damaged (Enquiry 1348615)permanent repair required to carriageway in hra	22/03/2022	Outside 93	RD: CW Rutting	Internal		Uncommitted	50109955
Batch: 41120159 - Inspection Batch				Route: NW_CW1_East1		Date: 22/03/2022		
42097240	1 carriageway pothole	22/03/2022	Near junction of saughton hall avenue west	RD: CW Pothole	Internal		Committed	50109881
Batch: 41119265 - Inspection Batch				Route: Ad hoc Route		Date: 14/03/2022		
42096005	Pothole on carriageway	14/03/2022	Junction Corstorphine Road heading south	RD: CW Pothole	Internal		Committed	50108977
Batch: 41116501 - Inspection Batch				Route: NW_CW1_East1		Date: 22/02/2022		
42093750	10 carriageway potholes	22/02/2022	Junction with corstorphine road	RD: CW Pothole	Internal		Committed	50107088
Batch: 41114060 - Inspection Batch				Route: Ad hoc Route		Date: 26/01/2022		
42090925	Road: Defective / Damaged (Enquiry 1311429) pothole on carriageway	26/01/2022	Lpost 77	RD: CW Pothole	Internal		Committed	50104276
Batch: 41113686 - Inspection Batch				Route: NW_CW1_East1		Date: 21/01/2022		
42090357	1 carriageway pothole	21/01/2022	Junction with balgreen avenue	RD: CW Pothole	Internal		Committed	50103725
42090355	1 carriageway pothole	21/01/2022	Outside 24	RD: CW Pothole	Internal		Committed	50103723
42090356	1 carriageway pothole	21/01/2022	Outside 22	RD: CW Pothole	Internal		Committed	50103724
Batch: 41111391 - Inspection Batch				Route: NW_CW1_East1		Date: 21/12/2021		
No actionable defects found								
Batch: 41108756 - Inspection Batch				Route: NW_CF1_BalgreenRoad1		Date: 01/12/2021		
42085713	8 carriageway potholes	01/12/2021	Junction with corstorphine road	RD: CW Pothole	Internal		Committed	50098983
42085732	Damaged bollard and flags	01/12/2021	Balgreen Road junction Baird Drive	RD: Markings Refresh	Internal		Uncommitted	5003503
42085725	Sign face deterioration	01/12/2021	Outside 121	RD: Unlit Sign Damaged/Missing	Internal		Uncommitted	5003771
42085727	Break out existing HRA footway and replace with hra wearing course and dbm base course. Relay kerb and remove tree roots.	01/12/2021	outside no 123 the pavement is coming up because of the roots and is also affecting the ladies wall	RD: CW Pothole	Internal		Uncommitted	5004367
42085709	Form 2 new drop crossings and reinstate footway in hra with red chip.	01/12/2021	Balgreen Road junction Corstorphine Road	RD: NEW Dropped Kerbs	Internal		Uncommitted	5003458
42085730	Damaged sign pole	01/12/2021	Junction Saughtonhall Drive	RD: Unlit Sign Damaged/Missing	Internal		Uncommitted	5006024
42085714	1mx4m p	01/12/2021	Junction with corstorphine road	RD: CW Cracked/Broken	Internal		Uncommitted	50098984
42085729	Yellow hatching faded	01/12/2021	Junction Saughtonhall Drive	RD: Markings Refresh	Internal		Uncommitted	5000432
42085733	Replace damaged bollard and flags	01/12/2021	Junction Baird Drive	RD: Markings Refresh	Internal		Uncommitted	5003687
42085747	1 carriageway pothole	01/12/2021	Crossing at lamppost BCS77	RD: CW Pothole	Internal		Committed	50099013

Site History Report

Effective: 01/12/2021 to 01/04/2022
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Balgreen Road (7902555)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 6 - From Corstorphine Road south to railway	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41108756 - Inspection Batch			Route:	NW_CF1_BalgreenRoad1		Date:	01/12/2021
42085706	Yellow Hatching faded	01/12/2021	Junction South Beechwood	RD: Markings Refresh	Internal		Uncommitted	5000437
42085711	1 carriageway pothole	01/12/2021	Junction with corstorphine road	RD: CW Pothole	Internal		Committed	50098981
42085717	Pavement: Damaged / Defective (Enquiry 302752),break out and relay drop crossing, reinstate hra footway	01/12/2021	o/s 37 Balgreen Road cus says the kerb outside his driveway is to low and he keeps hitting the bottom of his car which is causing damage	RD: CW Pothole	Internal		Uncommitted	5005323
42085715	1 carriageway pothole	01/12/2021	At crossing near saughton crescent	RD: CW Pothole	Internal		Committed	50098986
42085716	Markings faded	01/12/2021	Whole Street	RD: Markings Refresh	Internal		Uncommitted	5000438
42085724	Replace damaged gully brander with new	01/12/2021	Outside 113	RD: CW Pothole	Internal		Uncommitted	50047759
42085746	2 carriageway potholes	01/12/2021	Outside 22	RD: CW Pothole	Internal		Committed	50099011
42085721	2 carriageway potholes	01/12/2021	Junction with glendevon avenue	RD: CW Pothole	Internal		Committed	50098989
42085737	Patch required around tree	01/12/2021	Outside 132	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50098998
42085723	Resurface east side footway from junction with saughtonhall ave to no 125 balgreen road	01/12/2021	Footway uneven caused by tree roots,	RD: FW Tree Root Tar	Internal		Uncommitted	5012982
42085734	Gully Chocked	01/12/2021	At bridge heading south	Gully: Blocked / Flooding	Internal		Uncommitted	5007163
42085744	2 carriageway potholes	01/12/2021	Outside 26	RD: CW Pothole	Internal		Committed	50099009
42085720	Tree roots pushing up the tar	01/12/2021	Outside 49	RD: FW Tree Root Tar	Internal		Uncommitted	50098988
42085718	Road: Defective / Damaged (Enquiry 535829)	01/12/2021	Entire road surface over length of road. Dangerous to cycle on Noisey for residents Vibrations actually vibrating houses when large vehicles pass. Needs smooth resurfacing	RD: Capital Assessment Requird	Internal		Uncommitted	5012256
Asset:	2.00	Asset - Locn.:	Ward 7 - From railway south to Gorgie Road including roundabo	Feature Type:	Road Asset		Area:	South West Locality
Batch:	41121586 - Inspection Batch			Route:	SW_CW1_North1		Date:	01/04/2022
	No actionable defects found							
Batch:	41121292 - Inspection Batch			Route:	Ad hoc Route		Date:	30/03/2022
42098192	Cw cracked broken needs permanent patch approximately 2 x 1 sqm	30/03/2022	In bus lane at roundabout cw edge	RD: CW Cracked/Broken	Internal		Uncommitted	50110728
Batch:	41121291 - Inspection Batch			Route:	Ad hoc Route		Date:	30/03/2022
42098191	Cw cracked broken needs permanent patch approximately 3 x 1 sqm	30/03/2022	On approach to roundabout	RD: CW Cracked/Broken	Internal		Uncommitted	50110727
Batch:	41121290 - Inspection Batch			Route:	Ad hoc Route		Date:	30/03/2022
42098190	Cw cracked broken needs permanent patch approximately 2 x 2 sqm	30/03/2022	Between roundabout at saughton park entrance	RD: CW Cracked/Broken	Internal		Uncommitted	50110726
Batch:	41121289 - Inspection Batch			Route:	Ad hoc Route		Date:	30/03/2022
42098189	Cw cracked broken needs permanent patch approximately 3 x 2 sqm	30/03/2022	On exiting roundabout heading towards saughton park	RD: CW Cracked/Broken	Internal		Uncommitted	50110725

Site History Report

Effective: 01/12/2021 to 01/04/2022
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Balgreen Road (7902555)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 7 - From railway south to Gorgie Road including roundabo		Feature Type: Road Asset		Area: South West Locality		
Batch:	41121284 - Inspection Batch		Route: Ad hoc Route				Date: 30/03/2022	
42098188	Cw cracked broken needs permanent patch approximately 10x 2 sqm	30/03/2022	On roundabout outside number 20	RD: CW Cracked/Broken	Internal		Uncommitted	50110724
Batch:	41121282 - Inspection Batch		Route: Ad hoc Route				Date: 30/03/2022	
42098187	Cw cracked broken needs permanent patch approximately 10 x 1 sqm	30/03/2022	On roundabout	RD: CW Cracked/Broken	Internal		Uncommitted	50110723
Batch:	41121281 - Inspection Batch		Route: Ad hoc Route				Date: 30/03/2022	
42098186	Pothole	30/03/2022	On roundabout	RD: CW Pothole	Internal		Committed	50110722
Batch:	41121280 - Inspection Batch		Route: Ad hoc Route				Date: 30/03/2022	
42098185	Cw cracked broken needs permanent patch approximately 6 x 2 sqm	30/03/2022	Adjacent to numbers 4 and 6 at bus stop	RD: CW Cracked/Broken	Internal		Uncommitted	50110721
Batch:	41121279 - Inspection Batch		Route: Ad hoc Route				Date: 30/03/2022	
42098184	Cw cracked broken needs permanent patch approximately 1.5 x 1.5 sqm	30/03/2022	Adjacent to number 6 at bus stop	RD: CW Cracked/Broken	Internal		Uncommitted	50110720
Batch:	41121278 - Inspection Batch		Route: Ad hoc Route				Date: 30/03/2022	
42098183	Cw cracked broken needs permanent patch approximately 6x2 sqm	30/03/2022	Outside number 8	RD: CW Cracked/Broken	Internal		Uncommitted	50110719
Batch:	41121277 - Inspection Batch		Route: Ad hoc Route				Date: 30/03/2022	
42098182	Cw cracked broken needs permanent patch approximately 13x1 sqm	30/03/2022	Outside number 191	RD: CW Cracked/Broken	Internal		Uncommitted	50110718
Batch:	41120052 - Inspection Batch		Route: Ad hoc Route				Date: 21/03/2022	
42097166	1x pothole	21/03/2022	At the start of the rail bridge	RD: CW Pothole	Internal		Committed	50109805
Batch:	41117466 - Inspection Batch		Route: SW_CW1_North1				Date: 01/03/2022	
42094469	Pothole	01/03/2022	Near bridge	RD: CW Pothole	Internal		Committed	50107773
42094472	Pothole	01/03/2022	At bus stop	RD: CW Pothole	Internal		Committed	50107776
Batch:	41117335 - Inspection Batch		Route: Ad hoc Route				Date: 01/03/2022	
42094429	Road: Defective / Damaged (Enquiry 1335005)	01/03/2022	There is a steel plate covering a collapsed road drain but the steel plate's non slip surface has worn away and needs replaced in line with the Safety at Streetworks and Roadworks Code of Practice. The ramping probably needs replaced too. As the steel plate is a serious hazard to cyclists it should be repaired without delay.	RD: Gully Damaged/Sunken	Internal		Committed	50107717

Site History Report

Effective: 01/12/2021 to 01/04/2022
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Balgreen Road (7902555)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 7 - From railway south to Gorgie Road including roundabo		Feature Type: Road Asset		Area: South West Locality		
Batch: 41116872 - Inspection Batch		Route: Ad hoc Route				Date: 24/02/2022		
42093977	<p>Road: Defective / Damaged - Dear Sir/Madam</p> <p>Last night I ran into a pothole which caused an immediate burst tire (front, passenger side) and damage to the alloy wheel to my car and still have to get it checked by a mechanic for other damage such as wheel misalignment, damaged spring or other damage caused by the impact. The car right in front of me suffered exactly the same fate. Also,- meanwhile waiting for the AA (30 minutes) - a third car stopped and the driver checked their front passenger side tyre (probably nearly missing to get a burst tyre). He said that this time it is ok but had a burst tyre not long ago (very likely on the same spot as me and the other driver). I would like to claim for the damage this huge and deep pothole caused to my car. It is very dangerous, I hope no more car get damaged by this pothole -or even worst, someone may can get hurt.</p> <div></div> <p>Date and time of the accident: 22/02/2022, 20:30</p> <p>Place of the accident: Balgreen Road, about 50 yards from the traffic light turning to Gorgie Road.</p> <p>I was driving from North Bridge <div></div> via the western Approach.</p> <p>Could you please send me a claim form.</p> <p>Your sincerely</p> <p><div></div></p> <p>(Enquiry 1333140) (RD: CW Pothole)Road: Defective / Damaged - pothole</p>	24/02/2022	Place of the accident: Balgreen Road, about 50 yards from the traffic light turning to Gorgie RoadO/s No 191	RD: CW Pothole	Internal	Committed	50107330	
Batch: 41116452 - Inspection Batch		Route: Ad hoc Route				Date: 22/02/2022		
42093739	Road: Defective / Damaged (Enquiry 1331170)	22/02/2022	Pot hole before entrance to park just after R/A	RD: CW Pothole	Internal	Committed	50107076	

Site History Report

Effective: 01/12/2021 to 01/04/2022

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Balgreen Road (7902555)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 2.00		Asset - Locn.: Ward 7 - From railway south to Gorgie Road including roundabo			Feature Type: Road Asset		Area: South West Locality	
Batch: 41115597 - Inspection Batch		Route: Ad hoc Route					Date: 15/02/2022	
42092777	Road: Defective / Damaged (Enquiry 1326487)	15/02/2022	West side of R/A	RD: CW Pothole	Internal		Committed	50106236
Batch: 41114595 - Inspection Batch		Route: SW_CW1_North1					Date: 03/02/2022	
42091812	Pothole	03/02/2022	On roundabout	RD: CW Pothole	Internal		Committed	50105202
42091813	Pothole	03/02/2022	20m from traffic lights	RD: CW Pothole	Internal		Committed	50105203
Batch: 41114191 - Inspection Batch		Route: Ad hoc Route					Date: 28/01/2022	
42091182	Road: Defective / Damaged (Enquiry 1300888)	28/01/2022	potholes at roundabout, west side Category: c/way breaking at R/A opp No 20	RD: CW Pothole	Internal		Committed	50104567
Batch: 41112137 - Inspection Batch		Route: SW_CW1_North1					Date: 06/01/2022	
42088396	Potholes x 2	06/01/2022	Near lamppost BCS 15	RD: CW Pothole	Internal		Committed	50101889
42088395	2 x potholes	06/01/2022	Opp no 4 at bus stop	RD: CW Pothole	Internal		Committed	50101888
Batch: 41111724 - Inspection Batch		Route: Ad hoc Route					Date: 29/12/2021	
42088127	Road: Defective / Damaged (Enquiry 1297002)	29/12/2021	Steel plate protecting defective gully but not sure up lift plate make good c/way ?	RD: Gully Damaged/Sunken	Internal		Committed	50101454
Batch: 41110954 - Inspection Batch		Route: Ad hoc Route					Date: 16/12/2021	
42087479	Road: Defective / Damaged (Enquiry 1291054)	16/12/2021	Collapsed water value cover on c:way south side of rail bridge see attached photos	RU: Utility Apparatus	Internal		Uncommitted	50100602
Batch: 41109429 - Inspection Batch		Route: SW_CW1_North1					Date: 06/12/2021	
42086003	Damaged utility cover on fw x2 needs replaced	06/12/2021	Just coming off roundabout heading towards Stevenson drive. At lamppost 17	RU: Utility Apparatus	Internal		Uncommitted	50099314
42085999	Pothole on cw	06/12/2021	At bus stop just before roundabout	RD: CW Pothole	Internal		Committed	50099311