

37629 Pavement Repairs - Ladywell House

In a follow-up to 34078 –

We refer to the attached Site History Report.

We note 3 entries in relation to the damaged pavement near no.22 / Ladywell House.

We would be grateful if you would supply us with your records showing the works carried out to repair this section of the pavement following the inspections on 28/06/2016, 07/06/2019 & 17/05/2021.

28/06/2016 and 17/05/2021 Record:

Job		Additional		Current Status	
Job Number	5006445	Placed on W.O.		Uncommitted	Parent Job
Site	Ladywell Road 7900460 ... Broomhall, Edinburgh, City of Edinburgh				
Asset Id		Location	Whole Street		
Asset No	1.00 Road Asset				
Area	North West Locality	Ward	06-Corstonphine/Murrayfield		
Description	Pavement: Damaged / Defective - Broken up paving surface (Enquiry 373023).break out existing		Work Location	at bus stop just before Ladywell House,outside 22	
Job Type	RDHR RD: HRA / Bituminous Repair		Estimated Value	.00	
Hazard Type	RD: Programmed Work				
Priority	Non Routine (One Off Works)	Price Factor	Priced/Target		
Cost Code				Partial Payments	
Customer	CEC Roads	Est. Start Date	00/00/0000 00:00:00		
Customer Reference		Actual Start Date	00/00/0000 00:00:00		
Pref. Contr.		Est. Completion	00/00/0000 00:00:00		
Status	9300 Job Annulled	Target Completion	00/00/0000 00:00:00		
Officer	ROMU Ronnie Murray	Actual Completion	00/00/0000 00:00:00		

SOR Items		Status Log		Child Jobs	
Log No.	Logged Date	Effective Date	Status	Notes	Detail
2	17/05/2021 09:51:14	17/05/2021 09:51:14	Job Annulled	Inspected 17/05/2021	
1	28/06/2016 14:54:03	28/06/2016 14:52:11	Job Raised	Defect Job created via Connector	

The records for 28/06/2016 and 17/05/2021 are the same record. The defect was originally recorded on 28/06/2016 and closed (annulled) on 17/05/2021, hence it shows up on the report under both dates.

07/06/2019 Record:

Job		Additional		Current Status	
Job Number	50035109	Placed on W.O.	ROAD/82022260	Committed	Parent Job
Site	Ladywell Road 7900460 ...				
	Broomhall, Edinburgh, City of Edinburgh				
Asset Id	...		Location	Whole Street	
Asset No	1.00 Road Asset				
Area	North West Locality		Ward	06-Constorphine/Murrayfield	
Description	Pavement: Damaged / Defective - pavement badly repaired - see attached letter (Enquiry 30008824)		Work Location	Potholes on footway between bus stop and ladywell house	
Job Type	RDSR RD: Surfacing Response ...		Estimated Value	80.00	
Hazard Type	RD: Standard				
Priority	RD: Cat 2 - 5 Day		Price Factor	Zero Rated	
Cost Code	...		Partial Payments <input type="checkbox"/>		
Customer	CEC Roads		Est. Start Date	00/00/0000 00:00:00	
Customer Reference			Actual Start Date	10/06/2019 08:01:20	
Pref. Contr.	ROAD Roads: Reactive ...		Est. Completion	14/06/2019 10:28:06	
Status	RD02 RD: Made Safe Job Complete ...		Target Completion	14/06/2019 10:28:06	
Officer	KWO0 Kevin Wood ...		Actual Completion	10/06/2019 08:04:15	

SOR Items			Status Log		Child Jobs	
Log No.	Logged Date	Effective Date	Status	Notes		
5	10/06/2019 08:04:15	10/06/2019 08:04:15	RD: Made Safe Job Complete	Job has been allocated to Team 'RD: Surfacing 2' (SUR2)		
4	10/06/2019 08:01:20	10/06/2019 08:01:20	Arrived on site	Job has been allocated to Team 'RD: Surfacing 2' (SUR2)		
3	07/06/2019 11:27:40	07/06/2019 11:27:40	Job Scheduled	Job has been allocated to Team 'RD: Surfacing 2' (SUR2)		
2	07/06/2019 10:30:14	07/06/2019 10:30:14	Job Committed	Updating Job Status to Committed		
1	07/06/2019 10:30:11	07/06/2019 10:28:06	Job Raised	Defect Job created via Connector		