

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Site: Crewe Road North (7901387)

Locality: Royston, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality		
Batch: 41178661 - Inspection Batch		Route: NW_CF2_Crewe1				Date: 16/01/2024		
42144126	break out existing HRA footway and replace with hra wearing course and dbm base course, adjust street furniture as required	16/01/2024	From 165-171	RD: FW HRA Depression/Sunker	Internal		Uncommitted	5011280
42144132	Footpath needs resurfaced	16/01/2024	Outside 152	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50099869
42144135	Footway needs renewed	16/01/2024	Between 75-71	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50099845
42144133	1 low kerb	16/01/2024	At arneil drive	RD: FW Kerb Dislodged/Rocking	Internal		Uncommitted	50124782
42144127	Patch required around box Approx 1m x 1m	16/01/2024	At west Granton road	RD: CW Cracked/Broken	Internal		Uncommitted	50124780
42144129	Whole footway needs resurfaced	16/01/2024	From 192-210	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50099880
42144130	.5mx5m patch	16/01/2024	Outside 184	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50099874
42144125	Collapsed double catv box on fw	16/01/2024	Opposite 194	RU: Utility Apparatus	Internal		Uncommitted	50150278
42144134	Raise sunken gully frame	16/01/2024	Opposite 71	RD: Gully Damaged/Sunken	Internal		Uncommitted	50031612
42144146	Cw cracked and broken Approx 4m x 1m Patch required	16/01/2024	Opposite scotmid at bus stop	RD: CW Cracked/Broken	Internal		Uncommitted	50124778
Batch: 41178602 - Inspection Batch		Route: NW_CW1_North1				Date: 16/01/2024		
No actionable defects found								
Batch: 41177282 - Inspection Batch		Route: Ad hoc Route				Date: 04/01/2024		
42143247	Road: Defective / Damaged (Enquiry 1670023) pothole on carriageway	04/01/2024	Outside 215	RD: CW Pothole	Internal		Committed	50149350
Batch: 41172963 - Inspection Batch		Route: Ad hoc Route				Date: 29/11/2023		
42140650	Sunken double manhole	29/11/2023	Opposite 192 at mast	RU: Utility Apparatus	Internal		Uncommitted	50146800
Batch: 41172429 - Inspection Batch		Route: Ad hoc Route				Date: 21/11/2023		
42140085	Drainage: General Enquiry - Crewe Road North - blocked drain, on the walk path. [redacted] is not able to get passed when it rains heavily [redacted] cannot get down the stairs another way. (Enquiry 34007779) footway gully chocked	21/11/2023	Outside 157	Gully: Blocked / Flooding	Internal		Committed	50146258
Batch: 41172058 - Inspection Batch		Route: Ad hoc Route				Date: 17/11/2023		
42139718	Road: Defective / Damaged (Enquiry 1645670) pothole on carriageway	17/11/2023	Opposite 71	RD: CW Pothole	Internal		Committed	50145937
Batch: 41168316 - Inspection Batch		Route: NW_CW1_North1				Date: 11/10/2023		
No actionable defects found								
Batch: 41161866 - Inspection Batch		Route: Ad hoc Route				Date: 27/07/2023		
42132878	Pavement: Damaged / Defective (Enquiry 1587847) relay loose kerb	27/07/2023	Outside 223	RD: FW Kerb Dislodged/Rocking	Internal		Committed	50140006

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality		
Batch: 41161822 - Inspection Batch				Route: NW_CW1_North1		Date: 26/07/2023		
No actionable defects found								
Batch: 41160544 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 06/07/2023		
42131374	Damaged cover x2	06/07/2023	Opposite side of footway from number 192	RU: Utility Apparatus	Internal		Uncommitted	50138883
Batch: 41160205 - Inspection Batch				Route: Ad hoc Route		Date: 03/07/2023		
42131159	Pavement: Damaged / Defective (Enquiry 1574877)trip at box	03/07/2023	East footway outside Leonardos	RD: FW HRA Pothole	Internal		Committed	50138714
Batch: 41158917 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 08/06/2023		
No actionable defects found								
Batch: 41157098 - Inspection Batch				Route: Ad hoc Route		Date: 12/05/2023		
42127338	Pavement: Damaged / Defective (Enquiry 1550129) damaged footway manhole	12/05/2023	Outside 163	RU: Utility Apparatus	Internal		Uncommitted	50135968
Batch: 41156836 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 10/05/2023		
42127070	Collapsed catv box Causing trip hazard and surrounding footway to break up Has been reported before (la ref 3299435)	09/05/2023	Opposite 192	RU: Utility Apparatus	Internal		Uncommitted	50135777
Batch: 41154988 - Inspection Batch				Route: NW_CW1_North1		Date: 18/04/2023		
No actionable defects found								
Batch: 41154425 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 06/04/2023		
No actionable defects found								
Batch: 41151393 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 06/03/2023		
No actionable defects found								
Batch: 41148086 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 06/02/2023		
42117533	Double catv box rocking and sunk Surrounding fw breaking up as a result	06/02/2023	Opposite 192	RU: Utility Apparatus	Internal		Uncommitted	50128484
42117538	Cabinet rusted away and lying on fw Cables exposed	06/02/2023	Outside 213	RU: Utility Apparatus	Internal		Uncommitted	50128486
Batch: 41142901 - Inspection Batch				Route: NW_CW1_North1		Date: 10/01/2023		
No actionable defects found								
Batch: 41142580 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 06/01/2023		
No actionable defects found								
Batch: 41140801 - Inspection Batch				Route: NW_CF2_Crewe1		Date: 22/12/2022		
42113677	break out existing HRA footway and replace with hra wearing course and dbm base course, adjust street furniture as required. Work to be carried out under chapter 8	22/12/2022	From 165-171	RD: FW HRA Depression/Sunker	Internal		No Action Required	

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout			Feature Type: Road Asset		Area: North West Locality	
Batch: 41140801 - Inspection Batch		Route: NW_CF2_Crewe1					Date: 22/12/2022	
42113685	1 low kerb	22/12/2022	At arneil drive	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42113687	Replace 2 m of missing railings	22/12/2022	Bottom of the steps to cycle path	RD: Railing Damage/Missing/New	Internal		Committed	50114040
42113678	Cw cracked and broken Approx 4m x 1m Patch required	22/12/2022	Opposite scotmid at bus stop	RD: CW Cracked/Broken	Internal		No Action Required	
42113680	Cw cracked and broken around box Approx 1m x 1m Patch required	22/12/2022	At west Granton road	RD: CW Cracked/Broken	Internal		No Action Required	
42113686	Footway needs renewed	22/12/2022	Between 75-71	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42113684	Footpath needs resurfaced	22/12/2022	Outside 152	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42113682	Whole footway needs resurfaced	22/12/2022	From 192-210	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42113683	.5mx5m patch	22/12/2022	Outside 184	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch: 41140109 - Inspection Batch		Route: Ad hoc Route					Date: 20/12/2022	
42113479	Road: Defective / Damaged (Enquiry 1477473)pothole on carriageway outside lane	20/12/2022	Heading to Crewe Toll roundabout	RD: CW Pothole	Internal		Committed	50124597
Batch: 41137771 - Inspection Batch No actionable defects found		Route: NW_Pennywell_6Month					Date: 06/12/2022	
Batch: 41134796 - Inspection Batch No actionable defects found		Route: NW_Pennywell_6Month					Date: 03/11/2022	
Batch: 41134430 - Inspection Batch No actionable defects found		Route: NW_CW1_North1					Date: 31/10/2022	
Batch: 41132075 - Inspection Batch No actionable defects found		Route: NW_Pennywell_6Month					Date: 05/10/2022	
Batch: 41130205 - Inspection Batch No actionable defects found		Route: NW_Pennywell_6Month					Date: 25/08/2022	
Batch: 41128587 - Inspection Batch No actionable defects found		Route: NW_CW1_North1					Date: 02/08/2022	
Batch: 41128417 - Inspection Batch No actionable defects found		Route: NW_Pennywell_6Month					Date: 28/07/2022	
Batch: 41126370 - Inspection Batch		Route: NW_Pennywell_6Month					Date: 23/06/2022	
42103777	Rel	23/06/2022	Outside 231	RD: FW Kerb Dislodged/Rocking	Internal		Uncommitted	50057942
42103768	Raise sunken gully frame	23/06/2022	Opposite 71	RD: Gully Damaged/Sunken	Internal		No Action Required	
42103771	Footpath needs resurfaced	23/06/2022	Outside 152	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42103767	Footpath broken up, carry out permanent repair	23/06/2022	On cycleway steps comming from North	RD: FW HRA Cracked/Broken	Internal		Archived	5010564

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 4 - From West Granton Road to Crewe Toll Roundabout	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41126370 - Inspection Batch			Route:	NW_Pennywell_6Month		Date:	23/06/2022
42103774	break out existing HRA footway and replace with hra wearing course and dbm base course, adjust street furniture as required. Work to be carried out under chapter 8	23/06/2022	From 165-171	RD: FW HRA Depression/Sunker	Internal		No Action Required	
42103770	Damaged bollard	23/06/2022	Outside number 146	RD: Bollard Damage/Missing/Nev	Internal		Committed	50115650
42103781	Broken fw at utility cover	23/06/2022	On opposite side of fw from number 192	RD: FW HRA Pothole	Internal		Committed	50115654
42103769	Footway needs renewed	23/06/2022	Between 75-71	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42103779	Pothole	23/06/2022	Adjacent to Boswall parkway	RD: CW Pothole	Internal		Committed	50115652
42103782	Fw edge is gone	23/06/2022	Between bridge and number 113	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50115655
42103776	1.5x2.5m patch	23/06/2022	Opposite 252	RD: CW Cracked/Broken	Internal		Uncommitted	50100683
42103783	Broken fw at steps. Trip hazard	23/06/2022	Bottom of steps	RD: FW HRA Pothole	Internal		Committed	50115656
42103772	.5mx5m patch	23/06/2022	Outside 184	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42103775	Damaged bollard	23/06/2022	Junction Boswall Parkway	RD: Bollard Damage/Missing/Nev	Internal		Archived	50021259
42103766	7m of railing missing	23/06/2022	North bound lane just before bridge	RD: Railing Damage/Missing/Nev	Internal		Uncommitted	50099850
42103773	Whole footway needs resurfaced	23/06/2022	From 192-210	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41125691 - Inspection Batch			Route:	NW_CW1_North1		Date:	09/06/2022
	No actionable defects found							
Batch:	41124593 - Inspection Batch			Route:	NW_Pennywell_6Month		Date:	23/05/2022
42101717	Replace 6m of missing railings	23/05/2022	Bottom of the steps to cycle path	RD: Railing Damage/Missing/Nev	Internal		No Action Required	
42101719	Tar surrounding catv box breaking up leaving gap into the chamber	23/05/2022	Outside 163	RU: Utility Apparatus	Internal		Uncommitted	50114042
42101724	1 carriageway pothole	23/05/2022	At crossing outside 150	RD: CW Pothole	Internal		Committed	50114047
Batch:	41123939 - Inspection Batch			Route:	Ad hoc Route		Date:	12/05/2022
42101027	Road: Defective / Damaged (Enquiry 1375479)carriageway collapse,break open carriageway and reinstate as required	12/05/2022	Outside Leonardo	RD: CW Pothole	Internal		Committed	50113443
Batch:	41123896 - Inspection Batch			Route:	Ad hoc Route		Date:	11/05/2022
42100978	C/W and F/W dangerous subsidence needs to be made safe	11/05/2022	At Leonardo approx 30m south of bridge	RD: Other Defect Type	Internal		Committed	50113387
Batch:	41123799 - Inspection Batch			Route:	NW_CW1_North1		Date:	10/05/2022
	No actionable defects found							
Batch:	41122834 - Inspection Batch			Route:	NW_Pennywell_6Month		Date:	26/04/2022
42099835	Replace missing bollard	26/04/2022	Outside scotmid	RD: Bollard Damage/Missing/Nev	Internal		Committed	50112384
Batch:	41122589 - Inspection Batch			Route:	Ad hoc Route		Date:	20/04/2022
42099705	Pothole on carriageway	20/04/2022	Opposite Boswall Parkway	RD: CW Pothole	Internal		Committed	50112145

Site History Report

Effective: 01/01/2020 to 05/02/2024

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality		
Batch:	41122456 - Inspection Batch			Route: Ad hoc Route		Date: 19/04/2022		
42099600	Pavement: Damaged / Defective (Enquiry 1362285)damaged brickwork at footway manhole	19/04/2022	Outside 163	RU: Utility Apparatus	Internal		Uncommitted	50112042
Batch: 41121990 - Inspection Batch No actionable defects found				Route: NW_CW1_North1		Date: 07/04/2022		
Batch: 41121676 - Inspection Batch No actionable defects found				Route: NW_Pennywell_6Month		Date: 04/04/2022		
Batch: 41119550 - Inspection Batch No actionable defects found				Route: NW_CW1_North1		Date: 16/03/2022		
Batch: 41118762 - Inspection Batch				Route: Ad hoc Route		Date: 08/03/2022		
42095466	Road: Defective / Damaged (Enquiry 1340966) pothole on footway	08/03/2022	Outside 213	RD: FW HRA Pothole	Internal		Committed	50108507
Batch: 41118741 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 08/03/2022		
42095400	1 carriageway pothole	08/03/2022	Opposite scotmid	RD: CW Pothole	Internal		Committed	50108470
Batch: 41115788 - Inspection Batch				Route: Ad hoc Route		Date: 16/02/2022		
42092989	Road: Defective / Damaged (Enquiry 1327169) pothole on carriageway	16/02/2022	Outside 213	RD: CW Pothole	Internal		Committed	50106406
Batch: 41115670 - Inspection Batch No actionable defects found				Route: NW_CW1_North1		Date: 15/02/2022		
Batch: 41115025 - Inspection Batch No actionable defects found				Route: NW_Pennywell_6Month		Date: 08/02/2022		
Batch: 41113092 - Inspection Batch No actionable defects found				Route: NW_CW1_North1		Date: 14/01/2022		
Batch: 41112923 - Inspection Batch No actionable defects found				Route: NW_Pennywell_6Month		Date: 12/01/2022		
Batch: 41111102 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 17/12/2021		
42087531	1.5x2.5m patch	17/12/2021	Opposite 252	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41110227 - Inspection Batch No actionable defects found				Route: NW_CW1_North1		Date: 10/12/2021		
Batch: 41110164 - Inspection Batch				Route: NW_CF1_CreweNorth1		Date: 09/12/2021		
42086685	.5mx5m patch	09/12/2021	Outside 184	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42086701	break out existing HRA footway and replace with hra wearing course and dbm base course, adjust street furniture as required. Work to be carried out under chapter 8	09/12/2021	From 165-171	RD: FW HRA Depression/Sunker	Internal		No Action Required	

Site History Report

Effective: 01/01/2020 to 05/02/2024

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality		
Batch: 41110164 - Inspection Batch		Route: NW_CF1_CreweNorth1				Date: 09/12/2021		
42086696	Parking: APM new (Enquiry 34003852)	09/12/2021	201 Crewe Road North Edinburgh City of Edinburgh EH5 1LP	RD: Markings APM Bay	Internal		Uncommitted	50087484
42086657	7m of railing missing	09/12/2021	North bound lane just before bridge	RD: Railing Damage/Missing/New	Internal		No Action Required	
42086672	Raise sunken gully frame	09/12/2021	Opposite 71	RD: Gully Damaged/Sunken	Internal		No Action Required	
42086693	Damaged bollard	09/12/2021	Junction Boswall Parkway	RD: Bollard Damage/Missing/New	Internal		No Action Required	
42086681	Footpath needs resurfaced	09/12/2021	Outside 152	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42086651	Footway needs renewed	09/12/2021	Between 75-71	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42086697	Rel	09/12/2021	Outside 231	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42086653	Footpath broken up, carry out permanent repair	09/12/2021	On cycleway steps comming from North direction	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42086694	Damaged bollards	09/12/2021	Junction Boswall Parkway	RD: Bollard Damage/Missing/New	Internal		Archived	50007274
42086676	Fpath upgrade 60x4	09/12/2021	159 to163	RD: Capital Assessment Requird	Internal		Archived	6002444
42086691	Whole footway needs resurfaced	09/12/2021	From 192-210	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42086695	1 rocking cut perfecta	09/12/2021	Outside granton art studios	RD: FW Slabs Rocking	Internal		Committed	50099882
Batch: 41107929 - Inspection Batch		Route: NW_Pennywell_6Month				Date: 22/11/2021		
42084698	1 Rocking cut at manhole	22/11/2021	Outside scotmid	RD: FW Slabs Rocking	Internal		Committed	50097982
Batch: 41107233 - Inspection Batch No actionable defects found		Route: NW_CW1_North1				Date: 11/11/2021		
Batch: 41105355 - Inspection Batch		Route: NW_Pennywell_6Month				Date: 26/10/2021		
42081154	Footway pothole at catv box	26/10/2021	Opposite no77	RD: FW HRA Pothole	Internal		Committed	50094771
Batch: 41104785 - Inspection Batch		Route: Ad hoc Route				Date: 20/10/2021		
42080877	1no cw pothole	20/10/2021	Opposite Lindsay and Gilmour chemist	RD: CW Pothole	Internal		Committed	50094389
Batch: 41103656 - Inspection Batch No actionable defects found		Route: NW_CW1_North1				Date: 11/10/2021		
Batch: 41102300 - Inspection Batch		Route: NW_Pennywell_6Month				Date: 01/10/2021		
42079257	1 carriageway pothole at gully	01/10/2021	Opposite no71	RD: CW Pothole	Internal		Committed	50092828
42079259	1 carriageway pothole	01/10/2021	Opposite Lindsay and gilmour pharmacy	RD: CW Pothole	Internal		Committed	50092830
Batch: 41100201 - Inspection Batch		Route: Ad hoc Route				Date: 15/09/2021		
42078249	1no pothole at Toby cover	15/09/2021	Just north of cycle path bridge	RD: CW Pothole	Internal		Committed	50091758
Batch: 41099833 - Inspection Batch No actionable defects found		Route: NW_CW1_North1				Date: 09/09/2021		
Batch: 41099566 - Inspection Batch		Route: NW_Pennywell_6Month				Date: 03/09/2021		
42077318	1 footway pothole	03/09/2021	Outside 170	RD: FW HRA Pothole	Internal		Committed	50091080
Batch: 41097680 - Inspection Batch		Route: NW_Pennywell_6Month				Date: 06/08/2021		
42075232	1 carriageway pothole	06/08/2021	At gully outside no77	RD: CW Pothole	Internal		Committed	50089020

Site History Report

Effective: 01/01/2020 to 05/02/2024

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality		
Batch: 41097613 - Inspection Batch				Route: NW_CW1_North1		Date: 05/08/2021		
No actionable defects found								
Batch: 41097107 - Inspection Batch				Route: Ad hoc Route		Date: 28/07/2021		
42074605	Parking: APM new (Enquiry 34003919)join to 201 make as one	28/07/2021	203 Crewe Road North Edinburgh City of Edinburgh EH5 1LP	RD: Markings APM Bay	Internal		Committed	50088405
Batch: 41097076 - Inspection Batch				Route: Ad hoc Route		Date: 28/07/2021		
42074580	Covers: Damaged / Defective - Raised manhole cover (Enquiry 1216225)loose footway box	28/07/2021	o/s 153	RU: Utility Apparatus	Internal		Uncommitted	50088356
Batch: 41096302 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 15/07/2021		
42073584	1 carriageway pothole	15/07/2021	At crossing opp lamppost 50	RD: CW Pothole	Internal		Committed	50087510
42073582	2 carriageway potholes	15/07/2021	Opposite Lindsay and gilmour pharmacy	RD: CW Pothole	Internal		Committed	50087509
Batch: 41096279 - Inspection Batch				Route: Ad hoc Route		Date: 14/07/2021		
42073561	Parking: APM new (Enquiry 34003852)	14/07/2021	201 Crewe Road North Edinburgh City of Edinburgh EH5 1LP	RD: Markings APM Bay	Internal		No Action Required	
Batch: 41096278 - Inspection Batch				Route: Ad hoc Route		Date: 14/07/2021		
42073560	Parking: APM new (Enquiry 34003852)	14/07/2021	201 Crewe Road North Edinburgh City of Edinburgh EH5 1LP	RD: Markings APM Bay	Internal		Committed	50087483
Batch: 41095648 - Inspection Batch				Route: NW_CW1_North1		Date: 07/07/2021		
No actionable defects found								
Batch: 41094654 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 21/06/2021		
No actionable defects found								
Batch: 41093164 - Inspection Batch				Route: NW_CW1_North1		Date: 28/05/2021		
No actionable defects found								
Batch: 41092644 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 19/05/2021		
42069321	Scottish water cover damaged	19/05/2021	Outside granton art studios	RU: Utility Apparatus	Internal		Uncommitted	50083402
42069323	1 rocking cut perfecta & 1 rocking perfecta at manhole	19/05/2021	Outside 234	RD: FW Slabs Rocking	Internal		Committed	50083404
Batch: 41091257 - Inspection Batch				Route: NW_CW1_North1		Date: 27/04/2021		
No actionable defects found								
Batch: 41090783 - Inspection Batch				Route: NW_Pennywell_6Month		Date: 21/04/2021		
No actionable defects found								

Site History Report

Effective: 01/01/2020 to 05/02/2024

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality		
Batch:	41089948 - Inspection Batch			Route: Ad hoc Route		Date: 08/04/2021		
42066762	Road: Defective / Damaged (Enquiry 1155141)replace missing traffic island bollards	08/04/2021	Outside 178	RD: Weebol Damage/Missing/Ne	Internal		Committed	50080716
Batch:	41089303 - Inspection Batch			Route: NW_CW1_North1		Date: 31/03/2021		
No actionable defects found								
Batch:	41088405 - Inspection Batch			Route: NW_Pennywell_6Month		Date: 22/03/2021		
42065006	Replace damaged bollard	22/03/2021	Junction with boswall parkway	RD: Bollard Damage/Missing/Nev	Internal		Committed	50079101
42065012	Cover damaged on manhole	22/03/2021	Outside no133	RU: Utility Apparatus	Internal		Committed	50079107
Batch:	41085806 - Inspection Batch			Route: NW_CW1_North1		Date: 01/03/2021		
No actionable defects found								
Batch:	41084317 - Inspection Batch			Route: NW_Pennywell_6Month		Date: 22/02/2021		
42061950	2no rocking slabs	22/02/2021	At cash machine outside scotmid	RD: FW Slabs Rocking	Internal		Committed	50075754
Batch:	41080890 - Inspection Batch			Route: Ad hoc Route		Date: 04/02/2021		
42060522	Road: Defective / Damaged (Enquiry 1112184) pothole on carriageway	04/02/2021	213 crewe road north	RD: CW Pothole	Internal		Committed	50074063
Batch:	41080814 - Inspection Batch			Route: Ad hoc Route		Date: 03/02/2021		
42060495	Road: Defective / Damaged (Enquiry 1111998) pothole on carriageway	03/02/2021	Opposite 234 crewe road north	RD: CW Pothole	Internal		Committed	50074023
Batch:	41080299 - Inspection Batch			Route: NW_CW1_North1		Date: 01/02/2021		
No actionable defects found								
Batch:	41075203 - Inspection Batch			Route: NW_Pennywell_6Month		Date: 15/01/2021		
No actionable defects found								
Batch:	41072041 - Inspection Batch			Route: NW_CW1_North1		Date: 30/12/2020		
No actionable defects found								
Batch:	41071319 - Inspection Batch			Route: NW_Pennywell_6Month		Date: 16/12/2020		
42057577	1no Footway pothole at kerb	16/12/2020	Opposite Crewe road gardens	RD: FW HRA Pothole	Internal		Committed	50070261
Batch:	41070357 - Inspection Batch			Route: NW_CW1_North1		Date: 07/12/2020		
42056686	Large pothole at gully	07/12/2020	Opp no71	RD: CW Pothole	Internal		Committed	50069224
Batch:	41069573 - Inspection Batch			Route: NW_Pennywell_6Month		Date: 20/11/2020		
No actionable defects found								
Batch:	41068602 - Inspection Batch			Route: NW_CW1_North1		Date: 06/11/2020		
No actionable defects found								
Batch:	41067195 - Inspection Batch			Route: NW_Pennywell_6Month		Date: 15/10/2020		
No actionable defects found								
Batch:	41064467 - Inspection Batch			Route: NW_CW1_North1		Date: 29/09/2020		
No actionable defects found								

Site History Report

Effective: 01/01/2020 to 05/02/2024

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 4 - From West Granton Road to Crewe Toll Roundabout	Feature Type:	Road Asset		Area: North West Locality	
Batch:	41063110 - Inspection Batch			Route:	NW_Pennywell_6Month		Date:	10/09/2020
42053324	Various potholes	10/09/2020	From junction of Crewe loan to no200	RD: FW HRA Pothole	Internal		Committed	50062370
Batch:	41062097 - Inspection Batch			Route:	NW_CW1_North1		Date:	24/08/2020
	No actionable defects found							
Batch:	41059886 - Inspection Batch			Route:	NW_CF1_CreweNorth1		Date:	07/07/2020
42051388	Footpath broken up, carry out permanent repair	07/07/2020	On cycleway steps comming from North direction	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42051387	Raise sunken gully frame	07/07/2020	Opposite 71	RD: Gully Frame Damaged	Internal		No Action Required	
42051386	Signs: Defective / Damaged - Bridge was hit by lorry, it impacted the height restriction sign, police advised that bridge looks ok but are requesting that its is checked by council to be sure, also sign will need replaced (Enquiry 679294),height sign damaged new sign and bracket required	07/07/2020	Bridge on Crewe road north	RD: Other Defect Type	Internal		Committed	50012961
42051384	Rel	07/07/2020	Outside 231	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42051383	Pothole on carriageway	07/07/2020	Outside 215	RD: CW Pothole	Internal		Committed	50057941
42051385	Sunken carriageway manhole	07/07/2020	Outside 113	RU: Utility Apparatus	Internal		Uncommitted	50057943
42051389	Damaged bollard	07/07/2020	Junction Boswall Parkway	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
Batch:	41059858 - Inspection Batch			Route:	NW_CW1_North1		Date:	06/07/2020
	No actionable defects found							
Batch:	41058644 - Inspection Batch			Route:	NW_Pennywell_6Month		Date:	15/06/2020
	No actionable defects found							
Batch:	41058397 - Inspection Batch			Route:	NW_CW1_North1		Date:	02/06/2020
	No actionable defects found							
Batch:	41057594 - Inspection Batch			Route:	NW_CW1_North1		Date:	04/05/2020
	No actionable defects found							
Batch:	41057283 - Inspection Batch			Route:	NW_Pennywell_6Month		Date:	29/04/2020
42050037	Relay loose flag and infill gap at bus stop	29/04/2020	Outside Pharmacy	RD: FW Slabs Rocking	Internal		Committed	50055942
42050039	Damaged bollards	29/04/2020	Junction Boswall Parkway	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42050038	Pavement: Damaged / Defective - Pavement in a complete mess according to the customer. [REDACTED] . Holes in the pavement. (Enquiry 512099)break out existing HRA footway and replace with hra wearing course and dbm base course, adjust street furniture as required. Work to be carried out under chapter 8	29/04/2020	From 165-171	RD: FW HRA Depression/Sunker	Internal		No Action Required	

Site History Report

Effective: 01/01/2020 to 05/02/2024

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset			Area: North West Locality	
Batch: 41056347 - Inspection Batch				Route: Ad hoc Route				Date: 02/04/2020
42049602	Pothole on carriageway	02/04/2020	Junction Boswall Parkway	RD: CW Pothole	Internal		Committed	50055517
Batch: 41056298 - Inspection Batch				Route: NW_CW1_North1				Date: 02/04/2020
42049589	Pothole	02/04/2020	Opposite no 71 at gully surrounds	RD: CW Pothole	Internal		Committed	50055504
42049592	4 potholes	02/04/2020	Opposite junction with Boswell Parkway	RD: CW Pothole	Internal		Committed	50055507
Batch: 41054395 - Inspection Batch				Route: NW_CW1_North1				Date: 02/03/2020
42048007	pothole on carriageway	02/03/2020	Junction Boswall Parkway	RD: CW Pothole	Internal		Committed	50053814
Batch: 41051732 - Inspection Batch				Route: Ad hoc Route				Date: 11/02/2020
42045829	Covers: Missing - Manhole cover missing (Enquiry 957798)	11/02/2020	o/s no 153 on pavement	RU: Utility Apparatus	Internal		Uncommitted	50051610
Batch: 41051286 - Inspection Batch				Route: NW_CW1_North1				Date: 04/02/2020
No actionable defects found								
Batch: 41048816 - Inspection Batch				Route: NW_CW1_North1				Date: 06/01/2020
No actionable defects found								
Asset:	2.00	Asset - Locn.: Ward 4 - 3 branches: 1 off east side of Crewe Road North; 2 off		Feature Type: Road Asset			Area: North West Locality	
Batch: 41178681 - Inspection Batch				Route: NW_CF2_Crewe1				Date: 16/01/2024
No actionable defects found								
Batch: 41161821 - Inspection Batch				Route: NW_CW1_North1				Date: 26/07/2023
No actionable defects found								
Batch: 41154989 - Inspection Batch				Route: NW_CW1_North1				Date: 18/04/2023
No actionable defects found								
Batch: 41142911 - Inspection Batch				Route: NW_CW1_North1				Date: 10/01/2023
No actionable defects found								
Batch: 41140846 - Inspection Batch				Route: NW_CF2_Crewe1				Date: 22/12/2022
No actionable defects found								
Batch: 41134440 - Inspection Batch				Route: NW_CW1_North1				Date: 31/10/2022
No actionable defects found								
Batch: 41128586 - Inspection Batch				Route: NW_CW1_North1				Date: 02/08/2022
No actionable defects found								
Batch: 41106616 - Inspection Batch				Route: NW_CF2_Crewe1				Date: 04/11/2021
No actionable defects found								
Asset:	3.00	Asset - Locn.: Remote footpath between Crewe Road North & Crewe Road We		Feature Type: Road Asset			Area: North West Locality	
Batch: 41178680 - Inspection Batch				Route: NW_CF2_Crewe1				Date: 16/01/2024
No actionable defects found								
Batch: 41161823 - Inspection Batch				Route: NW_CW1_North1				Date: 26/07/2023
No actionable defects found								

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Remote footpath between Crewe Road North & Crewe Road We		Feature Type: Road Asset		Area: North West Locality		
Batch: 41154990	- Inspection Batch No actionable defects found			Route: NW_CW1_North1			Date: 18/04/2023	
Batch: 41142912	- Inspection Batch No actionable defects found			Route: NW_CW1_North1			Date: 10/01/2023	
Batch: 41140845	- Inspection Batch No actionable defects found			Route: NW_CF2_Crewe1			Date: 22/12/2022	
Batch: 41134431	- Inspection Batch No actionable defects found			Route: NW_CW1_North1			Date: 31/10/2022	
Batch: 41128585	- Inspection Batch No actionable defects found			Route: NW_CW1_North1			Date: 02/08/2022	
Batch: 41106617	- Inspection Batch No actionable defects found			Route: NW_CF2_Crewe1			Date: 04/11/2021	

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality	
5011280	break out existing HRA footway and replace with hra wearing course and dbm base course, adjust street furniture as required. (RD: Asphalt / Bitmac Surface)	From 165-171	RD: Cat 4 - Programmed	Job Raised	12/06/2017	12/06/2018	Est.
50007276	Give way faded (RD: Markings Refresh)	Junction West Granton Road	Non Routine (One Off Works)	Job Complete	15/04/2018	24/01/2020	Act. ROAD/82021024
50012961	Signs: Defective / Damaged - Bridge was hit by lorry, it impacted the height restriction sign, police advised that bridge looks ok but are requesting that its is checked by council to be sure, also sign will need replaced (Enquiry 679294),height sign damaged new sign and bracket required (RD: Other Defect Type)	Bridge on Crewe road north	Non Routine (One Off Works)	Job Complete	10/07/2018	07/07/2020	Act. ROAD/82018711

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality	
50016845	Signs: Defective / Damaged - Bridge was hit by lorry, it impacted the height restriction sign, police advised that bridge looks ok but are requesting that its is checked by council to be sure, also sign will need replaced (Enquiry 679294),height sign damaged new sign and bracket required (RD: Other Defect Type)	Bridge on Crewe road north	RD: Cat 4 - Programmed	Job Complete	10/07/2018	27/11/2020	Act. RSTO16/82000241
50031612	Raise sunken gully frame (RD: Gully Sunken/Damaged Frame)	Opposite 71	RD: Cat 4 - Programmed	No code allocated	24/04/2019	24/04/2020	Est.
50043455	Replace missing railings with new (RD: Railing Damage/Missing/New)	Pedestrian crossing outside Leonardo heading south	RD: Cat 3 - 60 Day	Job Complete	03/10/2019	24/02/2020	Act. ROAD/82026842
50051610	Covers: Missing - Manhole cover missing (Enquiry 957798) (RU: Utility Apparatus)	o/s no 153 on pavement	RU: Fail Med.Risk (Apparatus)	Job Complete	11/02/2020	12/02/2020	Act.
50053814	pothole on carriageway (RD: CW Pothole)	Junction Boswall Parkway	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/03/2020	03/03/2020	Act. ROAD/82034289
50055504	Pothole (RD: CW Pothole)	Opposite no 71 at gully surrounds	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/04/2020	03/04/2020	Act. ROAD/82035684
50055507	4 potholes (RD: CW Pothole)	Opposite junction with Boswell Parkway	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/04/2020	03/04/2020	Act. ROAD/82035687
50055517	Pothole on carriageway (RD: CW Pothole)	Junction Boswall Parkway	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/04/2020	03/04/2020	Act. ROAD/82035697
50055942	Relay loose flag and infill gap at bus stop (RD: FW Slabs Rocking)	Outside Pharmacy	Non Routine (One Off Works)	Job Complete	29/04/2020	16/09/2020	Act. ROAD/82039433
50057941	Pothole on carriageway (RD: CW Pothole)	Outside 215	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/07/2020	07/07/2020	Act. ROAD/82037398
50057942	Rel (RD: FW Kerb Dislodged/Rocking)	Outside 231	RD: Cat 4 - Programmed	Job Annulled	07/07/2020	07/07/2021	Est.
50057943	Sunken carriageway manhole (RU: Utility Apparatus)	Outside 113	RU: Fail Med.Risk (Apparatus)	Job Complete	07/07/2020	07/07/2020	Act.
50062370	Various potholes (RD: FW HRA Pothole)	From junction of Crewe loan to no200	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/09/2020	17/09/2020	Act. ROAD/82039340
50069224	Large pothole at gully (RD: CW Pothole)	Opp no71	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	07/12/2020	07/12/2020	Act. ROAD/82042124
50070261	1no Footway pothole at kerb (RD: FW HRA Pothole)	Opposite Crewe road gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/12/2020	17/12/2020	Act. ROAD/82042609
50074023	Road: Defective / Damaged (Enquiry 1111998) pothole on carriageway (RD: CW Pothole)	Opposite 234 crewe road north	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/02/2021	05/02/2021	Act. ROAD/82044341
50074063	Road: Defective / Damaged (Enquiry 1112184) pothole on carriageway (RD: CW Pothole)	213 crewe road north	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/02/2021	08/02/2021	Act. ROAD/82044359

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality	
50075754	2no rocking slabs (RD: FW Slabs At cash machine outside scotmid Rocking)		RD: Cat 3 - 60 Day	Job Complete	22/02/2021	03/03/2021	Act. ROAD/82045310
50079101	Replace damaged bollard (RD: Bollard Damage/Missing/New)	Junction with boswall parkway	RD: Cat 3 - 60 Day	Job Complete	22/03/2021	06/05/2021	Act. ROAD/82047348
50079107	Cover damaged on manhole (RU: Utility Apparatus)	Outside no133	RD: Cat 2 - 5 Day	Job Complete	22/03/2021	08/06/2021	Act. ROAD/82047354
50080716	Road: Defective / Damaged (Enquiry 1155141)replace missing traffic island bollards (RD: Weebol Damage/Missing/New)	Outside 178	RD: Cat 3 - 60 Day	Job Complete	08/04/2021	30/07/2021	Act. ROAD/82048398
50083402	Scottish water cover damaged (RU: Utility Apparatus)	Outside granton art studios	RU: Fail Low Risk	Job Complete	19/05/2021	19/05/2021	Act.
50083404	1 rocking cut perfecta & 1 rocking perfecta at manhole (RD: FW Slabs Rocking)	Outside 234	RD: Cat 3 - 60 Day	Job Complete	19/05/2021	26/05/2021	Act. ROAD/82049915
50087483	Parking: APM new (Enquiry 34003852) (RD: Markings APM Bay)	201 Crewe Road North Edinburgh City of Edinburgh EH5 1LP	Parking Operations	Job Complete	14/07/2021	09/08/2021	Act. ROAD/82052409
50087484	Parking: APM new (Enquiry 34003852) (RD: Markings APM Bay)	201 Crewe Road North Edinburgh City of Edinburgh EH5 1LP	Parking Operations	Job Annulled	14/07/2021	14/07/2021	Act.
50087509	2 carriageway potholes (RD: CW Pothole)	Opposite Lindsay and gilmour pharmacy	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/07/2021	16/07/2021	Act. ROAD/82052036
50087510	1 carriageway pothole (RD: CW Pothole)	At crossing opp lamppost 50	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/07/2021	16/07/2021	Act. ROAD/82052037
50088356	Covers: Damaged / Defective - Raised manhole cover (Enquiry 1216225)loose footway box (RU: Utility Apparatus)	o/s 153	RU: Fail Med.Risk (Apparatus)	Job Complete	28/07/2021	02/08/2021	Act.
50088405	Parking: APM new (Enquiry 34003919)join to 201 make as one (RD: Markings APM Bay)	203 Crewe Road North Edinburgh City of Edinburgh EH5 1LP	Parking Operations	Job Complete	28/07/2021	09/08/2021	Act. ROAD/82052700
50089020	1 carriageway pothole (RD: CW Pothole)	At gully outside no77	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/08/2021	09/08/2021	Act. ROAD/82052869
50091080	1 footway pothole (RD: FW HRA Pothole)	Outside 170	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/09/2021	07/09/2021	Act. ROAD/82054051
50091758	1no pothole at Toby cover (RD: CW Pothole)	Just north of cycle path bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/09/2021	16/09/2021	Act. ROAD/82054334
50092828	1 carriageway pothole at gully (RD: CW Pothole)	Opposite no71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/10/2021	04/10/2021	Act. ROAD/82054651
50092830	1 carriageway pothole (RD: CW Pothole)	Opposite Lindsay and gilmour pharmacy	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/10/2021	04/10/2021	Act. ROAD/82054653

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality	
50094389	1no cw pothole (RD: CW Pothole)	Opposite Lindsay and Gilmour chemist	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/10/2021	21/10/2021	Act. ROAD/82055186
50094771	Footway pothole at catv box (RD: FW HRA Pothole)	Opposite no77	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/10/2021	27/10/2021	Act. ROAD/82055328
50097982	1 Rocking cut at manhole (RD: FW Slabs Rocking)	Outside scotmid	RD: Cat 3 - 60 Day	Job Complete	22/11/2021	10/01/2022	Act. ROAD/82056605
50099845	Footway needs renewed (RD: FW HRA Cracked/Broken)	Between 75-71	RD: Cat 4 - Programmed	Job Annulled	09/12/2021	09/12/2021	Act.
50099850	7m of railing missing (RD: Railing Damage/Missing/New)	North bound lane just before bridge	RD: Cat 4 - Programmed	Job Annulled	09/12/2021	09/12/2021	Act.
50099869	Footpath needs resurfaced (RD: FW HRA Cracked/Broken)	Outside 152	RD: Cat 4 - Programmed	No code allocated	09/12/2021	09/12/2022	Est.
50099874	.5mx5m patch (RD: FW HRA Cracked/Broken)	Outside 184	RD: Cat 4 - Programmed	No code allocated	09/12/2021	09/12/2022	Est.
50099880	Whole footway needs resurfaced (RD: FW HRA Cracked/Broken)	From 192-210	RD: Cat 4 - Programmed	No code allocated	09/12/2021	09/12/2022	Est.
50099882	1 rocking cut perfecta (RD: FW Slabs Rocking)	Outside granton art studios	RD: Cat 3 - 60 Day	Job Complete	09/12/2021	10/01/2022	Act. ROAD/82057418
50100683	1.5x2.5m patch (RD: CW Cracked/Broken)	Opposite 252	RD: Cat 4 - Programmed	Job Annulled	17/12/2021	17/12/2021	Act.
50106406	Road: Defective / Damaged (Enquiry 1327169) pothole on carriageway (RD: CW Pothole)	Outside 213	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/02/2022	17/02/2022	Act. ROAD/82060307
50108470	1 carriageway pothole (RD: CW Pothole)	Opposite scotmid	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061444
50108507	Road: Defective / Damaged (Enquiry 1340966) pothole on footway (RD: FW HRA Pothole)	Outside 213	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061468
50112042	Pavement: Damaged / Defective (Enquiry 1362285)damaged brickwork at footway manhole (RU: Utility Apparatus)	Outside 163	RU: Fail Med.Risk (Apparatus)	Job Complete	19/04/2022	19/04/2022	Act.
50112145	Pothole on carriageway (RD: CW Pothole)	Opposite Boswall Parkway	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/04/2022	20/04/2022	Act. ROAD/82063306
50112384	Replace missing bollard (RD: Bollard Damage/Missing/New)	Outside scotmid	RD: Cat 3 - 60 Day	Job Complete	26/04/2022	27/04/2022	Act. ROAD/82063391
50113387	C/W and F/W dangerous subsidence needs to be made safe (RD: Other Defect Type)	At Leonardo approx 30m south of bridge	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	11/05/2022	11/05/2022	Act. ROAD/82063943
50113443	Road: Defective / Damaged (Enquiry 1375479)carriageway collapse,break open carriageway and reinstate as required (RD: CW Pothole)	Outside Leonardo	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/05/2022	13/05/2022	Act. ROAD/82063975
50114040	Replace 6m of missing railings (RD: Railing Damage/Missing/New)	Bottom of the steps to cycle path	RD: Cat 3 - 60 Day	Job Complete	23/05/2022	18/09/2023	Act. ROAD/82064327

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality	
50114042	Tar surrounding catv box breaking up leaving gap into the chamber (RU: Utility Apparatus)	Outside 163	RU: Fail Low Risk	Job Complete	23/05/2022	23/05/2022	Act.
50114047	1 carriageway pothole (RD: CW Pothole)	At crossing outside 150	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/05/2022	24/05/2022	Act. ROAD/82064330
50115650	Damaged bollard (RD: Bollard Damage/Missing/New)	Outside number 146	RD: Cat 4 - Programmed	Job Complete	23/06/2022	28/07/2022	Act. ROAD/82065549
50115652	Pothole (RD: CW Pothole)	Adjacent to Boswall parkway	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2022	24/06/2022	Act. ROAD/82065168
50115654	Broken fw at utility cover (RD: FW HRA Pothole)	On opposite side of fw from number 192	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/06/2022	24/06/2022	Act. ROAD/82065169
50115655	Fw edge is gone (RD: FW HRA Cracked/Broken)	Between bridge and number 113	RD: Cat 4 - Programmed	No code allocated	23/06/2022	23/06/2023	Est.
50115656	Broken fw at steps. Trip hazard (RD: FW HRA Pothole)	Bottom of steps	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2022	24/06/2022	Act. ROAD/82065170
50124597	Road: Defective / Damaged (Enquiry 1477473) pothole on carriageway outside lane (RD: CW Pothole)	Heading to Crewe Toll roundabout	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/12/2022	23/12/2022	Act. ROAD/82069763
50124778	Cw cracked and broken Approx 4m x 1m Patch required (RD: CW Cracked/Broken)	Opposite scotmid at bus stop	RD: Cat 4 - Programmed	Job Annulled	22/12/2022	22/12/2022	Act.
50124780	Cw cracked and broken around box Approx 1m x 1m Patch required (RD: CW Cracked/Broken)	At west Granton road	RD: Cat 4 - Programmed	No code allocated	22/12/2022	22/12/2023	Est.
50124782	1 low kerb (RD: FW Kerb Dislodged/Rocking)	At arneil drive	RD: Cat 4 - Programmed	No code allocated	22/12/2022	22/12/2023	Est.
50128484	Double catv box rocking and sunk Surrounding fw breaking up as a result (RU: Utility Apparatus)	Opposite 192	RU: Fail Med.Risk (Apparatus)	Job Complete	06/02/2023	06/02/2023	Act.
50128486	Cabinet rusted away and lying on fw Cables exposed (RU: Utility Apparatus)	Outside 213	RU: Fail Med.Risk (Apparatus)	Job Complete	06/02/2023	06/02/2023	Act.
50135777	Collapsed catv box Causing trip hazard and surrounding footway to break up Has been reported before (la ref 3299435) (RU: Utility Apparatus)	Opposite 192	RU: Fail Med.Risk (Apparatus)	Job Complete	10/05/2023	11/05/2023	Act.
50135968	Pavement: Damaged / Defective (Enquiry 1550129) damaged footway manhole (RU: Utility Apparatus)	Outside 163	RU: Fail Med.Risk (Apparatus)	Job Complete	12/05/2023	12/05/2023	Act.

Site History Report

Effective: 01/01/2020 to 05/02/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Crewe Road North (7901387)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 4 - From West Granton Road to Crewe Toll Roundabout		Feature Type: Road Asset		Area: North West Locality	
50138714	Pavement: Damaged / Defective (Enquiry 1574877) trip at box (RD: FW HRA Pothole)	East footway outside Leonardos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/07/2023	03/07/2023	Act. ROAD/82078764
50138883	Damaged cover x2 (RU: Utility Apparatus)	Opposite side of footway from number 192	RU: Fail Med.Risk (Apparatus)	Job Complete	06/07/2023	06/07/2023	Act.
50140006	Pavement: Damaged / Defective (Enquiry 1587847) relay loose kerb (RD: FW Kerb Dislodged/Rocking)	Outside 223	RD: Cat 3 - 60 Day	Job Complete	27/07/2023	10/08/2023	Act. ROAD/82079483
50145937	Road: Defective / Damaged (Enquiry 1645670) pothole on carriageway (RD: CW Pothole)	Opposite 71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2023	21/11/2023	Act. ROAD/82082811
50146258	Drainage: General Enquiry - Crewe Road North - blocked drain, on the walk path. [REDACTED] is not able to get passed when it rains heavily [REDACTED] cannot get down the stairs another way. (Enquiry 34007779) footway gully chocked (Gully: Blocked / Flooding)	Outside 157	RG: Gully - Standard Priority	Reschedule: Parked Cars	21/11/2023	21/02/2024	Est. RDGC14/82005920
50146800	Sunken double manhole (RU: Utility Apparatus)	Opposite 192 at mast	RU: Fail Med.Risk (Apparatus)	Job Complete	29/11/2023	29/11/2023	Act.
50149350	Road: Defective / Damaged (Enquiry 1670023) pothole on carriageway (RD: CW Pothole)	Outside 215	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/01/2024	09/01/2024	Act. ROAD/82084920
50150278	Collapsed double catv box on fw (RU: Utility Apparatus)	Opposite 194	RU: Fail Med.Risk (Apparatus)	Job Complete	16/01/2024	16/01/2024	Act.