

47446

Client: Anne Whiteford

In relation to Crosswood Crescent, Balerno, EH14 7LX.

Please provide me with all documents and records, whether in hard copy or digital in relation to:-

The Policy in force as of 11th January 2024, in regards the inspection, maintenance and repair of the area at the above noted location.

[Please refer to the guidance attached.](#)

All records of inspection of the area at the above noted location from 1st January 2022 to date.

[Please refer to the site history report attached – Condition Survey section.](#)
[The inspection batch SW_CF2_BalernoWest1 is a walked inspection](#)

All records of complaints in regards to the area at the above noted location from 1st January 2022 to date.

[Please refer to the site history report attached – Customer Services section.](#)

All records of repairs at the area at the above noted location from 1st January 2022 to date.

[Please refer to the site history report attached – Maintenance Management section.](#)

Confirmation of the number of inspections carried out at the above noted location on an annual basis.

[All the inspections are listed in the site history report.](#)