

Site History Report

Effective: 29/05/2019 to 29/05/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Dalmahoy Road (7906100)

Site: Dalmahoy Road (7906100)

Locality: Ratho, Edinburgh, City of Edinburgh

Area: South West Locality

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
42707114	Gully: Flooding - What is the problem with the gully : flooding. What surface is the gully on : road. Are cars avoiding the flood : Yes. Is flood affecting a property : No (Enquiry 968804)		RG: Gully - High Priority	Job Complete	02/03/2020	09/03/2020	Act. RDGC14/10006098
50039905	Road: Defective / Damaged (Enquiry 874681) pothole (RD: CW Pothole)	Pot hole on the road going north Dalmahoy Road northbound approximately 60 mts prior to junction of Ransfield Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/08/2019	15/08/2019	Act. ROAD/82025088
50048327	Road: Defective / Damaged (Enquiry 931042) 3x potholes (RD: CW Pothole)	As marked on map. Heading towards ratho Main Street just past dalmahoy junction	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/12/2019	20/12/2019	Act. ROAD/82029855
50048769	Road: Defective / Damaged (Enquiry 931626) (RD: CW Pothole)	N bound after jct for ratho mason farm for 150 m several potholes	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/12/2019	08/01/2020	Act. ROAD/82030072
50049683	Road: Defective / Damaged (Enquiry 942434) 1 x completely blocked gully (Gully: Blocked - Hand Clear)	Approx 200m along road heading from A71 towards ratho	RG: Gully - Standard Priority	Job Complete	16/01/2020	15/06/2020	Act. RDGC14/82000627
50051050	15 x potholes (RD: CW Pothole)	Junction as dalmahoy road meets A71. Entire junction is badly potholed and needs tempmtte	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/02/2020	02/03/2020	Act. ROAD/82031794
50052664	2 x potholes (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2020	01/03/2020	Act. ROAD/82033271
50052666	4 x potholes (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2020	01/03/2020	Act. ROAD/82033273
50052667	3 x potholes (RD: CW Pothole)	Near junction with ransfield road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2020	01/03/2020	Act. ROAD/82033274
50052878	Existing patch breaking out (RD: CW Pothole)	At Hillview Cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033437
50052881	Pothole (RD: CW Pothole)	Approx 76 yards past farm entrance	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033439
50052883	Carriageway pothole (RD: CW Pothole)	Approx 10 yards past farm entrance	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033441
50052885	Carriageway pothole (RD: CW Pothole)	At farm entrance	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033443
50052886	Carriageway pothole (RD: CW Pothole)	5m before farm entrance	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033444
50052887	Carriageway pothole (RD: CW Pothole)	10m from farm entrance	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2020	02/03/2020	Act. ROAD/82033445
50052888	Carriageway pothole (RD: CW Pothole)	At Ransfield Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033446

Site History Report

Effective: 29/05/2019 to 29/05/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Dalmahoy Road (7906100)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50052889	Carriageway pothole (RD: CW Pothole)	Approx 10m from Ransfield Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033447
50052890	Open joint/pothole (RD: CW Open Joint)	Approx 20m from Ransfield Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	12/06/2020	Act. ROAD/82033448
50052891	Carriageway pothole (RD: CW Pothole)	Approx 25m from Ransfield Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033449
50052892	Carriageway pothole (RD: CW Pothole)	Approx 60m from Ransfield Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2020	02/03/2020	Act. ROAD/82033450
50052893	Carriageway pothole (RD: CW Pothole)	Approx 65m from Ransfield Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033451
50052894	Carriageway pothole (RD: CW Pothole)	On bend before Ransfield Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2020	02/03/2020	Act. ROAD/82033452
50052895	Carriageway pothole (RD: CW Pothole)	Approx 60m before bend	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2020	02/03/2020	Act. ROAD/82033453
50052896	2 carriageway potholes (RD: CW Pothole)	Approx 100m from bend	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033454
50052897	3 carriageway potholes (RD: CW Pothole)	30m past first bend from A71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033455
50052898	2 carriageway potholes (RD: CW Pothole)	On first bend from A71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033456
50052899	Carriageway pothole (RD: CW Pothole)	Opposite Ratho Park	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2020	02/03/2020	Act. ROAD/82033457
50052900	Carriageway pothole (RD: CW Pothole)	20m from A71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2020	01/03/2020	Act. ROAD/82033458
50052901	Multiple carriageway potholes (RD: CW Pothole)	At A71	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2020	02/03/2020	Act. ROAD/82033459
50060147	Blocked gully needs flushed (Gully: Blocked - HP Jet Req'd)	At dip in road before hill. Next to national speed limit signs	RG: Gully - Standard Priority	Job Complete	11/08/2020	29/06/2021	Act. RDGC14/82001085
50060149	Centre lines need remarked as faded (RD: Markings Refresh)	Entire road	Non Routine (One Off Works)	Job Annulled	11/08/2020	11/08/2020	Act. ROAD/82039121
50063630	Pothole (RD: CW Pothole)	Dalmahoy road heading towards ratho on way down hill as marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/09/2020	30/09/2020	Act. ROAD/82039777
50063631	Mirror on pole for blind corner is missing . Needs replaced asap (RD: Unlit Sign Damaged/Missing)	Dalmahoy road heading towards ratho just past ratho mains junction	RD: Cat 3 - 60 Day	Job Complete	29/09/2020	18/11/2020	Act. ROAD/82039778
50071821	Pothole near cw edge (RD: CW Pothole)	Approximately 20m past entrance to ratho park carvery heading towards ratho	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2021	14/01/2021	Act. ROAD/82043232
50074176	Pothole cw edge (RD: CW Pothole)	Approximately 10m from entrance to carvery heading towards ratho	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2021	15/02/2021	Act. ROAD/82044446
50074177	Pothole (RD: CW Pothole)	Approximately 10m past carvery entrance heading towards ratho	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2021	15/02/2021	Act. ROAD/82044447

Site History Report

Effective: 29/05/2019 to 29/05/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Dalmahoy Road (7906100)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50074416	Pothole cw edge (RD: CW Pothole)	Just past national speed limit signs heading towards ratho	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/02/2021	15/02/2021	Act. ROAD/82044555
50074418	Pothole cw edge (RD: CW Pothole)	Heading towards ratho, as marked on map, see pics	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/02/2021	15/02/2021	Act. ROAD/82044556
50079170	Pothole on cw (RD: CW Pothole)	Heading towards A71 approx 30m from ratio mains sign on way up hill	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/03/2021	25/03/2021	Act. ROAD/82047370
50079443	Road: Defective / Damaged (Enquiry 1133449) (RD: CW Pothole)	See map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2021	25/03/2021	Act. ROAD/82047585
50079446	Road: Defective / Damaged (Enquiry 1109340) (RD: CW Pothole)	See map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2021	25/03/2021	Act. ROAD/82047588
50079449	Road: Defective / Damaged (Enquiry 1101121) (RD: CW Pothole)	See map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2021	25/03/2021	Act. ROAD/82047591
50079452	Road: Defective / Damaged (Enquiry 1110391) (RD: CW Pothole)	Pothole	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/03/2021	25/03/2021	Act. ROAD/82047594
50079453	Potholes (RD: CW Pothole)	See map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2021	25/03/2021	Act. ROAD/82047595
50079455	Potholes (RD: CW Pothole)	See map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2021	25/03/2021	Act. ROAD/82047597
50079465	Road: Defective / Damaged (Enquiry 1128959) (RD: CW Pothole)	See map	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/03/2021	25/03/2021	Act. ROAD/82047606
50079472	Road: Defective / Damaged (Enquiry 1131227) refresh giveaway markings (RD: Markings Refresh)	At jct with Calder road	RD: Cat 3 - 60 Day	Job Complete	24/03/2021	23/06/2021	Act. ROAD/82047617
50085759	Pothole (RD: CW Pothole)	Approximately 50m past ransfield road junction heading towards A71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2021	24/06/2021	Act. ROAD/82051224
50085760	Gully surround (RD: CW Pothole)	Approximately 30m past junction with ransfield road A71 bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/06/2021	24/06/2021	Act. ROAD/82051225
50085762	Brander damaged needs replaced (RD: Gully Damaged/Sunken)	Approximately 30m past junction with Ransfield road heading towards A71	RD: Cat 3 - 60 Day	Job Complete	23/06/2021	26/08/2021	Act. ROAD/82051227
50093179	2 x potholes on cw (RD: CW Pothole)	Approximately 15m past carvery heading towards ratho	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/10/2021	07/10/2021	Act. ROAD/82054760
50097513	Road: Defective / Damaged (Enquiry 1275165) (RD: CW Pothole)	At jct with A70	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2021	18/11/2021	Act. ROAD/82056460
50102190	1no pothole (RD: CW Pothole)	Near the junction of Calder Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/01/2022	13/01/2022	Act. ROAD/82058399
50102195	1no pothole (RD: CW Pothole)	At the junction of Hillview cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/01/2022	13/01/2022	Act. ROAD/82058402

Site History Report

Effective: 29/05/2019 to 29/05/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Dalmahoy Road (7906100)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50107289	Road: Defective / Damaged (Enquiry 1327915) (RD: CW Pothole)	C/way pot holes south bound see attached photo	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2022	24/02/2022	Act. ROAD/82060839
50107291	Road: Defective / Damaged (Enquiry 1330925) (RD: CW Pothole)	Opp Ratho Park Restaurant entrance	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2022	27/02/2022	Act. ROAD/82060840
50108595	1x Pothole (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/03/2022	10/03/2022	Act. ROAD/82061505
50110047	Road: Defective / Damaged (Enquiry 1348092) (RD: CW Pothole)	Pot hole at junction	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/03/2022	24/03/2022	Act. ROAD/82062223
50113118	5no potholes (RD: CW Pothole)	At the junction of Calder Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/05/2022	09/05/2022	Act. ROAD/82063815
50113119	2no potholes (RD: CW Pothole)	20m from the junction of Calder Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/05/2022	09/05/2022	Act. ROAD/82063816
50113120	1no pothole (RD: CW Pothole)	No reference point please use pin location	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/05/2022	09/05/2022	Act. ROAD/82063817
50119176	Road: Defective / Damaged (Enquiry 1437115) (RD: CW Pothole)	Pot hole south bound at channel	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	27/09/2022	28/09/2022	Act. ROAD/82067070
50119733	1no pothole (RD: CW Pothole)	Just south of entrance to Ratho park carvery	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/10/2022	10/10/2022	Act. ROAD/82067353
50120159	Pothole (RD: CW Pothole)	Approximately 30m from junction with Ransfield road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/10/2022	18/10/2022	Act. ROAD/82067598
50120160	Pothole (RD: CW Pothole)	At ratho mains junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/10/2022	18/10/2022	Act. ROAD/82067599
50120161	Broken cw . Overlay required (RD: CW Cracked/Broken)	Approximately 10m past ratho mains junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/10/2022	24/10/2022	Act. ROAD/82067600
50120164	Pothole (RD: CW Pothole)	Approximately 40m past ratho mains	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/10/2022	18/10/2022	Act. ROAD/82067601
50120166	Pothole (RD: CW Pothole)	Approximately 20m past ratho mains	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/10/2022	18/10/2022	Act. ROAD/82067602
50129415	9x potholes (RD: CW Pothole)	At the junction with the A71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/02/2023	19/02/2023	Act. ROAD/82072916
50129420	2x potholes (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/02/2023	19/02/2023	Act. ROAD/82072919
50129422	1x pothole (RD: CW Pothole)	As marked on map	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/02/2023	19/02/2023	Act. ROAD/82072921
50129427	1x pothole (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/02/2023	19/02/2023	Act. ROAD/82072924
50129429	1x pothole (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/02/2023	19/02/2023	Act. ROAD/82072926
50129430	1x pothole (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/02/2023	19/02/2023	Act. ROAD/82072927
50130767	2x potholes (RD: CW Pothole)	At the junction with Hillview Cottages	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/02/2023	03/03/2023	Act. ROAD/82073632

Site History Report

Effective: 29/05/2019 to 29/05/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Dalmahoy Road (7906100)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50130769	2x potholes (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/02/2023	01/03/2023	Act. ROAD/82073634
50134515	Pothole (RD: CW Pothole)	Just past ratio park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82075987
50134519	Pothole (RD: CW Pothole)	Approximately 30m from ransfield road junction . Heading towards ratio.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82075989
50134520	Pothole near gully (RD: CW Pothole)	Approximately 30m past ransfield road heading towards Calder Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82075990
50134522	Pothole (RD: CW Pothole)	Heading towards Calder road approximately 120m past ransfield road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82075991
50134524	Pothole (RD: CW Pothole)	As marked just before entrance to fields ratio bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82075993
50134525	Pothole (RD: CW Pothole)	At fields entrance ratio bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82075994
50134526	Pothole (RD: CW Pothole)	Just past fields ratio bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82075995
50134532	Pothole (RD: CW Pothole)	Just after ratio mains Calder road bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82075999
50134533	Pothole (RD: CW Pothole)	At ratio mains ratio bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82076000
50134538	Pothole (RD: CW Pothole)	Approximately 50m before ratho mains	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82076002
50134541	Pothole (RD: CW Pothole)	Approximately 30m from ratho mains Calder road bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2023	19/04/2023	Act. ROAD/82076004
50139666	1no pothole (RD: CW Pothole)	No reference point please use pin location	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/07/2023	21/07/2023	Act. ROAD/82079314
50141841	001PK sign-Remove existing sign , post and install new sign , posts and found as per sign detail 001PK (RD: Unlit Sign Damaged/Missing)	001PK sign at Dalmahoy Rd at A71 junction	RD: Cat 3 - 60 Day	Job Complete	30/08/2023	07/09/2023	Act. ROAD/82080351
50144829	4 x potholes (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/11/2023	06/11/2023	Act. ROAD/82082219
50144831	1x pothole (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/11/2023	06/11/2023	Act. ROAD/82082221
50146241	1x pothole (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/11/2023	26/11/2023	Act. ROAD/82082979
50146245	1x pothole (RD: CW Pothole)	As marked on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/11/2023	26/11/2023	Act. ROAD/82082983
50146410	1 cw pothole (RD: CW Pothole)	No exact reference point See pin location	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/11/2023	26/11/2023	Act. ROAD/82083079
50146422	1 cw pothole (RD: CW Pothole)	Opposite lp aag05	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/11/2023	26/11/2023	Act. ROAD/82083083

Site History Report

Effective: 29/05/2019 to 29/05/2024
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Dalmahoy Road (7906100)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50151734	Road: Defective / Damaged (Enquiry 1687578) (RD: CW Pothole)	OPP entrance to Ratho Park Bistro	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/01/2024	01/02/2024	Act. ROAD/82086525
50152094	Road: Defective / Damaged (Enquiry 1691160) (RD: CW Pothole)	2 potholes in middle of road	RD: Cat 4 - Programmed	RD: Made Safe Job Complete	04/02/2024	08/02/2024	Act. ROAD/82087022
50153444	Road: Defective / Damaged (Enquiry 1696596) (RD: Gully Damaged/Sunken)	deep pot hole up to 5 inches deep in middle of road	RD: Cat 3 - 60 Day	Job Complete	19/02/2024	28/02/2024	Act. ROAD/82087761
50154582	Road: Defective / Damaged (Enquiry 1697908) (RD: CW Pothole)	1x pothole Northbound Close to 30mph boundary	RD: Cat 4 - Programmed	RD: Made Safe Job Complete	03/03/2024	02/04/2024	Act. ROAD/82088541
50156389	3no potholes (RD: CW Pothole)	At 30mph markings	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/03/2024	21/03/2024	Act. ROAD/82089786
50156472	1nr pothole marked on site (RD: CW Pothole)	As marked on map - heading towards Ratho	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/03/2024	02/04/2024	Act. ROAD/82089839
50157112	Pothole (RD: CW Pothole)	Near ratho park carvery	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2024	02/04/2024	Act. ROAD/82090299
50158296	Cw x4 potholes Road: Defective / Damaged (Enquiry 1731055) (RD: CW Pothole)	Just after junction with A71 and just before Ratho Park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/04/2024	02/05/2024	Act. ROAD/82091215
50158740	Cw x1 pothole Road: Defective / Damaged (Enquiry 1725567) (RD: CW Pothole)	Heading towards Ratho	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2024	02/05/2024	Act. ROAD/82091538
50158741	Cw x2 potholes Road: Defective / Damaged (Enquiry 1728614) (RD: CW Pothole)	At the junction with Main Street Ratho	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/04/2024	02/05/2024	Act. ROAD/82091539
50159310	1nr pothole (RD: CW Pothole)	As marked on map, heading towards Ratho	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/04/2024	02/05/2024	Act. ROAD/82091894