

Effective: 26/06/2023 to 26/06/2024

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: Clifton Road (7906105)

Site: Clifton Road (7906105)

Locality:

Area: South West Locality

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Ward 02 - From access road to carpark at Lins Mill generally soi			<b>Feature Type:</b> Road Asset		<b>Area:</b> South West Locality	
<b>Batch:</b> 41195225 - Inspection Batch				<b>Route:</b> NW_CW1_West1		<b>Date:</b> 24/06/2024		
No actionable defects found								
<b>Batch:</b> 41195017 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 20/06/2024		
42160067	1no pothole	20/06/2024	No reference point please use pin location	RD: CW Pothole	Internal		Committed	50162697
<b>Batch:</b> 41191933 - Inspection Batch				<b>Route:</b> SW_CF1_CliftonRoad1		<b>Date:</b> 14/05/2024		
42157180	Pothole	14/05/2024	Outside number 1	RD: CW Pothole	Internal		Committed	50160334
42157187	Cracked broken cw	14/05/2024	At bend	RD: CW Cracked/Broken	Internal		Uncommitted	50136233
42157182	Cracked broken cw	14/05/2024	As marked	RD: CW Cracked/Broken	Internal		Uncommitted	50136223
42157183	Cracked broken cw	14/05/2024	As marked	RD: CW Cracked/Broken	Internal		Uncommitted	50136224
42157179	Cracked broken cw	14/05/2024	As marked	RD: CW Cracked/Broken	Internal		Uncommitted	50136221
42157177	Pothole	14/05/2024	At junction	RD: CW Pothole	Internal		Committed	50160332
42157188	Pothole	14/05/2024	On bend	RD: CW Pothole	Internal		Committed	50160338
42157185	Damaged sign	14/05/2024	As marked	RD: Unlit Sign Damaged/Missing	Internal		Uncommitted	50136231
42157186	Cracked broken cw	14/05/2024	Section of 50m	RD: CW Cracked/Broken	Internal		Uncommitted	50136230
42157184	Cracked broken cw	14/05/2024	Up to caravan park	RD: CW Cracked/Broken	Internal		Uncommitted	50136227
42157178	Pothole	14/05/2024	Outside number 5	RD: CW Pothole	Internal		Committed	50160333
<b>Batch:</b> 41190072 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 20/04/2024		
42155251	1nr pothole	20/04/2024	As marked on map. Heading towards Newbridge	RD: CW Pothole	Internal		Committed	50158847
<b>Batch:</b> 41189925 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 18/04/2024		
42155146	Cw x3 potholes Road: Defective / Damaged (Enquiry 1736916)	18/04/2024	Both sides of carriageway between two S bends	RD: CW Pothole	Internal		Committed	50158745
<b>Batch:</b> 41189923 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 18/04/2024		
42155144	Cw x 6 potholes Road: Defective / Damaged (Enquiry 1737600)	18/04/2024	Outside of 120	RD: CW Pothole	Internal		Committed	50158743
<b>Batch:</b> 41187396 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 24/03/2024		
42152858	1x pothole Eastbound Approximately 50 meters east of junction with Sandilands Road	24/03/2024	1x pothole Eastbound Approximately 50 meters east of junction with Sandilands Road	RD: CW Pothole	Internal		Committed	50156728
<b>Batch:</b> 41186982 - Inspection Batch				<b>Route:</b> NW_CW1_West1		<b>Date:</b> 20/03/2024		
42152330	1no pothole	20/03/2024	See pin location	RD: CW Pothole	Internal		Committed	50156378
<b>Batch:</b> 41174622 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 17/12/2023		
42142122	1no pothole	17/12/2023	See pin location	RD: CW Pothole	Internal		Committed	50148241
<b>Batch:</b> 41174497 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 15/12/2023		
42142007	Road: Defective / Damaged (Enquiry 1660768) pothole on carriageway	15/12/2023	From East Calder to Clifton Road	RD: CW Pothole	Internal		Committed	50148142

Effective: 26/06/2023 to 26/06/2024

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: Clifton Road (7906105)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 02 - From access road to carpark at Lins Mill generally soi			Feature Type: Road Asset		Area: South West Locality	
Batch: 41174167 - Inspection Batch				Route: NW_CW1_West1		Date: 12/12/2023		
No actionable defects found								
Batch: 41172529 - Inspection Batch				Route: Ad hoc Route		Date: 22/11/2023		
42140195	Road: Defective / Damaged (Enquiry 1645100)	22/11/2023	Pot holes at verge just before junction	RD: CW Pothole	Internal		Committed	50146370
Batch: 41172398 - Inspection Batch				Route: Ad hoc Route		Date: 20/11/2023		
42140065	2 cw potholes	20/11/2023	No exact reference point see pin location	RD: CW Pothole	Internal		Committed	50146234
Batch: 41171531 - Inspection Batch				Route: Ad hoc Route		Date: 09/11/2023		
42139133	Take down existing sign face and post and Install new 750mm bend on right ahead warning sign face on new post and found.	09/11/2023	Clifton Road	RD: Unlit Sign Damaged/Missing	Internal		Committed	50145413
Batch: 41170943 - Inspection Batch				Route: Ad hoc Route		Date: 02/11/2023		
42138523	Please remove existing sign and pole and replace with new bend ahead sign (750). Please collect from stores. At bend prior to linwater caravan park, please see attached location plan.	02/11/2023	Refer to map attached	RD: Unlit Sign Damaged/Missing	Internal		Committed	50144887
Batch: 41164394 - Inspection Batch				Route: Ad hoc Route		Date: 07/09/2023		
42135714		07/09/2023	Please install new giveaway sign and pole at the junction with sandilands road.	RD: Unlit Sign Damaged/Missing	Internal		Committed	50142268
Batch: 41164274 - Inspection Batch				Route: NW_CW1_West1		Date: 05/09/2023		
No actionable defects found								
Batch: 41162217 - Inspection Batch				Route: SW_CW1_West1		Date: 01/08/2023		
No actionable defects found								
Batch: 41160471 - Inspection Batch				Route: Ad hoc Route		Date: 05/07/2023		
42131272	Wearing course breaking up infill all defects between Junction and School entrance hot sand carpet repairs	05/07/2023	From Camps junction to Cliftonhall School and Canal junction to Cliftonhall Road junction	RD: CW Pothole	Internal		Committed	50138816