

Site History Report

Effective: 01/01/2021 to 02/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Johnston Terrace (7901878)

Site: Johnston Terrace (7901878)

Locality: Old Town, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality		
Batch: 41224959 - Inspection Batch	No actionable defects found			Route: SE_CW1_Central1			Date: 02/04/2025	
Batch: 41218054 - Inspection Batch				Route: Ad hoc Route			Date: 07/02/2025	
42175319	1no Cw pothole	07/02/2025	Please check pin location	RD: CW Pothole	Internal		Committed	50174558
Batch: 41218052 - Inspection Batch	No actionable defects found			Route: SE_CW1_Central1			Date: 07/02/2025	
Batch: 41211351 - Inspection Batch				Route: SE_CW1_Central1			Date: 18/12/2024	
Batch: 41208814 - Inspection Batch				Route: Ad hoc Route			Date: 27/11/2024	
42169970				2 number potholes	27/11/2024	between Lampost number 10 and 11	RD: CW Pothole	Internal
Batch: 41208565 - Inspection Batch	Please replace missing handrail approximately 6m			Route: Ad hoc Route			Date: 25/11/2024	
42169806				On the steps at the side of Code Base down towards King Stables Road	RD: Railing Damage/Missing/New	Internal	Committed	50170319
Batch: 41205087 - Inspection Batch				Route: Ad hoc Route			Date: 25/10/2024	
42167589				1no pothole	25/10/2024	Opposite Noks Kitchen	RD: CW Pothole	Internal
Batch: 41205086 - Inspection Batch				Route: Ad hoc Route			Date: 25/10/2024	
42167588				3no very large potholes	25/10/2024	Outside The Hub	RD: CW Pothole	Internal
Batch: 41205085 - Inspection Batch				Route: Ad hoc Route			Date: 25/10/2024	
42167587				1no pothole	25/10/2024	Opposite Hardy Feral	RD: CW Pothole	Internal
Batch: 41205084 - Inspection Batch	2no potholes			Route: Ad hoc Route			Date: 25/10/2024	
42167586				Down near the bend near Castle Terrace end	RD: CW Pothole	Internal	Committed	50168675
Batch: 41201372 - Inspection Batch	No actionable defects found			Route: SE_CW1_Central1			Date: 25/09/2024	
Batch: 41200491 - Inspection Batch				Route: Ad hoc Route			Date: 11/09/2024	
42164796	1no pothole	11/09/2024	Opposite lp18	RD: CW Pothole	Internal		Committed	50166374
Batch: 41196506 - Inspection Batch				Route: SE_CF2_CastleTerrace1			Date: 12/07/2024	
42161565				Footway broken up approx 0.8x2m	12/07/2024	Approx 20 downhill from Patrick Geddes steps	RD: FW HRA Cracked/Broken	Internal
42161562	Approx 1x1m subsidence	12/07/2024	Opposite Hardy Feral cashmere shop	RD: CW Subsidence/Heaving	Internal		Uncommitted	50163785
42161564	3no subsidence 1x2.5m, 2x3m, 2x3m	12/07/2024	Just before roundabout heading uphill	RD: CW Subsidence/Heaving	Internal		Uncommitted	50163787
42161558	Patching required approx 2x2m 1x4m 1x1m	12/07/2024	Approx 10m ,15m and 30m uphill from where new wall starts on castle side	RD: CW Cracked/Broken	Internal		Uncommitted	50141106
42161563	Approx 1x3m subsidence	12/07/2024	Opposite Noks kitchen	RD: CW Subsidence/Heaving	Internal		Uncommitted	50163786
42161560	1no dislodged kerb	12/07/2024	At lp jbj21	RD: FW Kerb Dislodged/Rocking	Internal		Action Required	
42161561	Refresh 20mph roundals	12/07/2024	At lamppost no20	RD: Markings Refresh	Internal		Committed	50163784

Site History Report

Effective: 01/01/2021 to 02/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Johnston Terrace (7901878)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch:	41194937 - Inspection Batch			Route: SE_CW1_Central1			Date: 20/06/2024	
42160036	3 cw potholes	20/06/2024	Opposite little inn cafe	RD: CW Pothole	Internal		Committed	50162665
Batch:	41192325 - Inspection Batch			Route: Ad hoc Route			Date: 20/05/2024	
42157606	1no pothole	20/05/2024	At the bottom bend near Castle Terrace	RD: CW Pothole	Internal		Committed	50160680
Batch:	41189707 - Inspection Batch			Route: Ad hoc Route			Date: 16/04/2024	
42154926	3 no Cw potholes	16/04/2024	Opposite little inn cafe	RD: CW Pothole	Internal		Committed	50158542
Batch:	41189672 - Inspection Batch			Route: Ad hoc Route			Date: 16/04/2024	
42154871	9 no fw potholes	16/04/2024	Opposite bus stop at start of Johnston terrace	RD: FW HRA Pothole	Internal		Committed	50158499
Batch:	41189671 - Inspection Batch			Route: Ad hoc Route			Date: 16/04/2024	
42154870	1no fw pothole between boxes	16/04/2024	150 yds uphill from castle terrace	RD: FW HRA Pothole	Internal		Committed	50158498
Batch:	41187822 - Inspection Batch			Route: SE_CW1_Central1			Date: 27/03/2024	
No actionable defects found								
Batch:	41183955 - Inspection Batch			Route: Ad hoc Route			Date: 27/02/2024	
42149277	1no pothole	27/02/2024	Near the bend towards Castle Terrace	RD: CW Pothole	Internal		Committed	50154215
Batch:	41183951 - Inspection Batch			Route: Ad hoc Route			Date: 27/02/2024	
42149272	1no pothole	27/02/2024	Opposite lp Jbj18	RD: CW Pothole	Internal		Committed	50154210
Batch:	41180440 - Inspection Batch			Route: Ad hoc Route			Date: 29/01/2024	
42145507	2no potholes	29/01/2024	Opposite Little Inn Cafe	RD: CW Pothole	Internal		Committed	50151545
Batch:	41180437 - Inspection Batch			Route: Ad hoc Route			Date: 29/01/2024	
42145505	1no pothole	29/01/2024	Opposite Noks Kitchen	RD: CW Pothole	Internal		Committed	50151543
Batch:	41178451 - Inspection Batch			Route: SE_CW1_Central1			Date: 15/01/2024	
No actionable defects found								
Batch:	41178231 - Inspection Batch			Route: Ad hoc Route			Date: 11/01/2024	
42143814	1no pothole	11/01/2024	Outside the Hub	RD: CW Pothole	Internal		Committed	50149959
Batch:	41173503 - Inspection Batch			Route: Ad hoc Route			Date: 05/12/2023	
42141069	2no potholes	05/12/2023	Opposite little inn cafe	RD: CW Pothole	Internal		Committed	50147182
Batch:	41171653 - Inspection Batch			Route: Ad hoc Route			Date: 10/11/2023	
42139299	1no pothole	10/11/2023	At the steps next to code base	RD: FW HRA Pothole	Internal		Committed	50145541
Batch:	41171652 - Inspection Batch			Route: Ad hoc Route			Date: 10/11/2023	
42139297	1no pothole	10/11/2023	On south side next to barrier	RD: FW HRA Pothole	Internal		Uncommitted	50141114
Batch:	41170555 - Inspection Batch			Route: Ad hoc Route			Date: 31/10/2023	
42138384	2no potholes	31/10/2023	Opposite Noks Kitchen .	RD: CW Pothole	Internal		Committed	50144757
Batch:	41170554 - Inspection Batch			Route: Ad hoc Route			Date: 31/10/2023	
42138383	1no pothole	31/10/2023	Outside the Hub	RD: CW Pothole	Internal		Committed	50144756

Site History Report

Effective: 01/01/2021 to 02/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Johnston Terrace (7901878)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41170553 - Inspection Batch				Route: Ad hoc Route			Date: 31/10/2023	
42138382	1no pothole	31/10/2023	At the bend before turning to Castle Terrace	RD: CW Pothole	Internal		Committed	50144755
Batch: 41168211 - Inspection Batch				Route: SE_CW1_Central1			Date: 10/10/2023	
42137326	1 carriageway pothole	10/10/2023	Opposite lamppost 18	RD: CW Pothole	Internal		Committed	50143814
Batch: 41165523 - Inspection Batch				Route: Ad hoc Route			Date: 18/09/2023	
42136276	1no pothole	18/09/2023	Outside the Hub	RD: CW Pothole	Internal		Committed	50142674
Batch: 41165518 - Inspection Batch				Route: Ad hoc Route			Date: 18/09/2023	
42136275	1no pothole	18/09/2023	Opposite Ip 20	RD: CW Pothole	Internal		Committed	50142673
Batch: 41163007 - Inspection Batch				Route: SE_CF2_CastleTerrace1			Date: 16/08/2023	
42134202	Footway broken up approx 0.8x2m	16/08/2023	Approx 20 downhill from Patrick Geddes steps	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42134203	7no small potholes over approx 20m stretch of footpath	16/08/2023	Opposite lamppost no22	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50141113
42134201		16/08/2023		RD: FW Slabs Rocking	Internal		Uncommitted	1009764
42134196	Patching required approx 2x2m 1x4m 1x1m	16/08/2023	Approx 10m ,15m and 30m uphill from where new wall starts on castle side	RD: CW Cracked/Broken	Internal		No Action Required	
42134204	1no pothole	16/08/2023	On south side next to barrier	RD: FW HRA Pothole	Internal		No Action Required	
42134197	1no pothole	16/08/2023	Approx 10m downhill from lamppost no18	RD: CW Pothole	Internal		Committed	50141107
42134194	1no dislodged kerb	16/08/2023	At Ip jbj21	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
Batch: 41162603 - Inspection Batch				Route: Ad hoc Route			Date: 08/08/2023	
42133589	3no potholes	08/08/2023	Outside the Hub	RD: FW HRA Pothole	Internal		Committed	50140680
Batch: 41162599 - Inspection Batch				Route: Ad hoc Route			Date: 08/08/2023	
42133585	1no pothole	08/08/2023	Outside the Hub	RD: CW Pothole	Internal		Committed	50140678
Batch: 41161573 - Inspection Batch				Route: SE_CW1_Central1			Date: 25/07/2023	
No actionable defects found								
Batch: 41159899 - Inspection Batch				Route: Ad hoc Route			Date: 23/06/2023	
42130651	1 number pothole at crossing	23/06/2023	As you come out of Johnston Terrace	RD: CW Pothole	Internal		Committed	50138294
Batch: 41159898 - Inspection Batch				Route: Ad hoc Route			Date: 23/06/2023	
42130650	1 number pothole	23/06/2023	At bottom of Johnson Terrace just before the crash barriers	RD: CW Pothole	Internal		Committed	50138293
Batch: 41156765 - Inspection Batch				Route: Ad hoc Route			Date: 09/05/2023	
42126994	1no pothole	09/05/2023	Outside the Hub	RD: CW Pothole	Internal		Committed	50135712
Batch: 41156764 - Inspection Batch				Route: Ad hoc Route			Date: 09/05/2023	
42126990	1no pothole	09/05/2023	Opposite no4	RD: CW Pothole	Internal		Committed	50135710
Batch: 41156762 - Inspection Batch				Route: Ad hoc Route			Date: 09/05/2023	
42126987	3no potholes	09/05/2023	At Ip 15	RD: CW Pothole	Internal		Committed	50135709

Site History Report

Effective: 01/01/2021 to 02/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Johnston Terrace (7901878)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41155217 - Inspection Batch				Route: SE_CW1_Central1			Date: 19/04/2023	
No actionable defects found								
Batch: 41154630 - Inspection Batch				Route: Ad hoc Route			Date: 12/04/2023	
42125104	1 cw pothole	12/04/2023	At junction with lawn market	RD: CW Pothole	Internal		Committed	50134140
Batch: 41150178 - Inspection Batch				Route: Ad hoc Route			Date: 23/02/2023	
42119690	2 number potholes	23/02/2023	At roundabout outside church	RD: CW Pothole	Internal		Committed	50130059
Batch: 41150174 - Inspection Batch				Route: Ad hoc Route			Date: 23/02/2023	
42119688	1 number pothole	23/02/2023	Outside Castle View Gift Shop	RD: CW Pothole	Internal		Committed	50130056
Batch: 41150172 - Inspection Batch				Route: Ad hoc Route			Date: 23/02/2023	
42119687	1 number pothole	23/02/2023	Next to lamppost number JBJ15	RD: CW Pothole	Internal		Committed	50130054
Batch: 41150167 - Inspection Batch				Route: Ad hoc Route			Date: 23/02/2023	
42119682	1 number pothole	23/02/2023	Opposite Lamppost number JBJ18	RD: CW Pothole	Internal		Committed	50130048
Batch: 41147728 - Inspection Batch				Route: Ad hoc Route			Date: 01/02/2023	
42117161	1no pothole	01/02/2023	On the bend 20m east of the bus stop	RD: CW Pothole	Internal		Committed	50128153
Batch: 41143102 - Inspection Batch				Route: SE_CW1_Central1			Date: 11/01/2023	
42114778	2 cw potholes	11/01/2023	Opposite lp 21	RD: CW Pothole	Internal		Committed	50125875
Batch: 41140444 - Inspection Batch				Route: Ad hoc Route			Date: 21/12/2022	
42113565	Reset loose slab	21/12/2022	Outside number 2b	RD: FW Slabs Rocking	Internal		Committed	50124703
Batch: 41139975 - Inspection Batch				Route: Ad hoc Route			Date: 19/12/2022	
42113396	1no pothole	19/12/2022	15m east of crossing on the corner	RD: CW Pothole	Internal		Committed	50124509
Batch: 41134661 - Inspection Batch				Route: SE_CW1_Central1			Date: 02/11/2022	
42110398	1 carriageway pothole	02/11/2022	Opposite lamppost 18	RD: CW Pothole	Internal		Committed	50121340
Batch: 41128735 - Inspection Batch				Route: SE_CW1_Central1			Date: 03/08/2022	
No actionable defects found								
Batch: 41124422 - Inspection Batch				Route: SE_CF2_CastleTerrace1			Date: 23/05/2022	
42101610	1no dislodged kerb	19/05/2022	At lp jbj21	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42101835	Very uneven area of footway needs relaid completely 25mx2.4m	20/05/2022	Outside castle rock hostel	RD: FW Slabs Rocking	Internal		No Action Required	
Batch: 41117511 - Inspection Batch				Route: Ad hoc Route			Date: 01/03/2022	
42094497	1no pothole	01/03/2022	Opposite no2	RD: CW Pothole	Internal		Committed	50107798
Batch: 41113485 - Inspection Batch				Route: Ad hoc Route			Date: 19/01/2022	
42089958	1no pothole	19/01/2022	Opposite lp JDJ18	RD: CW Pothole	Internal		Committed	50103380
Batch: 41092187 - Inspection Batch				Route: SE_CF2_CastleTerrace1			Date: 12/05/2021	
42068796	Carriageway patching required along joint approx 22mx1m	12/05/2021	At lp JBJ11	RD: CW Cracked/Broken	Internal		Uncommitted	50082937
42068790	1no rocking tactile flag	12/05/2021	On the bend near Castle Terrace	RD: FW Slabs Rocking	Internal		Uncommitted	50082932
42068799	Pothole	12/05/2021	Opp Noks Kitchen at bus stop	RD: CW Pothole	Internal		Committed	50082848

Site History Report

Effective: 01/01/2021 to 02/06/2025

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Johnston Terrace (7901878)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41092187 - Inspection Batch			Route:	SE_CF2_CastleTerrace1		Date:	12/05/2021
42068795	Carriageway patching required approx 4mx1m	12/05/2021	Opposite Thai Orchid in bus stand	RD: CW Cracked/Broken	Internal		Uncommitted	50082935
42068793		12/05/2021		RD: FW Slabs Rocking	Internal		Uncommitted	1009761
42068794	Carriageway patching required approx 9mx1.5m	12/05/2021	Opposite Balmoral Cashmere	RD: CW Cracked/Broken	Internal		Uncommitted	50082934
42068797	Carriageway patching required along joint approx 19mx.5m	12/05/2021	At Castle wynd north	RD: CW Cracked/Broken	Internal		Uncommitted	50082938
42068798	Cracked and broken asphalt surface approx 4mx2m	12/05/2021	Opposite the Little Inn	RD: CW Cracked/Broken	Internal		Uncommitted	50082939
42068716	Cracked and broken asphalt surface approx 10mx2m	12/05/2021	At Granny's Green steps	RD: CW Cracked/Broken	Internal		Uncommitted	50082895
42068721	Pothole as marked	12/05/2021	5m North of lamppost NEW19	RD: CW Pothole	Internal		Committed	50082833
42068702	Pothole as marked	12/05/2021	O/S no 5A	RD: CW Pothole	Internal		Committed	50082819
42068699	Carriageway patching required approx 2mx1m	12/05/2021	Outside Thai orchid	RD: CW Cracked/Broken	Internal		Uncommitted	50082891
42068696	Loose rocking cut slab please reset	12/05/2021	O/S no 5A Maxies	RD: FW Slabs Rocking	Internal		Committed	50082817
42068695		12/05/2021		RD: FW Slabs Broken/Missing	Internal		Uncommitted	50082888
42068792	1no pothole	12/05/2021	Near lp jbj20	RD: FW HRA Pothole	Internal		Uncommitted	50082933
42068694		12/05/2021		RD: FW Slabs Broken/Missing	Internal		Uncommitted	50082887
42068693		12/05/2021		RD: FW Slabs Broken/Missing	Internal		Uncommitted	50082886
42068714	Carriageway patching required along joint approx 22mx1m	12/05/2021	At lp JBJ8	RD: CW Cracked/Broken	Internal		Uncommitted	50082894
42068791	1no dislodged kerb	12/05/2021	At lp jbj21	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42068710	Very uneven area of footway needs relaid completely 25mx2.4m	12/05/2021	Outside castle rock hostel	RD: FW Slabs Rocking	Internal		No Action Required	
42068708		12/05/2021		RD: FW Slabs Rocking	Internal		Uncommitted	50082893
42068705		12/05/2021		RD: FW Slabs Broken/Missing	Internal		Uncommitted	50082892
42068698		12/05/2021		RD: FW Slabs Broken/Missing	Internal		Uncommitted	50082890
42068697	1no rocking cut flag at gas toby	12/05/2021	Outside Thai orchid	RD: FW Slabs Rocking	Internal		Uncommitted	50082889
42068692		12/05/2021		RD: FW Grano Open Joint	Internal		Uncommitted	50082885