Service: Roads General Site: Dalry Road (7902757)

Asset Number: 1.00 to 1.00 Display Action Officer: No

Site: Dalry Road (7902757) Locality: Dalry, Edinburgh, City of Edinburgh Area: South West Locality

Condition Surv	rey	
Defect No: Descri	ption	
Asset:	1.00	

Defect No: Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No.
Asset: 1.00 Asset - Locn.:	Ward 7 - Fron	n No.11 Dalry Road to Henderson Terrac	Asset	Area: South West Locality		
Batch: 41183037 - Inspection Batch		Route: Sou	th Mobile Inspection Route			Date: 19/02/2024
42148253 1no pothole	19/02/2024	Outside no104	RD: CW Pothole	Internal	Committed	50153421
42148250 1no pothole	19/02/2024	Outside no228	RD: CW Pothole	Internal	Committed	50153418
Batch: 41182474 - Inspection Batch		Route: SfP	_SouthWest			Date: 14/02/2024
42147685 1no missing bollard	14/02/2024	Opposite no 228	RD: SFP Damaged Bollard	Internal	Committed	50153003
Batch: 41180412 - Inspection Batch		Route: SW	_FW1_Dalry1			Date: 29/01/2024
42145456 Pothole	29/01/2024	At junction with Richmond terrace	RD: CW Pothole	Internal	Committed	50151510
Batch: 41179085 - Inspection Batch		Route: Sou	th Mobile Inspection Route			Date: 18/01/2024
42144423 1no pothole	18/01/2024	Outside no34	RD: CW Pothole	Internal	Committed	50150545
42144421 1no pothole	18/01/2024	At the junction with Richmond Terrace	RD: CW Pothole	Internal	Committed	50150543
42144422 1no pothole	18/01/2024	Outside no52	RD: CW Pothole	Internal	Committed	50150544
Batch: 41178890 - Inspection Batch		Route: SfP	_SouthWest			Date: 17/01/2024
No actionable defects found						
Batch: 41176560 - Inspection Batch		Route: SW	_FW1_Dalry1			Date: 03/01/2024
42143009 Relay 1 rocking slab	03/01/2024	Outside Thai @ haymarket	RD: FW Slabs Rocking	Internal	Committed	50149113
42143002 Relay 1 rocking slab	03/01/2024	Outside glenmore mobility & furniture	RD: FW Slabs Rocking	Internal	Committed	50149103
42143007 Relay/ replace Approx 7.5 sqm of slabs	03/01/2024	Outside Victorian heart tattoo studio	RD: FW Slabs Broken/Missing	Internal	Committed	50149110
42143008 Relay 1 rocking 900 x 600 slab	03/01/2024	Outside 22	RD: FW Slabs Rocking	Internal	Committed	50149111
Batch: 41174779 - Inspection Batch		Route: Sou	th Mobile Inspection Route			Date: 18/12/2023
42142285 1no pothole	18/12/2023	Outside Troy cafe	RD: CW Pothole	Internal	Committed	50148401
42142284 1no pothole	18/12/2023	At the bus stop opposite Orwell Place	RD: CW Pothole	Internal	Committed	50148400
Batch: 41173038 - Inspection Batch		Route: SW	_FW1_Dalry1			Date: 30/11/2023
42140733 Relay 1 rocking 600 x 600 slab	30/11/2023	Outside 224	RD: FW Slabs Rocking	Internal	Committed	50146896
42140732 Replace broken 3 900 x 600 slabs Relay 4 600 x 600 slabs & 1 small cut sla Renew granite at toby	30/11/2023 b	Outside 254	RD: FW Slabs Broken/Missing	Internal	Committed	50146895
42140739 Relay 1 rocking 900 x 600 slab	30/11/2023	Outside stitch express	RD: FW Slabs Rocking	Internal	Committed	50146902
42140735 Relay 1 rocking 900 x 600 slab	30/11/2023	Outside 22	RD: FW Slabs Rocking	Internal	Committed	50146898
Batch: 41172959 - Inspection Batch		Route: Ad	hoc Route			Date: 29/11/2023
42140646 Road: Defective / Damaged (Enquiry 1652367)	29/11/2023	Pothole in centre of road, just back from junction o/s 260	RD: CW Pothole	Internal	Committed	50146796
Batch: 41172955 - Inspection Batch		Route: Ad	hoc Route			Date: 29/11/2023
42140641 Road: Defective / Damaged (Enquiry 1652363)	29/11/2023	O/s 103_105 depression on c/way	RD: CW Pothole	Internal	Committed	50146791

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00 Display Action Officer: No

Condition Survey

Defect No: Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No
Asset: 1.00 Asset - Locn.:	Ward 7 - Fron	No.11 Dalry Road to Henderson Terrac	e Feature Type: Road A	sset	Area: South W	Vest Locality
Batch: 41172642 - Inspection Batch		Route: Ad	hoc Route			Date: 23/11/2023
42140326 Damaged cross footway channel please replace with new metal box section approximately 3.2m	23/11/2023	Outside Bensons Bar	RD: FW Channel Miss Cover (BL	. Internal	Committed	50146482
Batch: 41172562 - Inspection Batch		Route: Ad	hoc Route			Date: 22/11/2023
42140238 1no pothole	22/11/2023	Outside Bensons Bar	RD: CW Pothole	Internal	Committed	50146394
Batch: 41171985 - Inspection Batch		Route: Sou	th Mobile Inspection Route			Date: 16/11/2023
No actionable defects found						
Batch: 41171057 - Inspection Batch		Route: SfP	_SouthWest			Date: 03/11/2023
No actionable defects found						
Batch: 41170442 - Inspection Batch		Route: SW	_FW1_Dalry1			Date: 30/10/2023
42138269 2no broken 400x400 buff tactile slabs 1no broken 600x900 pcc slab 1no rocking cut pcc slab	30/10/2023	Outside Kebabish Original	RD: FW Slabs Broken/Missing	Internal	Committed	50144643
42138281 Renew all broken grano around box	30/10/2023	Outside Dickens bar	RD: FW Grano Cracked/Broken	Internal	Committed	5014465
42138289 Renew all broken grano around box	30/10/2023	Outside Epl	RD: FW Grano Cracked/Broken	Internal	Committed	50144663
42138273 2no rocking tactile slabs	30/10/2023	Outside Locavore Canteen	RD: FW Slabs Rocking	Internal	Committed	5014464
42138278 Renew all broken grano around box	30/10/2023	At base of cctv camera opposite Orwel terrace	I RD: FW Grano Cracked/Broken	Internal	Committed	50144652
42138285 1no rocking 600x900 pcc slab	30/10/2023	Outside Inkdependent tattoo	RD: FW Slabs Rocking	Internal	Committed	50144659
42138287 1no rocking 600x900 pcc slab	30/10/2023	Outside Mediterranean supermarket	RD: FW Slabs Rocking	Internal	Committed	5014466
42138274 1no c/w pothole	30/10/2023	Outside Locavore Canteen	RD: CW Pothole	Internal	Committed	50144648
42138280 Renew all broken grano around triple caty box	30/10/2023	Outside British Heart Foundation next to bus stop	RD: FW Grano Cracked/Broken	Internal	Committed	50144654
Batch: 41168821 - Inspection Batch		Route: Sou	th Mobile Inspection Route			Date: 16/10/2023
No actionable defects found						
Batch: 41167665 - Inspection Batch		Route: Ad	hoc Route			Date: 04/10/2023
42136987 Road: Defective / Damaged (Enquiry 1622767)	04/10/2023	Pot hole at bus stop o/s pub	RD: CW Pothole	Internal	Committed	50143500
Batch: 41167003 - Inspection Batch		Route: SW	_FW1_Dalry1			Date: 27/09/2023
No actionable defects found						
Batch: 41166977 - Inspection Batch		Route: Ad	hoc Route			Date: 27/09/2023
42136779 Pavement: Damaged / Defective (Enquiry 1617315)	27/09/2023	At the bus stop outside British heart foundation shop on f/path area No 103	RU: Utility Apparatus	Internal	Uncommitted	50143264
Batch: 41166971 - Inspection Batch		Route: Ad	hoc Route			Date: 27/09/2023
42136772 Road: Defective / Damaged - Orwell Terrace please inspect for potholes (Enquiry 34007533)	27/09/2023	C/way breaking up at junction	RD: CW Pothole	Internal	Committed	50143258

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00 Display Action Officer: No

Condition Survey

efect No: Descriptio	n		Log Date	Location		Defect Type	Class.	Organisation	Status		Job No.
Asset:	1.00	Asset - Locn.:	Ward 7 - Fron	n No.11 Dalry Road to Hender	son Terrace	Feature Type: Road A	sset		Area: South W	est Loca	ality
Batch: 4116596	66 - Inspection E	Batch		F	Route: Sout	n Mobile Inspection Route				Date:	20/09/2023
No actional	ble defects foun	ıd									
Batch: 4116563	35 - Inspection E	Batch		F	Route: Ad h	oc Route				Date:	18/09/2023
42136315 Cw cracked	d and broken		18/09/2023	At the junction with Muriesto	n Crescent	RD: CW Cracked/Broken	Internal		Uncommitted		50142717
Batch: 4116502	29 - Inspection E	Batch		F	Route: Ad h	oc Route				Date:	14/09/2023
42136217 Missing gra	ano requires infi	II	14/09/2023	At the bus stop		RD: FW Grano Depression/Sunke	Internal		Committed		50142597
Batch: 4116441	I1 - Inspection B	Batch		F	Route: Ad h	oc Route				Date:	07/09/2023
42135765 Remove Ki the column	ilmarnock / Lana and dispose	ark sign from	07/09/2023	Dalry Road, on column DAZ	34	RD: Unlit Sign Damaged/Missing	Internal		Committed		50142298
Batch: 4116441	10 - Inspection E	Batch		F	Route: Ad h	oc Route				Date:	07/09/2023
42135764 Remove sp from the co	peed reducing molumn and dispo		07/09/2023	Dalry Road, on column DAZ	33	RD: Unlit Sign Damaged/Missing	Internal		Committed		50142297
Batch: 4116406	63 - Inspection E	Batch		F	Route: SW_	FW1_Dalry1				Date:	31/08/2023
2135259 Pothole			31/08/2023	Outside 104		RD: CW Pothole	Internal		Committed		50141937
Batch: 4116327	71 - Inspection E	Batch		F	Route: Sout	n Mobile Inspection Route				Date:	21/08/2023
No actional	ble defects foun	ıd									
Batch: 4116216	62 - Inspection E	Batch		F	Route: SW_	FW1_Dalry1				Date:	31/07/2023
No actional	ble defects foun	ıd									
Batch: 4116109	95 - Inspection E	Batch		F	Route: Sout	n Mobile Inspection Route				Date:	17/07/2023
No actional	ble defects foun	ıd									
Batch: 4116095	<u> </u>			F	Route: Ad h	oc Route				Date:	13/07/2023
12131924 Remove ru make safe		ign pole and	13/07/2023	Rusty/damaged sign pole on footway opposite house no 6		RD: Unlit Sign Damaged/Missing	Internal		Committed		50139255
Batch: 4116092	27 - Inspection E	Batch		F	Route: Ad h	oc Route				Date:	13/07/2023
12131859 Road: Defe 1580728)	ective / Damage	d (Enquiry	13/07/2023	O/s No 228 /way pot holes		RD: CW Pothole	Internal		Committed		50139217
Batch: 4116006	67 - Inspection E	Batch		F	Route: SW_	FW1_Dalry1				Date:	28/06/2023
12130935 Pothole			28/06/2023	Outside 104		RD: CW Pothole	Internal		Committed	_	50138530
42130936 Sunken co surround	ver, lift cover an	d patch	28/06/2023	Near 104 dalry road		RU: Utility Apparatus	Internal		Uncommitted		50138531
Batch: 4116000	09 - Inspection E	Batch		F	Route: Ad h	oc Route				Date:	27/06/2023
42130785 Road: Defe 1571047)	ective / Damage	d (Enquiry	27/06/2023	C/way breaking up at pelicar area hot sand carpet repairs full width of c/way		RD: CW Rutting	Internal		Committed		50138386

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00 Display Action Officer: No

Condition Survey

Defect No: Description		Log Date	Location	Defect T	уре	Class.	Organisation	Status	Job No
Asset:	1.00 Asset - Locr	1.: Ward 7 - Fron	n No.11 Dalry Road to Hender	rson Terrace	Feature Type: Ro	ad Asset		Area: South \	West Locality
Batch: 41160008	- Inspection Batch			Route: Ad hoc Route	1				Date: 27/06/2023
42130784 Road: Defect 1571744)	tive / Damaged (Enquiry	27/06/2023	Just off junction with Cathca and Dalry Road, road has a road cut 2m x 8m 40mm de resurface hra	depression	Rutting	Internal		Committed	5013838
Batch: 41159143	- Inspection Batch		1	Route: South Mobile	Inspection Route				Date: 13/06/2023
No actionable	e defects found								
Batch: 41158336	- Inspection Batch			Route: SW_FW1_Da	ılry1				Date: 31/05/2023
No actionable	e defects found								
Batch: 41157520	- Inspection Batch			Route: South Mobile	Inspection Route				Date: 18/05/2023
No actionable	e defects found								
Batch: 41156659	- Inspection Batch			Route: Ad hoc Route					Date: 05/05/2023
42126813 Road: Defect 1546649)	tive / Damaged (Enquiry	05/05/2023	O/s no 59.	RD: CW	Pothole	Internal		Committed	50135600
Batch: 41156508	- Inspection Batch		1	Route: SW_FW1_Da	alry1				Date: 03/05/2023
42126625 Pothole		03/05/2023	Outside dickens bar	RD: CW	Pothole	Internal		Committed	5013548
Batch: 41155539	- Inspection Batch		1	Route: South Mobile	Inspection Route				Date: 24/04/2023
No actionable	e defects found								
Batch: 41154469	- Inspection Batch			Route: Ad hoc Route					Date: 11/04/2023
42124950 Road: Defect 1534923)	tive / Damaged (Enquiry	11/04/2023	Full width of c/way at crossic c/way breaking up hot sand repairs only		Pothole	Internal		Committed	50133986
Batch: 41153890	- Inspection Batch			Route: SW_FW1_Da	alry1				Date: 03/04/2023
No actionable	e defects found								
Batch: 41153060	- Inspection Batch		l	Route: South Mobile	Inspection Route				Date: 23/03/2023
No actionable	e defects found								
Batch: 41152440	- Inspection Batch		1	Route: Ad hoc Route					Date: 16/03/2023
42122676 Road: Defect 1522838)	tive / Damaged (Enquiry	16/03/2023	At pedestrian crossing full w materials only	vidth hot RD: CW	Pothole	Internal		Committed	5013213
Batch: 41151487	- Inspection Batch			Route: Ad hoc Route					Date: 07/03/2023
42121495 Road: Defect 1519496)	tive / Damaged (Enquiry	07/03/2023	C/way pot holes at junction	area RD: CW	Pothole	Internal		Committed	5013129
Batch: 41151289	- Inspection Batch			Route: SW_FW1_Da	alry1				Date: 04/03/2023
No actionable	e defects found								

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 34007533 Logged by: on: 22/09/2023 09:59

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.: Orwell Terrace please inspect for potholes

Location: Orwell Terrace Contact: denis dixon

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1700539 Logged by: Verint CRM Connector on: 16/02/2024 09:56
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Dalry Road near the bus stop after ardmillan, looks like a plough has been through Contact:

it, westbound.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1688201 Logged by: Verint CRM Connector on: 29/01/2024 13:31
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: Slabs and tactile paving at pedestrian crossing loose creating trip hazard Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1683227 Logged by: Verint CRM Connector on: 22/01/2024 18:38

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: outside 79 Dalry road Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1681670 Logged by: on: 20/01/2024 09:42
Service: Roads General Subject: Road: General Enquiry Classification: General Enquiry

Desc.: electoric parking signage is above this box

Location: electrical box is open exposing wires, on dalry rd at haymarket Contact:

Enquiry No.: 1674212 Logged by: Verint CRM Connector on: 08/01/2024 22:05
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: The full stretch of Dalry road from the bottom of Ardmillan to Dalry primary school Contact:

travelling towards town centre is full of potholes. The cycle lane is not safe to cycle

in forcing bikes into the main carriageway to avoid the potholes

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1673689 Logged by: on: 08/01/2024 11:32

Service: Roads General Subject: Roadworks: Defect Classification: Request for service

Desc.: Description: Abandoned road sign been there for 6 months.

View full report with images from link below: https://clearwaste.com/flytipping/report/60330

Address: Dalry Road, Edinburgh, EH11 2JG

Lat Lng: 55.939693229562, -3.2255539509245

Location: Contact:

Enquiry No.: 1671137 Logged by: on: 04/01/2024 11:00
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.: Outside simpsons Barbar shop loose and broken paving stones pls inspect

Location: Contact:

Enquiry No.: 1665525 **Logged by:** Verint CRM Connector **on:** 21/12/2023 21:09

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: On the corner across from the Snax Cafe. The road/pedestrian crossing area. This **Contact:**

area has a massive dip and every time it rains it fills up and cars splash the entire pavement including the pedestrians on it. It's unacceptable particularly for those with

physical disabilities and cannot dodge the splashing

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1652367 Logged by: Verint CRM Connector on: 28/11/2023 21:38

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Pothole in centre of road, just back from junction.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50146796 **Defect Number:** 42140646

Enquiry No.: 1652363 Logged by: Verint CRM Connector on: 28/11/2023 21:36
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Previous works that have dug a trench across road and then refilled have depressed Contact:

leaving a carriageway wide deep depression

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50146791 **Defect Number:** 42140641

Enquiry No.: 1625754 Logged by: Verint CRM Connector on: 09/10/2023 18:56
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: A tile is completely lose.

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1622777 Logged by: Verint CRM Connector on: 03/10/2023 21:10
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Surface course breaking into large pieces, potholes forming. Bits of road dislodged. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1622776 Logged by: Verint CRM Connector on: 03/10/2023 21:08
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Utility scar patch is crumbling and exposing the original utility scar. Large depression Contact:

forming, Dalry Road needs completely resurfaced.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1622775 Logged by: Verint CRM Connector on: 03/10/2023 21:05
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Bus stop patch is breaking up and cracked. Depression forming into a large pothole. Contact:

Dalry Road needs resurfaced.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1622773 Logged by: Verint CRM Connector on: 03/10/2023 21:03
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Utility scar patch is crumbling and exposing the original utility scar. Large depression Contact:

forming. Dalry Road needs completely resurfaced.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1622771 Logged by: Verint CRM Connector on: 03/10/2023 21:01
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Road patch cracked and breaking up. Dalry Road needs completely resurfaced. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1622769 Logged by: Verint CRM Connector on: 03/10/2023 20:59
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Road patch cracked and breaking up. Dalry Road needs completely resurfaced. **Contact:**

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1622767 Logged by: Verint CRM Connector on: 03/10/2023 20:52

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Large pothole formed in the bus stop, large depression forming around pothole **Contact:**

suggesting subbase has failed.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50143506 **Defect Number:** 42136987

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1622219 Logged by: Verint CRM Connector on: 02/10/2023 18:22

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Just off the junction of Cathcart Place and Dalry Road, headed toward Co-Op Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1617315 Logged by: Verint CRM Connector on: 21/09/2023 12:22

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: At the bus stop outside British heart foundation shop.. There's broken pavements **Contact:**

and is very loose when standing on and is unsafe especially for the elderly. Please

see picture attached

Many thanks

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50143264 **Defect Number:** 42136779

Enquiry No.: 1612258 Logged by: Verint CRM Connector on: 11/09/2023 12:49
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: There are a number of potholes on Dalry Road at the top of Murieston Crescent Contact:

Category: Potholes

These potholes have been there for a considerable time patched twice and now as bad as ever. Our property vibrates and it's very noisy when vehicles pass over the potholes especially buses and HGV vehicles.

These potholes require URGENT attention and should be repaired properly!

Location:

Easting/Northing: 323592/672589 (55.940253, -3.224801) Nearest road to the pin placed on the map (automaticall

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50142717 **Defect Number:** 42136315

Enquiry No.: 1599304 Logged by: Verint CRM Connector on: 17/08/2023 09:38
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: The section of Dalry Road from the junction at Haymarket to Cathcart Place is badly Contact:

potholed. This is very dangerous for cyclists as they cannot use the cycle lane due to the volume of parked cars in the cycle lane, and so are forced onto the main

carriageway.

the missing drain covers and potholes make it very difficult to cycle safe. The worst

area of condition is travelling west.

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1598013 Logged by: Verint CRM Connector on: 15/08/2023 13:49
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: The full cycle lane along the length of Dalry Road is dangerous. It is full of deep pot Contact:

holes, loose drain covers and debris. It is so unsafe to cycle in it is safer to cycle on

the main carriageway.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1594613 Logged by: Verint CRM Connector on: 08/08/2023 18:39
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: On Dalry Road at the old Scottish Building no Society. There is a rusty frame from a Contact:

road sign with a sandbag holding it. I was walking along Dalry Road. I saw the sign leaning against the wall of the Scottish building society building. But didn't notice that there was a bit sticking out. I tripped and was extremely lucky that I didn't fall

onto a rusty metal frame.

Enquiry No.: 1580728 Logged by: Verint CRM Connector on: 12/07/2023 21:50
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Plot Number: 1.00

Location: There are a number of deep potholes on Dalry Road at the top of Murieston

Crescent also the manhole needs to be replaced it is very worn and loose exacerbated by traffic passing over it in particular HGV vehicles and buses.

Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Contact:

Job Number: 50139217 **Defect Number:** 42131859

Enquiry No.: 1580521 Logged by: Verint CRM Connector on: 12/07/2023 16:25

Service: Roads General Subject: Traffic Sign:Defective/Damaged Classification: Request for service

Desc.: What type of sign is it? Road sign problem, type unlit

Location: Pole is rusted through, it's swaying on the wind and is in danger of collapsing onto **Contact:**

someone.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50139255 **Defect Number:** 42131924

Enquiry No.: 1577708 Logged by: Verint CRM Connector on: 06/07/2023 20:26
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Depression on the road Contact:

Contact:

Effective: 28/02/2023 to 29/02/2024

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1573633 Logged by: Verint CRM Connector on: 28/06/2023 21:47

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Travelling west on Dalry Road approaching the traffic lights at the large junction with Contact:

Ardmillan Terrace, etc. There is an uneven surface in the cycle lane just when entering the red cycle section of the road immediately before the traffic lights at this junction. I would perhaps describe it as a bad joint/seam of the tarmac? It's quite

bad when travelling over it on a bicycle.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1571744 Logged by: Verint CRM Connector on: 25/06/2023 13:31

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Just off junction with Cathcart Place and Dalry Road, road has a large depression / Contact:

pothole

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50138385 **Defect Number:** 42130784

Enquiry No.: 1571047 Logged by: Verint CRM Connector on: 23/06/2023 10:34
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Hi there, this location, just as you enter dalry Road there are fairly big pot holes in

the road, likewise as you enter Gorgie Road towards Gorgie there are also fairly big

potholes, this junction is covered in them and this issue really needs to be

addressed as its really poor and quite likely to damage vehicles.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50138386 **Defect Number:** 42130785

Enquiry No.: 1560470 Logged by: Verint CRM Connector on: 01/06/2023 12:54

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: pot holes at traffic lights Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1558225 Logged by: Verint CRM Connector on: 29/05/2023 09:17

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: One of the traffic lights at the end of Dalry Road where it meets Gorgie Road, Contact:

Ardmillan Terrace, Warriston Crescent and Henderson Terrace is broken. The filter which allows a person coming from Dalry Road to go up either Ardmillan Terrace or Henderson Terrace isn't working. This has been the case for a few weeks but doesn't seem to have been picked up because it's a filter only and the light does eventually turn green. However it does unnecessarily impede the flow of traffic.

Contact:

Effective: 28/02/2023 to 29/02/2024

Service: Roads General Site: Dalry Road (7902757) Display Action Officer: No

Asset Number: 1.00 to 1.00

Customer Services

Logged by: Verint CRM Connector **Enquiry No.: 1546649** on: 04/05/2023 09:50 Classification: Request for service

Service: Roads General Subject: Road: Defective / Damaged

Desc.:

Location: Near no 59. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50135606 Defect Number: 42126813

on: 01/05/2023 11:50 Enquiry No.: 1545233 Logged by: Verint CRM Connector Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Traffic light issue, the green filter light for traffic to move from Dalry Road (A70) to

Ardmillian Terrace does not appear to be functioning, only the filter light for Dalry Road to Henderson Terrace is operating. This issue is causing drivers distress and

traffic congestion.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1543278 Logged by: Verint CRM Connector on: 26/04/2023 13:52 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: I can see that someone has recently filled two large potholes here, but the road is so Contact:

uneven and damaged that my flat still shakes when buses speed over the bumps at

30 mph.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1540756 Logged by: Verint CRM Connector on: 21/04/2023 10:15 Subject: Road: Defective / Damaged Classification: Request for service Service: Roads General

Desc.:

Location: Please come and fix these potholes! I've been reporting them for weeks. My flat Contact:

> shakes and my windows rattle when heavy vehicles drive over them. It's not good for the structure of the building and there are cracks in the walls in the bottom of the

stairwell.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1536555 Logged by: Verint CRM Connector on: 13/04/2023 12:28 Subject: Roadworks: General Enquiry Service: Roads General Classification: Request for service

Desc.: What type of sign is it? Road sign problem, type unlit

Location: there has been a yellow 'Diverted Traffic' sign that's been left outside for months. Contact:

on: 09/04/2023 22:47 Enquiry No.: 1534923 Logged by: Verint CRM Connector Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Potholes been here for weeks. Cyclist swerved to avoid it in front of me. Just a Contact:

matter of time before someone is killed again. When this happens i will be showing

this report to the media

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Job Number: 50133986 Defect Number: 42124950

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1531936 Logged by: Verint CRM Connector on: 03/04/2023 13:48

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Please fix these potholes soon! I've been reporting them for weeks. When heavy Contact:

traffic drives over them my whole flat shudders and my windows rattle. There are cracks in the walls in the bottom of the stairwell and the vibration from the potholes

can only worsen and accelerate any structural problems.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1531044 Logged by: Verint CRM Connector on: 31/03/2023 11:43

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Please fix these potholes. Traffic hitting the potholes causes my whole flat to **Contact:**

shudder, which can't be good for the structure of the building. I first reported it about

2 weeks ago.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1528961 Logged by: Verint CRM Connector on: 27/03/2023 15:33

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: very large pot hole, dangerous to cyclists and damaging to vehicles **Contact:**

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1526430 Logged by: Verint CRM Connector on: 22/03/2023 09:01
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Intersection of Dalry road and Murieston Road there are few deep potholes. **Contact:**

If I damaged my suspension car you will pay the bill. Absolutely road safe issue

Enquiry No.: 1525520 Logged by: Verint CRM Connector on: 20/03/2023 13:20
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Heavy traffic driving over large potholes at the traffic-light the junction between Dalry **Contact:**

Road and Gorgie Road are causing my flat to shake so much that I'm woken by it.

Please fill them as soon as you can.

Enquiry No.: 1524919 Logged by: Verint CRM Connector on: 18/03/2023 15:08
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Series of bad potholes present, road in terrible condition Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1524083 Logged by: Verint CRM Connector on: 16/03/2023 15:11

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: At junction of Dalry Road.

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1522838 Logged by: Verint CRM Connector on: 14/03/2023 13:07
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Deep and widespread road damage on the pedestrian crossing on Gorgie Road. **Contact:**

Dangerous surface for cycles and motorcycles in particular.

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Enquiry No.: 1519496 Logged by: Verint CRM Connector on: 06/03/2023 19:27
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: The surface is badly broken Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - From No.11 Dalry Road to Henderson Terrace Feature Type: Road Asset

Maintenance Management

Job No.	Description		Location	Priority	Job Status	Entered	Completion	Works Order
	Asset:	1.00	Asset - Locn.: Ward 7 - From No.11 Dalry Road to Henderson	Terrace Feature	Type: Road Asset		Area: South V	Vest Locality
5009736	1 Refresh marking Refresh)	ıs (RD: Markin	gs Entire cw including all junctions	RD: Cat 4 - Programmed	No code allocated	16/11/2021	16/11/2022	Est.
50118966	6 1x pothole (RD:	CW Pothole)	Outside no.253	RD: Cat 4 - Programmed	No code allocated	20/09/2022	20/09/2023	Est.
50131298	Road: Defective (Enquiry 151949 Pothole)		C/way pot holes at junction area	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/03/2023	08/03/2023	Act. ROAD/82073934
50132138	Road: Defective (Enquiry 152283 Pothole)		At pedestrian crossing full width hot materials only	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/03/2023	23/03/2023	Act. ROAD/82074390
50133986	6 Road: Defective (Enquiry 153492 Pothole)	•	Full width of c/way at crossing point c/way breaking up hot sand carpet repairs only	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/04/2023	12/04/2023	Act. ROAD/82075568
5013548	1 Pothole (RD: CV	V Pothole)	Outside dickens bar	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/05/2023	04/05/2023	Act. ROAD/82076729
50135606	6 Road: Defective (Enquiry 154664 Pothole)	•	O/s no 59.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/05/2023	09/05/2023	Act. ROAD/82076823
50138385	5 Road: Defective (Enquiry 157174 Rutting)	-	Just off junction with Cathcart Place and Dalry Road, road has a depression road cut 2m x 8m 40mm depth resurface hra	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/06/2023	09/07/2023	Act. ROAD/82078581
50138386	6 Road: Defective (Enquiry 157104 Rutting)	-	C/way breaking up at pelican crossing area hot sand carpet repairs required full width of c/way	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/06/2023	09/07/2023	Act. ROAD/82078582
50138530) Pothole (RD: CV	V Pothole)	Outside 104	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/06/2023	29/06/2023	Act. ROAD/82078633

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00 Display Action Officer: No

Maintenance Management

Job No.	Description		Location	Priority	Job Status	Entered	Completion	Works Order
	Asset:	1.00	Asset - Locn.: Ward 7 - From No.11 Dalry Road to Henderson	Terrace Feature	Type: Road Asset		Area: South W	est Locality
	Sunken cover, lift patch surround (Apparatus)		Near 104 dalry road	RU: Fail Med.Risk (Apparatus)	Job Complete	28/06/2023	28/06/2023 A	ct.
	Road: Defective (Enquiry 158072 Pothole)		O/s No 228 /way pot holes	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/07/2023	14/07/2023 A	ct. ROAD/8207907
	Remove rusty /d pole and make s Unlit Sign Dama	afe footway (RD	Rusty/damaged sign pole on 2: south footway opposite house no 6	RD: Cat 3 - 60 Day	Job Complete	13/07/2023	02/08/2023 A	ct. ROAD/8207909
	Pothole (RD: CW		Outside 104	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/08/2023	01/09/2023 A	ct. ROAD/8208040
	Remove speed r measures sign fr and dispose. (RI Damaged/Missin	om the column D: Unlit Sign	Dalry Road, on column DAZ33	RD: Cat 3 - 60 Day	Job Complete	07/09/2023	11/09/2023 A	ct. ROAD/8208053
50142298	Remove Kilmarn sign from the col dispose (RD: Un Damaged/Missin	ock / Lanark umn and lit Sign	Dalry Road, on column DAZ34	RD: Cat 3 - 60 Day	Job Complete	07/09/2023	23/09/2023 A	ct. ROAD/8208054
0142597	Missing grano re FW Grano Depre	quires infill (RD ession/Sunken)	: At the bus stop	RD: Cat 3 - 60 Day	Job Complete	14/09/2023	15/09/2023 A	ct. ROAD/8208067
50142717	Cw cracked and Cracked/Broken)		V At the junction with Murieston Crescent	RD: Cat 4 - Programmed	No code allocated	18/09/2023	18/09/2024 E	st.
	Road: Defective Orwell Terrace p potholes (Enquir (RD: CW Pothole	lease inspect fo y 34007533)	C/way breaking up at junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/09/2023	28/09/2023 A	ct. ROAD/8208107
50143264		aged / Defective	At the bus stop outside British heart foundation shop on f/path area No 103	RU: Fail Med.Risk (Apparatus)	Job Complete	27/09/2023	27/09/2023 A	ct.
	Road: Defective (Enquiry 162276 Pothole)		Pot hole at bus stop o/s pub	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/10/2023	04/10/2023 A	ct. ROAD/8208127
	2no broken 400x slabs 1no broken 600x 1no rocking cut p FW Slabs Broke	900 pcc slab occ slab (RD:	Outside Kebabish Original	RD: Cat 2 - 5 Day	Job Complete	30/10/2023	06/11/2023 A	ct. ROAD/8208204
	2no rocking tacti FW Slabs Rockin		Outside Locavore Canteen	RD: Cat 2 - 5 Day	Job Complete	30/10/2023	06/11/2023 A	ct. ROAD/8208204
50144648	1no c/w pothole Pothole)	(RD: CW	Outside Locavore Canteen	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/10/2023	30/10/2023 A	ct. ROAD/8208205
0144652	Renew all broker box (RD: FW Gra Cracked/Broken)	ano	At base of cctv camera opposite Orwell terrace	RD: Cat 3 - 60 Day	Job Complete	30/10/2023	07/11/2023 A	ct. ROAD/8208205

Service: Roads General Site: Dalry Road (7902757) Asset Number: 1.00 to 1.00 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00 A s	sset - Locn.: Ward 7 - From No.11 Dalry Road	to Henderson Terrace Featu	Terrace Feature Type: Road Asset			t Locality
50144654	Renew all broken grano around triple catv box (RD: FW Grano Cracked/Broken)	Outside British Heart Foundation next to bus stop	RD: Cat 3 - 60 Day	Job Complete	30/10/2023	13/11/2023 Act.	ROAD/82082054
50144655	5 Renew all broken grano around box (RD: FW Grano Cracked/Broken)	Outside Dickens bar	RD: Cat 3 - 60 Day	Job Complete	30/10/2023	07/11/2023 Act.	ROAD/82082055
50144659	1no rocking 600x900 pcc slab (RD: FW Slabs Rocking)	Outside Inkdependent tattoo	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/10/2023	07/11/2023 Act.	ROAD/82082059
5014466	1 no rocking 600x900 pcc slab (RD: FW Slabs Rocking)	Outside Mediterranean supermarket	RD: Cat 3 - 60 Day	Job Complete	30/10/2023	08/11/2023 Act.	ROAD/82082061
50144663	B Renew all broken grano around box (RD: FW Grano Cracked/Broken)	Outside Epl	RD: Cat 3 - 60 Day	Job Complete	30/10/2023	07/11/2023 Act.	ROAD/82082063
50146394	1 1no pothole (RD: CW Pothole)	Outside Bensons Bar	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/11/2023	28/11/2023 Act.	ROAD/82083064
50146482	2 Damaged cross footway channel please replace with new metal box section approximately 3.2m (RD: FW Channel Miss Cover (BL))	Outside Bensons Bar	RD: Cat 3 - 60 Day	Job Complete	23/11/2023	05/12/2023 Act.	ROAD/82083114
5014679	(Page 1977) (Page	O/s 103_105 depression on c/way	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/11/2023	04/12/2023 Act.	ROAD/82083277
50146796	6 Road: Defective / Damaged (Enquiry 1652367) (RD: CW Pothole)	Pothole in centre of road, just back from junction o/s 260	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/11/2023	04/12/2023 Act.	ROAD/82083280
50146895	5 Replace broken 3 900 x 600 slab Relay 4 600 x 600 slabs & 1 small cut slab Renew granite at toby (RD: FW Slabs Broken/Missing)	SOutside 254	RD: Cat 3 - 60 Day	Job Complete	30/11/2023	15/12/2023 Act.	ROAD/82083327
50146896	Relay 1 rocking 600 x 600 slab (RD: FW Slabs Rocking)	Outside 224	RD: Cat 3 - 60 Day	Job Complete	30/11/2023	11/12/2023 Act.	ROAD/82083328
50146898	Relay 1 rocking 900 x 600 slab (RD: FW Slabs Rocking)	Outside 22	RD: Cat 3 - 60 Day	Job Complete	30/11/2023	13/12/2023 Act.	ROAD/82083329
50146902	Relay 1 rocking 900 x 600 slab (RD: FW Slabs Rocking)	Outside stitch express	RD: Cat 3 - 60 Day	Job Complete	30/11/2023	13/12/2023 Act.	ROAD/82083332
50148400	1 no pothole (RD: CW Pothole)	At the bus stop opposite Orwell Place	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/12/2023	28/12/2023 Act.	ROAD/82084278
5014840	1 1no pothole (RD: CW Pothole)	Outside Troy cafe	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/12/2023	28/12/2023 Act.	ROAD/82084279
50149103	Relay 1 rocking slab (RD: FW Slabs Rocking)	Outside glenmore mobility & furniture	RD: Cat 3 - 60 Day	Job Complete	03/01/2024	08/01/2024 Act.	ROAD/82084742
50149110	Relay/ replace Approx 7.5 sqm of slabs (RD: FW Slabs Broken/Missing)	f Outside Victorian heart tattoo studio	RD: Cat 3 - 60 Day	Job Complete	03/01/2024	22/01/2024 Act.	ROAD/82084747

Service: Roads General

Asset Number: 1.00 to 1.00 Display Action Officer: No

Site: Dalry Road (7902757)

Mainten	ance Managem	nent						
Job No.	Description		Location	Priority	Job Sta	tus Entered	Completion	Works Order
	Asset: 1	.00	Asset - Locn.: Ward 7 - From No.11 Dalry Road to Henders	on Terrace	Feature Type: Roa	ad Asset	Area: South W	est Locality
50149111	Relay 1 rocking 90 (RD: FW Slabs Ro		Outside 22	RD: Cat 3 - 60	Day Job Con	nplete 03/01/2024	08/01/2024 A	ct. ROAD/82084748
50149113	Relay 1 rocking sla Slabs Rocking)	ab (RD: FW	Outside Thai @ haymarket	RD: Cat 3 - 60	Day Job Con	nplete 03/01/2024	09/01/2024 A	ct. ROAD/82084749
50150543	1no pothole (RD: C	CW Pothole)	At the junction with Richmond Terrace	RD: Cat 3 - 60	Day RD: Mad Complete		29/01/2024 A	ct. ROAD/82085676
50150544	1no pothole (RD: 0	CW Pothole)	Outside no52	RD: Cat 3 - 60	Day RD: Mad Complete	de Safe Job 18/01/2024 te	29/01/2024 A	ct. ROAD/82085677
50150545	1no pothole (RD: C	CW Pothole)	Outside no34	RD: Cat 3 - 60	Day RD: Mad Complete		29/01/2024 A	ct. ROAD/82085678
50151510	Pothole (RD: CW I	Pothole)	At junction with Richmond terrace	RD: Cat 3 - 60	Day RD: Mad Complet	de Safe Job 29/01/2024 te	18/02/2024 A	ct. ROAD/82086353
50153003	1no missing bollard Damaged Bollard)	`	Opposite no 228	RD: Cat 3 - 60	Day Job Con	nplete 14/02/2024	15/02/2024 A	ct. ROAD/82087411
50153418	1no pothole (RD: C	CW Pothole)	Outside no228	RD: Cat 3 - 60	Day RD: Mad Complet		21/02/2024 A	ct. ROAD/82087743
50153421	1no pothole (RD: C	CW Pothole)	Outside no104	RD: Cat 2 - 5 I	•	de Safe Job 19/02/2024	20/02/2024 A	ct. ROAD/82087745