

Site History Report

Effective: 20/06/2019 to 20/06/2025

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Ladywell Road (7900460)

Site: Ladywell Road (7900460)

Locality: Broomhall, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41229353 - Inspection Batch			Route: SfP_NorthWest			Date: 27/05/2025	
No actionable defects found								
Batch:	41228153 - Inspection Batch			Route: NW_CW1_East1			Date: 13/05/2025	
No actionable defects found								
Batch:	41227587 - Inspection Batch			Route: NW_CF1_BroomhallEast1			Date: 06/05/2025	
42182952	Extensive patching required east bound lane	06/05/2025	Just before traffic lights	RD: CW Cracked/Broken	Internal		Uncommitted	50113517
Batch:	41226836 - Inspection Batch			Route: SfP_NorthWest			Date: 25/04/2025	
No actionable defects found								
Batch:	41224912 - Inspection Batch			Route: Ad hoc Route			Date: 02/04/2025	
42180483	Permanent repair required	02/04/2025	Junction Dunsmuir Court	RD: CW Pothole	Internal		Committed	50178034
Batch:	41223713 - Inspection Batch			Route: SfP_NorthWest			Date: 22/03/2025	
No actionable defects found								
Batch:	41221517 - Inspection Batch			Route: Ad hoc Route			Date: 05/03/2025	
42177823	Permanent repair required	05/03/2025	Opposite 32 at bus stop	RD: CW Pothole	Internal		Committed	50176415
Batch:	41221515 - Inspection Batch			Route: Ad hoc Route			Date: 05/03/2025	
42177822	Pothole on carriageway	05/03/2025	Outside 36	RD: CW Pothole	Internal		Committed	50176414
Batch:	41220632 - Inspection Batch			Route: SfP_NorthWest			Date: 25/02/2025	
No actionable defects found								
Batch:	41219254 - Inspection Batch			Route: NW_CW1_East1			Date: 17/02/2025	
42176125	2 cw potholes	17/02/2025	Outside 36	RD: CW Pothole	Internal		Committed	50175176
Batch:	41218641 - Inspection Batch			Route: Ad hoc Route			Date: 12/02/2025	
42175745	Pothole on carriageway	12/02/2025	Outside 36	RD: CW Pothole	Internal		Committed	50174883
Batch:	41217260 - Inspection Batch			Route: SfP_NorthWest			Date: 03/02/2025	
42174693	Replace missing bollard	03/02/2025	Outside no1	RD: SFP Damaged Bollard	Internal		Committed	50174087
Batch:	41217181 - Inspection Batch			Route: Ad hoc Route			Date: 03/02/2025	
42174612	Pothole on carriageway at bus stop	03/02/2025	Junction Dunsmuir Court	RD: CW Pothole	Internal		Committed	50174028
Batch:	41216772 - Inspection Batch			Route: Ad hoc Route			Date: 29/01/2025	
42174332	Pothole on carriageway	29/01/2025	Outside 36	RD: CW Pothole	Internal		Committed	50173827
Batch:	41214660 - Inspection Batch			Route: NW_CW1_East1			Date: 14/01/2025	
No actionable defects found								
Batch:	41213428 - Inspection Batch			Route: Ad hoc Route			Date: 09/01/2025	
42172489	Pothole on carriageway	09/01/2025	Outside 36	RD: CW Pothole	Internal		Committed	50172450
Batch:	41212679 - Inspection Batch			Route: Ad hoc Route			Date: 03/01/2025	
42171984	Pothole on carriageway	03/01/2025	Outside 36	RD: CW Pothole	Internal		Committed	50172029

Site History Report

Effective: 20/06/2019 to 20/06/2025

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Ladywell Road (7900460)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch: 41212472 - Inspection Batch				Route: SfP_NorthWest				Date: 30/12/2024
No actionable defects found								
Batch: 41212108 - Inspection Batch				Route: Ad hoc Route				Date: 30/12/2024
42171879	Pothole on carriageway	30/12/2024	Junction Ladywell Avenue	RD: CW Pothole	Internal		Committed	50171934
Batch: 41212107 - Inspection Batch				Route: Ad hoc Route				Date: 30/12/2024
42171878	Pothole on carriageway	30/12/2024	Outside Ladywell House	RD: CW Pothole	Internal		Committed	50171933
Batch: 41212106 - Inspection Batch				Route: Ad hoc Route				Date: 30/12/2024
42171877	Pothole on carriageway	30/12/2024	Outside 36	RD: CW Pothole	Internal		Committed	50171932
Batch: 41210777 - Inspection Batch				Route: Ad hoc Route				Date: 12/12/2024
42171128	Pothole on carriageway	12/12/2024	Heading east from Meadow Place Road	RD: CW Pothole	Internal		Committed	50171351
Batch: 41209638 - Inspection Batch				Route: SfP_NorthWest				Date: 04/12/2024
No actionable defects found								
Batch: 41209266 - Inspection Batch				Route: Ad hoc Route				Date: 02/12/2024
42170202	Pothole on carriageway	02/12/2024	Bus stop at junction Dunsmuir Court	RD: CW Pothole	Internal		Committed	50170633
Batch: 41207715 - Inspection Batch				Route: SfP_NorthWest				Date: 14/11/2024
No actionable defects found								
Batch: 41206975 - Inspection Batch				Route: NW_CW1_East1				Date: 08/11/2024
No actionable defects found								
Batch: 41205409 - Inspection Batch				Route: Ad hoc Route				Date: 28/10/2024
42167623	Pothole on carriageway	28/10/2024	Outside 36	RD: CW Pothole	Internal		Committed	50168720
Batch: 41203959 - Inspection Batch				Route: SfP_NorthWest				Date: 17/10/2024
No actionable defects found								
Batch: 41201565 - Inspection Batch				Route: NW_CW1_East1				Date: 27/09/2024
No actionable defects found								
Batch: 41200099 - Inspection Batch				Route: SfP_NorthWest				Date: 06/09/2024
No actionable defects found								
Batch: 41198521 - Inspection Batch				Route: SfP_NorthWest				Date: 13/08/2024
No actionable defects found								
Batch: 41197312 - Inspection Batch				Route: SfP_NorthWest				Date: 23/07/2024
No actionable defects found								
Batch: 41195279 - Inspection Batch				Route: SfP_NorthWest				Date: 24/06/2024
No actionable defects found								
Batch: 41195023 - Inspection Batch				Route: NW_CW1_East1				Date: 20/06/2024
No actionable defects found								
Batch: 41193554 - Inspection Batch				Route: Ad hoc Route				Date: 04/06/2024
42158957	Pothole on carriageway	04/06/2024	Outside Ladywell Medical Centre	RD: CW Pothole	Internal		Committed	50161726

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41193553 - Inspection Batch			Route:	Ad hoc Route		Date:	04/06/2024
42158956	Pothole on carriageway	04/06/2024	Outside 36	RD: CW Pothole	Internal		Committed	50161725
Batch:	41192195 - Inspection Batch			Route:	SfP_NorthWest		Date:	16/05/2024
	No actionable defects found							
Batch:	41192084 - Inspection Batch			Route:	Ad hoc Route		Date:	15/05/2024
42157311	Pothole on carriageway	15/05/2024	Junction Ladywell Court	RD: CW Pothole	Internal		Committed	50160449
Batch:	41191421 - Inspection Batch			Route:	NW_CF1_BroomhallEast1		Date:	08/05/2024
42156665	Extensive patching required east bound lane	08/05/2024	Just before traffic lights	RD: CW Cracked/Broken	Internal		No Action Required	
42156664	permanent repair required to carriageway	08/05/2024	Junction Ladywell Avenue	RD: CW Rutting	Internal		Uncommitted	50124908
Batch:	41191096 - Inspection Batch			Route:	Ad hoc Route		Date:	03/05/2024
42156411	Pothole on carriageway	03/05/2024	Junction Meadow Place Road	RD: CW Pothole	Internal		Committed	50159765
Batch:	41188428 - Inspection Batch			Route:	SfP_NorthWest		Date:	04/04/2024
	No actionable defects found							
Batch:	41188082 - Inspection Batch			Route:	Ad hoc Route		Date:	02/04/2024
42153422	Pothole on carriageway	02/04/2024	At traffic lights junction Meadow Place Road	RD: CW Pothole	Internal		Committed	50157152
Batch:	41188080 - Inspection Batch			Route:	Ad hoc Route		Date:	02/04/2024
42153420	Pothole on carriageway	02/04/2024	Junction Ladywell Avenue	RD: CW Pothole	Internal		Committed	50157150
Batch:	41186812 - Inspection Batch			Route:	NW_CW1_East1		Date:	19/03/2024
	No actionable defects found							
Batch:	41184371 - Inspection Batch			Route:	SfP_NorthWest		Date:	01/03/2024
	No actionable defects found							
Batch:	41181528 - Inspection Batch			Route:	Ad hoc Route		Date:	06/02/2024
42146527	Pothole on carriageway	06/02/2024	Junction Ladywell Avenue	RD: CW Pothole	Internal		Committed	50152268
Batch:	41181035 - Inspection Batch			Route:	SfP_NorthWest		Date:	02/02/2024
	No actionable defects found							
Batch:	41180162 - Inspection Batch			Route:	Ad hoc Route		Date:	26/01/2024
42145205	Pothole on carriageway	26/01/2024	Outside 36	RD: CW Pothole	Internal		Committed	50151276
Batch:	41180161 - Inspection Batch			Route:	Ad hoc Route		Date:	26/01/2024
42145204	Pothole on carriageway	26/01/2024	Outside 1-3	RD: CW Pothole	Internal		Committed	50151275
Batch:	41178012 - Inspection Batch			Route:	NW_CW1_East1		Date:	10/01/2024
	No actionable defects found							
Batch:	41177604 - Inspection Batch			Route:	Ad hoc Route		Date:	05/01/2024
42143329	Road: Defective / Damaged (Enquiry 1671391) pothole on carriageway	05/01/2024	Outside 36	RD: CW Pothole	Internal		Committed	50149433

Site History Report

Effective: 20/06/2019 to 20/06/2025

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Ladywell Road (7900460)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41175119 - Inspection Batch			Route:	Ad hoc Route			Date: 20/12/2023
42142538	Pothole on carriageway	20/12/2023	Outside 8	RD: CW Pothole	Internal		Committed	50148638
Batch:	41175117 - Inspection Batch			Route:	Ad hoc Route			Date: 20/12/2023
42142536	Road: Defective / Damaged (Enquiry 1663793) pothole on carriageway	20/12/2023	Heading east from Meadow Place Road	RD: CW Pothole	Internal		Committed	50148636
Batch:	41171229 - Inspection Batch			Route:	Ad hoc Route			Date: 06/11/2023
42138739	Road: Defective / Damaged (Enquiry 1638300) pothole on carriageway	06/11/2023	Outside Ladywell House	RD: CW Pothole	Internal		Committed	50145099
Batch:	41167771 - Inspection Batch			Route:	NW_CW1_East1			Date: 05/10/2023
	No actionable defects found							
Batch:	41159937 - Inspection Batch			Route:	NW_CW1_East1			Date: 26/06/2023
	No actionable defects found							
Batch:	41158283 - Inspection Batch			Route:	NW_CF1_BroomhallEast1			Date: 31/05/2023
42129043	Extensive patching required east bound lane	31/05/2023	Just before traffic lights	RD: CW Cracked/Broken	Internal		No Action Required	
42129102	1 cw pothole	31/05/2023	As you enter Ladywell road from meadow place road	RD: CW Pothole	Internal		Committed	50137050
42129100	1 cw pothole	31/05/2023	At car park entrance to Ladywell house	RD: CW Pothole	Internal		Committed	50137048
42129049	Road: Defective / Damaged (Enquiry 1479678) permanent repair required to carriageway	31/05/2023	Junction Ladywell Avenue	RD: CW Rutting	Internal		No Action Required	
Batch:	41154490 - Inspection Batch			Route:	Ad hoc Route			Date: 11/04/2023
42124971	Pothole on carriageway	11/04/2023	Junction Ladywell Avenue	RD: CW Pothole	Internal		Committed	50134010
Batch:	41154011 - Inspection Batch			Route:	Ad hoc Route			Date: 05/04/2023
42124628	Road: Defective / Damaged (Enquiry 1528856) pothole on carriageway heading east	05/04/2023	Junction Meadow Place Road	RD: CW Pothole	Internal		Committed	50133675
Batch:	41153651 - Inspection Batch			Route:	NW_CW1_East1			Date: 30/03/2023
	No actionable defects found							
Batch:	41147658 - Inspection Batch			Route:	Ad hoc Route			Date: 01/02/2023
42117045	Pothole on carriageway	01/02/2023	Outside 3	RD: CW Pothole	Internal		Committed	50128088
Batch:	41146549 - Inspection Batch			Route:	Ad hoc Route			Date: 25/01/2023
42116446	Road: Defective / Damaged (Enquiry 1493606) Pothole on carriageway	25/01/2023	Outside 36	RD: CW Pothole	Internal		Committed	50127469
Batch:	41144884 - Inspection Batch			Route:	Ad hoc Route			Date: 20/01/2023
42115944	Road: Defective / Damaged (Enquiry 1488762)	20/01/2023	At feather hall avenue potholes and rutting of joints	RD: CW Pothole	Internal		Committed	50126971
Batch:	41144843 - Inspection Batch			Route:	Ad hoc Route			Date: 20/01/2023
42115907	2x potholes	20/01/2023	Right turn lane at traffic lights.	RD: CW Pothole	Internal		Committed	50126923

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality		
Batch: 41142421 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 05/01/2023		
Batch: 41141004 - Inspection Batch				Route: Ad hoc Route		Date: 28/12/2022		
42113784	Pothole on carriageway	28/12/2022	Outside 36	RD: CW Pothole	Internal		Committed	50124918
Batch: 41140963 - Inspection Batch				Route: Ad hoc Route		Date: 28/12/2022		
42113774	Road: Defective / Damaged (Enquiry 1479678)permanent repair required to carriageway	28/12/2022	Junction Ladywell Avenue	RD: CW Rutting	Internal		No Action Required	
Batch: 41133258 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 21/10/2022		
Batch: 41127865 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 19/07/2022		
Batch: 41126227 - Inspection Batch				Route: NW_CW1_East1		Date: 21/06/2022		
42103638	1no pothole	21/06/2022	Outside no36	RD: CW Pothole	Internal		Committed	50115565
Batch: 41124548 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 20/05/2022		
Batch: 41124039 - Inspection Batch				Route: NW_CF1_BroomhallEast1		Date: 12/05/2022		
42101119	1 carriageway pothole	12/05/2022	At ladywell court	RD: CW Pothole	Internal		Committed	50113516
42101121		12/05/2022		RD: CW Cracked/Broken	Internal		Uncommitted	5005713
42101123	Extensive patching required east bound lane	12/05/2022	Just before traffic lights	RD: CW Cracked/Broken	Internal		No Action Required	
42101122		12/05/2022		RD: CW Cracked/Broken	Internal		Uncommitted	5005714
42101120		12/05/2022		RD: Unlit Sign Damaged/Missing	Internal		Uncommitted	5012625
Batch: 41122665 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 21/04/2022		
Batch: 41121363 - Inspection Batch				Route: Ad hoc Route		Date: 31/03/2022		
42098247	Pothole on carriageway	31/03/2022	Junction Ladywell Avenue	RD: CW Pothole	Internal		Committed	50110790
Batch: 41121360 - Inspection Batch				Route: Ad hoc Route		Date: 31/03/2022		
42098246	Pothole on carriageway	31/03/2022	Outside 1-3	RD: CW Pothole	Internal		Committed	50110788
Batch: 41121356 - Inspection Batch				Route: Ad hoc Route		Date: 31/03/2022		
42098245	Pavement: Damaged / Defective - @edinhelp Hello, there is quite a large hole in the pavement on Ladywell Road that will cause injury to anyone who steps in it. See attached image to show approx location (Enquiry 1354030) Pothole on footway	31/03/2022	Outside 2 at bus stop	RD: FW HRA Pothole	Internal		Committed	50110787
Batch: 41120131 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 22/03/2022		

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality		
Batch: 41116567 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 22/02/2022		
Batch: 41116281 - Inspection Batch				Route: Ad hoc Route		Date: 21/02/2022		
42093507	Road: Defective / Damaged (Enquiry 1329167) pothole on carriageway	21/02/2022	Outside 36	RD: CW Pothole	Internal		Committed	50106886
Batch: 41113694 - Inspection Batch				Route: NW_CW1_East1		Date: 21/01/2022		
42090368	1 carriageway pothole	21/01/2022	Outside 36	RD: CW Pothole	Internal		Committed	50103736
42090367	4 carriageway potholes	21/01/2022	Near junction of meadow place road	RD: CW Pothole	Internal		Committed	50103735
Batch: 41111402 - Inspection Batch				Route: NW_CW1_East1		Date: 21/12/2021		
42087809	5 carriageway potholes	21/12/2021	At traffic lights for meadow place road	RD: CW Pothole	Internal		Committed	50101012
Batch: 41108306 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 25/11/2021		
Batch: 41107190 - Inspection Batch				Route: Ad hoc Route		Date: 11/11/2021		
42083274	Road: Defective / Damaged (Enquiry 1272859) Pothole on carriageway	11/11/2021	Outside 36	RD: CW Pothole	Internal		Committed	50096770
Batch: 41105071 - Inspection Batch				Route: NW_CW1_East1		Date: 22/10/2021		
42080998	Potholes x 2 as marked	22/10/2021	20m east of junction	RD: CW Pothole	Internal		Committed	50094532
Batch: 41101176 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 22/09/2021		
Batch: 41098920 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 25/08/2021		
Batch: 41096998 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 27/07/2021		
Batch: 41094918 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 25/06/2021		
Batch: 41092901 - Inspection Batch No actionable defects found				Route: NW_CW1_East1		Date: 24/05/2021		
Batch: 41092474 - Inspection Batch				Route: NW_CF1_BroomhallEast1		Date: 17/05/2021		
42069099		17/05/2021		Gully: Brander Damaged	Internal		Uncommitted	5004194
42069098	Patching required	17/05/2021	Just before traffic lights	RD: CW Cracked/Broken	Internal		No Action Required	
42069092		17/05/2021		RD: FW HRA Cracked/Broken	Internal		Uncommitted	5006445
42069094	Signs: Defective / Damaged - What type of sign is it?: Traffic sign (Enquiry 545105) remove damaged pole and replace with new pole.	17/05/2021	Damaged sign pole on footway about 20mt before traffic lights at junction with meadow place road,	RD: Unlit Sign Damaged/Missing	Internal		No Action Required	
42069097	Break out existing HRA carriageway and relay with hra wearing course	17/05/2021	Lpost 22	RD: CW Cracked/Broken	Internal		No Action Required	
42069095	Break out existing HRA carriageway and relay with hra wearing course	17/05/2021	Lpost 23	RD: CW Cracked/Broken	Internal		No Action Required	

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: North West Locality	
Batch:	41092474 - Inspection Batch			Route:	NW_CF1_BroomhallEast1			Date: 17/05/2021
42069091		17/05/2021		Gully: Blocked / Flooding	Internal		Uncommitted	5004381
Batch:	41090801 - Inspection Batch			Route:	Ad hoc Route			Date: 21/04/2021
42067375	Pothole on carriageway	21/04/2021	Outside 1	RD: CW Pothole	Internal		Committed	50081437
Batch:	41090502 - Inspection Batch			Route:	NW_CW1_East1			Date: 16/04/2021
No actionable defects found								
Batch:	41087845 - Inspection Batch			Route:	NW_CW1_East1			Date: 17/03/2021
42064582	1no pothole	17/03/2021	At the junction with feather hall avenue	RD: CW Pothole	Internal		Committed	50078684
42064579	3no potholes	17/03/2021	Outside no1	RD: CW Pothole	Internal		Committed	50078681
Batch:	41086816 - Inspection Batch			Route:	Ad hoc Route			Date: 09/03/2021
42063675	Road: Defective / Damaged (Enquiry 1136566) pothole on carriageway	09/03/2021	Massive pothole on the corner of Ladywell Avenue and Road. Very difficult to avoid if turning left out of Ladywell Avenue because of the traffic island.	RD: CW Pothole	Internal		Committed	50077771
Batch: 41084697 - Inspection Batch				Route:	Ad hoc Route			Date: 23/02/2021
42062239	Road: Defective / Damaged (Enquiry 1127406) Pothole on carriageway	23/02/2021	Ladywell Road outside 36	RD: CW Pothole	Internal		Committed	50076124
Batch: 41084695 - Inspection Batch				Route:	Ad hoc Route			Date: 23/02/2021
42062236	Road: Defective / Damaged (Enquiry 1127406)	23/02/2021	Ladywell Road outside 3	RD: CW Pothole	Internal		Committed	50076122
Batch: 41084693 - Inspection Batch				Route:	Ad hoc Route			Date: 23/02/2021
42062234	Road: Defective / Damaged (Enquiry 1127406) Pothole on carriageway	23/02/2021	Ladywell Road outside 1	RD: CW Pothole	Internal		Committed	50076120
Batch: 41083991 - Inspection Batch				Route:	NW_CW1_East1			Date: 19/02/2021
No actionable defects found								
Batch: 41080838 - Inspection Batch				Route:	Ad hoc Route			Date: 03/02/2021
42060510	Pothole on carriageway	03/02/2021	Junction Meadowplace Road	RD: CW Pothole	Internal		Committed	50074034
Batch: 41079299 - Inspection Batch				Route:	NW_CW1_East1			Date: 28/01/2021
No actionable defects found								
Batch: 41072596 - Inspection Batch				Route:	Ad hoc Route			Date: 05/01/2021
42058277	Pothole on carriageway	05/01/2021	Outside 36	RD: CW Pothole	Internal		Committed	50071265
Batch: 41072594 - Inspection Batch				Route:	Ad hoc Route			Date: 05/01/2021
42058275	Street Furniture: Defective - Large pothole on Ladywell Road, Police Scotland reporting. Police advise towards Tesco side of Ladywell Road (Enquiry 1093999) pothole on carriageway	05/01/2021	LADYWELL HOUSE 10 Ladywell Road Edinburgh City of Edinburgh EH12 7TF	RD: CW Pothole	Internal		Committed	50071258

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset			Area: North West Locality	
Batch: 41071935 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 29/12/2020	
Batch: 41069765 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 24/11/2020	
Batch: 41068194 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 29/10/2020	
Batch: 41066691 - Inspection Batch				Route: Ad hoc Route			Date: 13/10/2020	
42054324	Pothole on carriageway at bus stop	13/10/2020	Outside 3	RD: CW Pothole	Internal		Committed	50064700
Batch: 41065281 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 01/10/2020	
Batch: 41062286 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 26/08/2020	
Batch: 41060163 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 14/07/2020	
Batch: 41059349 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 25/06/2020	
Batch: 41058711 - Inspection Batch				Route: Ad hoc Route			Date: 16/06/2020	
42050663	Road: Defective / Damaged (Enquiry 993266)	16/06/2020	4 potholes at traffic lights prior to meadow place rd	RD: CW Pothole	Internal		Committed	50056578
Batch: 41058227 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 26/05/2020	
Batch: 41057135 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 27/04/2020	
Batch: 41056498 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 07/04/2020	
Batch: 41056052 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 24/03/2020	
Batch: 41054549 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 02/03/2020	
Batch: 41052556 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1			Date: 17/02/2020	
Batch: 41051251 - Inspection Batch				Route: NW_CW1_East1			Date: 04/02/2020	
42045410	H	04/02/2020	Pothole on west heading carriageway approximately 5m west of junction with Ladywell Avenue at pedestrian crossing	RD: CW Pothole	Internal		Committed	50051172
Batch: 41051245 - Inspection Batch				Route: Ad hoc Route			Date: 04/02/2020	
42045403	H	04/02/2020	Potholes on carriageway outside no 36	RD: CW Pothole	Internal		Committed	50051165

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset			Area: North West Locality	
Batch: 41049991 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 20/01/2020
Batch: 41049923 - Inspection Batch				Route: Ad hoc Route				Date: 20/01/2020
42044155 H		20/01/2020	Potholes on carriageway outside no 3	RD: CW Pothole	Internal		Committed	50049833
Batch: 41049922 - Inspection Batch				Route: Ad hoc Route				Date: 20/01/2020
42044154 H		20/01/2020	Potholes on carriageway outside no 1	RD: CW Pothole	Internal		Committed	50049832
Batch: 41049502 - Inspection Batch				Route: Ad hoc Route				Date: 13/01/2020
42043707	Road: Defective / Damaged (Enquiry 938150)	13/01/2020	Pothole & depression on right hand turn lane at traffic lights	RD: CW Pothole	Internal		Committed	50049392
	Hot temp make safe							
Batch: 41049291 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 09/01/2020
Batch: 41048284 - Inspection Batch				Route: Ad hoc Route				Date: 18/12/2019
42042816	Hot temp make safe	18/12/2019	Pothole on carriageway at l/p no 17	RD: CW Pothole	Internal		Committed	50048112
Batch: 41048043 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 16/12/2019
Batch: 41047699 - Inspection Batch				Route: Ad hoc Route				Date: 11/12/2019
42042318	Hot temp make safe	11/12/2019	Pothole on carriageway at l/p no 01	RD: CW Pothole	Internal		Committed	50047496
Batch: 41047144 - Inspection Batch				Route: Ad hoc Route				Date: 04/12/2019
42041979	Hot temp make safe	04/12/2019	Potholes on carriageway approximately 10m west of junction with Ladywell Avenue	RD: CW Pothole	Internal		Committed	50047004
Batch: 41047037 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 02/12/2019
Batch: 41044917 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 29/10/2019
Batch: 41040512 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 20/09/2019
Batch: 41038772 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 27/08/2019
Batch: 41036910 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 26/07/2019
Batch: 41035216 - Inspection Batch	No actionable defects found			Route: NW_CW1_East1				Date: 26/06/2019

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
42705672	Gully: Blocked / Needs Clean - customer has asked if this can be cleaned out as soon as possible due to leaves blocking it (Enquiry 30602935)		RG: Gully - High Priority	Job Complete	02/08/2019	01/12/2020	Act. RDGC14/10004650
50047004	Hot temp make safe (RD: CW Pothole)	Potholes on carriageway approximately 10m west of junction with Ladywell Avenue	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/12/2019	05/12/2019	Act. ROAD/82028920
50047496	Hot temp make safe (RD: CW Pothole)	Pothole on carriageway at l/p no 01	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/12/2019	12/12/2019	Act. ROAD/82029252
50048112	Hot temp make safe (RD: CW Pothole)	Pothole on carriageway at l/p no 17	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/12/2019	19/12/2019	Act. ROAD/82029710
50049392	Road: Defective / Damaged (Enquiry 938150)	Pothole & depression on right hand turn lane at traffic lights	RD: Cat 2 - 5 Day	Job Complete	13/01/2020	15/01/2020	Act. ROAD/82030490
	Hot temp make safe (RD: CW Pothole)						
50049832	H (RD: CW Pothole)	Potholes on carriageway outside no 1	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/01/2020	20/01/2020	Act. ROAD/82030846
50049833	H (RD: CW Pothole)	Potholes on carriageway outside no 3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/01/2020	20/01/2020	Act. ROAD/82030847
50051165	H (RD: CW Pothole)	Potholes on carriageway outside no 36	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/02/2020	05/02/2020	Act. ROAD/82031897
50051172	H (RD: CW Pothole)	Pothole on west heading carriageway approximately 5m west of junction with Ladywell Avenue at pedestrian crossing	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/02/2020	05/02/2020	Act. ROAD/82031904
50056578	Road: Defective / Damaged (Enquiry 993266) (RD: CW Pothole)	4 potholes at traffic lights prior to meadow place rd	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/06/2020	16/06/2020	Act. ROAD/82036519
50064700	Pothole on carriageway at bus stop (RD: CW Pothole)	Outside 3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/10/2020	14/10/2020	Act. ROAD/82040223
50071258	Street Furniture: Defective - Large pothole on Ladywell Road, Police Scotland reporting. Police advise towards Tesco side of Ladywell Road (Enquiry 1093999) pothole on carriageway (RD: CW Pothole)	LADYWELL HOUSE 10 Ladywell Road Edinburgh City of Edinburgh EH12 7TF	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/01/2021	06/01/2021	Act. ROAD/82043006
50071265	Pothole on carriageway (RD: CW Pothole)	Outside 36	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/01/2021	06/01/2021	Act. ROAD/82043007
50074034	Pothole on carriageway (RD: CW Pothole)	Junction Meadowplace Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/02/2021	04/02/2021	Act. ROAD/82044352
50076120	Road: Defective / Damaged (Enquiry 1127406) Pothole on carriageway (RD: CW Pothole)	Ladywell Road outside 1	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2021	24/02/2021	Act. ROAD/82045504

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50076122	Road: Defective / Damaged (Enquiry 1127406) (RD: CW Pothole)	Ladywell Road outside 3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2021	24/02/2021	Act. ROAD/82045506
50076124	Road: Defective / Damaged (Enquiry 1127406) Pothole on carriageway (RD: CW Pothole)	Ladywell Road outside 36	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2021	24/02/2021	Act. ROAD/82045508
50077771	Road: Defective / Damaged (Enquiry 1136566) pothole on carriageway (RD: CW Pothole)	Massive pothole on the corner of Ladywell Avenue and Road. Very difficult to avoid if turning left out of Ladywell Avenue because of the traffic island.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/03/2021	10/03/2021	Act. ROAD/82046550
50078681	3no potholes (RD: CW Pothole)	Outside no1	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2021	22/03/2021	Act. ROAD/82047119
50078684	1no pothole (RD: CW Pothole)	At the junction with feather hall avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2021	22/03/2021	Act. ROAD/82047122
50081437	Pothole on carriageway (RD: CW Pothole)	Outside 1	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/04/2021	22/04/2021	Act. ROAD/82048787
50094532	Potholes x 2 as marked (RD: CW Pothole)	20m east of junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/10/2021	25/10/2021	Act. ROAD/82055259
50096770	Road: Defective / Damaged (Enquiry 1272859) Pothole on carriageway (RD: CW Pothole)	Outside 36	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/11/2021	12/11/2021	Act. ROAD/82056105
50101012	5 carriageway potholes (RD: CW Pothole)	At traffic lights for meadow place road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/12/2021	22/12/2021	Act. ROAD/82057853
50103735	4 carriageway potholes (RD: CW Pothole)	Near junction of meadow place road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2022	24/01/2022	Act. ROAD/82059111
50103736	1 carriageway pothole (RD: CW Pothole)	Outside 36	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2022	24/01/2022	Act. ROAD/82059112
50106886	Road: Defective / Damaged (Enquiry 1329167) pothole on carriageway (RD: CW Pothole)	Outside 36	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/02/2022	21/02/2022	Act. ROAD/82060571
50110787	Pavement: Damaged / Defective - @edinhelp Hello, there is quite a large hole in the pavement on Ladywell Road that will cause injury to anyone who steps in it. See attached image to show approx location (Enquiry 1354030) Pothole on footway (RD: FW HRA Pothole)	Outside 2 at bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/03/2022	31/03/2022	Act. ROAD/82062558
50110788	Pothole on carriageway (RD: CW Pothole)	Outside 1-3	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2022	31/03/2022	Act. ROAD/82062559
50110790	Pothole on carriageway (RD: CW Pothole)	Junction Ladywell Avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2022	31/03/2022	Act. ROAD/82062560
50113516	1 carriageway pothole (RD: CW Pothole)	At ladywell court	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/05/2022	13/05/2022	Act. ROAD/82064009

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50113517	Extensive patching required east bound lane (RD: CW Cracked/Broken)	Just before traffic lights	RD: Cat 4 - Programmed	No code allocated	12/05/2022	12/05/2023	Est.
50115565	1no pothole (RD: CW Pothole)	Outside no36	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/06/2022	22/06/2022	Act. ROAD/82065125
50124908	permanent repair required to carriageway (RD: CW Rutting)	Junction Ladywell Avenue	RD: Cat 4 - Programmed	No code allocated	28/12/2022	28/12/2023	Est.
50124918	Pothole on carriageway (RD: CW Pothole)	Outside 36	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/12/2022	29/12/2022	Act. ROAD/82069948
50126923	2x potholes (RD: CW Pothole)	Right turn lane at traffic lights.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/01/2023	23/01/2023	Act. ROAD/82071317
50126971	Road: Defective / Damaged (Enquiry 1488762) (RD: CW Pothole)	At feather hall avenue potholes and rutting of joints	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	06/02/2023	Act. ROAD/82071354
50127469	Road: Defective / Damaged (Enquiry 1493606) Pothole on carriageway (RD: CW Pothole)	Outside 36	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/01/2023	26/01/2023	Act. ROAD/82071712
50128088	Pothole on carriageway (RD: CW Pothole)	Outside 3	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2023	06/02/2023	Act. ROAD/82072149
50133675	Road: Defective / Damaged (Enquiry 1528856) pothole on carriageway heading east (RD: CW Pothole)	Junction Meadow Place Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/04/2023	06/04/2023	Act. ROAD/82075316
50134010	Pothole on carriageway (RD: CW Pothole)	Junction Ladywell Avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/04/2023	11/04/2023	Act. ROAD/82075590
50137048	1 cw pothole (RD: CW Pothole)	At car park entrance to Ladywell house	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/05/2023	31/05/2023	Act. ROAD/82077814
50137050	1 cw pothole (RD: CW Pothole)	As you enter Ladywell road from meadow place road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/05/2023	31/05/2023	Act. ROAD/82077816
50145099	Road: Defective / Damaged (Enquiry 1638300) pothole on carriageway (RD: CW Pothole)	Outside Ladywell House	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/11/2023	06/11/2023	Act. ROAD/82082358
50148636	Road: Defective / Damaged (Enquiry 1663793) pothole on carriageway (RD: CW Pothole)	Heading east from Meadow Place Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/12/2023	21/12/2023	Act. ROAD/82084447
50148638	Pothole on carriageway (RD: CW Pothole)	Outside 8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/12/2023	21/12/2023	Act. ROAD/82084449
50149433	Road: Defective / Damaged (Enquiry 1671391) pothole on carriageway (RD: CW Pothole)	Outside 36	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/01/2024	06/01/2024	Act. ROAD/82084976
50151275	Pothole on carriageway (RD: CW Pothole)	Outside 1-3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/01/2024	28/01/2024	Act. ROAD/82086171
50151276	Pothole on carriageway (RD: CW Pothole)	Outside 36	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/01/2024	28/01/2024	Act. ROAD/82086172
50152268	Pothole on carriageway (RD: CW Pothole)	Junction Ladywell Avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2024	09/02/2024	Act. ROAD/82086905

Site History Report

Effective: 20/06/2019 to 20/06/2025
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Ladywell Road (7900460)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50157150	Pothole on carriageway (RD: CW Junction Ladywell Avenue Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/04/2024	22/04/2024	Act. ROAD/82090324
50157152	Pothole on carriageway (RD: CW At traffic lights junction Meadow Pothole)	Place Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/04/2024	03/04/2024	Act. ROAD/82090326
50159765	Pothole on carriageway (RD: CW Junction Meadow Place Road Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/05/2024	05/05/2024	Act. ROAD/82092203
50160449	Pothole on carriageway (RD: CW Junction Ladywell Court Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/05/2024	16/05/2024	Act. ROAD/82092596
50161725	Pothole on carriageway (RD: CW Outside 36 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/06/2024	05/06/2024	Act. ROAD/82093301
50161726	Pothole on carriageway (RD: CW Outside Ladywell Medical Centre Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/06/2024	05/06/2024	Act. ROAD/82093302
50168720	Pothole on carriageway (RD: CW Outside 36 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/10/2024	28/10/2024	Act. ROAD/82097749
50170633	Pothole on carriageway (RD: CW Bus stop at junction Dunsmuir Court Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/12/2024	02/12/2024	Act. ROAD/82098998
50171351	Pothole on carriageway (RD: CW Heading east from Meadow Pothole)	Place Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/12/2024	12/12/2024	Act. ROAD/82099558
50171932	Pothole on carriageway (RD: CW Outside 36 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/12/2024	30/12/2024	Act. ROAD/82100011
50171933	Pothole on carriageway (RD: CW Outside Ladywell House Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/12/2024	30/12/2024	Act. ROAD/82100012
50171934	Pothole on carriageway (RD: CW Junction Ladywell Avenue Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/12/2024	30/12/2024	Act. ROAD/82100013
50172029	Pothole on carriageway (RD: CW Outside 36 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/01/2025	06/01/2025	Act. ROAD/82100079
50172450	Pothole on carriageway (RD: CW Outside 36 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/01/2025	09/01/2025	Act. ROAD/82100427
50173827	Pothole on carriageway (RD: CW Outside 36 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	29/01/2025	30/01/2025	Act. ROAD/82101454
50174028	Pothole on carriageway at bus stop (RD: CW Pothole)	Junction Dunsmuir Court	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/02/2025	03/02/2025	Act. ROAD/82101621
50174087	Replace missing bollard (RD: SFP Damaged Bollard)	Outside no1	RD: Cat 3 - 60 Day	Job Complete	03/02/2025	10/02/2025	Act. ROAD/82101660
50174883	Pothole on carriageway (RD: CW Outside 36 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/02/2025	13/02/2025	Act. ROAD/82102316
50175176	2 cw potholes (RD: CW Pothole)	Outside 36	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/02/2025	18/02/2025	Act. ROAD/82102574
50176414	Pothole on carriageway (RD: CW Outside 36 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/03/2025	06/03/2025	Act. ROAD/82103601
50176415	Permanent repair required (RD: CW Pothole)	Opposite 32 at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/03/2025	06/03/2025	Act. ROAD/82103602
50178034	Permanent repair required (RD: CW Pothole)	Junction Dunsmuir Court	RD: Cat 3 - 60 Day	Job Complete	02/04/2025	07/04/2025	Act. ROAD/82104738